

FARM CREDIT SYSTEM INSURANCE CORPORATION**12 CFR Part 1411**

RIN 3055-AA15

Rules of Practice and Procedure; Adjusting Civil Money Penalties for Inflation**AGENCY:** Farm Credit System Insurance Corporation.**ACTION:** Final rule.

SUMMARY: This rule implements inflation adjustments to civil money penalties (CMPs) that the Farm Credit System Insurance Corporation (FCSIC) may impose under the Farm Credit Act of 1971, as amended. These adjustments are required by 2015 amendments to the Federal Civil Penalties Inflation Adjustment Act of 1990.

DATES Effective Date: This rule will become effective February 7, 2019.

FOR FURTHER INFORMATION CONTACT: Howard Rubin, General Counsel, Farm Credit System Insurance Corporation, 1501 Farm Credit Drive, McLean, Virginia 22102, (703) 883-4380, TTY (703) 883-4390.

SUPPLEMENTARY INFORMATION:**A. Background**

The Federal Civil Penalties Inflation Adjustment Act Improvements Act of 2015 (the 2015 Act) amended the Federal Civil Penalties Inflation Adjustment Act of 1990 (the Inflation Adjustment Act)¹ to improve the effectiveness of civil monetary penalties and to maintain their deterrent effect. The Inflation Adjustment Act provides for the regular evaluation of CMPs and requires FCSIC, and every other Federal agency with authority to impose CMPs, to ensure that CMPs continue to maintain their deterrent values.²

FCSIC must enact regulations that annually adjust its CMPs pursuant to the inflation adjustment formula of the amended Inflation Adjustment Act and rounded using a method prescribed by the Inflation Adjustment Act. The new

amounts will apply to penalties assessed on or after the effective date of this rule. Agencies do not have discretion in choosing whether to adjust a CMP, by how much to adjust a CMP, or the methods used to determine the adjustment.

B. CMPs Imposed Pursuant to Section 5.65 of the Farm Credit Act

First, section 5.65(c) of the Farm Credit Act, as amended (Act), provides that any insured Farm Credit System bank that willfully fails or refuses to file any certified statement or pay any required premium shall be subject to a penalty of not more than \$100 for each day that such violations continue, which penalty FCSIC may recover for its use.³ Second, section 5.65(d) of the Act provides that, except with the prior written consent of the Farm Credit Administration, it shall be unlawful for any person convicted of any criminal offense involving dishonesty or a breach of trust to serve as a director, officer, or employee of any System institution.⁴ For each willful violation of section 5.65(d), the institution involved shall be subject to a penalty of not more than \$100 for each day during which the violation continues, which FCSIC may recover for its use.

FCSIC's current § 1411.1 provides that FCSIC can impose a maximum penalty of \$205 per day for a violation under section 5.65(c) and (d) of the Act.

C. Required Adjustments

The 2015 Act requires agencies to make annual adjustments for inflation. Annual inflation adjustments are based on the percent change between the October Consumer Price Index for all Urban Consumers (CPI-U) preceding the date of the adjustment, and the prior year's October CPI-U. Based on the CPI-U for October 2018, not seasonally adjusted, the cost-of-living adjustment multiplier for 2019 is 1.02522.⁵ Multiplying 1.02522 times the current penalty amount of \$205, after rounding to the nearest dollar as required by the 2015 Act, results in a new penalty amount of \$210.

D. Notice and Comment Not Required by Administrative Procedure Act

In accordance with the 2015 Act, Federal agencies shall adjust civil monetary penalties "notwithstanding" Section 553 of the Administrative Procedures Act. This means that public procedure generally required for agency

rulemaking—notice, an opportunity for comment, and a delay in effective date—is not required for agencies to issue regulations implementing the annual adjustment.

List of Subjects in 12 CFR Part 1411

Banks, banking, Civil money penalties, Penalties.

For the reasons stated in the preamble, part 1411 of chapter XIV, title 12 of the Code of Federal Regulations is amended as follows:

PART 1411—RULES OF PRACTICE AND PROCEDURE

■ 1. The authority citation for part 1411 continues to read as follows:

Authority: 12 U.S.C. 2277a–7(10), 2277a–14(c) and (d); 28 U.S.C. 2461 *note*.

■ 2. Revise § 1411.1 to read as follows:

§ 1411.1 Inflation adjustment of civil money penalties for failure to file a certified statement, pay any premium required or obtain approval before employment of persons convicted of criminal offenses.

In accordance with the Federal Civil Penalties Inflation Adjustment Act of 1990, as amended, a civil money penalty imposed pursuant to section 5.65(c) or (d) of the Farm Credit Act of 1971, as amended, shall not exceed \$210 per day for each day the violation continues.

Dated: January 30, 2019.

Dale Aultman,

Secretary, Farm Credit System Insurance Corporation.

[FR Doc. 2019–00948 Filed 2–6–19; 8:45 am]

BILLING CODE 6705–01–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2019–0015; Product Identifier 2018–NM–179–AD; Amendment 39–19550; AD 2019–02–03]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for all The Boeing Company Model 787–8, 787–9, and 787–10 airplanes. This AD requires revising the existing maintenance or inspection program, as applicable, to

¹ Pub. L. 101–410, Oct. 5, 1990, 104 Stat. 890, as amended by Pub. L. 104–134, title III, sec. 31001(s)(1), Apr. 26, 1996, 110 Stat. 1321–373; Pub. L. 105–362, title XIII, sec. 1301(a), Nov. 10, 1998, 112 Stat. 3293; Pub. L. 114–74, title VII, sec. 701(b), Nov. 2, 2015, 129 Stat. 599.

² Under the amended Inflation Adjustment Act, a CMP is defined as any penalty, fine, or other sanction that: (1) Either is for a specific monetary amount as provided by Federal law or has a maximum amount provided for by Federal law; (2) is assessed or enforced by an agency pursuant to Federal law; and (3) is assessed or enforced pursuant to an administrative proceeding or a civil action in the Federal courts. All three requirements must be met for a fine to be considered a CMP.

³ 12 U.S.C. 2277a–14(c).

⁴ 12 U.S.C. 2277a–14(d).

⁵ See Office of Management and Budget Memorandum M–19–04 (December 14, 2018).

incorporate new or more restrictive airworthiness limitations. This AD was prompted by reports of warpage of internal engine fire handle components, which can cause binding and prevent proper operation. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective February 22, 2019.

We must receive comments on this AD by March 25, 2019.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0015; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Rebel Nichols, Aerospace Engineer, Propulsion Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3556; email: Rebel.Nichols@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We have received reports from Boeing of warpage of internal engine fire handle components, which can cause binding and prevent proper operation. A latently failed engine fire handle could prevent the fire extinguishing agent from being able to be released. In the event of certain engine fires, the potential exists for an engine fire to be uncontrollable. This unsafe condition, if not addressed, could result in the inability to extinguish an engine fire that, if

uncontrollable, could lead to wing failure.

FAA's Determination

We are issuing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

AD Requirements

This AD requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations.

Compliance with these actions is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by this AD, the operator may not be able to accomplish the actions described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance according to paragraph (j) of this AD.

Interim Action

We consider this AD interim action. The manufacturer is currently developing a terminating action that will address the unsafe condition identified in this AD. Once this terminating action is developed, approved, and available, we might consider additional rulemaking.

FAA's Justification and Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because warpage of internal engine fire handle components can cause binding and prevent proper operation. A latently failed engine fire handle could prevent the fire extinguishing agent from being able to be released. In the event of certain engine fires, the potential exists for an engine fire to be uncontrollable, which could lead to wing failure. Additionally, the compliance time for the required action is shorter than the time necessary for the public to comment and for publication of the final rule. Therefore, we find good cause that notice and opportunity for prior public comment are impracticable. In addition, for the reasons stated above, we find that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment. However, we invite you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under the **ADDRESSES** section. Include the docket number FAA-2019-0015 and Product Identifier 2018-NM-179-AD at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this final rule. We will consider all comments received by the closing date and may amend this final rule because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this final rule.

Costs of Compliance

We estimate that this AD affects 120 airplanes of U.S. registry. We estimate the following costs to comply with this AD:

We have determined that revising the existing maintenance or inspection program takes an average of 90 work-hours per operator, although we recognize that this number may vary from operator to operator. In the past, we have estimated that this action takes 1 work-hour per airplane. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), we have determined that a per-operator estimate is more accurate than a per-airplane estimate. Therefore, we estimate the total cost per operator to be \$7,650 (90 work-hours × \$85 per work-hour).

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs" describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation

is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2019-02-03 The Boeing Company:

Amendment 39-19550; Docket No. FAA-2019-0015; Product Identifier 2018-NM-179-AD.

(a) Effective Date

This AD is effective February 22, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model 787-8, 787-9, and 787-10 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 26, Fire protection.

(e) Unsafe Condition

This AD was prompted by reports of warpage of internal fire handle components, which can cause binding and prevent proper operation. We are issuing this AD to address a latent failure of the engine fire handle, which could result in the inability to extinguish an engine fire that, if uncontrollable, could lead to wing failure.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Revision of Maintenance or Inspection Program

Within 14 days after the effective date of this AD, revise the existing maintenance or inspection program, as applicable, to add airworthiness limitation 28-AWL-FIRE, by incorporating the information specified in figure 1 to paragraph (g) of this AD into the Airworthiness Limitations Section of the Instructions for Continued Airworthiness. The initial compliance time for accomplishing the actions specified in figure 1 to paragraph (g) of this AD is within 45 days after the effective date of this AD.

Figure 1 to paragraph (g) of this AD: Engine fire handle operational check

AWL No.	Task	Interval	Applicability	Description
28-AWL-FIRE	ALI	30 days	787-8, -9, and -10 airplanes	Engine Fire Handle Operational Check. Concern: The fire handle design can result in airplanes operating with an engine fire handle that cannot be operated. A latently failed engine fire handle could prevent the fire

				extinguishing agent from being able to be released. In the event of certain engine fires, the potential exists for an engine fire to be uncontrollable. Perform the following engine fire handle checks (unless checked by the flightcrew in a manner approved by the principal operations inspector): 1. Press the left engine fire handle solenoid override button, and verify that the handle can be pulled up using normal force. CAUTION: Do not rotate the engine fire handle; inadvertent discharge of the fire extinguishing agent would result. Although not required, pulling the FIRE EXT BOTTLE – ENG L1 and L2 circuit breakers will prevent fire bottle discharge. 2. Stow the handle. 3. Press the right engine fire handle solenoid override button, and verify that the handle can be pulled up using normal force. CAUTION: Do not rotate the engine fire handle; inadvertent discharge of the fire extinguishing agent would result. Although not required, pulling the FIRE EXT BOTTLE – ENG R1 and R2 circuit breakers will prevent fire bottle discharge. 4. Stow the handle. Replace any engine fire handle that fails any operational check before further flight.
--	--	--	--	--

(h) No Alternative Actions or Intervals

After accomplishment of the existing maintenance or inspection program revision required by paragraph (g) of this AD, no alternative actions (*e.g.*, inspections) or intervals may be used unless the actions or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (j) of this AD.

(i) Special Flight Permit

Special flight permits, as described in 14 CFR 21.197 and 21.199, are not allowed.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your

principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(k) Related Information

For more information about this AD, contact Rebel Nichols, Aerospace Engineer, Propulsion Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3556; email: Rebel.Nichols@faa.gov.

(l) Material Incorporated by Reference

None.

Issued in Des Moines, Washington, on January 30, 2019.

Michael Kaszycki,

*Acting Director, System Oversight Division,
Aircraft Certification Service.*

[FR Doc. 2019-01244 Filed 2-6-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

[Docket No. 31229; Amdt. No. 3831]

Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This rule establishes, amends, suspends, or removes Standard Instrument Approach Procedures (SIAPs) and associated Takeoff Minimums and Obstacle Departure Procedures (ODPs) for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: This rule is effective February 7, 2019. The compliance date for each SIAP, associated Takeoff Minimums,

and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the **Federal Register** as of February 7, 2019.

ADDRESSES: Availability of matters incorporated by reference in the amendment is as follows:

For Examination

1. U.S. Department of Transportation, Docket Ops-M30, 1200 New Jersey Avenue SE, West Bldg., Ground Floor, Washington, DC 20590-0001.

2. The FAA Air Traffic Organization Service Area in which the affected airport is located;

3. The office of Aeronautical Navigation Products, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 or,

4. The National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/code-of-federal-regulations/ibr-locations.html>.

Availability

All SIAPs and Takeoff Minimums and ODPs are available online free of charge. Visit the National Flight Data Center at nfdc.faa.gov to register. Additionally, individual SIAP and Takeoff Minimums and ODP copies may be obtained from the FAA Air Traffic Organization Service Area in which the affected airport is located.

FOR FURTHER INFORMATION CONTACT:

Thomas J. Nichols, Flight Procedures and Airspace Group, Flight Technologies and Procedures Division, Flight Standards Service, Federal Aviation Administration. Mailing Address: FAA Mike Monroney Aeronautical Center, Flight Procedures and Airspace Group, 6500 South MacArthur Blvd., Registry Bldg. 29 Room 104, Oklahoma City, OK 73125. Telephone: (405) 954-4164.

SUPPLEMENTARY INFORMATION: This rule amends Title 14 of the Code of Federal Regulations, Part 97 (14 CFR part 97), by establishing, amending, suspending, or removes SIAPs, Takeoff Minimums and/or ODPs. The complete regulatory description of each SIAP and its associated Takeoff Minimums or ODP for an identified airport is listed on FAA form documents which are incorporated by reference in this amendment under 5 U.S.C. 552(a), 1 CFR part 51, and 14 CFR part 97.20. The applicable FAA forms are FAA Forms 8260-3, 8260-4, 8260-5, 8260-15A, and 8260-15B when required by an entry on 8260-15A.

The large number of SIAPs, Takeoff Minimums and ODPs, their complex nature, and the need for a special format make publication in the **Federal Register** expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, Takeoff Minimums or ODPs, but instead refer to their graphic depiction on charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP, Takeoff Minimums and ODP listed on FAA form documents is unnecessary. This amendment provides the affected CFR sections and specifies the types of SIAPs, Takeoff Minimums and ODPs with their applicable effective dates. This amendment also identifies the airport and its location, the procedure, and the amendment number.

Availability and Summary of Material Incorporated by Reference

The material incorporated by reference is publicly available as listed in the **ADDRESSES** section.

The material incorporated by reference describes SIAPs, Takeoff Minimums and/or ODPs as identified in the amendatory language for part 97 of this final rule.

The Rule

This amendment to 14 CFR part 97 is effective upon publication of each separate SIAP, Takeoff Minimums and ODP as Amended in the transmittal. Some SIAP and Takeoff Minimums and textual ODP amendments may have been issued previously by the FAA in a Flight Data Center (FDC) Notice to Airmen (NOTAM) as an emergency action of immediate flight safety relating directly to published aeronautical charts.

The circumstances that created the need for some SIAP and Takeoff Minimums and ODP amendments may require making them effective in less than 30 days. For the remaining SIAPs and Takeoff Minimums and ODPs, an effective date at least 30 days after publication is provided.

Further, the SIAPs and Takeoff Minimums and ODPs contained in this amendment are based on the criteria contained in the U.S. Standard for Terminal Instrument Procedures (TERPS). In developing these SIAPs and Takeoff Minimums and ODPs, the TERPS criteria were applied to the conditions existing or anticipated at the affected airports. Because of the close and immediate relationship between these SIAPs, Takeoff Minimums and ODPs, and safety in air commerce, I find