

airplanes that are equipped with a Honeywell KAP 140 autopilot computer system installed on the center instrument control panel near the throttle. We inadvertently duplicated affected airplane serial numbers and included a serial number that should not be affected by this AD in the applicability section. This action corrects the applicability section of AD 2003-24-13, Amendment 39-13382.

EFFECTIVE DATE: The effective date of this AD remains January 20, 2004.

FOR FURTHER INFORMATION CONTACT: Dan Withers, Aerospace Engineer, Wichita Aircraft Certification Office (ACO), FAA, 1801 Airport Road, Mid-Continent Airport, Wichita, Kansas 67209; telephone: (316) 946-4196; facsimile: (316) 946-4407.

SUPPLEMENTARY INFORMATION:

Discussion

On November 25, 2003, FAA issued AD 2003-24-13, Amendment 39-13382 (68 FR 67789, December 4, 2003), which applies to certain Cessna Models 172R, 172S, 182S, 182T, T182T, 206H, and T206H airplanes that are equipped with a Honeywell KAP 140 autopilot computer system installed on the center instrument control panel near the throttle. This AD requires you to install an update to the operating software of the KAP 140 autopilot computer system, change the unit's part number, and change the software modification identification tag.

Need for the Correction

The FAA inadvertently duplicated affected airplane serial numbers for Model T206H airplanes in the applicability section of this AD. We also inadvertently included serial number T20608368 for Model T206H airplanes in the applicability section of this AD

that is not affected by this AD. This correction is needed to ensure that the affected airplane owners/operators do not have unnecessary action performed on their airplanes.

Correction of Publication

■ Accordingly, the publication of December 4, 2003 (68 FR 67789), of Amendment 39-13382; AD 2003-24-13, which was the subject of FR Doc. 03-30075, is corrected as follows:

§ 39.13 [Corrected]

■ On page 67791, in section 39.13 [Amended], 2., replace paragraph (c) of the AD with the following text:

“What Airplanes Are Affected by This AD?”

(c) This AD affects the following airplane models and serial numbers that are:

- (1) equipped with a KAP 140 autopilot computer system, part number (P/N) 065-00176-2602, P/N 065-00176-5402, or P/N 065-00176-7702; and
- (2) certificated in any category;

Model	Serial No.
172R	17280001 through 17281073, 17281075 through 17281127, and 17281130
172S	172S8001 through 172S9195, 172S9197, 172S9198, and 172S9200 through 172S9203
182S	18280001 through 18280944
182T	18280945 through 18281064, 18281067 through 18281145, 18281147 through 18281163, 18281165 through 18281167, and 18281172
T182T	T18208001 through T18208109, and T18208111 through T18208177
206H	20608001 through 20608183, 20608185, 20608187, and 20608188
T206H	T20608001 through T20608039, T20608041 through T20608367, T20608369 through T20608379, T20608381, T20608382, and T20608385”

Action is taken herein to correct this reference in AD 2003-24-13 and to add this AD correction to § 39.13 of the Federal Aviation Regulations (14 CFR 39.13).

The effective date remains January 20, 2004.

Issued in Kansas City, Missouri, on December 16, 2003.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-31667 Filed 12-29-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NE-22-AD; Amendment 39-13369; AD 2003-23-05]

RIN 2120-AA64

Airworthiness Directives; Titeflex Corporation; Correction

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; correction.

SUMMARY: This document makes corrections to Airworthiness Directive (AD) 2003-23-05 applicable to certain Titeflex Corporation hoses installed on Boeing 737-300, -400, -500, -600, -700, -700C, -800, -900, 747-400, 757-200, -300, 767-200, -300, and -300F airplanes, that was published in the **Federal Register** on November 19, 2003 (68 FR 65157). The AD number is incorrect in the Preamble Section and in the Regulatory Section five corrections are needed in Table 1. This document corrects these errors. In all other respects, the original document remains the same.

EFFECTIVE DATE: Effective December 30, 2003.

FOR FURTHER INFORMATION CONTACT:

Terry Fahr, Aerospace Engineer, Boston Aircraft Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (781) 238-7155; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION: A final rule AD, FR Doc. 03-28730, applicable to certain Titeflex Corporation hoses installed on Boeing 737-300, -400, -500, -600, -700, -700C, -800, -900,

747-400, 757-200, -300, 767-200, -300, and -300F airplanes, was published in the **Federal Register** on November 19, 2003 (68 FR 65157). The following corrections are needed:

§ 39.13 [Corrected]

■ On page 65157, in the first column, in the Preamble Section, in the fifth line, “39-13369; AD 2003-23-05-AD “is corrected to read “39-13369; AD 2003-23-05”. Also, on page 65158, in Table 1, the following changes are made:

■ In the fifth column, for item (2) 737-600, -700, -700C, -800, and -900 airplanes, first line, “737-26A1109, Revision 12, dated May 8, 2003” is corrected to read “737-26A1109, Revision 2, dated May 8, 2003”.

■ In the second column, for item (3) 747-400 airplanes, “BACH5R0186XX” is corrected to read “BACH5S0186XX” and “BACH5S0080YY” is deleted.

■ In the second column, for item (4) 757-200 airplanes, under BACH5S0110XN, add “No number” and add in the third column on the same line, “109422”.

■ Also, on page 65159, in Table 1, in the second column, for item (5) 757-300

airplanes, under BACH5S0074XN, add: "Optional 453N2240-33"

Issued in Burlington, MA, on December 19, 2003.

Peter A. White,

Assistant Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 03-31850 Filed 12-29-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Parts 121, 125, 135, and 145

[Docket No. FA-2000-7952]

RIN 2120-A113

Service Difficulty Reports

AGENCY: Federal Aviation Administration, DOT

ACTION: Final rule; delay of effective date.

SUMMARY: The Federal Aviation Administration (FAA) is further delaying the effective date of a final rule that amends the reporting requirements for air carriers and certificated domestic and foreign repair station operators concerning failures, malfunctions, and defects of aircraft, aircraft engines, systems, and components. This action is prompted by the FAA's decision to address industry concerns about the final rule. Delaying the effective date of the final rule will allow the agency time for consideration of industry concerns.

DATES: The effective date of the rule amending 14 CFR parts 121, 125, 135, and 145 published at 65 FR 56191 (Sept. 15, 2000) and most recently delayed at 67 FR 78970 (Dec. 27, 2002) is further delayed from January 16, 2004, until January 30, 2006.

FOR FURTHER INFORMATION CONTACT: Jose E. Figueroa, Flight Standards Service, Tampa Flight Standards District Office, 5601 Mariner Street, Suite 310, Tampa, Florida 33609-3413, telephone 813-287-4932.

SUPPLEMENTARY INFORMATION:

Background

On September 15, 2000, the FAA published the final rule entitled "Service Difficulty Reports" (65 FR 56191). We also requested comments on the information collection requirements. The final rule, which had an effective date of January 16, 2001, amended the reporting requirements for air carriers and certificated domestic and foreign repair station operators concerning failures, malfunctions, and defects of aircraft, aircraft engines, systems, and

components. The FAA received extensive written comments on the Service Difficulty Reporting (SDR) requirements and on the potential duplicate reporting of certain failures, malfunctions, and defects.

On November 30, 2000, the FAA announced (65 FR 71247) that a public meeting on this rulemaking would be held on December 11, 2000. Participants at that meeting raised novel issues that the FAA was not aware of when preparing the final rule.

As a result of the concerns expressed at the meeting and those raised during the comment period for information collection requirements on the final rule, the FAA delayed the effective date on four separate occasions to January 16, 2004. The purpose of these delays was to allow the agency time to consider industry's concerns and to consider issuing a notice of proposed rulemaking (NPRM). Unfortunately, we have not completed action on this initiative, and a further delay of the effective date is necessary to allow additional time for us to address industry concerns.

Related Activity

Revised Aeronautical Repair Station Regulations

On August 6, 2001, the FAA published revisions to its repair station rule (66 FR 41088). As a part of that action, we removed §§ 145.63 and 145.79, and created a new § 145.221 to contain SDR requirements for repair stations. The FAA intends for the § 145.221 amendment to take effect on January 31, 2004, concurrent with other repair station requirements (see 66 FR 41088 (Aug. 6, 2001) delayed until Jan. 31, 2004, at 68 FR 55819 (Sept. 29, 2003).)

Good Cause for Immediate Adoption

Since the delay in the effective date of the final rule does not impose any new requirements or any additional burden on the regulated public, the FAA finds that good cause exists for immediate adoption of the new effective date without a 30-day notice.

The Effect of Our Decision

Our decision delays the effective date of the SDR final rule from January 16, 2004 until January 31, 2006. The FAA cautions the industry that the existing rules will remain in effect until the new dates are effective, with the exception of the § 145.221 amendment that will be effective on January 31, 2004.

Issued in Washington, DC, on December 19, 2003.

Marion Blakey

Administrator.

[FR Doc. 03-31883 Filed 12-23-03; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF HEALTH AND HUMAN SERVICES

Food and Drug Administration

21 CFR Part 600

[Docket No. 2003N-0528]

Revision of the Requirements for Spore-Forming Microorganisms

AGENCY: Food and Drug Administration, HHS.

ACTION: Direct final rule.

SUMMARY: The Food and Drug Administration (FDA) is amending the biologics regulations by providing options to the existing requirement for separate, dedicated facilities and equipment for work with spore-forming microorganisms. FDA is amending the regulations due to advances in facility, system, and equipment design and in sterilization technologies that will allow work with spore-forming microorganisms to be performed in multiproduct manufacturing areas. We are publishing this rule because the existing requirement for always using separate, dedicated facilities and equipment for work with spore-forming microorganisms is no longer necessary. We are taking this action as part of our continuing effort to reduce the burden of unnecessary regulations on industry and to revise outdated regulations without diminishing public health protection. We are issuing these amendments directly as a final rule because they are noncontroversial and there is little likelihood that we will receive any significant comments opposing the rule. Elsewhere in this issue of the **Federal Register**, we are publishing a companion proposed rule under our usual procedures for notice and comment in the event that we receive any significant adverse comments on the direct final rule. If we receive any significant adverse comments that warrant terminating the direct final rule, we will consider such comments on the proposed rule in developing the final rule.

DATES: This rule is effective June 1, 2004. Submit written or electronic comments on or before March 15, 2004. If we receive no significant adverse comments during the specified