

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979), and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

You can find our regulatory evaluation and the estimated costs of compliance in the AD Docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

2009-08-04 Hawker Beechcraft Corporation (Formerly Raytheon Aircraft Company): Amendment 39-15877. Docket No. FAA-2008-1240; Directorate Identifier 2008-NM-098-AD.

Effective Date

- (a) This airworthiness directive (AD) is effective May 14, 2009.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to Hawker Beechcraft Corporation Model BH.125 series 600A airplanes and Model HS.125 series 700A airplanes, certificated in any category; as identified in Hawker Beechcraft Mandatory Service Bulletin SB 24-3850, dated January 2008, which have been modified in accordance with Supplemental Type Certificate SA2271SW.

Unsafe Condition

(d) This AD results from a report indicating that a blower motor of the cockpit ventilation and avionics cooling system seized up and gave off smoke. We are issuing this AD to prevent smoke and fumes in the cockpit in the event that a blower motor seizes and overheats due to excessive current draw.

Compliance

- (e) Comply with this AD within the compliance times specified, unless already done.

Inspection and Rework

(f) Within 600 flight hours or 6 months after the effective date of this AD, whichever occurs first, inspect the wiring diagrams containing the cockpit blowers and compare with the current airplane configuration, in accordance with the Accomplishment Instructions of Hawker Beechcraft Mandatory Service Bulletin SB 24-3850, dated January 2008; except as provided by paragraph (g) of this AD.

(1) If the current airplane configuration does not match the applicable cockpit blower wiring diagrams, before further flight, rework the wiring using a method approved by the Manager, Special Certification Office, ASW-190, Rotorcraft Directorate, FAA. For the determination to be approved by the Manager, Special Certification Office, as required by this paragraph, the Manager's approval letter must specifically refer to this AD.

(2) If the current airplane configuration matches the applicable cockpit blower wiring diagrams, before further flight, rework the wiring in accordance with the Accomplishment Instructions of Hawker Beechcraft Mandatory Service Bulletin SB 24-3850, dated January 2008.

No Submission of Certain Information

(g) Although Hawker Beechcraft Mandatory Service Bulletin SB 24-3850, dated January 2008, specifies to submit certain information to the manufacturer, this AD does not include that requirement.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Special Certification Office, ASW-190, Rotorcraft Directorate, FAA, *Attn:* Andy Shaw, Aerospace Engineer, Special Certification Office, ASW-190, FAA, Southwest Regional Office, 2601 Meacham Boulevard, Fort Worth, Texas 76137; telephone (817) 222-5188; fax (817) 222-5785; has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Material Incorporated by Reference

- (i) You must use Hawker Beechcraft Mandatory Service Bulletin SB 24-3850,

dated January 2008, to do the actions required by this AD, unless the AD specifies otherwise.

(1) For service information identified in this AD, contact Hawker Beechcraft Corporation, Department 62, P.O. Box 85, Wichita, Kansas 67201-0085; telephone 316-676-8238; fax 316-676-6706; e-mail tmdc@hawkerbeechcraft.com; Internet https://www.hawkerbeechcraft.com/service_support/pubs.

(2) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(3) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 2, 2009.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-8080 Filed 4-8-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0329; Directorate Identifier 2009-CE-020-AD; Amendment 39-15878; AD 2009-08-05]

RIN 2120-AA64

Airworthiness Directives; Liberty Aerospace Incorporated Model XL-2 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Liberty Aerospace Incorporated Model XL-2 airplanes. This AD requires you to repetitively inspect the exhaust muffler for cracks and to replace the exhaust muffler when cracks are found. This AD is the result of reports that cracks have been found in the exhaust muffler during maintenance and service inspections. We are issuing this AD to detect and correct cracks in the exhaust muffler, which could result in carbon monoxide entering the cabin through the heating system. Carbon monoxide entering into the airplane cabin could lead to incapacitation of the pilot.

DATES: This AD becomes effective on April 20, 2009.

On April 20, 2009, the Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD.

We must receive any comments on this AD by June 8, 2009.

ADDRESSES: Use one of the following addresses to comment on this AD.

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

To get the service information identified in this AD, contact Liberty Aerospace, 100 Aerospace Drive, Melbourne, Florida 32901; *telephone:* (321) 752-0332 or (800) 759-5953; *fax:* (321) 752-0377; *Internet:* <http://www.libertyaircraft.com>.

To view the comments to this AD, go to <http://www.regulations.gov>. The docket number is FAA-2009-0329; Directorate Identifier 2009-CE-020-AD.

FOR FURTHER INFORMATION CONTACT:

—Corey Spiegel, Aerospace Engineer, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Blvd., Suite 450, Atlanta, Georgia 30349; *telephone:* (770) 703-6045; *facsimile:* (770) 703-6097; *e-mail:* corey.spiegel@faa.gov; or
 —Cindy Lorenzen, Aerospace Engineer, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Blvd., Suite 450, Atlanta, Georgia 30349; *telephone:* (770) 703-6078; *facsimile:* (770) 703-6097; *e-mail:* cindy.lorenzen@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We received reports of cracks found in the exhaust mufflers of Liberty Aerospace Incorporated (Liberty Aerospace) Model XL-2 airplanes. One crack was found during maintenance, which prompted Liberty Aerospace to publish service information requesting the exhaust mufflers be inspected for cracks on all Model XL-2 airplanes. Seven additional cracks have been found during these service inspections.

Investigation is ongoing to determine what is causing the exhaust mufflers to

crack. Excessive vibration caused by improper propeller clocking position may be a contributing factor.

This condition, if not corrected, could result in carbon monoxide entering the cabin through the heating system and cause incapacitation of the pilot.

Relevant Service Information

We reviewed Liberty Aerospace, Inc. Service Document Critical Service Bulletin (CSB) CSB-09-001, Revision Level B, Revised on March 18, 2009. The service information describes procedures for inspecting the exhaust muffler for cracks and replacing the exhaust muffler when cracks are found.

FAA's Determination and Requirements of This AD

We are issuing this AD because we evaluated all the information and determined the unsafe condition described previously is likely to exist or develop on other products of the same type design. This AD requires repetitively inspecting the exhaust muffler for cracks and replacing the exhaust muffler when cracks are found. This AD also requires inspecting the propeller for proper clocking position and correcting any discrepancies found.

Liberty Aerospace is reviewing the information related to the occurrences referenced in this AD and may develop a modification that, when incorporated, would eliminate the need for the repetitive inspections required by this AD. The FAA will review any modification that is developed, determine whether it would eliminate the need for the requirements of this action, and then determine whether additional AD action is necessary.

FAA's Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because cracks in the exhaust muffler could result in carbon monoxide entering the cabin through the heating system. Carbon monoxide entering into the airplane cabin could lead to incapacitation of the pilot. Therefore, we determined that notice and opportunity for public comment before issuing this AD are impracticable and that good cause exists for making this amendment effective in fewer than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not precede it by notice and an

opportunity for public comment. We invite you to send any written relevant data, views, or arguments regarding this AD. Send your comments to an address listed under the **ADDRESSES** section. Include the docket number "FAA-2009-0329; Directorate Identifier 2009-CE-020-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the AD. We will consider all comments received by the closing date and may amend the AD in light of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive concerning this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

Examining the AD Docket

You may examine the AD docket that contains the AD, the regulatory evaluation, any comments received, and other information on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone (800) 647-5527) is located at the street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2009-08-05 Liberty Aerospace

Incorporated: Amendment 39-15878; Docket No. FAA-2009-0329; Directorate Identifier 2009-CE-020-AD.

Effective Date

(a) This AD becomes effective on April 20, 2009.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Model XL-2 airplanes, serial numbers 0007, 0009, and subsequent, that are certificated in any category.

Unsafe Condition

(d) This AD is the result of reports that eight cracks have been found in the exhaust muffler during maintenance and service inspections. We are issuing this AD to detect and correct cracks in the exhaust muffler, which could result in carbon monoxide entering the cabin heating system. This condition could lead to incapacitation of the pilot.

Compliance

(e) To address this problem, you must do the following, unless already done:

Actions	Compliance	Procedures
(1) Inspect the following: (i) The exhaust muffler for cracks. There are two different exhaust systems available for the affected airplanes. They are: (A) Standard exhaust system, part number (P/N) DEL200201-002 that incorporates muffler P/N DEL200201-101; and (B) Reduced sound exhaust system, P/N DEL200201-003 that incorporates muffler P/N 200201-104. (ii) The tail pipe and the tail pipe opening in the lower cowl for a 0.5-inch minimum clearance. (iii) Inspect the propeller for proper propeller clocking position. (2) As a result of the inspections required in paragraphs (e)(1)(ii) and (e)(1)(iii) of this AD: (i) If the clearance between the tail pipe and the tail pipe opening is less than the required 0.5-inch minimum, trim the lower cowl as needed to achieve the minimum clearance. (ii) If there is a discrepancy in the propeller clocking position, remove and reinstall the propeller at the correct position. (3) As a result of the initial inspection required in paragraph (e)(1)(i) of this AD or any repetitive inspection required in paragraph (e)(5) of this AD, if a crack is found, replace the exhaust muffler. (i) The manufacturer will provide the replacement exhaust system. (ii) A reduced sound exhaust system may be replaced with a standard exhaust system. (iii) Installing a reduced sound exhaust system as a replacement part also requires installing a bypass SCAT tube and a "Do Not Use" placard on or near the heater knob.	Initially inspect within the next 10 hours time-in-service (TIS) after April 20, 2009 (the effective date of this AD) or at the next annual inspection, whichever occurs first. Repetitively inspect the exhaust muffler thereafter as specified in paragraph (e)(5) of this AD. Before further flight after the inspection required in paragraph (e)(1) of this AD. Before further flight after the initial inspection required in paragraph (e)(1) of this AD and before further flight after any repetitive inspection required in paragraph (e)(5) of this AD.	Follow Liberty Aerospace, Inc. Service Document Critical Service Bulletin (CSB) CSB-09-001, Revision Level B, Revised on March 18, 2009. As specified in Liberty Aerospace, Inc. Service Document Critical Service Bulletin (CSB) CSB-09-001, Revision Level B, Revised on March 18, 2009. Follow Liberty Aerospace, Inc. Service Document Critical Service Bulletin (CSB) CSB-09-001, Revision Level B, Revised on March 18, 2009.

Actions	Compliance	Procedures
(4) If the airplane is equipped with a reduced sound exhaust system and no cracks are found during the initial inspection required in paragraph (e)(1) of this AD, install a bypass SCAT tube and a "Do Not Use" placard on or near the heater knob. (5) If no cracks are found in the exhaust muffler during the initial inspection required in paragraph (e)(1) of this AD or if the exhaust muffler was replaced as required in paragraph (e)(3) of this AD, repetitively inspect thereafter at the intervals specified in paragraphs (e)(5)(i), (e)(5)(ii), and (e)(5)(iii) of this AD. (6) Report the results of the following inspections required in this AD to the FAA. (i) Initial inspection required in paragraph (e)(1) of this AD. (ii) Repetitive inspections required in paragraph (e)(5) of this AD only if cracks are found. (iii) The Office of Management and Budget (OMB) approved the information collection requirements contained in this regulation under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 <i>et seq.</i>) and assigned OMB Control Number 2120-0056.	Within the next 10 hours TIS after April 20, 2009 (the effective date of this AD). (i) For airplanes equipped with a standard exhaust system and the optional bypass SCAT tube has not been installed, repetitively inspect thereafter every 25 hours TIS or every 12 months, whichever occurs first. (ii) For airplanes equipped with a standard exhaust system and the optional bypass SCAT tube has been installed, repetitively inspect thereafter every 50 hours TIS or every 12 months, whichever occurs first. (iii) For airplanes equipped with a reduced sound exhaust system and the required bypass SCAT tube has been installed, repetitively inspect thereafter every 50 hours TIS or every 12 months, whichever occurs first. Within 10 days after each inspection required by this AD.	Follow Liberty Aerospace, Inc. Service Document Critical Service Bulletin (CSB) CSB-09-001, Revision Level B, Revised on March 18, 2009. Follow Liberty Aerospace, Inc. Service Document Critical Service Bulletin (CSB) CSB-09-001, Revision Level B, Revised on March 18, 2009. Use the form (Figure 1 of this AD) and submit it to FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Blvd., Suite 450, Atlanta, Georgia 30349.

AD 2009-08-05 Inspection Report		
Airplane Serial Number		
Airplane Tach Hours at time of inspection		
Propeller type (circle one)	MT	Sensenich
Propeller Tach Hours at time of inspection		
Exhaust Type (circle one)	Standard	Reduced Sound
Is Exhaust Cracked? (circle one)	Yes	No
Did lower cowl require trimming at the tail pipe opening? (circle one) <i>Not applicable after initial inspection.</i>	Yes	No
Did the propeller clocking position need to be corrected? (circle one) <i>Not applicable after initial inspection.</i>	Yes	No
Were any other discrepancies noticed during the inspection?		
Name:		
Telephone and/or e-mail address:		
Date:		
<i>Send report to: Corey Spiegel, Aerospace Engineer, Atlanta ACO, One Crown Center, 1895 Phoenix Blvd., Suite 450, Atlanta Georgia 30349; facsimile: (770) 703-6097; email: corey.spiegel@faa.gov.</i>		

Figure 1

Special Flight Permit

(f) Under 14 CFR part 39.23, we are limiting the special flight permits for this AD by the following conditions:

- (1) The cabin heat turned off; and
- (2) The fresh air vents are open.

Alternative Methods of Compliance (AMOCs)

(g) The Manager, Atlanta Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Corey Spiegel, Aerospace Engineer, Atlanta ACO, One Crown Center, 1895 Phoenix Blvd., Suite 450, Atlanta, Georgia 30349. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Material Incorporated by Reference

(h) You must use Liberty Aerospace, Inc. Service Document Critical Service Bulletin (CSB) CSB-09-001, Revision Level B, Revised on March 18, 2009, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Liberty Aerospace, 100 Aerospace Drive, Melbourne, Florida 32901; telephone: (321) 752-0332 or (800) 759-5953; fax: (321) 752-0377; Internet: <http://www.libertyaircraft.com>.

(3) You may review copies of the service information incorporated by reference for this AD at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the Central Region, call (816) 329-3768.

(4) You may also review copies of the service information incorporated by reference for this AD at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Kansas City, MO, on April 3, 2009.

John R. Colomy,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-8075 Filed 4-8-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2008-0899; Directorate Identifier 2008-NM-022-AD; Amendment 39-15874; AD 2009-08-01]

RIN 2120-AA64

Airworthiness Directives; Honeywell Flight Management Systems (FMSs) Equipped With Honeywell NZ-2000 Navigation Computers and Honeywell IC-800 or IC-800E Integrated Avionics Computers; as Installed on Various Transport Category Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD), which applies to all Honeywell FMSs served by Honeywell NZ-2000 navigation computers and IC-800 integrated avionics computers. That AD currently requires identifying affected computers by part number and software modification level and revising the Limitations section of applicable airplane flight manuals to provide procedures for retaining optimum position determination and intended navigation. This new AD requires upgrading new software, which terminates the existing requirements. This AD results from reports of in-flight unannounced shifts of computed position in airplanes with the subject FMS computers. We are issuing this AD to prevent a shift in the FMS computed position, which could result in uncommanded deviations from the intended flight path of the airplane, and, if those deviations are undetected by the flight crew, compromised terrain/traffic avoidance.

DATES: This AD becomes effective May 14, 2009.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of May 14, 2009.

On April 18, 2007 (72 FR 15818, April 3, 2007), the Director of the Federal Register approved the incorporation by reference of Honeywell Technical Newsletter A23-6111-008, Revision 001, dated February 22, 2007.

ADDRESSES: For service information identified in this AD, contact Honeywell Technical Operations Center, 1944 East Sky Harbor Circle, Phoenix, Arizona 85034-3442; telephone (U.S. and Canada) 800-601-3099, (international)

602-365-3099; e-mail AeroTechSupport@Honeywell.com; Internet <http://www.honeywell.com>.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Daniel Bui, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5339; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:**Discussion**

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that supersedes AD 2007-07-12, amendment 39-15009 (72 FR 15818, April 3, 2007). The existing AD applies to all Honeywell FMSs served by Honeywell NZ-2000 navigation computers and IC-800 integrated avionics computers. That NPRM was published in the **Federal Register** on August 21, 2008 (73 FR 49368). That NPRM proposed to retain the existing requirements of identifying affected airplanes by part numbers/modification levels and revising the Limitations section of the airplane flight manual. That NPRM also proposed to require uploading new software, which would terminate the existing requirements.

Actions Since NPRM Was Issued

Since we issued the NPRM, Honeywell has published Alert Service Bulletin 7017300-22-A6112, Revision 001, dated February 7, 2008. In the NPRM, we referred to Honeywell Alert Service Bulletin 7017300-22-A6112, dated June 22, 2007, as the appropriate source of service information for accomplishing the proposed actions. The procedures in Revision 001 of this service bulletin are essentially the same as those in the original issue of this service bulletin. Revision 001 of this service bulletin includes instructions to load software onboard as an alternative