

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this proposed AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Boeing: Docket 2003–NM–191–AD.

Applicability: Model 727, 727–100C, 727–200F, and 727C series airplanes, certificated in any category, as listed in Boeing Alert Service Bulletin 727–53A0226, dated September 11, 2003.

Compliance: Required as indicated, unless accomplished previously.

To detect and correct fatigue cracks in the fuselage skin, strap (bearstrap), or doubler at the forward and aft hinge fittings for the main deck cargo door, which could reach critical crack length and result in rapid decompression of the airplane, accomplish the following:

Inspection

(a) Perform an open-hole high frequency eddy current inspection for cracks in the fuselage skin, strap (bearstrap), and doubler at the forward and aft hinge fittings for the main deck cargo door. Do the inspection at the applicable initial compliance time listed in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 727–53A0226, dated September 11, 2003; except, where the service bulletin specifies a compliance time after the service bulletin date, this AD requires compliance within the specified compliance time after the effective date of this AD. Perform the inspection in accordance with the Accomplishment Instructions of the service bulletin.

(1) If no crack is found: Repeat the inspection within the interval listed in paragraph 1.E., "Compliance," of the service bulletin.

(2) If any crack is found: Repair it before further flight in accordance with a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA; or per data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative who has been authorized by the Manager, Seattle ACO, to make such findings. For a repair method to be approved, the approval must specifically refer to this AD. Within 12 months following a repair, implement an inspection program for the repair into the 727 maintenance program in accordance with a method and compliance times approved by the Manager, Seattle ACO; or per data meeting 14 CFR 25.571 (Amendment 25–54 or later) approved by a Boeing Company Designated Engineering Representative who has been authorized by the Manager, Seattle ACO, to make such findings.

Alternative Methods of Compliance

(b) In accordance with 14 CFR 39.19, the Manager, Seattle Aircraft Certification Office, FAA, is authorized to approve alternative methods of compliance for this AD.

Issued in Renton, Washington, on November 12, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03–28738 Filed 11–17–03; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003–NE–43–AD]

RIN 2120–AA64

Airworthiness Directives; General Electric Company (GE) CF6–80C2 Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for GE CF6–80C2 turbofan engines with certain part number (P/N) high pressure turbine stage 2 nozzle guide vanes (HPT S2 NGVs) installed. This proposed AD would require flex borescope inspections of HPT S2 NGVs installed in CF6–80C2 turbofan engines. This proposed AD is prompted by an uncontained engine failure due to HPT S2 NGV distress. We are proposing this AD to prevent blade failure from HPT S2 NGV distress, which could result in an uncontained engine failure.

DATES: We must receive any comments on this proposed AD by January 20, 2004.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD:

- By mail: Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 2003–NE–43–AD, 12 New England Executive Park, Burlington, MA 01803–5299.
- By fax: (781) 238–7055.
- By e-mail: 9-ane-adcomment@faa.gov.

You can get the service information identified in this proposed AD from General Electric Company via Lockheed Martin Technology Services, 10525 Chester Road, suite C, Cincinnati, Ohio 45215, telephone (513) 672–8400; fax (513) 672–8422.

You may examine the AD docket, by appointment, at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA.

FOR FURTHER INFORMATION CONTACT: Eugene Triozzi, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA; telephone (781) 238–7148; fax (781) 238–7199.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any written relevant data, views, or arguments regarding this proposal. Send your comments to an address listed under **ADDRESSES**. Include "AD Docket No. 2003-NE-43-AD" in the subject line of your comments. If you want us to acknowledge receipt of your mailed comments, send us a self-addressed, stamped postcard with the docket number written on it; we will date-stamp your postcard and mail it back to you. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. If a person contacts us verbally, and that contact relates to a substantive part of this proposed AD, we will summarize the contact and place the summary in the docket. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We are reviewing the writing style we currently use in regulatory documents. We are interested in your comments on whether the style of this document is clear, and your suggestions to improve the clarity of our communications that affect you. You can get more information about plain language at <http://www.faa.gov/language> and <http://www.plainlanguage.gov>.

Examining the AD Docket

You may examine the AD Docket (including any comments and service information), by appointment, between 8 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays. See **ADDRESSES** for the location.

Discussion

On May 18, 2001, an uncontained engine failure and an in-flight shutdown occurred on a CF6-80C2 engine installed in an Airbus A300 airplane. The engine nacelle was penetrated, and damage occurred to wing skin panels and an inboard aileron. Investigation revealed that the uncontained engine failure was caused by cracking and sagging of HPT S2 NGVs, which resulted in multiple HPT stage 2 blade failure and uncontainment at the low pressure turbine case. To date, three uncontained failures of this type on CF6-80C2 engines have been reported. Additionally, twelve reports have been received of HPT S2 NGV outer airfoil fillet cracking, NGV sagging, and HPT stage 2 blade damage. Eleven of these report findings resulted in engine removal, and one finding was discovered during engine disassembly. Similar events have occurred on other

CF6 engine models with similar design HPT S2 NGVs, which have resulted in nacelle penetration and minor airplane damage. CF6-80C2 engines with pre-service bulletin (SB) No. S/B 72-0978 HPT S2 NGVs installed, are more susceptible to airfoil outer fillet cracking. This cracking can propagate to a condition where the nozzle segment sags backward and contacts the HPT stage 2 blade row. This contact can progress to notching of the blade airfoil at the root and lead to blade failure. The actions specified in this AD are intended to prevent blade failure from HPT S2 NGV distress, which could result in an uncontained engine failure.

Relevant Service Information

We have reviewed and approved the technical contents of GE SB No. CF6-80C2 S/B 72-0952, Revision 6, dated May 5, 2003, that describes procedures for initial and repetitive flex borescope inspections of affected HPT S2 NGVs.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other products of this same type design. Therefore, we are proposing this AD, which would require flex borescope inspections of the following P/N HPT S2 NGVs installed in CF6-80C2A1, -80C2A2, -80C2A3, -80C2A5, -80C2A5F, -80C2A8, -80C2B1, -80C2B1F, -80C2B2, -80C2B2F, -80C2B4, -80C2B4F, -80C2B5F, -80C2B6, -80C2B6F, -80C2B6FA, -80C2B7F, and -80C2D1F turbofan engines:

- P/N 1347M66G03, P/N 1347M66G04, and P/Ns 1815M81G01 through 1815M81G07, if insert P/N 1957M40G01/G02 was installed during repair.
- P/Ns 9373M80G07 through 9373M80G22, and P/Ns 9373M80G25 through 9373M80G32, if insert P/N 1957M40G01/G02 was installed during repair, or if NGV was repaired by GE between April 1, 1998 through September 30, 1999.
- P/Ns 9373M80G33 through 9373M80G36.
- P/Ns 2080M38G01 through 2080M38G16, and P/Ns 2080M38G19 through 2080M38G24.
- P/Ns 2080M19G01 through 2080M19G04, P/Ns 2080M19G07 through 2080M19G16, P/Ns 2080M19G19 through 2080M19G46, P/Ns 2080M19G49 through 2080M19G70, and P/Ns 2080M19G73 through 2080M19G80.

The proposed AD would require you to use the service information described previously to perform these actions.

Changes to 14 CFR Part 39—Effect on the Proposed AD

On July 10, 2002, we issued a new version of 14 CFR part 39 (67 FR 47998, July 22, 2002), which governs the FAA's AD system. This regulation now includes material that relates to altered products, special flight permits, and alternative methods of compliance. This material previously was included in each individual AD. Since this material is included in 14 CFR part 39, we will not include it in future AD actions.

Costs of Compliance

There are about 1,100 GE CF6-80C2 turbofan engines of the affected design in the worldwide fleet. We estimate that 300 of these engines installed on airplanes of U.S. registry would be affected by this proposed AD. We also estimate that it would take approximately 2 work hours per engine to perform the proposed inspections on engines that exhibit no damage, and therefore require no mapping of damage, and that the average labor rate is \$65 per work hour. Based on these figures, we estimate the total cost of the proposed AD to U.S. operators to be \$39,000.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this proposal and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include "AD Docket No. 2003-NE-43-AD" in your request.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive:

General Electric Company: Docket No. 2003–NE–43–AD.

Comments Due Date

(a) The Federal Aviation Administration (FAA) must receive comments on this airworthiness directive (AD) action by January 20, 2004.

Affected ADs

(b) None.

Applicability

(c) This AD applies to General Electric Company (GE) CF6–80C2A1, –80C2A2, –80C2A3, –80C2A5, –80C2A5F, –80C2A8, –80C2B1, –80C2B1F, –80C2B2, –80C2B2F, –80C2B4, –80C2B4F, –80C2B5F, –80C2B6, –80C2B6F, –80C2B6FA, –80C2B7F, and –80C2D1F turbofan engines, with the part numbers (P/Ns) of high pressure turbine (HPT) stage 2 nozzle guide vanes (HPT S2 NGVs) listed in the following Table 1, installed:

TABLE 1.—AFFECTED HPT S2 NGVS

HPT S2 NGV:	Provided that:
P/N 1347M66G03, P/N 1347M66G04, and P/Ns 1815M81G01 through 1815M81G07.	Insert, P/N 1957M40G01/G02 was installed during repair.
P/Ns 9373M80G07 through 9373M80G22, and P/Ns 9373M80G25 through 9373M80G32.	Insert, P/N 1957M40G01/G02 was installed during repair, or NGV was repaired by GE between April 1, 1998 through September 30, 1999.
P/Ns 9373M80G33 through 9373M80G36.	
P/Ns 2080M38G01 through 2080M38G16, and P/Ns 2080M38G19 through 2080M38G24.	
P/Ns 2080M19G01 through 2080M19G04, P/Ns 2080M19G07 through 2080M19G16, P/Ns 2080M19G19 through 2080M19G46, P/Ns 2080M19G49 through 2080M19G70, and P/Ns 2080M19G73 through 2080M19G80.	

These engines are installed on, but not limited to, Airbus A300, Airbus A310, Boeing 747, Boeing 767, and McDonnell Douglas MD–11 airplanes.

Unsafe Condition

(d) This AD is prompted by an uncontained engine failure due to HPT S2 NGV distress. We are issuing this AD to prevent blade failure from HPT S2 NGV distress, which could result in an uncontained engine failure.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

Initial Flex Borescope Inspection of NGVs

(f) Flex borescope-inspect the NGVs, following paragraph 3. of Accomplishment Instructions of GE Service Bulletin (SB) No. CF6–80C2 S/B 72–0952, Revision 6, dated May 5, 2003, as follows:

Initial Inspection Thresholds

(1) For all P/N NGVs except for P/Ns 9373M80G33 through 9373M80G36 that were installed new at time of original build or were installed new or used and serviceable (not repaired) at HPT overhaul, initial-inspect after the effective date of this AD at the following applicable interval:

(i) For CF6–80C2A2, –80C2B2, and –80C2B2F engines, inspect at or before accumulating 1,600 HPT cycles-since-overhaul (CSO).

(ii) For CF6–80C2A1, –80C2A3, –80C2A5, –80C2A5F, –80C2A8, –80C2B1, –80C2B1F, –80C2B4, –80C2B4F, –80C2B5F, –80C2B6, –80C2B6F, –80C2B6FA, –80C2B7F, and

–80C2D1F engines, inspect at or before accumulating 800 CSO.

Initial Inspection Thresholds for NGVs P/Ns 9373M80G33 Through 9373M80G36 Installed at HPT Overhaul

(2) For NGVs P/Ns 9373M80G33 through 9373M80G36 that were installed new at the time of original engine build, initial-inspect after the effective date of this AD at the following applicable interval:

(i) For CF6–80C2A2, –80C2B2, and –80C2B2F engines, inspect at or before accumulating 3,600 CSO.

(ii) For CF6–80C2A1, –80C2A3, –80C2A8, –80C2B1, –80C2B1F, –80C2B4, and –80C2B4F engines, inspect at or before accumulating 3,000 CSO.

(iii) For CF6–80C2A5, –80C2A5F, –80C2B5F, –80C2B6, –80C2B6F, –80C2B6FA, –80C2B7F, and –80C2D1F engines, inspect at or before accumulating 2,800 CSO.

Initial Inspection Thresholds for Original Build NGVs P/Ns 9373M80G33 Through 9373M80G36

(3) For NGVs P/Ns 9373M80G33 through 9373M80G36 that were installed new, or used and serviceable (not repaired) at HPT overhaul, initial-inspect after the effective date of this AD at the following applicable interval:

(i) For CF6–80C2A2, –80C2B2, and –80C2B2F engines, inspect at or before accumulating 2,400 CSO.

(ii) For CF6–80C2A1, –80C2A3, –80C2A5, –80C2A5F, –80C2A8, –80C2B1, –80C2B1F, –80C2B4, –80C2B4F, –80C2B5F, –80C2B6, –80C2B6F, –80C2B6FA, –80C2B7F, and –80C2D1F engines, inspect at or before accumulating 1,600 CSO.

Reinspection

(g) Reinspect or remove from service NGVs following the Conditions and Reinspection intervals listed in the “Inspection Table for Cracking in the Airfoil Outer Fillet”, Figure 5, of GE SB No. CF6–80C2 S/B 72–0952, Revision 6, dated May 5, 2003.

Engines With Mixed NGV Configurations

(h) For engines with mixed NGV configurations of part numbers or repair status, use the lowest applicable initial inspection thresholds and re-inspection intervals.

Alternative Methods of Compliance

(i) The Manager, Engine Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Material Incorporated by Reference

(j) You must use GE SB No. CF6–80C2 S/B 72–0952, Revision 6, dated May 5, 2003, to perform the inspections and removals required by this AD. Approval of incorporation by reference from the Office of the Federal Register is pending.

Related Information

(k) None.

Issued in Burlington, Massachusetts, on November 12, 2003.

Francis A. Favara,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 03–28739 Filed 11–17–03; 8:45 am]

BILLING CODE 4910–13–P