

of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(d) This amendment becomes effective on November 22, 2000.

Issued in Fort Worth, Texas, on October 30, 2000.

Mark R. Schilling,

*Acting Manager, Rotorcraft Directorate,
Aircraft Certification Service.*

[FR Doc. 00-28437 Filed 11-7-00; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-204-AD; Amendment 39-11956; AD 2000-22-10]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-135 and EMB-145 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment supersedes an existing airworthiness directive (AD), applicable to certain EMBRAER Model EMB-135 and EMB-145 series airplanes, that currently requires various inspections to detect discrepancies of the elevator servo tab and spring tab hinge fittings of the horizontal stabilizer, and follow-on corrective actions, if necessary. This amendment clarifies certain fiberoptic inspection and replacement procedures, and corrective actions; revises the applicability of the existing AD; and adds an inspection procedure for the servo tab center hinge fittings to detect the presence of washers for both attaching fasteners, and follow-on corrective actions, if necessary. This amendment also provides for optional terminating action for the repetitive inspections. The actions specified in this AD are intended to prevent the linkage of the elevator servo tab or spring tab hinge fittings from separating from the horizontal stabilizer, which could result in loss of control of the airplane.

DATES: Effective November 22, 2000.

The incorporation by reference of Embraer Service Bulletin 145-55-0024, dated May 25, 2000, as listed in the regulations, is approved by the Director of the Federal Register as of November 22, 2000.

Comments for inclusion in the Rules Docket must be received on or before December 7, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-204-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-iarcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2000-NM-204-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in this AD may be obtained from Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Viswa Padmanabhan, Aerospace Engineer, Airframe and Propulsion Branch, ACE-117A, FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30337-2748; telephone (770) 703-6049; fax (770) 703-6097.

SUPPLEMENTARY INFORMATION: On February 15, 2000, the FAA issued AD 2000-04-09, amendment 39-11591 (65 FR 9217, February 24, 2000), applicable to certain EMBRAER Model EMB-135 and EMB-145 series airplanes, to require various inspections to detect discrepancies of the elevator servo tab and spring tab hinge fittings of the horizontal stabilizer, and follow-on corrective actions, if necessary. That action was prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions required by that AD are intended to prevent the linkage of the elevator servo tab or spring tab hinge fittings from separating from the horizontal stabilizer,

which could result in loss of control of the airplane.

Actions Since Issuance of Previous Rule

Since the issuance of that AD, the Departamento de Aviação Civil (DAC), which is the airworthiness authority for Brazil, has received new information regarding the corrective action necessary to address this unsafe condition. As a result, the DAC has issued the following Brazilian airworthiness directives:

- 1999-09-01R2, dated May 1, 2000, supersedes Brazilian airworthiness directive 1999-09-01R1, dated October 25, 1999. This new revision was issued to specify repetitive inspection intervals and final rework of certain components. Part III of this revision specifies that, for certain Model EMB-135 and EMB-145 series airplanes, certain modifications of the elevator mass balance assembly and control column nose-up spring modifications, in accordance with Embraer Service Bulletin (S.B.) 145-27-0034, must be completed before accomplishment of the rework specified in Part III of S.B. 145-55-0022, Change 01, dated January 25, 2000.

- 2000-05-01, dated May 25, 2000, corrects any possible misinterpretation of the replacement procedures included in Brazilian airworthiness directive 1999-09-01R2, and in alert S.B. 145-55-A022 and S.B. 145-55-0022.

Reports indicated that loose hinge fittings were found, which was attributed to the incorrect application of the attachment fasteners to the tab upper skin. It is considered that the loss of fitting rigidity could cause damage to the other fasteners in the tab spar. Reports also indicated that some of the fasteners (which attach the spring-tab actuating arm to the tab upper skin and the servo-tab actuating linkage hinge to the tab lower skin) were not replaced with fasteners having a washer, because the collar conformation of those fasteners was found to be correct. In addition, maintenance records revealed that such fasteners may not have been replaced on certain airplanes. As a result of these findings, the DAC issued the previously referenced Brazilian airworthiness directives to clarify that all attachment fasteners must be installed with a washer, and that the fasteners must be replaced independently of the installation condition (even if the collar conformation is found to be "correct").

FAA's Conclusions

These airplane models are manufactured in Brazil and are type certificated for operation in the United States under the provisions of section

21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Relevant Service Information

Embraer has issued the following service information:

- Service Bulletin 145-55-0022, Change 02, dated May 4, 2000, adds a fiberoptic inspection in Part II of the Accomplishment Instructions to detect the presence of a washer; and installation of a washer, if necessary. Part III of this service bulletin revises certain rework procedures (including rework and installation of the elevator servo and spring tabs; and reidentification, static balancing, and installation of the elevator). This rework procedure also specifies that, for certain airplanes, the modification specified by Embraer S.B. 145-27-0034 must be accomplished before Part III of S.B. 145-55-0022, Change 02, is accomplished. Accomplishment of the actions specified in Part III of S.B. 145-55-0022, Change 02, eliminates the need for the repetitive inspections.

- Service Bulletin 145-55-0024, dated May 25, 2000, adds a fiberoptic inspection of the attachment of the servo tab center hinge fitting to the tab skin in Part II of the Accomplishment Instructions of this service bulletin. This inspection specifies detecting the presence of washers under the collar bases of both attaching fasteners, in the inner side of the tab skin; and corrective actions, if necessary. Procedures include additional action to clarify certain replacement procedures that were specified in alert S.B. 145-55-A022, Change 01, dated October 7, 1999, and Change 02, dated October 8, 1999. Such action specifies that any discrepant fastener must be replaced with a new fastener having a washer, and that the action if required to be accomplished independently of the installation condition. In addition, S.B. 145-55-0024 specifies that operators report any discrepancy found during inspections of elevator spring tab and servo tab hinge fittings that are specified in Part I of the Accomplishment Instructions of the service bulletin.

- Service Bulletin 145-27-0034, Change 01, dated August 5, 1998,

revises procedures for replacing the elevator mass-balance weight assembly and nose-up spring. Procedures also revise static balancing and weight and balance, add new mass-balance weight and its attachment bolt, and delete the instruction for checking the backlash.

The DAC mandated compliance with the preceding service bulletins, and issued previously referenced Brazilian airworthiness directive 1999-09-01R2 in order to assure the continued airworthiness of these airplanes in Brazil.

Explanation of Requirements of Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, this AD supersedes AD 2000-04-09 to continue to require various inspections to detect discrepancies of the elevator servo tab and spring tab hinge fittings of the horizontal stabilizer, and follow-on corrective actions, if necessary. This amendment clarifies certain fiberoptic inspection and replacement procedures, and corrective actions; revises the applicability of the existing AD; and adds an inspection procedure for the servo tab center hinge fittings to detect the presence of washers for both attaching fasteners, and follow-on corrective actions. This amendment also provides for optional terminating action for the repetitive inspections. In addition, this amendment requires that operators report to the manufacturer any discrepancy found during any detailed visual inspection accomplished in accordance with S.B. 145-55-0024, dated May 25, 2000. This AD requires accomplishment of actions specified in the service bulletin described previously, except as discussed below.

Differences Between This AD, Brazilian Airworthiness Directives, and Related Service Information

Operators should note that, although the previously referenced Brazilian airworthiness directives and Embraer service information specify that certain rework actions are required, this AD provides those actions as optional. The FAA has determined that such action may be required in subsequent rulemaking action to provide sufficient time for public comment.

Explanation of Changes to the Applicability of AD 2000-04-09

The applicability of AD 2000-04-09 included all of the serial numbers for Model EMB-135 and EMB-145 series airplanes, as listed in alert S.B. 145-55-A022, Change 02, dated October 8, 1999.

However, this AD revises the applicability of this AD to those airplanes listed in S.B. 145-55-0022, Change 02, dated May 4, 2000, or S.B. 145-55-0024, dated May 25, 2000, and those airplanes on which the elevator servo tabs and spring tabs have been replaced in accordance with alert S.B. 145-55-A022, Change 02, dated October 8, 1999, or S.B. 145-55-0022, Change 01, dated January 25, 2000.

Interim Action

This AD is considered to be interim action. The FAA is currently considering requiring the rework of all elevator servo and spring tabs, which will constitute terminating action for the repetitive inspections required by this AD action. However, such action will be proposed in a separate rulemaking action since the compliance time for the rework is sufficiently long so that notice and opportunity for prior public comment will be practicable.

Determination of Rule's Effective Date

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

Although this action is in the form of a final rule that involves requirements affecting flight safety and, thus, was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified under the caption ADDRESSES. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the AD is being requested.

• Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2000-NM-204-AD." The postcard will be date stamped and returned to the commenter.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the

Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39-11591 (65 FR 9217, February 24, 2000), and by adding a new airworthiness directive (AD), amendment 39-11956, to read as follows:

2000-22-10 Empresa Brasileira de Aeronautica S.A. (EMBRAER):
Amendment 39-11956. Docket 2000-NM-204-AD. Supersedes AD 2000-04-09, Amendment 39-11591.

Applicability: Model EMB-135 and EMB-145 series airplanes, certificated in any category, as listed in Embraer Service Bulletin 145-55-0022, Change 02, dated May 4, 2000, or Embraer Service Bulletin 145-55-0024, dated May 25, 2000; and those airplanes on which the elevator servo tabs and spring tabs have been replaced in accordance with Embraer Alert Service Bulletin 145-55-A022, Change 02, dated October 8, 1999, or Embraer Service Bulletin 145-55-0022, dated October 20, 1999.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e)(1) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent disconnection of the elevator spring tab or servo tab hinge from their attachments, which could result in loss of elevator control and reduced controllability of the airplane, accomplish the following:

Detailed Visual Inspection

(a) Within 20 flight hours after the effective date of this AD, perform a detailed visual inspection of the hinge fittings of the left and right elevator spring tabs and servo tabs to detect any discrepancy (including incorrect attachment of the hinge fittings; signs of scratches on painted surfaces of the tab spar; detachment of hinge fitting from the tab; and relative movement and gap between hinge fittings and tab spars, and between the spring tab spar or skin) in accordance with Part I of

the Accomplishment Instructions of Embraer Service Bulletin (S.B.) 145-55-0024, dated May 25, 2000.

Note 2: Inspections accomplished prior to the effective date of this amendment, in accordance with Part I of the Accomplishment Instructions of S.B. 145-55-0022, dated October 20, 1999, or Change 01, dated January 25, 2000, or alert S.B. 145-55-A022, Change 02, dated October 8, 1999, are considered acceptable for compliance with the requirements of paragraph (a) of this AD.

(1) If no discrepancy is detected, repeat the detailed visual inspection thereafter at intervals not to exceed 100 flight hours until accomplishment of either paragraph (b) or (c) of this AD.

(2) If any discrepancy is detected, prior to further flight, accomplish the action specified by either paragraph (a)(2)(i) or (a)(2)(ii) of this AD.

(i) Replace any discrepant elevator tab with a new tab in accordance with the service bulletin, and repeat the detailed visual inspection thereafter at intervals not to exceed 100 flight hours until accomplishment of either the actions required by paragraph (b) or the optional terminating action specified by paragraph (c) of this AD.

Note 3: The inspection and fastener replacement actions required by paragraph (b) of this AD do not constitute terminating action for the requirements of this AD, but only extend the inspection intervals from 100 to 400 flight hours.

(ii) Perform the optional terminating action specified by paragraph (c) of this AD.

Note 4: For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc. may be used. Surface cleaning and elaborate access procedures may be required."

Inspection and Fastener Replacement

(b) Within 400 flight hours after the effective date of this AD, perform a one-time detailed visual inspection, using a fiberscope, of the servo tab center hinge fitting to the tab skin to detect any discrepancy (including the absence of washers under the collar bases of both attaching fasteners, and incorrect fastener connection) in accordance with Part II of the Accomplishment Instructions of S.B. 145-55-0024, dated May 25, 2000.

(1) If no discrepancy is detected, repeat the inspection required by paragraph (a) of this AD thereafter at intervals not to exceed 400 flight hours until accomplishment of the optional terminating action specified by paragraph (c) of this AD.

(2) If any discrepancy is detected, prior to further flight, replace, one at a time, each affected fastener with a new fastener having a washer, in accordance with the service bulletin. Repeat the inspection required by paragraph (a) of this AD thereafter at intervals not to exceed 400 flight hours until accomplishment of the optional terminating action specified by paragraph (c) of this AD.

Note 5: Replacement of the attaching fasteners one at a time will avoid the loss of the servo tab or spring tab hinge fittings position.

Optional Terminating Action

(c) Rework (including installation of the elevator servo and spring tabs; and reidentification, static balancing, and installation of the elevator) of all elevator servo and spring tabs in accordance with Part III of the Accomplishment Instructions of S.B. 145-055-0022, Change 02, dated May 4, 2000, constitutes terminating action for the repetitive inspections required by this AD. Model EMB-135 and EMB-145 series airplanes having serial numbers 145004 through 145043, must accomplish the modifications specified by S.B. 145-27-0034, Change 01, dated August 5, 1998, prior to the rework specified by this paragraph.

Note 6: Modifications of certain airplanes specified in paragraph (c) of this AD, accomplished before the effective date of this amendment, in accordance with S.B. 145-27-0034, dated April 3, 1998, are considered acceptable for compliance with the modification requirement in paragraph (c) of this AD.

Reporting Requirement

(d) Submit a report of inspection findings for any discrepancy detected during any inspection required by paragraph (a) of this AD to Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil; at the applicable time specified in paragraph (d)(1) or (d)(2) of this AD. Information collection requirements contained in this regulation have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*) and have been assigned OMB Control Number 2120-0056.

(1) For airplanes on which any inspection is accomplished after the effective date of this AD: Submit the report within 10 days after performing any detailed visual inspection required by paragraph (a) of this AD.

(2) For airplanes on which any inspection has been accomplished prior to the effective date of this AD: Submit the report within 10 days after the effective date of this AD.

Alternative Methods of Compliance

(e)(1) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Atlanta Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance

Inspector, who may add comments and then send it to the Manager, Atlanta ACO.

(2) Alternative methods of compliance, approved previously in accordance with AD 2000-04-09, amendment 39-11591, are approved as alternative methods of compliance with this AD.

Note 7: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Atlanta ACO.

Special Flight Permits

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(g) The inspections shall be done in accordance with Embraer Service Bulletin 145-55-0024, dated May 25, 2000. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil. Copies may be inspected at the FAA, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 8: The subject of this AD is addressed in Brazilian airworthiness directives 1999-09-01R2, dated May 1, 2000, and 2000-05-01, dated May 25, 2000.

Effective Date of This AD

(h) This amendment becomes effective on November 22, 2000.

Issued in Renton, Washington, on October 27, 2000.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-28087 Filed 11-6-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-121-AD; Amendment 39-11958; AD 2000-22-12]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-120 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain EMBRAER Model EMB-120 series airplanes, that requires replacement of the existing wire between certain circuit breakers with an improved wire. The actions specified by this AD are intended to prevent overheating of the wire between certain circuit breakers, which could result in smoke emissions in the cockpit. This action is intended to address the identified unsafe condition.

DATES: Effective December 12, 2000.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of December 12, 2000.

ADDRESSES: The service information referenced in this AD may be obtained from Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Carla Worthey, Program Manager, Program Management & Services Branch, ACE-118A, FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30349; telephone (770) 703-6062; fax (770) 703-6097.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain EMBRAER Model EMB-120 series airplanes, was published in the **Federal Register** on