

(4) If no indications are found during the FPI required by paragraph (g)(3) of this AD, within 15,000 part cycles from the date of the FPI, remove the CCA from service and replace with P/N 4180T27G07, 4180T27G08, or a later approved P/N, as applicable.

(5) For affected Group 1 and 2 engines with an installed CCA having more than 25,000 PCSN as of the effective date of this AD, at the next engine shop visit after the effective date of this AD, perform an FPI on the forward flange of the CCA for any indications.

(6) If no indications are found during the FPI required by paragraph (g)(5) of this AD, within 15,000 part cycles from the date of the FPI and not to exceed 41,100 PCSN, remove the CCA from service and replace with P/N 4180T27G07, 4180T27G08, or a later approved P/N, as applicable.

(7) If an indication is found during any FPI required by paragraph (g)(3) or (5) of this AD, before further flight, remove the CCA from service and replace with P/N 4180T27G07, P/N 4180T27G08, or a later approved P/N, as applicable.

#### (h) Definitions

For the purpose of this AD:

(1) “Group 1 engines” are GE Model CF34–8C1, CF34–8C5, CF34–8C5A1, CF34–8C5A2, CF34–8C5A3, and CF34–8C5B1 engines.

(2) “Group 2 engines” are GE Model CF34–8E2, CF34–8E2A1, CF34–8E5, CF34–8E5A1, CF34–8E5A2, CF34–8E6, and CF34–8E6A1 engines.

(3) An “engine shop visit” is the induction of an engine into the shop for maintenance involving the separation of major mating engine case flanges, except for the following situations, which do not constitute an engine shop visit:

(i) Separation of engine flanges solely for the purposes of transportation of the engine without subsequent maintenance.

(ii) Separation of engine flanges solely for the purposes of replacing the fan or propulsor without subsequent maintenance.

#### (i) Installation Prohibition

After the effective date of this AD, do not reinstall any CCAs that were removed as a result of paragraphs (g)(1), (2), (4), (6), and (7) of this AD in any engine.

#### (j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, AIR–520 Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the AIR–520 Continued Operational Safety Branch, send it to the attention of the person identified in paragraph (k) of this AD and email to: [AMOC@faa.gov](mailto:AMOC@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### (k) Additional Information

For more information about this AD, contact Alexei Marqueen, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198; phone: (781) 238–7178; email: [alexei.t.marqueen@faa.gov](mailto:alexei.t.marqueen@faa.gov).

#### (l) Material Incorporated by Reference

None.

Issued on December 19, 2024.

**Suzanne Masterson,**

*Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.*

[FR Doc. 2024–30785 Filed 12–26–24; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2024–2713; Project Identifier AD–2024–00328–T]

RIN 2120–AA64

#### Airworthiness Directives; The Boeing Company Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 777–200, –200LR, –300, –300ER, and 777F series airplanes. This proposed AD was prompted by a report indicating that an airplane experienced a glideslope (G/S) beam anomaly during an instrument landing system (ILS) approach, which resulted in a higher-than-expected descent rate during the final segment of an ILS approach. The flightcrew might follow misleading flight director (F/D) guidance after disconnecting the autopilot, without reference to the other available information and flight deck indications. This proposed AD would require installing new autopilot flight director computer (AFDC) operational program software (OPS) and doing a software configuration check. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by February 25, 2025.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

*AD Docket:* You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2024–2713; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

*Material Incorporated by Reference:*

- For Boeing material identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; website [myboeingfleet.com](https://myboeingfleet.com).

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2024–2713.

**FOR FURTHER INFORMATION CONTACT:** Michael Closson, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206–231–3973; email: [Michael.P.Closson@faa.gov](mailto:Michael.P.Closson@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2024–2713; Project Identifier AD–2024–00328–T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal

information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

**Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Michael Closson, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3973; email: [Michael.P.Closson@faa.gov](mailto:Michael.P.Closson@faa.gov). Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

**Background**

The FAA has received a report indicating that a Model 787-8 airplane captured an anomalous G/S beam during an ILS approach, which resulted

in a higher-than-expected descent rate during the final segment of an ILS approach due to persistent inertial coasting, which can result in misleading flight director guidance. When the autopilot was disconnected, the F/D continued to command a flight path away from the G/S without warning, which the flightcrew appeared to follow. Both GLIDESLOPE and TOO LOW TERRAIN alerts annunciated while the airplane continued to descend. Ultimately, the flightcrew was able to recover the airplane and conducted a Go-Around procedure. No injuries to passengers or crew, or damage to the airframe, was reported.

It has been determined that Model 777 airplanes can experience the same anomaly. G/S beam anomalies that occur in a discrete G/S capture window can result in reversion to inertial paths in which the auto-flight vertical guidance diverges from the G/S beam at higher-than-expected descent rates. The flightcrew may follow the misleading F/D guidance after disconnecting the A/P, without reference to the other available information and flight deck indications. This condition, if not addressed, could result in a late touchdown, a runway excursion, or controlled flight into terrain.

**Related Rulemaking**

The FAA may consider issuing additional rulemaking to address the identified unsafe condition on additional Boeing airplane models with the same G/S issue.

**FAA's Determination**

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

**Material Incorporated by Reference Under 1 CFR Part 51**

The FAA reviewed Boeing Alert Requirements Bulletin 777-22A0046 RB, dated October 25, 2022. This material specifies procedures for installing new AFDC OPS, doing a software configuration check, and making sure that the correct software part number is installed in the correct location. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

**Proposed AD Requirements in This NPRM**

This proposed AD would require accomplishing the actions specified in the material already described, except for any differences identified as exceptions in the regulatory text of this proposed AD. For information on the procedures and compliance times, see this material at [regulations.gov](http://regulations.gov) under Docket No. FAA-2024-2713.

**Costs of Compliance**

The FAA estimates that this AD, if adopted as proposed, would affect 266 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Software installation and configuration check ..	2 work-hours × \$85 per hour = \$170 .....	\$13	\$183	\$48,678

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds

necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Would not affect intrastate aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**The Boeing Company:** Docket No. FAA–2024–2713; Project Identifier AD–2024–00328–T.

#### (a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by February 10, 2025.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to The Boeing Company Model 777–200, –200LR, –300, –300ER, and 777F series airplanes, certificated in any category, as identified in Boeing Alert Requirements Bulletin 777–22A0046 RB, dated October 25, 2022.

#### (d) Subject

Air Transport Association (ATA) of America Code 22, Auto flight.

#### (e) Unsafe Condition

This AD was prompted by a report indicating that an airplane experienced a glideslope (G/S) beam anomaly during an instrument landing system (ILS) approach, which resulted in a higher-than-expected descent rate during the final segment of an ILS approach. The FAA is issuing this AD to address misleading flight director guidance that the flightcrew might follow after disconnecting the autopilot, without reference to the other available information and flight deck indications. The unsafe condition, if not addressed, could result in a late touchdown, a runway excursion, or controlled flight into terrain.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Required Actions

Except as specified in paragraph (h) of this AD: At the applicable times specified in paragraph 3., “Compliance,” of Boeing Alert Requirements Bulletin 777–22A0046 RB, dated October 25, 2022, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 777–22A0046 RB, dated October 25, 2022.

**Note 1 to paragraph (g):** Guidance for accomplishing the actions required by this

AD can be found in Boeing Alert Service Bulletin 777–22A0046, dated October 25, 2022, which is referred to in Boeing Alert Requirements Bulletin 777–22A0046 RB, dated October 25, 2022.

#### (h) Exception to Service Information Specifications

Where the Compliance Time column of the table in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 777–22A0046 RB, dated October 25, 2022, refers to “the Original Issue date of Requirements Bulletin 777–22A0046 RB,” this AD requires using the effective date of this AD.

#### (i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, AIR–520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: *AMOC@faa.gov*.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, AIR–520, Continued Operational Safety Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

#### (j) Related Information

(1) For more information about this AD, contact Michael Closson, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206–231–3973; email: *Michael.P.Closson@faa.gov*.

(2) Material identified in this AD that is not incorporated by reference is available at the address specified in paragraph (k)(3) of this AD.

#### (k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 777–22A0046 RB, dated October 25, 2022.

(ii) [Reserved]

(3) For Boeing material identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; website *myboeingfleet.com*.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations) or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

Issued on December 19, 2024.

**Suzanne Masterson,**

*Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.*

[FR Doc. 2024–30918 Filed 12–26–24; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2024–2714; Project Identifier MCAI–2024–00405–T]

RIN 2120–AA64

#### Airworthiness Directives; Deutsche Aircraft GmbH (Type Certificate Previously Held by 328 Support Services GmbH; AvCraft Aerospace GmbH; Fairchild Dornier GmbH; Dornier Luftfahrt GmbH) Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all Deutsche Aircraft GmbH (Type Certificate previously held by 328 Support Services GmbH; AvCraft Aerospace GmbH; Fairchild Dornier GmbH; Dornier Luftfahrt GmbH) Model 328–100 and Model 328–300 airplanes. This proposed AD was prompted by a report of a nose landing gear (NLG) uplock bracket assembly cracking. This proposed AD would require an inspection of the affected part and applicable on-condition actions, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference (IBR). The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by February 10, 2025.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods: