

13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD. You may get a copy

of this summary at the address listed under **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Under the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive:

General Electric Company: Docket No. FAA-2007-28367; Directorate Identifier 2007-NE-19-AD.

Comments Due Date

(a) The Federal Aviation Administration (FAA) must receive comments on this airworthiness directive (AD) action by November 19, 2007.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to the CF6-80C2 and CF6-80E1 engines specified in the following Table 1 of this AD. These engines are installed on, but not limited to, Airbus A300, A310, and A330 series airplanes, Boeing 747 and 767 series airplanes, and McDonnell Douglas MD11 series airplanes.

TABLE 1.—APPLICABLE ENGINES BY ENGINE MODEL

Engine model	With low pressure turbine (LPT) case part No. (P/N) installed
CF6-80C2A1, -80C2A2, -80C2A3, -80C2A5, -80C2A5F, -80C2A8, -80C2B1, -80C2B1F, -80C2B1F1, -80C2B1F2, -80C2B2, -80C2B2F, -80C2B3F, -80C2B4, -80C2B4F, -80C2B5F, -80C2B6, -80C2B6F, -80C2B6FA, -80C2B7F, -80C2B8F, -80C2D1F, and -80C2L1F.	1336M99G01, 1336M99G02, 1336M99G03, 1336M99G04, 1336M99G06, 1336M99G07, 1336M99G08, 1336M99G09, 1336M99G10, 1336M99G12, 1336M99G13, or 1336M99G15. 1647M68G05, 1647M68G08, 1647M68G09, 1647M68G15. 1713M73G01, 1713M73G02, or 1713M73G05. 9367M99G11 or 9367M99G17.
CF6-80E1A1, -80E1A2, -80E1A3, -80E1A4, -80E1A4/B	1647M68G02, 1647M68G04, 1647M68G07, 1647M68G12, or 1647M68G13.

Unsafe Condition

(d) This AD results from four events of hardware fragments, which liberated into the flowpaths and wore through LPT cases on CF6-80C2 and -80E1 series engines. We are issuing this AD to prevent an uncontained release of engine debris and loss of the structural integrity of the mount system that supports the engine. Loss of the mount system structural integrity could result in the engine separating from the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed the next time the LPT module is disassembled, but not to exceed 8 years after the effective date of this AD, unless the actions have already been done.

CF6-80C2 Engines

(f) For CF6-80C2 engines specified in Table 1 of this AD that have an LPT case with a P/N specified in Table 1 of this AD, do either of the following:

- (1) Rework the LPT case to install deflectors. Use the Accomplishment Instructions of GE Service Bulletin (SB) CF6-80C2 S/B 72-1171, Revision 1, dated February 1, 2006, and Repair Document (RD) 935-314-S3, dated August 10, 2006, to rework the LPT case, or
- (2) Install an LPT case that has case skin doubler pads.

CF6-80E1 Engines

(g) For CF6-80E1 engines specified in Table 1 of this AD, that have an LPT case with a P/N specified in Table 1 of this AD, do either of the following:

- (1) Rework the LPT case to install deflectors. Use the Accomplishment Instructions of SB CF6-80E1 S/B 72-0303, Revision 1, dated February 1, 2006, and RD 935-314-S3, dated August 10, 2006, to rework the LPT case, or
- (2) Install an LPT case that has case skin doubler pads.

Alternative Methods of Compliance

(h) The Manager, Engine Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Related Information

- (i) None.
- (j) Contact Robert Green, Aerospace Engineer, Engine Certification Office, FAA, Engine & Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: robert.green@faa.gov; telephone (781) 238-7754; fax (781) 238-7199, for more information about this AD.

Issued in Burlington, Massachusetts, on September 11, 2007.

Francis A. Favara,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E7-18418 Filed 9-18-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-28670; Directorate Identifier 2007-CE-060-AD]

RIN 2120-AA64

Airworthiness Directives; GROB-WERKE GMBH & CO KG Models G102 CLUB ASTIR III, G102 CLUB ASTIR IIIB, and G102 STANDARD ASTIR III Gliders

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed

AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

GROB received isolated difficulty reports regarding cracks on welded parts of the flight control system of the type G102, model CLUB ASTIR III & IIIb, and STANDARD ASTIR III. The cracks progress slowly from the welding seams periphery, and may eventually result in rupture at a matured stage.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by October 19, 2007.

ADDRESSES: You may send comments by any of the following methods:

- *DOT Docket Web Site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Greg Davison, Glider Program Manager, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; fax: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments

to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2007-28670; Directorate Identifier 2007-CE-060-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued Emergency AD No.: 2007-0135-E, dated May 14, 2007 (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

GROB received isolated difficulty reports regarding cracks on welded parts of the flight control system of the type G102, model CLUB ASTIR III & IIIb, and STANDARD ASTIR III. The cracks progress slowly from the welding seams periphery, and may eventually result in rupture at a matured stage.

The MCAI requires all welded parts to be inspected and replaced if any cracks are found.

You may obtain further information by examining the MCAI in the AD.

Relevant Service Information

Grob Aerospace has issued Service Bulletin No. MSB 306-35, dated April 27, 2007. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA’s Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This Proposed AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the proposed AD.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 35 products of U.S. registry. We also estimate that it would take about 1 work-hour per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$2,800, or \$80 per product.

In addition, we estimate that any necessary follow-on actions would take about 5 work-hours and require parts costing \$5,058, for a cost of \$5,458 per product. We have no way of determining the number of products that may need these actions.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications

under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Grob-Werke GmbH & Co Kg: Docket No. FAA-2007-28670; Directorate Identifier 2007-CE-060-AD.

Comments Due Date

(a) We must receive comments by October 19, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to the gliders Model G102 CLUB ASTIR III, serial numbers (SNs) 5501 (suffix C) through 5652 (suffix C); Model G102 CLUB ASTIR IIIB, SNs 5501 (suffix Cb) through 5652 (suffix Cb); and Model G102 STANDARD ASTIR III, SNs 5501 (suffix S) through 5652 (suffix S), that are certificated in any category.

Subject

(d) Air Transport Association of America (ATA) Code 27: Flight Controls.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

GROB received isolated difficulty reports regarding cracks on welded parts of the flight control system of the type G102, model CLUB ASTIR III & IIIB, and STANDARD ASTIR III. The cracks progress slowly from the welding seams periphery, and may eventually result in rupture at a matured stage.

The MCAI requires all welded parts to be inspected and replaced if any cracks are found.

Actions and Compliance

(f) Unless already done, do the following actions:

(1) Within the next 25 hours time-in-service (TIS) after the effective date of this AD or within the next 6 calendar months after the effective date of this AD, whichever occurs first, inspect the welded parts of the flight control system for any cracks, deformations, or distortions following Grob Aerospace Service Bulletin No. MSB 306-35, dated April 27, 2007. Thereafter, repetitively inspect at intervals not to exceed 12 calendar months.

(2) If you find any cracks, deformations, or distortions as a result of any inspection required by paragraph (e)(1) of this AD, before further flight, replace the affected part following Grob Aerospace Service Bulletin No. MSB 306-35, dated April 27, 2007.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Greg Davison, Glider Program Manager, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501, et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) Emergency AD No.:

2007-0135-E, dated May 14, 2007, and Grob Aerospace Service Bulletin No. MSB 306-35, dated April 27, 2007, for related information.

Issued in Kansas City, Missouri, on September 13, 2007.

Kim Smith,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-18443 Filed 9-18-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-29226; Directorate Identifier 2006-NM-256-AD]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model DC-9-81 (MD-81) and DC-9-82 (MD-82) Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain McDonnell Douglas Model DC-9-81 (MD-81) and DC-9-82 (MD-82) airplanes. This proposed AD would require, for certain airplanes, inspecting for cracking of the fuselage skin at the upper corners of the forward passenger doorjamb, installing or replacing doublers as applicable, and doing applicable repairs. This proposed AD results from reports of fatigue cracking in the fuselage skin at the upper corners of the forward passenger doorjamb. We are proposing this AD to prevent cracking of the fuselage skin at the upper corners of the forward passenger doorjamb, which could lead to loss of overall structural integrity of the airplane.

DATES: We must receive comments on this proposed AD by November 5, 2007.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- **DOT Docket Web site:** Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- **Government-wide rulemaking Web site:** Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room