

2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Cirrus Design Corporation: Docket No. FAA–2005–23023; Directorate Identifier 2005–CE–49–AD.

When Is the Last Date I Can Submit Comments on This Proposed AD?

(a) The Federal Aviation Administration (FAA) must receive comments on this airworthiness directive (AD) action by February 7, 2006.

What Other ADs Are Affected by This Action?

(b) None.

What Airplanes Are Affected by This AD?

(c) This AD affects the following airplane models and serial numbers that are certificated in any category:

Model	Serial Nos.
SR20	1005 through 1581.
SR22	0002 through 1643 and 1645 through 1662.

What Is the Unsafe Condition Presented in This AD?

(d) This AD results from reports of fuel line leaks resulting from wire chafing on the fuel lines. The actions specified in this AD are intended to detect and correct damage to the fuel line and wire bundles, which could result in fuel leaks. This failure could lead to unsafe fuel vapor within the cockpit and possible fire.

What Must I Do To Address This Problem?

(e) To address this problem, you must do the following:

Actions	Compliance	Procedures
(1) Inspect the fuel line and wire harness for any chafing damage.	Within the next 50 hours time-in-service (TIS) after the effective date of this AD.	Follow Cirrus Design Corporation Service Bulletin SB 2X–28–04 R1, Issued: November 1, 2005, Revised: November 8, 2005.
(2) If any chafing damage is found as a result of the inspection required by paragraph (e)(1) of this AD:	Before further flight after the inspection required by paragraph (e)(1) of this AD.	Follow Cirrus Design Corporation Service Bulletin SB 2X–28–04 R1, Issued: November 1, 2005, Revised: November 8, 2005.
(i) Replace any damaged fuel line; and		
(ii) Repair any damaged wires or sheathing of the wire harness.		
(3) Install the following:	Within the next 50 hours time-in-service (TIS) after the effective date of this AD.	Follow Cirrus Design Corporation Service Bulletin SB 2X–28–04 R1, Issued: November 1, 2005, Revised: November 8, 2005.
(i) Forward loop clamp;		
(ii) Fuel line shield;		
(iii) Aft loop clamp; and		
(iv) Anti-chafe tubing.		

May I Request an Alternative Method of Compliance?

(f) The Manager, Chicago Aircraft Certification Office (ACO), FAA, has the authority to approve alternative methods of compliance for this AD, if requested using the procedures found in 14 CFR 39.19.

(g) For information on any already approved alternative methods of compliance or for information pertaining to this AD, contact Wess Rouse, Aerospace Engineer, ACE–117C, Chicago ACO, 2300 East Devon Avenue, Room 107, Des Plaines, Illinois 60018; telephone: (847) 294–8113; facsimile: (847) 294–7834.

May I Get Copies of the Documents Referenced in This AD?

(h) To get copies of the documents referenced in this AD, contact Cirrus Design Corporation, 4515 Taylor Circle, Duluth, Minnesota 55811; telephone: (218) 727–2737 or on the Internet at www.cirrusdesign.com. To view the AD docket, go to the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL–401, Washington, DC, or on the Internet at <http://dms.dot.gov>.

The docket number is Docket No. FAA–2005–23023; Directorate Identifier 2005–CE–49–AD.

Issued in Kansas City, Missouri, on December 2, 2005.

John R. Colomy,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05–23772 Filed 12–7–05; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2005–21691; Directorate Identifier 2005–NE–13–AD]

RIN 2120–AA64

Airworthiness Directives; Hamilton Sundstrand Model 14RF–19 Propellers

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for Hamilton Sundstrand (formerly Hamilton Standard Division of United Technologies Corporation) Model 14RF–19 propellers. This proposed AD would require replacing certain actuator yokes with improved actuator yokes. This proposed AD results from certain propeller system actuator yoke arms breaking during flight. We are proposing this AD to prevent actuator yoke arms breaking during flight, which could cause high propeller vibration, requiring the pilot to feather the propeller, and could contribute to reduced controllability of the airplane.

DATES: We must receive any comments on this proposed AD by February 6, 2006.

ADDRESSES: Use one of the following addresses to comment on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001.

- Fax: (202) 493-2251.

- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

You can get the service information identified in this proposed AD from Hamilton Sundstrand, A United Technologies Company, Publications Manager, Mail Stop 2AM-EE50, One Hamilton Road, Windsor Locks, CT 06096.

You may examine the comments on this proposed AD in the AD docket on the Internet at <http://dms.dot.gov>.

FOR FURTHER INFORMATION CONTACT:

Frank Walsh, Aerospace Engineer, Boston Aircraft Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (781) 238-7158; fax (781) 238-7170.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send us any written relevant data, views, or arguments regarding this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2005-21691; Directorate Identifier 2005-NE-13-AD" in the subject line of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of the DMS Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may

review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78) or you may visit <http://dms.dot.gov>.

Examining the AD Docket

You may examine the docket that contains the proposal, any comments received, and any final disposition in person at the DMS Docket Offices between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone (800) 647-5227) is located on the plaza level of the Department of Transportation Nassif Building at the street address stated in **ADDRESSES**. Comments will be available in the AD docket shortly after the DMS receives them.

Discussion

Hamilton Sundstrand notified us that there have been four occurrences of propeller system actuator yoke arms, part number (P/N) 810436-2, breaking during flight. A high-stress concentration that can exist at the intersection of the wear plate face of the forward yoke ear and the existing machining cut for the anti-torque and bushing caused these breaks. This condition, if not corrected, could result in high propeller vibration, requiring the pilot to feather the propeller, and could contribute to reduced controllability of the airplane.

Relevant Service Information

We have reviewed and approved the technical contents of Hamilton Sundstrand Service Bulletin 14RF-19-61-113, Revision 1, dated September 2, 2003, that describes procedures for installing a new propeller system actuator yoke arm, P/N 810436-3.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other products of this same type design. We are proposing this AD, which would require replacing the actuator yoke arm, P/N 810436-2 on model 14RF-19 propellers with an improved actuator yoke arm, P/N 810436-3. The proposed AD would require you to use the service information described previously to perform these actions.

Costs of Compliance

We estimate that 80 actuator yoke arms installed on airplanes of U.S. registry would be affected by this proposed AD. We also estimate that the required parts would cost

approximately \$1,350 per propeller and that it would take about 2 work hours per propeller to perform the proposed actions, and that the average labor rate is \$65 per work hour. Based on these figures, we estimate the total cost of the proposed AD to be \$118,400.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Under the authority delegated to me by the Administrator, the Federal

Aviation Administration proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Hamilton Sundstrand: Docket No. FAA–2005–21691; Directorate Identifier 2005–NE–13–AD.

Comments Due Date

(a) The Federal Aviation Administration (FAA) must receive comments on this airworthiness directive (AD) action by February 6, 2006.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Hamilton Sundstrand Model 14RF–19 propellers with propeller system actuator yoke arms, part number (P/N) 810436–2, which might be installed in actuator assemblies P/N 790119–6. These propellers are installed on, but not limited to, SAAB 340 airplanes.

Unsafe Condition

(d) This AD results from propeller system actuator yoke arms breaking during flight. We are issuing this AD to prevent actuator yoke arms breaking during flight, which could cause high propeller vibration, requiring the pilot to feather the propeller, and could contribute to reduced controllability of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within 60 days after the effective date of this AD, unless the actions have already been done.

Install Improved Actuator Yoke Arms

(f) Using the Accomplishment Instructions of Hamilton Sundstrand Service Bulletin 14RF–19–61–113, Revision 1, dated September 2, 2003, replace all actuator yoke arms, P/N 810436–2 with improved actuator yoke arms, P/N 810436–3.

(g) Mark newly installed actuators using the Accomplishment Instructions of Hamilton Sundstrand Service Bulletin 14RF–19–61–113, Revision 1, dated September 2, 2003.

(h) After the effective date of this AD, do not install any actuator yoke arms, P/N 810436–2, into any propeller assembly.

Alternative Methods of Compliance

(i) The Manager, Boston Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Related Information

(j) None.

Issued in Burlington, Massachusetts, on December 2, 2005.

Peter A. White,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 05–23770 Filed 12–7–05; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA–2005–23081; Airspace Docket No. 05–AAL–31]

RIN 2120–AA66

Proposed Amendments to Colored Federal Airways; AK

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to revoke colored Federal Airway B–12, modify three colored Federal Airways B–4, R–50 and G–7, and establish colored Federal Airway R–4 in Alaska. These amendments would remove all airways and routes off the Bishop, AK, Nondirectional Radio Beacon (NDB) in preparation for the NDB's eventual decommissioning from the National Airspace System (NAS).

DATES: Comments must be received on or before January 23, 2006.

ADDRESSES: Send comments on this proposal to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW., Washington, DC 20590–0001. You must identify the docket number FAA–2005–23081 and Airspace Docket No. 05–AAL–31, at the beginning of your comments. You may also submit comments through the Internet at <http://dms.dot.gov>.

FOR FURTHER INFORMATION CONTACT: Ken McElroy, Airspace and Rules, Office of System Operations Airspace and AIM, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone: (202) 267–8783.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis

supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA–2005–23081 and Airspace Docket No. 05–AAL–31) and be submitted in triplicate to the Docket Management System (see **ADDRESSES** section for address and phone number). You may also submit comments through the Internet at <http://dms.dot.gov>.

Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed, stamped postcard on which the following statement is made: “Comments to Docket No. FAA–2005–23081 and Airspace Docket No. 05–AAL–31.” The postcard will be date/time stamped and returned to the commenter.

All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this action may be changed in light of comments received. All comments submitted will be available for examination in the public docket both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRM's

An electronic copy of this document may be downloaded through the Internet at <http://dms.dot.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at <http://www.faa.gov> or the Federal Register's Web page at <http://www.gpoaccess.gov/fr/index.html>.

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office (see **ADDRESSES** section for address and phone number) between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. An informal docket may also be examined during normal business hours at the office of the Regional Air Traffic Division, Federal Aviation Administration, 222 West 7th Avenue, #14, Anchorage, AK 99533.

Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking, (202) 267–9677, for a copy of Advisory Circular No. 11–2A, Notice of Proposed