

(1) Within the next 150 hours time-in-service (TIS) after the effective date of this AD, and thereafter at intervals not to exceed 150 hours TIS, inspect the rudder trim tab upper pivot following the instructions in Pacific Aerospace Limited Mandatory Service Bulletin PACSB/XL/023, dated February 15, 2007.

(i) If there is any lateral movement of the bush found in any inspection required in paragraph (f)(1) of this AD, before further flight, install modification PAC/XL/0267, following Pacific Aerospace Limited Mandatory Service Bulletin PACSB/XL/023, dated February 15, 2007; and Pacific Aerospace Ltd. Drawing No. 11-03131, Drawing Approved Date: February 17, 2007.

(ii) Modification PAC/XL/0267 comprises removing the upper bush P/N 11-33119-1 and installing upper bearing P/N 11-33121-1 following Pacific Aerospace Ltd. Drawing No. 11-03131, Drawing Approved Date: February 17, 2007. Modification PAC/XL/0267 is a terminating action to the requirements of this AD.

(2) Within the next 450 hours TIS after the effective date of this AD or within 24 months after the effective date of this AD, whichever occurs sooner, modify the rudder trim tab upper pivot with modification PAC/XL/0267 following Pacific Aerospace Limited Mandatory Service Bulletin PACSB/XL/023, dated February 15, 2007, and Pacific Aerospace Ltd. Drawing No. 11-03131, Drawing Approved Date: February 17, 2007.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Staff, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI Civil Aviation Authority of New Zealand AD DCA/750XL/11, dated March 29, 2007; Pacific Aerospace Ltd. Mandatory Service Bulletin PACSB/XL/023, dated February 15, 2007; and Pacific Aerospace Ltd. Drawing No. 11-03131, Drawing Approved Date: February 17, 2007, for related information.

Issued in Kansas City, Missouri, on May 11, 2007.

David R. Showers,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-9597 Filed 5-17-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-27861; Directorate Identifier 2007-CE-035-AD]

RIN 2120-AA64

Airworthiness Directives; British Aerospace Regional Aircraft Model Jetstream HP.137 Jetstream Mk.1, Jetstream Series 200, Jetstream Series 3101, and Jetstream Model 3201 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

In-service reports have been received by BAE of failed bolts fitted to frame 199 wing spigot post assembly. If left uncorrected failure of these bolts will severely compromise the structural integrity of the wing to fuselage attachment. Failure of which would lead to loss of the aircraft. To address these concerns, BAE issued SB 57-JA020740 original issue in February 2003 mandated by CAA AD 006-02-2003. Recently received additional information has caused BAE to raise the Service Bulletin to revision 2. Revision 2 of the SB introduces various changes. One is substantive, it relates to the need to check for correct washer installation. Incorrect installation could lead to fretting and fatigue crack initiation in the fitting followed by failure or bending loads in the bolt leading to failure of the affected bolts. If left uncorrected failure of these bolts or a

wing fitting will severely compromise the structural integrity of the wing to fuselage attachment, failure of which would lead to loss of the aircraft. This substantive change to the service bulletin necessitates the raising of this superseding AD.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by June 18, 2007.

ADDRESSES: You may send comments by any of the following methods:

- *DOT Docket Web Site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Fax:* (202) 493-2251.

- *Mail:* Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001.

- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5227) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Streamlined Issuance of AD

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. This streamlined process will allow us to adopt MCAI safety requirements in a more efficient manner and will reduce safety risks to the public. This process continues to follow all FAA AD issuance processes to meet legal, economic, Administrative Procedure Act, and **Federal Register** requirements. We also continue to meet our technical decision-making responsibilities to identify and correct

unsafe conditions on U.S.-certificated products.

This proposed AD references the MCAI and related service information that we considered in forming the engineering basis to correct the unsafe condition. The proposed AD contains text copied from the MCAI and for this reason might not follow our plain language principles.

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2007-27861; Directorate Identifier 2007-CE-035-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued AD No: G-2006-0003, dated February 2, 2006 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products.

The MCAI states:

In-service reports have been received by BAE of failed bolts fitted to frame 199 wing spigot post assembly. If left uncorrected failure of these bolts will severely compromise the structural integrity of the wing to fuselage attachment. Failure of which would lead to loss of the aircraft. To address these concerns, BAE issued SB 57-JA020740 original issue in February 2003 mandated by CAA AD 006-02-2003. Recently received additional information has caused BAE to raise the Service Bulletin to revision 2. Revision 2 of the SB introduces various changes. One is substantive, it relates to the need to check for correct washer installation. Incorrect installation could lead to fretting and fatigue crack initiation in the fitting followed by failure or bending loads in the bolt leading to failure of the affected bolts. If left uncorrected failure of these bolts or a wing fitting will severely compromise the structural integrity of the wing to fuselage attachment, failure of which would lead to loss of the aircraft. This substantive change to the service bulletin necessitates the raising of this superseding AD.

You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

British Aerospace Regional Aircraft has issued British Aerospace Jetstream Series 3100 and 3200 Service Bulletin 57-JA020740, Revision 2, dated November 2, 2005. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This Proposed AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a **Note** within the proposed AD.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 195 products of U.S. registry. We also estimate that it would take about 50 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour. Required parts would cost about \$100 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these costs. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$799,500, or \$4,100 per product.

Estimate above is based on Pre-Mod 7130 installed per airplane. We estimate it would take about 25 work-hours per product if Post-Mod 7130 is installed.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

British Aerospace Regional Aircraft: Docket No. FAA–2007–27861; Directorate Identifier 2007–CE–035–AD.

Comments Due Date

(a) We must receive comments by June 18, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Jetstream HP.137 Jetstream Mk.1, Jetstream Series 200, Jetstream Series 3101, and Jetstream Model 3201 airplanes, all serial numbers, certificated in any category.

Subject

(d) Air Transport Association of America (ATA) Code 57: Wings.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states: In-service reports have been received by BAE of failed bolts fitted to frame 199 wing spigot post assembly. If left uncorrected failure of these bolts will severely compromise the structural integrity of the wing to fuselage attachment. Failure of which would lead to loss of the aircraft. To address these concerns, BAE issued SB 57–JA020740 original issue in February 2003 mandated by CAA AD 006–02–2003. Recently received additional information has caused BAE to raise the Service Bulletin to revision 2. Revision 2 of the SB introduces various changes. One is substantive, it relates to the need to check for correct washer installation. Incorrect installation could lead to fretting and fatigue crack initiation in the fitting followed by failure or bending loads in the bolt leading to failure of the affected bolts. If left uncorrected failure of these bolts or a wing fitting will severely compromise the structural integrity of the wing to fuselage attachment. Failure of which would lead to loss of the aircraft. This substantive change to the service bulletin necessitates the raising of this superseding AD.

Actions and Compliance

(f) Unless already done, do the following actions using British Aerospace Jetstream Series 3100 and 3200 Service Bulletin 57–JA020740, Revision 2, dated November 2, 2005.

(1) Initially, within 90 days or 100 hours time-in-service (TIS), whichever occurs first, after the effective date of this AD and repetitively thereafter at intervals not to

exceed 4,000 hours TIS, inspect and torque check the bolts at frame 199.

(2) If any discrepancies are found in any of the inspections required in paragraph (f)(1) of this AD, before further flight, correct any discrepancies.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: We added repetitive inspection requirements in this proposed AD to coincide with the service bulletin.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Staff, FAA, ATTN: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4059; fax: (816) 329–4090, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120–0056.

Related Information

(h) Refer to European Aviation Safety Agency (EASA) AD No: G–2006–0003, dated February 2, 2006; and BAE SYSTEMS Jetstream Series 3100 and 3200 Service Bulletin 57–JA020740, Revision 2, dated November 2, 2005, for related information.

Issued in Kansas City, Missouri, on May 11, 2007.

David R. Showers,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7–9603 Filed 5–17–07; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF EDUCATION

34 CFR Part 303

Early Intervention Program for Infants and Toddlers With Disabilities

AGENCY: Office of Special Education and Rehabilitative Services, Department of Education.

ACTION: Notice of public meetings about the Part C notice of proposed rulemaking (NPRM).

SUMMARY: On May 9, 2007, the Secretary published the Part C NPRM, proposing to amend the regulations governing the Early Intervention Program for Infants and Toddlers with Disabilities. The Secretary announces plans to hold a series of public meetings to seek comments and suggestions about the proposed rules. The proposed regulations would implement changes made to the Individuals with Disabilities Education Act (IDEA) by the Individuals with Disabilities Education Improvement Act of 2004.

DATES: Four public meetings will be held on June 4, 2007, June 6, 2007, June 11, 2007, and June 14, 2007.

ADDRESSES: We will hold four public meetings about the Part C NPRM:

1. June 4, 2007, 4 p.m. to 7:30 p.m., Portland—Embassy Suites Hotel Portland Airport (Pine & Spruce Room), 7900 Northeast 82nd Avenue, Portland, OR.

2. June 6, 2007, 4 p.m. to 7:30 p.m., Oklahoma City—Metro Technology Centers (Auditorium), 1900 Springlake Drive, Oklahoma City, OK.

3. June 11, 2007, 4 p.m. to 7:30 p.m., Indianapolis—Indiana Government Center South Conference Center (Auditorium), 402 W. Washington Street, Indianapolis, IN.

4. June 14, 2007, 3 p.m. to 7:30 p.m., Washington—Academy for Educational Development, 1825 Connecticut Ave. NW., Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Katherine Race, U.S. Department of Education, 400 Maryland Avenue, SW., Room 5145, Potomac Center Plaza, Washington, DC 20202–2600. Telephone: (202) 245–6443.

SUPPLEMENTARY INFORMATION: If you use a telecommunications device for the deaf (TDD), you may call the Federal Relay System (FRS) at 1–800–877–8339.

Individuals with disabilities may obtain this document in an alternative format (e.g. Braille, large print, audiotope, or computer diskette) on request to the contact person listed under **FOR FURTHER INFORMATION CONTACT**.

Assistance to Individuals With Disabilities at the Public Meetings

The meeting sites are accessible to individuals with disabilities. If you will need an auxiliary aid or service to participate in the meeting (e.g., interpreting service, assistive listening device, or materials in an alternate format), notify the contact person listed