

(a) Effective Date

This airworthiness directive (AD) becomes effective July 9, 2013.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc. Model BD-100-1A10 (Challenger 300) airplanes, certificated in any category, having serial numbers 20003 through 20335 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 29, Hydraulic Power.

(e) Reason

This AD was prompted by reports of failure of a screw-cap or end cap of the hydraulic system accumulator while on the ground, which resulted in loss of use of that hydraulic system and high-energy impact damage to adjacent systems and structures. We are issuing this AD to prevent failure of a screw cap or end cap and loss of the related hydraulic system, which could result in damage to airplane structure and consequent reduced controllability of the airplane.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Inspection

At the applicable time specified in paragraph (g)(1), (g)(2), or (g)(3) of this AD: Inspect the identification plate on the hydraulic system accumulator having part number (P/N) 900095-1 to determine if an "E" is part of the suffix of the serial number stamped on the identification plate, as listed in paragraph 2.B. of the Accomplishment Instructions of Bombardier Service Bulletin 100-29-14, dated December 16, 2010. A review of airplane maintenance records is acceptable in lieu of this inspection if the suffix of the serial number can be conclusively determined from that review.

(1) For an accumulator that has accumulated more than 3,150 total flight cycles as of the effective date of this AD, inspect that accumulator within 350 flight cycles after the effective date of this AD.

(2) For an accumulator that has accumulated 3,150 or fewer total flight cycles as of the effective date of this AD, inspect that accumulator before it has accumulated 3,500 total flight cycles.

(3) For an accumulator on which it is not possible to determine the total flight cycles accumulated as of the effective date of this AD, inspect that accumulator within 350 flight cycles after the effective date of this AD.

(h) Replacement

If, during the inspection required by paragraph (g) of this AD, any accumulator having P/N 900095-1 is found on which the letter "E" is not part of the suffix of the serial number on the identification plate: Before further flight, replace the accumulator with a new or serviceable accumulator, in accordance with paragraph 2.C. of the

Accomplishment Instructions of Bombardier Service Bulletin 100-29-14, dated December 16, 2010.

(i) Parts Installation Prohibition

As of the effective date of this AD, no person may install on any airplane a hydraulic system accumulator having P/N 900095-1, on which the letter "E" is not part of the suffix of the serial number on the identification plate.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to the Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone (516) 228-7300; fax (516) 794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(k) Related Information

Refer to MCAI Canadian Airworthiness Directive CF-2011-41, dated October 31, 2011; and Bombardier Service Bulletin 100-29-14, dated December 16, 2010; for related information.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Bombardier Service Bulletin 100-29-14, dated December 16, 2010.

(ii) Reserved.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton,

WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 22, 2013.

Jeffrey E. Duven,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2013-12898 Filed 6-3-13; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF DEFENSE**Department of the Navy****32 CFR Part 706****Certifications and Exemptions Under the International Regulations for Preventing Collisions at Sea, 1972**

AGENCY: Department of the Navy, DoD.

ACTION: Final rule.

SUMMARY: The Department of the Navy (DoN) is amending its certifications and exemptions under the International Regulations for Preventing Collisions at Sea, 1972 (72 COLREGS), to reflect that the Deputy Assistant Judge Advocate General (DAJAG) (Admiralty and Maritime Law) of the DoN has determined that USS THEODORE ROOSEVELT (CVN 71) is a vessel of the Navy which, due to its special construction and purpose, cannot comply fully with certain provisions of the 72 COLREGS without interfering with its special function as a naval ship. The intended effect of this rule is to warn mariners in waters where 72 COLREGS apply.

DATES: This rule is effective June 4, 2013 and is applicable beginning May 20, 2013.

FOR FURTHER INFORMATION CONTACT:

Lieutenant Jocelyn Loftus-Williams, JAGC, U.S. Navy, Admiralty Attorney, (Admiralty and Maritime Law), Office of the Judge Advocate General, Department of the Navy, 1322 Patterson Ave. SE., Suite 3000, Washington Navy Yard, DC 20374-5066, telephone number: 202-685-5040

SUPPLEMENTARY INFORMATION: Pursuant to the authority granted in 33 U.S.C. 1605, the DoN amends 32 CFR Part 706.

This amendment provides notice that the DAJAG (Admiralty and Maritime Law) of the DoN, under authority delegated by the Secretary of the Navy,

has certified that USS THEODORE ROOSEVELT (CVN 71) is a vessel of the Navy which, due to its special construction and purpose, cannot comply fully with the following specific provisions of 72 COLREGS without interfering with its special function as a naval ship: Annex I, paragraph 2(g), pertaining to the placement of the sidelights above the hull; and Annex I, paragraph 2(i) (iii), pertaining to the vertical line spacing of the task lights. The DAJAG (Admiralty and Maritime Law) has also certified that the lights involved are located in closest possible compliance with the applicable 72 COLREGS requirements.

Moreover, it has been determined, in accordance with 32 CFR Parts 296 and 701, that publication of this amendment for public comment prior to adoption is impracticable, unnecessary, and

contrary to public interest since it is based on technical findings that the placement of lights on this vessel in a manner differently from that prescribed herein will adversely affect the vessel's ability to perform its military functions.

List of subjects in 32 CFR Part 706

Marine Safety, Navigation (Water), and Vessels.

For the reasons set forth in the preamble, amend part 706 of title 32 of the CFR as follows:

PART 706—CERTIFICATIONS AND EXEMPTIONS UNDER THE INTERNATIONAL REGULATIONS FOR PREVENTING COLLISIONS AT SEA, 1972

- 1. The authority citation for part 706 continues to read:

Authority: 33 U.S.C. 1605

- 2. Section 706.2 is amended as follows:

■ A. In Table Two by revising the entry for USS THEODORE ROOSEVELT (CVN 71); and

■ B. In Table Four by adding the following entry for USS THEODORE ROOSEVELT (CVN 71).

The additions read as follows:

§ 706.2 Certifications of the Secretary of the Navy under Executive Order 11964 and 33 U.S.C. 1605.

* * * * *

TABLE TWO

Vessel	Number	Masthead lights, distance to stbd of keel in meters; Rule 21(a)	Forward anchor light, distance below flight dk in meters; § 2(K), Annex I	Forward anchor light, number of; Rule 30(a)(i)	AFT anchor light, distance below flight dk in meters; Rule 21(e), Rule 30(a)(ii)	AFT anchor light, number of; Rule 30(a)(ii)	Side lights, distance below flight dk in meters; § 2 (g), Annex I	Side lights, distance forward of forward mast-head light in meters; § 3(b), Annex I	Side lights, distance in-board of ship's sides in meters; § 3(b), Annex I
USS THEODORE ROOSEVELT.	CVN 71 ..	30.0	—		—		0.43	—	—

* * * * *

* * * * *

* * * * *

TABLE FOUR

Vessel	No	Vertical separation of the task light array is not equally spaced, the separation between the middle and lower task light exceed the separation between the upper and middle light by
USS THEODORE ROOSEVELT	CVN 71	0.18 meter

* * * * *

A. B. Fischer,

Captain, JAGC, U.S. Navy, Deputy Assistant Judge Advocate, General (Admiralty and Maritime Law).

C. K. Chiappetta,

Lieutenant Commander, Office of the Judge Advocate General, U.S. Navy, Federal Register Liaison Officer.

[FR Doc. 2013-13138 Filed 6-3-13; 8:45 am]

BILLING CODE 3810-FF-P

OFFICE OF SCIENCE AND TECHNOLOGY POLICY

32 CFR Part 2402

Implementation of the Freedom of Information Act

AGENCY: Office of Science and Technology Policy.

ACTION: Final rule.

SUMMARY: The White House Office of Science and Technology Policy (OSTP) issues this final rule to implement the Freedom of Information Act (FOIA), as

amended. This final rule implements the requirement of the FOIA by setting forth procedures for requesting access to, and making disclosures of, information contained by OSTP.

This final rule contains provisions to comply with the President's January 21, 2009, Executive Memoranda on "The Freedom of Information Act" and "Transparency and Open Government," and Attorney General Holder's March 19, 2009, Memorandum on "The Freedom of Information Act (FOIA)." In addition, this rule reflects OSTP's policy and practices and reaffirms its