

**Alternative Methods of Compliance**

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office (ECO). Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, ECO.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the ECO.

**Special Flight Permits**

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

**Incorporation by Reference**

(e) The actions required by this AD must be performed in accordance with the Accomplishment Instructions of RR MSB No. RB.211-78-C931, Revision 1, dated June 13, 2000. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Rolls-Royce plc, PO Box 31, Derby, England; telephone: International Access Code 011, Country Code 44, 1332-249428, fax: International Access Code 011, Country Code 44, 1332-249223. Copies may be inspected at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

**Effective Date of This AD**

(f) This amendment becomes effective on January 12, 2001.

Issued in Burlington, Massachusetts, on November 28, 2000.

**Mark C. Fulmer,**

*Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 00-31113 Filed 12-12-00; 8:45 am]

**BILLING CODE 4910-13-U**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. 98-ANE-33-AD; Amendment 39-12033; AD 2000-24-26]

**RIN 2120-AA64**

**Airworthiness Directives; Rolls-Royce plc RB211 Trent 800 Series Turbofan Engines**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment supersedes an existing airworthiness directive (AD), applicable to certain Rolls-Royce plc RB211 Trent 800 series turbofan engines, that currently requires initial and repetitive ultrasonic inspections of fan blade roots for cracks, and replacement, if necessary, with serviceable parts. This amendment requires the reduction of the initial cyclic compliance threshold and repetitive inspection intervals. This amendment also allows inspections to be accomplished within 100 cycles-in-service if the initial or repetitive thresholds are exceeded on the effective date of this AD. This amendment is prompted by an improved understanding of the crack propagation mechanism and the latest service operational data. The actions specified by this AD are intended to detect and prevent fan blade failure, which could result in multiple fan blade releases, uncontained engine failure, and possible damage to the airplane.

**DATES:** Effective February 12, 2001. The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of February 12, 2001.

**ADDRESSES:** The service information referenced in this AD may be obtained from Rolls-Royce North America, Inc., 2001 South Tibbs Ave., Indianapolis, IN 46241; telephone: (317) 230-3995, fax: (317) 230-4743. This information may be examined at the Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA 01803-5299; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Richard Woldan, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone: (781) 238-7136, fax: (781) 238-7199.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) by superseding AD 98-19-21, Amendment 39-10762 (63 FR 50484, September 22, 1998, corrected by 63 FR 52961, October 2, 1998), applicable to Rolls-Royce plc (RR) RB211 Trent 800 series turbofan engines, was published in the **Federal Register** on December 3, 1999 (64 FR 67806). That action proposed to require the reduction of initial compliance thresholds and repetitive cyclic inspection intervals. The action also proposed the allowance for inspections to be accomplished

within 100 cycles-in-service if the initial or repetitive thresholds are exceeded on the effective date of the AD.

**Comments Received**

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the one comment received.

**Request To Revise Economic Analysis**

The comment states that all RR Trent 800 series engines on the US registry that will be affected by the AD have already been modified to RR Service Bulletin RB.211-72-C629. Therefore, the estimate of the total cost impact of the proposed action on US operators is zero.

The FAA disagrees. Although some Trent 800 series engines on US registered airplanes may have already been modified to RR Service Bulletin RB.211-72-C629 and the actual cost may be reduced, the original economic analysis is retained.

**Conclusion**

After careful review of the available data, including the comment noted above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

**Regulatory Impact**

This rule does not have federalism implications, as defined in Executive Order (EO) 13132, because it does not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Accordingly, the FAA has not consulted with state authorities prior to publication of this rule.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under EO 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration (FAA) amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by removing Amendment 39–10762 (63 FR 50484, September 22, 1998) and by adding a new airworthiness directive, Amendment 39–12033, to read as follows:

#### AD 2000–24–26 Rolls-Royce plc.:

Amendment 39–12033. Docket 98–ANE–33–AD. Supersedes AD 98–19–21, Amendment 39–10762.

**Applicability:** Rolls-Royce plc (RR) RB211 Trent 875, RB211 Trent 877, RB211 Trent 884, RB211 Trent 892, and RB211 Trent 892B series turbofan engines, except if the fan blades described in RR Service Bulletin (SB) RB.211–72–C629 were installed as complete sets. These engines are installed on but not limited to Boeing 777 series airplanes.

**Note 1:** This airworthiness directive (AD) applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b)

of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

#### Compliance

Required as indicated, unless accomplished previously.

To prevent fan blade failure, which could result in multiple fan blade releases, uncontained engine failure, and possible damage to the airplane, accomplish the following:

#### Ultrasonic Inspections (Reduced Thresholds and Repetitive Intervals)

(a) Perform initial and repetitive inspections of fan blade roots for cracks, in accordance with RR SB No. RB211–72–C445, Revision 6, dated September 3, 1999, as follows:

(1) For Trent 875 series engines, inspect as follows:

(i) Initially, prior to accumulating 3,000 cycles-since-new (CSN).

(ii) Thereafter, at intervals not to exceed 400 cycles-in-service (CIS) since last inspection.

(2) For Trent 877 series engines, inspect as follows:

(i) Initially, prior to accumulating 2,000 CSN.

(ii) Thereafter, at intervals not to exceed 350 CIS since last inspection.

(3) For Trent 884 series engines, inspect as follows:

(i) Initially, prior to accumulating 1,500 CSN.

(ii) Thereafter, at intervals not to exceed 350 CIS since last inspection.

(4) For Trent 892 and 892B series engines, inspect as follows:

(i) Initially, prior to accumulating 900 CSN.

(ii) Thereafter, at intervals not to exceed 200 CIS since last inspection.

#### Engines Exceeding Thresholds and Repetitive Intervals

(5) For engines that exceed the initial inspection thresholds listed in paragraphs (a)(1)(i), (a)(2)(i), (a)(3)(i), and (a)(4)(i) on the effective date of this AD, conduct initial inspection within 100 CIS after the effective date of this AD.

(6) For engines that exceed the repetitive inspection intervals listed in paragraphs (a)(1)(ii), (a)(2)(ii), (a)(3)(ii), and (a)(4)(ii) on the effective date of this AD, inspect within 100 CIS after the effective date of this AD.

#### Cracked Parts

(7) Prior to further flight, remove from service cracked fan blades and replace with serviceable parts.

#### Alternate Method of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office (ECO). Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, ECO.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the ECO.

#### Ferry Flights

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the inspection requirements of this AD can be accomplished.

#### Incorporation by Reference Material

(d) The actions required by this AD must be done in accordance with the following Rolls-Royce SB:

Document No.	Pages	Revision	Date
RB.211–72–C445 .....	1–9 .....	6 .....	September 3, 1999.
Appendix 1 .....	1 .....	Original .....	February 13, 1998.
	2 .....	6 .....	September 3, 1999.
	3–4 .....	Original .....	February 13, 1998.
Appendix 2 .....	1 .....	Revision 4 .....	November 6, 1998.
	2–3 .....	Original .....	February 13, 1998.

Total pages: 16.

The incorporations by reference were approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Rolls-Royce North America, Inc., 2001 South Tibbs Ave., Indianapolis, IN 46241; telephone: (317) 230-3995; fax: (317) 230-4743. Copies may be inspected at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA 01803-5299; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

#### Effective Date

(e) This amendment becomes effective on February 12, 2001.

Issued in Burlington, Massachusetts, on November 30, 2000.

**Mark C. Fulmer,**

*Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 00-31066 Filed 12-12-00; 8:45 am]

**BILLING CODE 4910-13-U**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2000-SW-49-AD; Amendment 39-12037; AD 2000-25-03]

**RIN 2120-AA64**

#### **Airworthiness Directives; Bell Helicopter Textron Inc. Model 205A-1, 205B, 212, 412, and 412CF Helicopters**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD) for Bell Helicopter Textron Inc. (BHTI) Model 205A-1, 205B, 212, 412, and 412CF helicopters. This action requires inspecting the locking washer on each main rotor actuator (actuator) for twisting or damage to the tab and replacing any locking washer that has a twisted or damaged tab. Replacing certain locking washers, regardless of condition, is also required within a specified time period. Installing a certain airworthy locking device on each actuator constitutes terminating action for the requirements of this AD. This amendment is prompted by an incident in which a damaged locking washer allowed the rod end to detach from the collective actuator, causing loss of collective control of the main rotor. The current locking washer is subject to mechanical damage and failure, which allows the actuator piston to unthread itself from its rod end. This

condition, if not corrected, could cause loss of control of the main rotor and subsequent loss of control of the helicopter.

**DATES:** Effective December 28, 2000.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of December 28, 2000.

Comments for inclusion in the Rules Docket must be received on or before February 12, 2001.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Office of the Regional Counsel, Southwest Region, Attention: Rules Docket No. 2000-SW-49-AD, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. You may also send comments electronically to the Rules Docket at the following address: 9-asw-adcomments@faa.gov.

The service information referenced in this AD may be obtained from HR Textron, 25200 W. Rye Canyon Road, Santa Clarita, California 91355-1265, telephone (611) 702-5509, fax (661) 702-5970. This information may be examined at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

#### **FOR FURTHER INFORMATION CONTACT:**

Alfred Boutin, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Rotorcraft Certification Office, Fort Worth, Texas 76193-0170, telephone (817) 222-5157, fax (817) 222-5783.

**SUPPLEMENTARY INFORMATION:** This amendment adopts a new AD for BHTI Model 205A-1, 205B, 212, 412, and 412CF helicopters. This AD requires, within 25 hours time-in-service (TIS), inspecting the tab on the NAS513-6 locking washer on all actuators, part number (P/N) 41105950, serial number with an "HR" prefix up to and including 490 and P/N 41000470, serial numbers with a prefix of "HR" up to and including 10010, for a twisted or damaged tab. P/N's 41105950 and 41000470 were assigned by the manufacturer; the BHTI P/N's are 205-076-036 and 212-076-005. Replacing any twisted or damaged locking washer with an airworthy NAS1193K6C locking device is required before further flight. Replacing any NAS513-6 locking washer with an airworthy NAS1193K6C locking device, regardless of the condition of the tab, is required within 100 hours TIS or at the next actuator overhaul, whichever occurs first. Installing an airworthy NAS 1193K6C locking device on all actuators

constitutes terminating action for the requirements of this AD. This AD is prompted by the discovery of a damaged locking washer. The damage to the locking washer was discovered when an operator experienced a problem with a collective control while attempting to take off. The collective control could not be moved upward from the full down position. Further inspection revealed that the lower piston of the actuator had unthreaded and separated from the lower rod end, causing the piston to make contact with the rod end support assembly and lodge itself against the rod end shank at an angle limiting any movement of the collective control. The collective servo cylinder assembly is used to provide irreversible collective control of the main rotor. Because the actuator end locking washer failed, the servo lower piston could rotate inside the lower servo head assembly and unthread itself from the rod end. This condition, if not corrected, could cause loss of control of the main rotor and subsequent loss of control of the helicopter.

The FAA has reviewed HR Textron Alert Service Bulletin (ASB) No. 41000470-67A-05, Revision 1 and HR Textron ASB No. 41105950-67A-01, Basic Issue, both dated October 19, 2000, which describe procedures for inspecting and replacing certain locking washers. BHTI has issued ASB No.'s 205-00-79, 205B-00-33, 212-00-109, 412-00-105, and 412CF-00-12, all dated October 19, 2000, which include the applicable HR Textron Alert Service Bulletins.

Since an unsafe condition has been identified that is likely to exist or develop on other BHTI Model 205A-1, 205B, 212, 412, and 412CF helicopters of the same type designs, this AD is being issued to prevent an actuator piston from unthreading itself from its rod end causing loss of collective control and subsequent loss of control of the helicopter. This AD requires inspecting the locking washers on all actuators for twisting or damage to the tab and replacing any locking washer that has a twisted or damaged tab. Replacing certain locking washers, regardless of condition, is also required within 100 hours TIS or at the next actuator overhaul, whichever occurs first. Installing an airworthy NAS1193K6C locking device on all actuators constitutes terminating action for the requirements of this AD. The actions must be accomplished in accordance with the HR Textron service bulletins described previously. The short compliance time involved is required because the previously described critical unsafe condition can