

Actions	Compliance	Procedures
(2) If corrosion is found during any inspection that does not exceed the limits specified in Shorts Service Bulletin 27-77, repair the corrosion damage on the affected flight control rod.	Prior to further flight after the inspection where the damage is found.	In accordance with the ACCOMPLISHMENT INSTRUCTIONS section of Shorts Service Bulletin Number 27-77, Original Issue 27/FEB/03.
(3) If any crack is found or if corrosion damage that exceeds the limits specified in Shorts Service Bulletin 27-77 is found during any inspection required by this AD, replace the affected flight control rod.	Prior to further flight after the inspection where the damage or cracks are found.	In accordance with the ACCOMPLISHMENT INSTRUCTIONS section of Shorts Service Bulletin Number 27-77, Original Issue 27/FEB/03.
(4) Do not install any used flight control rod on any affected airplane unless it has been inspected and found to be corrosion and crack free as specified in this AD. Then repetitively inspect as required in paragraph (d)(1) of this AD.	As of August 11, 2003 (the effective date of this AD).	In accordance with the ACCOMPLISHMENT INSTRUCTIONS section of Shorts Service Bulletin Number 27-77, Original Issue 27/FEB/03.

(e) *Can I comply with this AD in any other way?* To use an alternative method of compliance or adjust the compliance time, use the procedures in 14 CFR 39.19. Send these requests to the Manager, Standards Office, Small Airplane Directorate. For information on any already approved alternative methods of compliance, contact Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; facsimile: (816) 329-4090.

(f) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with Shorts Service Bulletin Number 27-77, Original Issue February 27, 2003. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You may get copies from Short Brothers PLC, P.O. Box 241, Airport Road, Belfast BT3 9DZ Northern Ireland; telephone: +44 (0) 28 9045 8444; facsimile: +44 (0) 28 9073 3396. You may view copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note: The United Kingdom Civil Airworthiness Authority (CAA) classified Shorts Service Bulletin Number 27-77, Original Issue 27/FEB/03, as mandatory. The CAA classifying a service bulletin as mandatory is the equivalent for airplanes on the British registry as an AD is for airplanes on the U.S. registry.

(g) *When does this amendment become effective?* This amendment becomes effective on August 11, 2003.

Issued in Kansas City, Missouri, on June 16, 2003.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-15853 Filed 6-27-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-NE-23-AD; Amendment 39-13210; AD 2003-13-10]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce Corporation (Formerly Allison Engine Company, Allison Gas Turbine Division, and Detroit Diesel Allison) Models 250-C30R/3, -C30R/3M, -C47B, and -C47M Turboshaft Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for Rolls-Royce Corporation (formerly Allison Engine Company, Allison Gas Turbine Division, and Detroit Diesel Allison) models 250-C30R/3, -C30R/3M, -C47B, and -C47M turboshaft engines. This AD requires initial and repetitive electrical signal inspections of the hydromechanical unit (HMU) Power Lever Angle (PLA) potentiometer. This AD is prompted by an investigation by the National Transportation Safety Board (NTSB), which revealed that a potential undetected failure of the PLA potentiometer electrical signal could cause uncommanded and sudden changes in engine power. The actions specified in this AD are intended to prevent uncommanded and sudden changes in engine power.

DATES: Effective July 15, 2003. The Director of the Federal Register approved the incorporation by reference

of certain publications listed in the regulations as of July 15, 2003.

We must receive any comments on this AD by August 29, 2003.

ADDRESSES: Use one of the following addresses to submit comments on this AD:

- By mail: The Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 2003-NE-23-AD, 12 New England Executive Park, Burlington, MA 01803-5299.
- By fax: (781) 238-7055.
- By e-mail: 9-ane-adcomment@faa.gov

You may get the service information referenced in this AD from Rolls-Royce Corporation, P.O. Box 420, Indianapolis, IN 46206-0420; telephone (317) 230-6400; fax (317) 230-4243.

You may examine the AD docket at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA. You may examine the service information at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Khailaa Hosny, Aerospace Engineer, Chicago Aircraft Certification Office, FAA, 2300 East Devon Avenue, Des Plaines, IL 60018-4696; telephone (847) 294-7134; fax (847) 294-7834.

SUPPLEMENTARY INFORMATION: This AD applies to Rolls-Royce Corporation models 250-C30R/3, -C30R/3M, -C47B, and -C47M turboshaft engines. This AD requires initial and repetitive electrical signal inspections of the HMU PLA

potentiometer. This AD is prompted by an investigation by the NTSB into uncommanded and sudden changes in engine power on a Bell 407 helicopter on March 27, 2003. The NTSB investigation revealed that a potential undetected failure of the PLA potentiometer electrical signal, provided by the HMU of the full-authority digital electronic control (FADEC) system, could cause uncommanded and sudden changes in engine power. The actions specified in this AD are intended to prevent uncommanded and sudden changes in engine power.

Relevant Service Information

We have reviewed and approved the technical contents of section 2.B. of the Accomplishment Instructions of Rolls-Royce Corporation combined Service Bulletin (SB) CEB A-73-3103 (250-C30 engines) and CEB A-73-6030 (250-C47 engines), Revision 3, dated June 5, 2003, that describes procedures for inspecting the PLA potentiometer signal.

Differences Between This Proposed AD and the Manufacturer's Service Information

Although the combined SB CEB A-73-3103 (250-C30 engines) and CEB A-73-6030 (250-C47 engines), Revision 3, dated June 5, 2003, also includes 250-C40 engines, as CEB A-73-5021, the 250-C40 engine model is not affected by this AD because it is used in twin engine applications.

FAA's Determination and Requirements of This AD

The unsafe condition described previously is likely to exist or develop on other Rolls-Royce Corporation (formerly Allison Engine Company, Allison Gas Turbine Division, and Detroit Diesel Allison) models 250-C30R/3, -C30R/3M, -C47B, and -C47M turboshaft engines of the same type design. Therefore, we are issuing this AD to prevent uncommanded and sudden changes in engine power. This AD requires an initial electrical signal inspection of the HMU PLA potentiometer within 50 flight hours after the effective date of this AD, but no later than July 15, 2003, and thereafter, repetitive inspections every 300 flight hours. You must do these inspections in accordance with the service information described previously.

FAA's Determination of the Effective Date

Since an unsafe condition exists that requires the immediate adoption of this AD, we have found that notice and opportunity for prior public comment are impracticable, and that good cause

exists for making this amendment effective in less than 30 days.

Changes to 14 CFR Part 39—Effect on the AD

On July 10, 2002, we issued a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs our AD system. This regulation now includes material that relates to special flight permits, alternative methods of compliance, and altered products. This material previously was included in each individual AD. Since this material is included in 14 CFR part 39, we will not include it in future AD actions.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment; however, we invite you to submit any written relevant data, views, or arguments regarding this AD. Send your comments to an address listed under **ADDRESSES**. Include "AD Docket No. 2003-NE-23-AD" in the subject line of your comments. If you want us to acknowledge receipt of your mailed comments, send us a self-addressed, stamped postcard with the docket number written on it; we will date-stamp your postcard and mail it back to you. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify it. If a person contacts us through a nonwritten communication, and that contact relates to a substantive part of this AD, we will summarize the contact and place the summary in the docket. We will consider all comments received by the closing date and may amend the AD in light of those comments.

We are reviewing the writing style we currently use in regulatory documents. We are interested in your comments on whether the style of this document is clear, and your suggestions to improve the clarity of our communications with you. You may get more information about plain language at <http://www.plainlanguage.gov>.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this AD and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include "AD Docket No. 2003-NE-23-AD" in your request.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2003-13-10 Rolls-Royce Corporation (formerly Allison Engine Company, Allison Gas Turbine Division, and Detroit Diesel Allison): Amendment 39-13210. Docket No. 2003-NE-23-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective July 15, 2003.

Affected ADs

(b) None.

Applicability

(c) This AD is applicable to Rolls-Royce Corporation (formerly Allison Engine Company, Allison Gas Turbine Division, and Detroit Diesel Allison) models 250-C30R/3, -C30R/3M, -C47B, and -C47M turboshaft engines. These engines are installed on, but not limited to, Bell OH-58D, Bell Helicopter Textron 407, Boeing AH/MH-6M, and MD Helicopters Inc. 600N helicopters.

Unsafe Condition

(d) This AD was prompted by an investigation by the National Transportation Safety Board that revealed that a potential undetected failure of the Power Lever Angle (PLA) potentiometer electrical signal could cause uncommanded and sudden changes in

engine power. The actions specified in this AD are intended to prevent uncommanded and sudden changes in engine power.

Compliance

(e) Compliance with this AD is required as indicated, unless already done.

Initial Inspection

(f) Perform an initial electrical signal inspection of the hydromechanical unit (HMU) PLA potentiometer, within 50 flight hours after the effective date of this AD, but no later than July 15, 2003, in accordance with paragraph 2.B. of the Accomplishment Instructions of Rolls-Royce Corporation combined service bulletin (SB) No. CEB A-73-3103 (250-C30 engines), or CEB A-73-6030 (250-C47 engines), Revision 3, dated June 5, 2003.

(g) Replace the HMU before further flight if the electrical signal inspection result is unacceptable.

Repetitive Inspections

(h) Thereafter, perform repetitive electrical signal inspections of the HMU PLA potentiometer within 300 flight hours of the previous inspection, in accordance with section 2.B. of the Accomplishment Instructions of Rolls-Royce Corporation combined SB No. CEB A-73-3103 (250-C30 engines), or CEB A-73-6030 (250-C47 engines), Revision 3, dated June 5, 2003.

(i) Replace the HMU before further flight if the electrical signal inspection is unacceptable.

Alternative Methods of Compliance

(j) Alternative methods of compliance must be requested in accordance with 14 CFR part 39.19, and must be approved by the Manager, Chicago Aircraft Certification Office, FAA.

Material Incorporated by Reference

(k) The inspections in this AD must be done in accordance with section 2.B. of the Accomplishment Instructions of Rolls-Royce Corporation combined Service Bulletin (SB) CEB A-73-3103 (250-C30 engines) and CEB A-73-6030 (250-C47 engines), Revision 3, dated June 5, 2003. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. You may get a copy from Rolls-Royce Corporation, P.O. Box 420, Indianapolis, IN 46206-0420; telephone (317) 230-6400; fax (317) 230-4243. You may review copies at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

Related Information

(l) None.

Issued in Burlington, Massachusetts, on June 19, 2003.

Robert G. Mann,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 03-15993 Filed 6-27-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-NE-24-AD; Amendment 39-13211; AD 2003-13-11]

RIN 2120-AA64

Airworthiness Directives; Pratt & Whitney PW4074, PW4074D, PW4077, PW4077D, PW4090, and PW4090-3 Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for Pratt & Whitney (PW) PW4074, PW4074D, PW4077, PW4077D, PW4090, and PW4090-3 turbofan engines with high pressure compressor (HPC) rear cases, part numbers (P/Ns) 55H425-01, 55H385-01, and 56H396-01 installed. This AD requires initial and repetitive visual or fluorescent penetrant inspections (FPI) of the J flange on the HPC rear case, and removal from service of the rear case based on certain inspection results. This AD is prompted by reports of cracks propagating from bolt holes in the HPC rear case J flange, and reports of high-cycle HPC rear cases exhibiting cracks propagating into the shell wall. The actions specified in this AD are intended to prevent fracturing and rupturing of the HPC rear case, resulting in uncontained engine failure.

DATES: Effective July 15, 2003. The Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulations as of July 15, 2003.

We must receive any comments on this AD by August 29, 2003.

ADDRESSES: Use one of the following addresses to submit comments on this AD:

- By mail: The Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 2003-NE-24-AD, 12 New England Executive Park, Burlington, MA 01803-5299.

- By fax: (781) 238-7055.

- By e-mail: 9-ane-adcomment@faa.gov

You may get the service information referenced in this AD from Pratt & Whitney, 400 Main St., East Hartford, CT 06108, telephone (860) 565-6600; fax (860) 565-4503.

You may examine the AD docket at the FAA, New England Region, Office of the Regional Counsel, 12 New England

Executive Park, Burlington, MA. You may examine the service information at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Keith Lardie, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (781) 238-7189; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION:

This AD applies to PW PW4074, PW4074D, PW4077, PW4077D, PW4090, and PW4090-3 turbofan engines with HPC rear cases, P/Ns 55H425-01, 55H385-01, and 56H396-01 installed. This AD requires initial and repetitive visual or FPI inspections of the J flange on HPC rear cases, P/Ns 55H425-01, 55H385-01, and 56H396-01, which were previously produced with or modified to a scalloped flange configuration using PW Service Bulletin (SB) No. PW4G-112-72-150, dated April 16, 1998, or SB No. PW4G-112-72-151, dated April 16, 1998, or SB No. PW4G-112-72-195, dated May 5, 1999. This AD also requires removal from service of the rear case based on certain inspection results. This AD is prompted by 32 reports of cracks propagating from bolt holes in the HPC rear case J flange, and reports of high-cycle HPC rear cases exhibiting cracks propagating into the shell wall. The HPC rear cases, P/Ns 55H425-01, 55H385-01, and 56H396-01 were produced with or modified by PW SBs to incorporate a scalloped J flange design as corrective action to eliminate flange cracking at the bolt holes. The scalloped flange has not been effective in eliminating J flange cracking. Cracks found propagating into the shell wall could result in loss of case integrity, and require immediate removal before further flight. The actions specified in this AD are intended to prevent fracturing and rupturing of the HPC rear case, resulting in uncontained engine failure.

Relevant Service Information

We have reviewed and approved the technical contents of PW SB No. PW4G-112-72-256, dated April 2, 2003, that describes procedures for initial and repetitive visual or FPI inspections of the J flange on HPC rear cases, and removal from service of the rear case based on certain inspection results.