Authority: 49 U.S.C. 106(g), 40113, 44701.

## § 39.13 [Amended]

- 2. The FAA amends § 39.13 by:
- a. Removing Airworthiness Directive (AD) 2016–11–21, Amendment 39–18548 (81 FR 36137): and
- b. Adding the following new AD:

## Airbus Helicopters Deutschland GmbH: Docket No. FAA-2019-0113; Product

Docket No. FAA–2019–0113; Production Identifier 2017–SW–140–AD.

### (a) Applicability

This airworthiness directive (AD) applies to Airbus Helicopters Deutschland GmbH Model EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3 helicopters, certificated in any category.

## (b) Unsafe Condition

The FAA is issuing this AD to prevent certain parts from remaining in service beyond their fatigue life, resulting in failure of the part and subsequent loss of control of the helicopter.

#### (c) Affected ADs

This AD replaces AD 2016–11–21, Amendment 39–18548 (81 FR 36137, June 6, 2016).

#### (d) Comments Due Date

The FAA must receive comments by April 22, 2021.

## (e) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

## (f) Required Actions

- (1) Before further flight, establish a life limit for the tail rotor hub body (hub body), part number (P/N) L642A2003102, of 27,400 hours time-in-service (TIS). If you cannot determine the hub body's TIS, follow the instructions in Table 1, Examples and Calculations, Effectivity: The history of the hub body is not known or can't be identified, in Airbus Helicopters Alert Service Bulletin (ASB) EC135–04A–012, Revision 0, dated September 11, 2017, except where the service information specifies that you contact the manufacturer, you are required to remove the part from service instead.
- (2) Before further flight, revise the life limit for each part listed in paragraphs (f)(2)(i) and (ii) of this AD in the Airworthiness Limitations Section (ALS) of the existing maintenance manual for your helicopter and record the revised life limit on the component history card or equivalent record as follows:
  - (i) For swashplate parts:
- (A) The life limit for the ring (control ring), P/N L623M2001213, is 10,700 hours TIS.
- (B) The life limit for the cardan ring (two-part), P/N L623M2005205, is 14,300 hours
- (C) The life limit for the bolt (control ring), P/N L671M7001215, is 14,300 hours TIS.
- (D) The life limit for the bolt (sliding sleeve), P/N L623M2006206 and P/N L623M2006213, is 14,300 hours TIS.

- (ii) For mixing lever gear unit parts:
- (A) The life limit for the forked lever assembly, P/N L671M3012102, is 10,400 hours TIS.
- (B) The life limit for the hinged support, P/N L671M7003210, is 8,400 hours TIS.
- (C) The life limit for the bolt, P/N L671M7001220, is 8,400 hours TIS.
- (3) Before further flight, remove from service any part listed in paragraphs (f)(1) and (2) of this AD that has reached or exceeded its revised life limit.
- (4) Thereafter, for any part listed in paragraphs (f)(1) and (2) of this AD that has not reached or exceeded its life limit, continue to record the life limit of the part on its component history card or equivalent record and remove any part listed in paragraph (f)(1) and (2) of this AD from service before the part has reached or exceeded its revised life limit.

## (g) Special Flight Permits

Special flight permits are limited to a onetime flight to a maintenance facility to replace a part that has reached its life limit.

# (h) Alternative Methods of Compliance (AMOCs)

- (1) The Manager, Strategic Policy Rotorcraft Section, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. If sending information directly to the manager of the Strategic Policy Rotorcraft Section, send it to: Manager, Strategic Policy Rotorcraft Section, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817–222–5110. Information may be emailed to: 9-ASW-FTW-AMOC-Requests@faa.gov.
- (2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, the FAA suggests that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

# (i) Additional Information

The subject of this AD is addressed in European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD No. 2017–0243, dated December 6, 2017. You may view the EASA AD on the internet at <a href="https://www.regulations.gov">https://www.regulations.gov</a> in the AD Docket.

## (j) Subject

Joint Aircraft Service Component (JASC) Code: 6400, Tail Rotor System.

Issued on February 17, 2021.

## Lance T. Gant.

Director, Compliance & Airworthiness Division, Aircraft Certification Service. [FR Doc. 2021–03991 Filed 3–5–21; 8:45 am]

BILLING CODE 4910-13-P

#### DEPARTMENT OF TRANSPORTATION

## **Federal Aviation Administration**

#### 14 CFR Part 39

[Docket No. FAA-2021-0131; Project Identifier MCAI-2020-01628-T]

RIN 2120-AA64

# Airworthiness Directives; Airbus SAS Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking

(NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all Airbus SAS Model A330-200, -300, -800, and -900 series airplanes; and Model A340-200, -300, -500, and -600 series airplanes. This proposed AD was prompted by reports that certain oxygen supply solenoid valves are a potential source of increased flow resistance within the flightcrew oxygen system. This proposed AD would require a special detailed inspection (flow test) of certain solenoid valves, and replacement if necessary, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by April 22, 2021. **ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to https://www.regulations.gov. Follow the instructions for submitting comments.
  - Fax: 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M– 30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- Hand Delivery: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For material that will be incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@ easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at https://ad.easa.europa.eu. You may view this IBR material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For

information on the availability of this material at the FAA, call 206–231–3195. It is also available in the AD docket on the internet at https://www.regulations.gov by searching for and locating Docket No. FAA–2021–0131.

# Examining the AD Docket

You may examine the AD docket on the internet at https://www.regulations.gov by searching for and locating Docket No. FAA-2021-0131; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

### FOR FURTHER INFORMATION CONTACT:

Vladimir Ulyanov, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3229; email vladimir.ulyanov@faa.gov.

#### SUPPLEMENTARY INFORMATION:

## **Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under ADDRESSES. Include "Docket No. FAA-2021-0131; Project Identifier MCAI-2020-01628-T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to https://www.regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this proposed AD.

# **Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as

private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Vladimir Ulyanov, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3229; email vladimir.ulyanov@ faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

#### Discussion

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2020-0273, dated December 9, 2020 (EASA AD 2020-0273) (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for all Airbus SAS Model A330-201, A330-202, A330-203, A330-223, A330-243, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342, A330-343, A330-743L, A330-841, A330-941, A340-211, A340-212, A340-213, A340-311, A340-312, A340-313, A340-541, A340-542, A340-642, and A340-643 airplanes. Model A330-743L, A340-542, and A340-643 airplanes are not certificated by the FAA and are not included on the U.S. type certificate data sheet; this proposed AD therefore does not include those airplanes in the applicability.

This proposed AD was prompted by reports that oxygen supply solenoid valves having certain part numbers and a certain year of manufacture, are a potential source of increased flow resistance within the flightcrew oxygen system. The FAA is proposing this AD to address increased flow resistance within the flightcrew oxygen system, which could lead to a reduced flow of oxygen supply to the flightcrew oxygen masks, and in combination with inflight depressurization, smoke in the flight deck, or a smoke evacuation procedure, could lead to flightcrew hypoxia and loss of useful consciousness, resulting in loss of control of the airplane. See the MCAI for additional background information.

# Related Service Information Under 1 CFR Part 51

EASA AD 2020–0273 describes procedures for doing a special detailed

inspection (flow test) of certain solenoid valves by using the flightcrew oxygen masks and replacing any solenoid valve that fails the flow test with a serviceable part. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

# FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI referenced above. The FAA is proposing this AD because the FAA evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

## **Proposed AD Requirements**

This proposed AD would require accomplishing the actions specified in EASA AD 2020–0273 described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD.

# **Explanation of Required Compliance Information**

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA initially worked with Airbus and EASA to develop a process to use certain EASA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has since coordinated with other manufacturers and civil aviation authorities (CAAs) to use this process. As a result, EASA AD 2020-0273 will be incorporated by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2020-0273 in its entirety, through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in the EASA AD does not mean that operators need comply only with that section. For example, where the AD requirement refers to "all required actions and compliance times,' compliance with this AD requirement is not limited to the section titled "Required Action(s) and Compliance Time(s)" in the EASA AD. Service

information specified in EASA AD 2020–0273 that is required for compliance with EASA AD 2020–0273 will be available on the internet at https://www.regulations.gov by

searching for and locating Docket No. FAA–2021–0131 after the FAA final rule is published.

# **Costs of Compliance**

The FAA estimates that this proposed AD affects 112 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
3 work-hours × \$85 per hour = \$255	\$0	\$255	\$28,560

The FAA estimates the following costs to do any necessary replacement that would be required based on the

results of any proposed actions. The FAA has no way of determining the

number of aircraft that might need replacement:

### ESTIMATED COSTS OF ON-CONDITION ACTION

Labor cost	Parts cost	Cost per product
1 work-hour × \$85 per hour = \$85	Up to \$5,496	Up to \$5,581.

According to the manufacturer, some or all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected operators. The FAA does not control warranty coverage for affected operators. As a result, the FAA has included all known costs in the cost estimate.

## **Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

# **Regulatory Findings**

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

# The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

# PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

## § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**Airbus SAS:** Docket No. FAA–2021–0131; Project Identifier MCAI–2020–01628–T.

## (a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) action by April 22, 2021.

## (b) Affected ADs

None.

# (c) Applicability

This AD applies to all Airbus SAS airplanes, certificated in any category, identified in paragraphs (c)(1) through (8) of this AD.

- (1) Model A330–201, –202, –203, –223, and –243 airplanes.
- (2) Model A330–301, –302, –303, –321,
- –322, –323, –341, –342, and –343 airplanes.
- (3) Model A330-841 airplanes.
- (4) Model A330–941 airplanes.
- (5) Model A340–211, –212, and –213 airplanes.
- (6) Model A340–311, –312, and –313 airplanes.
  - (7) Model A340–541 airplanes.
  - (8) Model A340-642 airplanes.

## (d) Subject

Air Transport Association (ATA) of America Code 35, Oxygen.

# (e) Reason

This AD was prompted by reports that certain oxygen supply solenoid valves are a potential source of increased flow resistance within the flightcrew oxygen system. The FAA is issuing this AD to address increased flow resistance within the flightcrew oxygen system, which could lead to a reduced flow of oxygen supply to the flightcrew oxygen masks, and in combination with in-flight depressurization, smoke in the flight deck, or a smoke evacuation procedure, could lead to flightcrew hypoxia and loss of useful consciousness, resulting in loss of control of the airplane.

## (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

## (g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2020–0273, dated December 9, 2020 (EASA AD 2020–0273).

#### (h) Exceptions to EASA AD 2020-0273

- (1) Where EASA AD 2020–0273 refers to its effective date, this AD requires using the effective date of this AD.
- (2) The "Remarks" section of EASA AD 2020–0273 does not apply to this AD.

### (i) No Reporting Requirement

Although the service information referenced in EASA AD 2020–0273 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

# (j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Large Aircraft Section, International Validation Branch. FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): For any service information referenced in EASA AD 2020-0273 that contains RC procedures and tests: Except as required by paragraph (j)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

# (k) Related Information

(1) For information about EASA AD 2020–0273, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@ easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at https://ad.easa.europa.eu. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200

South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket on the internet at https://www.regulations.gov by searching for and locating Docket No. FAA–2021–0131.

(2) For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3229; email vladimir.ulyanov@faa.gov.

Issued on February 26, 2021.

#### Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–04442 Filed 3–5–21; 8:45 am]

BILLING CODE 4910-13-P

# **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

### 14 CFR Part 71

[Docket No. FAA-2021-0044; Airspace Docket No. 19-AWP-25]

RIN 2120-AA66

# Proposed Amendment of Class D and Class E Airspace; Bakersfield, CA

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking

(NPRM).

**SUMMARY:** This action proposes to modify the Class D airspace, at Meadows Field Airport. This action also proposes to modify the Class E airspace designated as a surface area and the Class E airspace extending upward from 700 feet above the surface. Additionally, this action proposes several administrative corrections to the Class D, Class E2, and Class E5 text headers. Lastly, this action proposes to update the term "Airport/Facility Directory" in the last sentence of the Class D's airspace description to "Chart Supplement." This action would ensure the safety and management of instrument flight rules (IFR) operations at the airport.

**DATES:** Comments must be received on or before April 22, 2021.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue SE, West Building Ground Floor, Room W12–140, Washington, DC 20590; telephone: 1–800–647–5527, or (202) 366–9826. You must identify FAA Docket No. FAA–2021–0044; Airspace Docket No. 19–

AWP-25, at the beginning of your comments. You may also submit comments through the internet at https://www.regulations.gov.

FAA Order 7400.11E, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at https://www.faa.gov/air traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11E at NARA, email fedreg.legal@nara.gov or go to https:// www.archives.gov/federal-register/cfr/ ibr-locations.html.

## FOR FURTHER INFORMATION CONTACT:

Matthew Van Der Wal, Federal Aviation Administration, Western Service Center, Operations Support Group, 2200 S. 216th Street, Des Moines, WA 98198; telephone (206) 231–3695.

## SUPPLEMENTARY INFORMATION:

# **Authority for This Rulemaking**

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority, as it would amend the Class D and Class E airspace at Meadows Field Airport, Bakersfield, CA, to support IFR operations at the airport.

## **Comments Invited**

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both