

Specialty occupation means an occupation which requires theoretical and practical application of a body of highly specialized knowledge in fields of human endeavor including, but not limited to, architecture, engineering, mathematics, physical sciences, social sciences, medicine and health, education, business specialties, accounting, law, theology, and the arts, and which requires the attainment of a bachelor's degree or higher in a specific specialty, or its equivalent, as a minimum for entry into the occupation in the United States.

* * * * *

United States employer means a person, firm, corporation, contractor, or other association or organization in the United States which:

(1) Engages a person to work within the United States;

(2) Has an employer-employee relationship with respect to employees under this part; as indicated by the fact that it may hire, pay, fire, supervise, or otherwise control the work of any such employee; and

(3) Has an Internal Revenue Service Tax identification number.

* * * * *

(iii) * * *

(A) *Standards for specialty occupation position.* To qualify as a specialty occupation, the position must meet one of the following criteria:

(1) A baccalaureate or higher degree or its equivalent is normally the minimum requirement for entry into the particular position;

(2) The degree requirement is common to the industry in parallel positions among similar organizations or, in the alternative, an employer may show that its particular position is so complex or unique that it can be performed only by an individual with a degree;

(3) The employer normally requires a degree or its equivalent for the position; or

(4) The nature of the specific duties are so specialized and complex that knowledge required to perform the duties is usually associated with the attainment of a baccalaureate or higher degree.

* * * * *

(9) * * *

(iii) * * *

(A)(1) *H-1B petition in a specialty occupation.* An approved petition classified under section 101(a)(15)(H)(i)(b) of the Act for an alien in a specialty occupation shall be valid for a period of up to three years but may

not exceed the validity period of the labor condition application.

* * * * *

Alejandro N. Mayorkas,

Secretary, U.S. Department of Homeland Security.

[FR Doc. 2021-10489 Filed 5-18-21; 8:45 am]

BILLING CODE 9111-97-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2021-0101; Project Identifier MCAI-2020-01084-T; Amendment 39-21531; AD 2021-09-17]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Bombardier, Inc., Model BD-100-1A10 airplanes. This AD was prompted by a report that the inboard multi-function spoiler (MFS) surfaces failed to deploy, which was caused by missing notches on the piston seal of the MFS power control units (PCUs). This AD requires an inspection to determine if affected MFS PCUs are installed, and replacement of affected MFS PCUs. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective June 23, 2021.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of June 23, 2021.

ADDRESSES: For service information identified in this final rule, contact Bombardier, Inc., 200 Côte-Vertu Road West, Dorval, Québec H4S 2A3, Canada; North America toll-free phone: 1-866-538-1247 or direct-dial phone: 1-514-855-2999; email: ac.yul@aero.bombardier.com; internet: <https://www.bombardier.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0101.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0101; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Siddeeq Bacchus, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7362; fax: 516-794-5531; email: 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued TCCA AD CF-2020-26, dated August 4, 2020 (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for certain Bombardier, Inc., Model BD-100-1A10 airplanes. You may examine the MCAI in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0101.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Bombardier, Inc., Model BD-100-1A10 airplanes. The NPRM published in the **Federal Register** on February 26, 2021 (86 FR 11667). The NPRM was prompted by a report that the inboard MFS surfaces failed to deploy, which was caused by missing notches on the piston seal of the MFS PCUs. The NPRM proposed to require an inspection to determine if affected MFS PCUs are installed, and replacement of affected MFS PCUs. The FAA is issuing this AD to address MFS PCUs with improperly configured piston seals, which could cause degraded proportional lift dumping (PLD) function. This condition could hinder the airplane from carrying out an emergency descent, resulting in structural damage and injury to occupants. See the MCAI for additional background information.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The FAA received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

The FAA reviewed the relevant data and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

Bombardier has issued the following service information. This service information describes procedures for an inspection to determine if affected MFS PCUs are installed, and replacement of affected MFS PCUs. These documents are distinct since they apply to different airplane configurations.

- Bombardier Service Bulletin 100–27–17, Revision 03, dated June 19, 2020.
- Bombardier Service Bulletin 350–27–010, dated June 19, 2020.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 630 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Up to 19 work-hours × \$85 per hour = Up to \$1,615.	Up to \$19,600 (up to 4 MFS PCUs per airplane).	Up to \$21,215 (up to 4 MFS PCUs per airplane).	Up to \$13,365,450 (up to 4 MFS PCUs per airplane).

According to the manufacturer, some or all of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected operators. The FAA does not control warranty coverage for affected operators. As a result, the FAA has included all known costs in the cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021–09–17 Bombardier, Inc.: Amendment 39–21531; Docket No. FAA–2021–0101; Project Identifier MCAI–2020–01084–T.

(a) Effective Date

This airworthiness directive (AD) is effective June 23, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc., Model BD–100–1A10 airplanes, certificated in any category, serial numbers 20003 through 20457 inclusive, and 20501 through 22999 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight controls.

(e) Reason

This AD was prompted by a report that the inboard multi-function spoiler (MFS) surfaces failed to deploy, which was caused by missing notches on the piston seal of the MFS power control units (PCUs). The FAA is issuing this AD to address MFS PCUs with improperly configured piston seals, which could cause degraded proportional lift dumping (PLD) function. This condition could hinder the airplane from carrying out an emergency descent, resulting in structural damage and injury to occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Definition of Affected Part

For the purpose of this AD, an affected MFS PCU is an MFS PCU that has a serial number of 0001 through 1410 inclusive, except for those MFS PCUs having the serial numbers listed in figure 1 to paragraph (g) of this AD and except for those with the suffix “A” at the end of the serial number (*i.e.*, serial number 1025A).

Figure 1 to paragraph (g): Serial numbers that are not affected

66	605	1287	1395
72	671	1334	1396
175	720	1337	1397
200	727	1368	1400
331	728	1369	1401
441	773	1370	1403
448	778	1373	1404
449	812	1376	1405
456	831	1380	1406
470	887	1382	1407
494	991	1385	1408
495	1049	1386	1409
498	1208	1387	-
499	1236	1388	-
561	1284	1394	-

(h) Required Actions

(1) Within 12 months after the effective date of this AD: Do an inspection to determine if affected MFS PCUs are installed on the airplane in accordance with Paragraph 2.B. of Bombardier Service Bulletin 100–27–17, Revision 03, dated June 19, 2020; or Bombardier Service Bulletin 350–27–010, dated June 19, 2020; as applicable. A review of airplane maintenance records is acceptable in lieu of this inspection if the serial number of the MFS PCU can be conclusively determined from that review.

(2) Within 12 months after the effective date of this AD: Replace any affected MFS PCUs with MFS PCUs that are not affected, in accordance with Paragraphs 2.C., 2.D., 2.E., and 2.F., as applicable, of Bombardier Service Bulletin 100–27–17, Revision 03, dated June 19, 2020; or Bombardier Service Bulletin 350–27–010, dated June 19, 2020; as applicable.

(i) Parts Installation Prohibition

As of the effective date of this AD, no person may install an affected MFS PCU, on any airplane.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516–228–7300; fax: 516–794–5531. Before using any approved AMOC, notify your appropriate

principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) TCCA AD CF–2020–26, dated August 4, 2020, for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0101.

(2) For more information about this AD, contact Siddeeq Bacchus, Aerospace

Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7362; fax: 516-794-5531; email: 9-avsn-yaco-cos@faa.gov.

(I) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 100-27-17, Revision 03, dated June 19, 2020.

(ii) Bombardier Service Bulletin 350-27-010, dated June 19, 2020.

(3) For service information identified in this AD, contact Bombardier, Inc., 200 Côte-Vertu Road West, Dorval, Québec H4S 2A3, Canada; North America toll-free phone: 1-866-538-1247 or direct-dial phone: 1-514-855-2999; email: ac.yul@aero.bombardier.com; internet: <https://www.bombardier.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on April 23, 2021.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-10467 Filed 5-18-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-0973; Project Identifier MCAI-2020-01113-T; Amendment 39-21527; AD 2021-09-13]

RIN 2120-AA64

Airworthiness Directives; ATR-GIE Avions de Transport Régional Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directives (AD) 2000-23-04 R1 and AD 2018-20-14, which

applied to certain ATR-GIE Avions de Transport Régional Model ATR42-500 airplanes. AD 2000-23-04 R1 and AD 2018-20-14 required revising the maintenance or inspection program, as applicable, to incorporate new and/or more restrictive maintenance requirements and airworthiness limitations. This AD requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations; as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. This AD was prompted by the FAA's determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective June 23, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of June 23, 2021.

The Director of the Federal Register approved the incorporation by reference of certain other publications listed in this AD as of November 20, 2018 (83 FR 52123, October 16, 2018).

ADDRESSES: For EASA material incorporated by reference (IBR) in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. For ATR-GIE service information identified in this AD, contact ATR-GIE Avions de Transport Régional, 1 Allée Pierre Nadot, 31712 Blagnac Cedex, France; telephone +33 (0) 5 62 21 62 21; fax +33 (0) 5 62 21 67 18; email continued.airworthiness@atr-aircraft.com; <http://www.atr-aircraft.com>. You may view this IBR material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0973.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and

other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Shahram Daneshmandi, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3220; email Shahram.Daneshmandi@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2020-0263, dated December 1, 2020 (EASA AD 2020-0263) (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for all Model ATR 42-400 and ATR 42-500 airplanes. Model ATR 42-400 airplanes are not certificated by the FAA and are not included on the U.S. type certificate data sheet; this AD therefore does not include those airplanes in the applicability. Airplanes with an original airworthiness certificate or original export certificate of airworthiness issued after July 7, 2020 must comply with the airworthiness limitations specified as part of the approved type design and referenced on the type certificate data sheet; this AD therefore does not include those airplanes in the applicability.

The FAA issued a supplemental notice of proposed rulemaking (SNPRM) to amend 14 CFR part 39 to supersede AD 2000-23-04 R1, Amendment 39-12174 (66 FR 19381, April 16, 2001) (AD 2000-23-04 R1) and AD 2018-20-14, Amendment 39-19448 (83 FR 52123, October 16, 2018) (AD 2018-20-14). ADs 2000-23-04 R1 and 2018-20-14 applied to certain ATR-GIE Avions de Transport Régional Model ATR42-500 airplanes. The SNPRM published in the **Federal Register** on February 24, 2021 (86 FR 11169). The FAA preceded the SNPRM with a notice of proposed rulemaking (NPRM) that published in the **Federal Register** on October 29, 2020 (85 FR 68503). The NPRM was prompted by the FAA's determination that new or more restrictive airworthiness limitations are necessary. The NPRM proposed to require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. The SNPRM proposed to require revising the existing