

Pages	Revision level	Date
2 and 4	Original Issue	Mar. 31, 1982.
1 and 3	Revision 1	May 23, 1988.

(2) British Aerospace Mandatory Service Bulletin No. 7/8, which applies to the affected Models HP.137 Jetstream Mk.1 and Jetstream Series 200 airplanes and incorporates the following effective pages:

Pages	Revision level	Date
2, 5, 6, 7, and 8	Revision 2	Jan. 6, 1983.
1, 3, and 4	Revision 3	May 23, 1988.

(3) Jetstream Alert Service Bulletin 32-A-JA 850127, which applies to the affected Jetstream Series 3101 airplanes and incorporates the following effective pages:

Pages	Revision level	Date
5 through 14	Original Issue	April 17, 1985.
1 through 4	Revision 2	Nov. 11, 1994.

(4) Jetstream Service Bulletin 57-JM 5218, which applies to all of the affected airplanes and incorporates the following effective pages:

Pages	Revision level	Date
11, 12, 17, 18, 19, 21, 22, 23, 24, 27, 28, 29, 30, and 31	Revision 1	Sept. 29, 1987.
20	Revision 3	Jan. 29, 1990.
13 and 14	Revision 4	Oct. 31, 1990.
1 through 10, 15, 16, 25, and 26	Revision 5	July 28, 1997.

(f) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

(i) Your alternative method of compliance provides an equivalent level of safety; and

(ii) The Manager, Small Airplane Directorate, approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

(2) Alternative methods of compliance approved in accordance with

AD 98-13-03, which is superseded by this AD, are approved as alternative methods of compliance with this AD.

Note 2: This AD applies to each airplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (f) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(g) *Where can I get information about any already-approved alternative methods of compliance?* Contact Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; facsimile: (816) 329-4090.

(h) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal

Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(i) *How do I get copies of the documents referenced in this AD?* You may obtain copies of the documents referenced in this AD from British Aerospace Regional Aircraft, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland; telephone: (01292) 479888; facsimile: (01292) 671715. You may examine these documents at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106.

(j) *Does this AD action affect any existing AD actions?* This amendment supersedes AD 98-13-03, Amendment 39-10591.

Issued in Kansas City, Missouri, on November 13, 2001.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01-28809 Filed 11-16-01; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-322-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A300 B4-600 and A300 B4-600R Series Airplanes, and Model A300 F4-605R Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Supplemental notice of proposed rulemaking; reopening of comment period.

SUMMARY: This document revises an earlier proposed airworthiness directive (AD), applicable to all Airbus Model A300 B4-600, A300 B4-600R, and A300 F4-600R series airplanes, that would have superseded an existing AD. The existing AD requires repetitive inspections to detect cracks of certain attachment holes, installation of new fasteners, and follow-on inspections or repair if necessary. The proposed AD would have reduced the inspection threshold and repetitive intervals and expanded the area to be inspected. This supplemental notice of proposed rulemaking (NPRM) would further expand the area to be inspected, and would require a modification of the angle fittings of frame FR47. This

supplemental NPRM would also remove certain airplanes from the applicability. The actions specified by this supplemental NPRM are intended to prevent fatigue cracking of the forward fitting of fuselage frame FR47, which could result in reduced structural integrity of the frame.

DATES: Comments must be received by December 14, 2001.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-322-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: *9-anm-nprmcomment@faa.gov*. Comments sent via fax or the Internet must contain "Docket No. 99-NM-322-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to

change the compliance time and a request to change the service bulletin reference as two separate issues.

- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket 99-NM-322-AD." The postcard will be date-stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket 99-NM-322-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to add an airworthiness directive (AD), applicable to all Airbus Model A300 B4-600, A300 B4-600R, and A300 F4-600R series airplanes, was published as a notice of proposed rulemaking (NPRM) in the **Federal Register** on July 20, 2000 (65 FR 44991). That original NPRM proposed to supersede AD 97-16-06, amendment 39-10097 (62 FR 41257, August 1, 1997), which is applicable to all Airbus Model A300 B4-600, A300 B4-600R, and A300 F4-600R series airplanes. A correction to AD 97-16-06 was published in the **Federal Register** on August 25, 1997 (62 FR 44888). The original NPRM proposed to continue to require repetitive inspections to detect cracks of certain attachment holes, installation of new fasteners, and follow-on inspections or repair if necessary. The original NPRM would have reduced the inspection threshold and repetitive intervals and expanded the area to be inspected. The original NPRM was prompted by reports of cracking in the internal angle fittings of the wing center box at fuselage frame

FR47 on airplanes that had not reached the inspection threshold required by AD 97-16-06, and cracking around certain fastener holes that were not required to be inspected by AD 97-16-06. Such fatigue cracking, if not corrected, could result in reduced structural integrity of the frame.

Actions Since Issuance of Original NPRM

Since the issuance of the original NPRM, the FAA has been advised by the Direction Generale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, of recent inspection results that warrant a revision of the existing inspection program for certain areas of fuselage frame FR47. Specifically, an investigation of new crack findings indicates the need for an inspection of additional holes (holes A, B, C, D, E, F, G, P, Q, and S) of the baseplate/horizontal section of the angle fittings of the wingbox. The investigation further revealed fatigue sensitivity of additional holes (holes Y, U, V, W, and X) of the angle web fitting on airplanes on which a particular modification had not been correctly embodied in production.

Explanation of Relevant Service Information

Airbus has issued Service Bulletin A300-57-6049, Revision 4, dated July 27, 2000, which describes procedures for repetitive rotating probe inspections to detect cracking of holes in the left and right internal angles of the wing center box. Corrective actions include reaming, drilling, drill-stopping holes, chamfering, follow-on inspections, and installing new or oversize fasteners. The original version of this service bulletin was cited as the appropriate source of service information for the inspections required by AD 97-16-06. Revision 3 was described in the original NPRM and cited as the appropriate source of service information for the proposed inspections. Revision 4 includes minor procedural changes not included in Revision 3, and includes procedures for the inspection of additional holes (holes Y, U, V, W, and X) on certain airplanes.

Airbus has also issued Service Bulletin A300-57-6086, dated June 6, 2000, which describes procedures for repetitive rotating probe inspections to detect cracking of ten holes (holes A, B, C, D, E, F, G, P, Q, and S) in the horizontal flange of the internal corner angle fitting at frame FR47. For crack repair, this service bulletin provides corrective actions that include inspecting hole T if any cracking is found around hole G, reaming the holes, and installing oversize fasteners.

Airbus has also issued Service Bulletin A300–57–6050, Revision 02, dated February 10, 2000, which describes procedures for a modification of the angle fittings at frame FR47, which involves performing a rotating probe inspection to detect cracking of fasteners holes most sensitive to fatigue, cold expanding the holes, and installing new medium interference fitting bolts. The modification is intended to improve the fatigue life of the subject area.

Accomplishment of the actions specified in the service bulletins is intended to adequately address the identified unsafe condition. The DGAC classified these service bulletins as mandatory and issued French airworthiness directive 2000–533–328(B), dated December 27, 2000, to ensure the continued airworthiness of these airplanes in France.

Comments

Due consideration has been given to comments received in response to the original NPRM.

Request To Remove Certain Airplanes From Applicability

One commenter requests that Model A300 F4–622R airplanes be removed from the applicability of the original NPRM to correspond to the revised French airworthiness directive, which was issued specifically to exclude those airplanes.

The FAA concurs. Model A300 F4–622R airplanes are not subject to the identified unsafe condition. The applicability of this supplemental NPRM has been revised to remove those airplanes.

Request To Revise Compliance Times

Several commenters request that the grace periods for inspection of holes H, I, K, L, M, and N, as specified in the original NPRM, be revised to correspond to the grace periods specified in Airbus Service Bulletin A300–57–6049. The commenters state that the grace periods provided in the service bulletin are intended to allow operators to properly plan the required work, and will ensure safety via a longer grace period for newer airplanes and a shorter grace period for older airplanes. One commenter, an operator, states that its newest airplanes would be subject to out-of-sequence inspections and

potential modifications, at significant cost to the operator. The operator contends that the grace periods provided in the service bulletin would provide an “equivalent level of safety.”

The FAA concurs, for the reasons provided by the commenters. Paragraphs (a) and (b) of this supplemental NPRM refer to the compliance thresholds and repetitive intervals specified in paragraph 1.A.(2), Planning Information, of the service bulletin.

Request To Remove Restriction on Flight With Cracks

One commenter requests that the original NPRM be revised to remove the exception to Service Bulletin A300–57–6049 regarding flight with cracks. The original NPRM had included a provision that would prohibit further flight with cracking detected in the attachment holes. The commenter states that the service bulletin does not allow flight with a free crack but rather recommends corrective action to eliminate the crack immediately or repair it temporarily until it can be eliminated.

The FAA partially concurs. In the section titled “Differences Between the Proposed Rule and Relevant Service Information,” the original NPRM incorrectly interpreted the service bulletin as allowing flight with cracks, in contrast to FAA policy. The service bulletin does provide for temporary repair with follow-up repetitive inspections, but specifies that, for certain conditions, operators must contact the manufacturer for further instructions prior to further flight. The original NPRM specified that corrective actions be performed in accordance with the service bulletin. To clarify the requirements for repair, this supplemental NPRM specifies that repair of cracking be done by “applicable corrective actions” in accordance with the service bulletin.

Conclusion

Since these changes expand the scope of the original NPRM, the FAA has determined that it is necessary to reopen the comment period to provide additional opportunity for public comment.

Explanation of Proposed Requirements of This Supplemental NPRM

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, this supplemental NPRM would require accomplishment of the actions specified in the service bulletins described in this supplemental NPRM, except as discussed below.

Differences Between This Supplemental NPRM and the Service Bulletins

Operators should note that, although the service bulletins specify that the manufacturer may be contacted for disposition of certain repair conditions, this supplemental NPRM would require the repair of those conditions to be accomplished in accordance with a method approved by either the FAA or the DGAC (or its delegated agent). In light of the type of repair that would be required to address the identified unsafe condition, and in consonance with existing bilateral airworthiness agreements, the FAA has determined that, for this supplemental NPRM, a repair approved by either the FAA or the DGAC would be acceptable for compliance with this supplemental NPRM.

Furthermore, Airbus Service Bulletins A300–57–6049 and A300–57–6086 specify that operators need not count touch-and-go landings in determining the total number of landings between consecutive inspections, when those landings represent less than five percent of the landings between inspection intervals. However, fatigue cracking, which was found on the forward fitting of fuselage frame FR47 at the level of the last fastener of the external angle fitting, is aggravated by landing. Therefore, the FAA has determined that all touch-and-go landings must be counted in determining the total number of flight cycles between two consecutive inspections.

Cost Impact

The FAA estimates that 74 airplanes of U.S. registry would be affected by this proposed AD. The average labor rate is \$60 per work hour. The FAA provides the following cost estimates for the actions proposed by this supplemental NPRM:

Action	Work hours	Parts cost	Per-airplane cost
Inspection per paragraph (a)	7 or 13 (depending on configuration).	\$0	\$420 or \$780, per inspection.
Inspection per paragraph (b)	30	6,637 or 19,091, depending on kit required.	8,437 or 20,891, per inspection.
Modification per paragraph (c)	65 to 365	3,370	7,270 to 25,270.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39-10097 (62 FR

41257, August 1, 1997), and by adding a new airworthiness directive (AD), to read as follows:

Airbus Industrie: Docket 99-NM-322-AD. Supersedes AD 97-16-06, Amendment 39-10097.

Applicability: All Model A300 B4-600 and A300 B4-600R series airplanes and all Model A300 F4-605R airplanes, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (f)(1) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent fatigue cracking of the forward fitting of fuselage frame FR47, which could result in reduced structural integrity of the frame, accomplish the following:

Inspections

(a) Perform a rotating probe inspection to detect cracking of the applicable attachment holes on the left and right internal angles of the wing center box, in accordance with Airbus Service Bulletin A300-57-6049, Revision 4, dated July 27, 2000. Do the inspection at the applicable time specified by paragraph 1.A.(2), Planning Information, of the service bulletin, except as required by paragraph (e) of this AD. Repeat the inspection thereafter at intervals not to exceed the applicable interval specified in the service bulletin, except that all touch-and-go landings must be counted in determining the total number of flight cycles between consecutive inspections.

(1) If no cracking is found: Prior to further flight, install new fasteners in accordance with the service bulletin.

(2) If any cracking is found: Prior to further flight, perform applicable corrective actions (including reaming, drilling, drill-stopping holes, chamfering, follow-on inspections, and installing new or oversize fasteners) in accordance with the service bulletin, except as required by paragraph (d) of this AD.

(b) Perform a rotating probe inspection to detect cracking of the applicable attachment holes in the horizontal flange of the internal corner angle fitting of frame FR47, in accordance with Airbus Service Bulletin A300-57-6086, dated June 6, 2000. Do the inspection at the applicable time specified by the service bulletin, except as required by paragraph (e) of this AD. Repeat the inspection thereafter at intervals not to exceed the applicable interval specified in the service bulletin, except that all touch-and-go landings must be counted in determining the total number of flight cycles between consecutive inspections.

(1) If no cracking is detected: Prior to further flight, install new fasteners in accordance with the service bulletin.

(2) If any cracking is detected: Prior to further flight, perform applicable corrective actions (including inspecting hole T, reaming the holes, and installing oversize fasteners) in accordance with the service bulletin, except as required by paragraph (d) of this AD.

Modification

(c) Modify the left and right internal angle fittings of the wing center box. The modification includes performing a rotating probe inspection to detect cracking, repairing cracks, cold expanding holes, and installing medium interference fitting bolts. Perform the modification in accordance with and at the applicable time specified by paragraph 1.B.(4), Accomplishment Timescale, of Airbus Service Bulletin A300-57-6050, Revision 02, dated February 10, 2000; except as required by paragraphs (d) and (e) of this AD.

Note 2: Modification prior to the effective date of this AD in accordance with Airbus Service Bulletin A300-57-6050, dated September 9, 1994, or Revision 01, dated May 31, 1999, is acceptable for compliance with the requirements of paragraph (c) of this AD.

Exception to Specifications in Service Bulletins

(d) If any crack is detected during any inspection required by paragraph (a), (b), or (c) of this AD, and the applicable service bulletin specifies to contact the manufacturer for disposition of certain corrective actions: Prior to further flight, repair in accordance with a method approved by either the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, or the Direction Generale de l'Aviation Civile (DGAC) (or its delegated agent).

(e) Where the service bulletins specified in paragraphs (a), (b), and (c) of this AD specify a grace period relative to receipt of the service bulletin, this AD requires compliance within the grace period following the effective date of this AD, if the threshold has been exceeded.

Alternative Methods of Compliance

(f)(1) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

(2) Alternative methods of compliance, approved previously in accordance with AD 97-16-06, amendment 39-10097, are not considered to be approved as alternative methods of compliance with any requirements of this AD.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(g) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 4: The subject of this AD is addressed in French airworthiness directive 2000-533-328(B), dated December 27, 2000.

Issued in Renton, Washington, on November 9, 2001.

Vi L. Lipski,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. 01-28794 Filed 11-16-01; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 2001-NM-253-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A300 B2 and A300 B4; A300 B4-600, B4-600R, and F4-600R (Collectively Called A300-600); and Model A310 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Airbus Model A300 B2 and A300 B4; A300 B4-600, B4-600R, and F4-600R (collectively called A300-600); and A310 series airplanes. This proposal would require repetitive overhaul, including associated modifications, of the ram air turbine (RAT). This action is necessary to prevent failure of the RAT to deploy or operate properly in the event of an emergency, which could result in reduced hydraulic pressure or electrical power on the airplane. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by December 19, 2001.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-253-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal

holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2001-NM-253-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:**Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket 2001-NM-253-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket 2001-NM-253-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, notified the FAA that an unsafe condition may exist on certain Airbus Model A300 B2 and A300 B4; A300 B4-600, B4-600R, and F4-600R (collectively called A300-600); and A310 series airplanes. The DGAC advises that the life limit of the ram air turbine (RAT) has been recently justified to 60,000 flight hours. Although the life limit of the RAT itself has been extended, the life limit of the grease must also be considered because of the possible development of corrosion. Therefore, periodic overhaul of the RAT has been recommended to ensure its proper functioning. In addition, the DGAC has identified certain modifications to the RAT or its associated systems that need to be incorporated to ensure a properly functioning RAT system in the event of an emergency. Failure of the RAT to deploy or operate properly, if not corrected, could result in reduced hydraulic pressure or electrical power on the airplane in the event of an emergency.

Explanation of Relevant Service Information

Airbus has issued Service Bulletin A300-29-0118, dated April 20, 2001 (for Model A300 B2 and A300 B4 series airplanes); A300-29-6049, Revision 02, dated September 10, 2001 (for Model A300-600 series airplanes); and A310-29-2087, dated April 20, 2001 (for Model A310 series airplanes). These service bulletins describe procedures for repetitive overhaul of the RAT.

The service bulletins refer to Hamilton Sundstrand Service Bulletins 730816-29-12, ERPS26T-29-4, and 732365-29-4 as additional sources of service information for the overhaul actions.