

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021–08–17 Airbus Helicopters:

Amendment 39–21511; Docket No. FAA–2021–0300; Project Identifier MCAI–2020–01077–R.

(a) Effective Date

This airworthiness directive (AD) is effective May 12, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Helicopters Model AS332L2 helicopters with main gearbox (MGB) part number (P/N) 332A323001.XX with a main reduction gear module (module) P/N 332A323011.XX that has free wheel shaft P/N 332A322191.20 installed, where “XX” stands for any two digit dash number, certificated in any category.

Note 1 to paragraph (c): Free wheel shaft P/N 332A322191.20 is also referred to as modification 07–53016.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 6320, Main Rotor Gearbox.

(e) Unsafe Condition

This AD defines the unsafe condition as wear on the ramps and roller cages of the MGB free wheel shaft. This condition could result in reduced one engine inoperative (OEI) power from by the right engine following an in-flight shut-down of the left engine, resulting in reduced control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless accomplished previously.

(g) Required Actions

(1) Within 50 hours time-in-service (TIS) after the effective date of this AD, install a placard on the instrument panel prohibiting use of the ENG1 “TRAINING IDLE” switch in accordance with Figure 3 of Airbus

Helicopters Alert Service Bulletin AS332–01.00.95, Revision 1, dated July 29, 2020.

(2) Replace the MGB with an airworthy MGB at the following compliance time:

(i) If the free wheel shaft has accumulated less than 950 total hours TIS, before the free wheel shaft accumulates 1,000 total hours TIS; or

(ii) If the free wheel shaft has accumulated 950 or more total hours TIS, within 50 hours TIS after the effective date of this AD.

(3) As of the effective date of this AD, do not install a right free wheel shaft P/N 332A322191.20 on any helicopter unless the free wheel shaft has accumulated less than 1,000 total hours TIS.

(4) If you replace the MGB with a MGB that does not have free wheel shaft P/N 332A322191.20 installed, you may remove the placard required by paragraph (g)(1) of this AD.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Rao Edupuganti, Aviation Safety Engineer, Dynamic Systems Section, Technical Innovation Policy Branch, Policy & Innovation Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817–222–5110; email rao.edupuganti@faa.gov.

(2) The subject of this AD is addressed in European Union Aviation Safety Agency (EASA) AD 2020–0141R1, dated July 30, 2020. You may view the EASA AD on the internet at <https://www.regulations.gov> by searching for and locating it in Docket No. FAA–2021–0300.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Airbus Helicopters Alert Service Bulletin AS332–01.00.95, Revision 1, dated July 29, 2020.

(ii) [Reserved]

(3) For service information identified in this AD, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; telephone 972–641–0000 or 800–232–0323; fax 972–641–3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817–222–5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on April 8, 2021.

Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–08568 Filed 4–26–21; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2021–0313; Project Identifier MCAI–2021–00348–T; Amendment 39–21516; AD 2021–09–03]

RIN 2120–AA64

Airworthiness Directives; Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; correction.

SUMMARY: The FAA is correcting an airworthiness directive (AD) that was published in the **Federal Register**. That AD applies to certain Airbus Canada Limited Partnership Model BD–500–1A10 and BD–500–1A11 airplanes. As published, two references to a Transport Canada Civil Aviation (TCCA) AD number specified in the regulatory text are incorrect. This document corrects those errors. In all other respects, the original document remains the same.

DATES: This correction is effective May 4, 2021. The effective date of AD 2021–09–03 remains May 4, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of May 4, 2021 (86 FR 20266, April 19, 2021).

The date by which FAA must receive comments on this AD remains June 3, 2021.

ADDRESSES: For material incorporated by reference (IBR) in this AD, contact TCCA, Transport Canada National

Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada; telephone 888-663-3639; email AD-CN@tc.gc.ca; internet <https://tc.canada.ca/en/aviation>. You may view this IBR material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0313.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0313; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Deep Gaurav, Aerospace Engineer, Airframe and Propulsion Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION: AD 2021-09-03, Amendment 39-21516 (86 FR 20266, April 19, 2021) (AD 2021-09-03), requires repetitive replacements of the emergency locator transmitter (ELT) antenna and repetitive inspections for damage of the exterior fuselage skin around the ELT antenna attachment area, as specified in TCCA AD CF-2021-10, dated March 18, 2021 (TCCA AD CF-2021-10). That AD applies to certain Airbus Canada Limited Partnership Model BD-500-1A10 and BD-500-1A11 airplanes.

Need for the Correction

As published, the TCCA AD number specified in paragraphs (h)(1) and (2) of the regulatory text of AD 2021-09-03 is incorrectly identified as "TCCA AD CF-2020-10," where the correct identification is "TCCA AD CF-2021-10."

Related Service Information Under 1 CFR Part 51

TCCA AD CF-2021-10 describes procedures for repetitive replacements of the ELT antenna with a new ELT antenna and repetitive inspections of the exterior fuselage skin around the ELT antenna attachment area for damage (including cracking). This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Correction of Publication

This document corrects multiple errors and correctly adds the AD as an amendment to 14 CFR 39.13. Although no other part of the preamble or regulatory information has been corrected, the FAA is publishing the entire rule in the **Federal Register**.

The effective date of this AD remains May 4, 2021.

Since this action only corrects references to a TCCA AD number, it has no adverse economic impact and imposes no additional burden on any person. Therefore, the FAA has determined that notice and public procedures are unnecessary.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Correction

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Corrected]

- 2. The FAA corrects § 39.13 by revising the following airworthiness directive to read:

2021-09-03 Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.): Amendment 39-21516; Docket No. FAA-2021-0313; Project Identifier MCAI-2021-00348-T.

(a) Effective Date

This airworthiness directive (AD) becomes effective May 4, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Canada Limited Partnership (type certificate previously held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) Model BD-500-1A10 and BD-500-1A11 airplanes, certificated in any category, as identified in Transport Canada Civil Aviation (TCCA) AD CF-2021-10, dated March 18, 2021 (TCCA AD CF-2021-10).

(d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/furnishings.

(e) Reason

This AD was prompted by reports of the failure of emergency locator transmitter (ELT) antennas. The FAA is issuing this AD to address ELT antenna failure, which can lead to the loss of the ELT antenna and the development of fuselage cracks that can result in an inability to maintain cabin pressure.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, TCCA AD CF-2021-10.

(h) Exception to TCCA AD CF-2021-10

(1) Where TCCA AD CF-2021-10 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where TCCA AD CF-2021-10 refers to hours air time, this AD requires using flight hours.

(3) If any damage is found as a result of the inspections required by this AD, repairs must be done before further flight.

(i) Special Flight Permit

Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the airplane to a location where the airplane can be modified (if the operator elects to do so), provided no passengers are onboard.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your

appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or TCCA; or Airbus Canada Limited Partnership's TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(k) Related Information

For more information about this AD, contact Deep Gaurav, Aerospace Engineer, Airframe and Propulsion Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on May 4, 2021 (86 FR 20266, April 19, 2021).

(i) Transport Canada Civil Aviation (TCCA) AD CF-2021-10, dated March 18, 2021.

(ii) [Reserved]

(4) For TCCA AD CF-2021-10, contact TCCA, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada; telephone 888-663-3639; email AD-CN@tc.gc.ca; internet <https://tc.canada.ca/en/aviation>.

(5) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0313.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on April 22, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-08760 Filed 4-23-21; 11:15 am]

BILLING CODE 4910-13-P

DEPARTMENT OF JUSTICE

Drug Enforcement Administration

21 CFR Part 1308

[Docket No. DEA-476]

Schedules of Controlled Substances: Placement of 10 Specific Fentanyl-Related Substances in Schedule I

AGENCY: Drug Enforcement Administration, Department of Justice.
ACTION: Final rule.

SUMMARY: In this rule, the Drug Enforcement Administration places 10 specified fentanyl-related substances permanently in schedule I of the Controlled Substances Act. These 10 specific substances all fall within the definition of fentanyl-related substances set forth in a February 6, 2018, temporary scheduling order. Through the Temporary Reauthorization and Study of the Emergency Scheduling of Fentanyl Analogues Act, which became law on February 6, 2020, Congress extended the temporary control of fentanyl-related substances until May 6, 2021. The regulatory controls and administrative, civil, and criminal sanctions applicable to schedule I controlled substances on persons who handle (manufacture, distribute, reverse distribute, import, export, engage in research, conduct instructional activities or chemical analysis, or possess), or propose to handle any of these 10 specified fentanyl-related substances will continue to be applicable permanently as a result of this action.

DATES: Effective date: April 27, 2021.

FOR FURTHER INFORMATION CONTACT: Terrence L. Boos, Drug and Chemical Evaluation Section, Diversion Control Division, Drug Enforcement Administration; Mailing Address: 8701 Morrisette Drive, Springfield, Virginia 22152; Telephone: (571) 362-3249.

SUPPLEMENTARY INFORMATION: This final rule imposes permanent controls on 10 specified fentanyl-related substances, which will continue to be listed in schedule I of the Controlled Substances Act (CSA). These 10 fentanyl-related substances are:

- *N*-(1-(2-fluorophenethyl)piperidin-4-yl)-*N*-(2-fluorophenyl)propionamide (2'-fluoro *ortho*-fluorofentanyl; 2'-fluoro 2-fluorofentanyl);
- *N*-(1-(4-methylphenethyl)piperidin-4-yl)-*N*-phenylacetamide (4'-methyl acetyl fentanyl);
- *N*-(1-phenethylpiperidin-4-yl)-*N*,3-diphenylpropanamide (β'-phenyl fentanyl; *beta*'-Phenyl fentanyl; 3-phenylpropanoyl fentanyl);

- *N*-phenyl-*N*-(1-(2-phenylpropyl)piperidin-4-yl)propionamide (β-methyl fentanyl);
- *N*-(2-fluorophenyl)-*N*-(1-phenethylpiperidin-4-yl)butyramide (*ortho*-fluorobutyryl fentanyl; 2-fluorobutyryl fentanyl);
- *N*-(2-methylphenyl)-*N*-(1-phenethylpiperidin-4-yl)acetamide (*ortho*-methyl acetyl fentanyl; 2-methyl acetyl fentanyl);
- 2-methoxy-*N*-(2-methylphenyl)-*N*-(1-phenethylpiperidin-4-yl)acetamide (*ortho*-methyl methoxyacetyl fentanyl; 2-methyl methoxyacetyl fentanyl);
- *N*-(4-methylphenyl)-*N*-(1-phenethylpiperidin-4-yl)propionamide (*para*-methyl fentanyl; 4-methyl fentanyl);
- *N*-(1-phenethylpiperidin-4-yl)-*N*-phenylbenzamide (phenyl fentanyl; benzoyl fentanyl); and
- *N*-(1-phenethylpiperidin-4-yl)-*N*-phenylthiophene-2-carboxamide (thiofuranyl fentanyl; 2-thiofuranyl fentanyl; thiophene fentanyl).

The schedule I listing of these 10 fentanyl-related substances includes their isomers, esters, ethers, salts, and salts of isomers, esters, and ethers whenever the existence of such isomers, esters, ethers, and salts is possible.

Legal Authority

The CSA provides that proceedings for the issuance, amendment, or repeal of the scheduling of any drug or other substance may be initiated by the Attorney General (delegated to the Administrator of the Drug Enforcement Administration (DEA) pursuant to 28 CFR 0.100) on his own motion. 21 U.S.C. 811(a). This action is supported by, *inter alia*, a recommendation from the Assistant Secretary for Health of HHS (Assistant Secretary) and an evaluation of all relevant data by DEA. This action continues the imposition of the regulatory controls and administrative, civil, and criminal sanctions of schedule I controlled substances on any person who handles (manufactures, distributes, imports, exports, engages in research, or conducts instructional activities or chemical analysis with, or possesses) or proposes to handle 2'-fluoro *ortho*-fluorofentanyl, 4'-methyl acetyl fentanyl, β'-phenyl fentanyl, β-methyl fentanyl, *ortho*-fluorobutyryl fentanyl, *ortho*-methyl acetyl fentanyl, *ortho*-methyl methoxyacetyl fentanyl, *para*-methyl fentanyl, phenyl fentanyl, and thiofuranyl fentanyl.

Background

On February 6, 2018, pursuant to 21 U.S.C. 811(h)(1), DEA published a temporary scheduling order in the