

Proposed Rules

Federal Register

Vol. 88, No. 176

Wednesday, September 13, 2023

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2023-1823; Project Identifier MCAI-2023-00314-T]

RIN 2120-AA64

Airworthiness Directives; MHI RJ Aviation ULC (Type Certificate Previously Held by Bombardier, Inc.)

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain MHI RJ Model CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-2C11 (Regional Jet Series 550), CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900), and CL-600-2E25 (Regional Jet Series 1000) airplanes. This proposed AD was prompted by a report of a passenger seat Y-belt (lap belt) re-installed in the wrong orientation, due to an incorrect maintenance manual. This proposed AD would require inspecting certain Y-belts for correct installation and damage and corrective actions if necessary. This proposed AD would also prohibit the use of certain revisions of a maintenance task. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this NPRM by October 30, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of

Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-1823; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For MHI RJ service information identified in this NPRM, contact MHI RJ Aviation Group, Customer Response Center, 3655 Ave. des Grandes-Tourelles, Suite 110, Boisbriand, Québec J7H 0E2 Canada; North America toll-free telephone 833-990-7272 or direct-dial telephone 450-990-7272; fax 514-855-8501; email thd.crj@mhirj.com; website [mhirj.com](https://www.mhirj.com).

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

FOR FURTHER INFORMATION CONTACT: Fatin Saumik, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone (516) 228-7300; email: 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2023-1823; Project Identifier MCAI-2023-00314-T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments

received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Fatin Saumik, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7350; email: Fatin.R.Saumik@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

Transport Canada, which is the aviation authority for Canada, has issued Transport Canada AD CF-2023-10, dated February 17, 2023 (Transport Canada AD CF-2023-10) (also referred to after this as the MCAI), to correct an unsafe condition on certain MHI RJ Aviation ULC (formerly Bombardier, Inc.) Model CL-600-2C10, CL-600-2C11, CL-600-2D15, CL-600-2D24, and CL-600-2E25 airplanes. The MCAI states that following maintenance on a Model CL-600-2C10 airplane, a Y-belt (also known as lap belt) was re-installed in the wrong orientation. The MCAI further states that the instructions contained within the aircraft maintenance manual (AMM) on how to install the passenger seat Y-belts, showed an incorrect orientation of the Y-belt assembly. The MCAI confirms the manufacturer updated the AMM tasks and these instructions have been

corrected. Y-belts installed in the wrong orientation, if not corrected, could result in passenger injury due to head impact on the front monument during an emergency landing.

The FAA is proposing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA–2023–1823.

Related Service Information Under 14 CFR Part 51

The FAA reviewed MHI RJ Service Bulletin 670BA–25–135, Revision B, dated November 25, 2022. This service information specifies procedures to inspect for correct installation (as shown in certain maintenance tasks) of each passenger seat Y-belt. This service information also specifies corrective

actions, which include re-installing each incorrectly installed Y-belt per certain maintenance tasks and addressing damage (includes dents or misshapen hooks that attach the belt to the seat).

This is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in

ADDRESSES.

FAA’s Determination

These products has/have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service information described above. The FAA

is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require inspecting certain Y-belts for correct installation and damage and corrective actions if necessary. This proposed AD would also prohibit the use of certain revisions of a maintenance task.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 606 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
2 work-hours × \$85 per hour = \$170	\$0	\$170	\$103,020

The FAA estimates the following costs to do any necessary replacements that would be required based on the

results of the proposed inspection. The agency has no way of determining the

number of aircraft that might need these replacements.

ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
Up to 0.5 work-hours × \$85 per hour = \$43	Up to \$550 per Y-belt assembly	Up to \$593.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

MHI RJ Aviation ULC (Type Certificate Previously Held by Bombardier, Inc.); Docket No. FAA–2023–1823; Project Identifier MCAI–2023–00314–T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by October 30, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to MHI RJ Aviation ULC (Type Certificate previously held by Bombardier, Inc.) airplanes, certificated in any category, identified in paragraphs (c)(1) through (3) of this AD.

(1) Model CL-600-2C10 (Regional Jet Series 700, 701 & 702) and CL-600-2C11 (Regional Jet Series 550) airplanes, serial numbers (S/N) 10001 through 10348 inclusive.

(2) Model CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900) airplanes, S/N 15001 through 15499 inclusive.

(3) Model CL-600-2E25 (Regional Jet Series 1000) airplanes, S/N 19001 through 19064 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code: 25, Equipment/Furnishings.

(e) Unsafe Condition

This AD was prompted by a report of a passenger seat Y-belt (lap-belt) re-installed in the wrong orientation, due to an incorrect maintenance manual. The FAA is issuing this AD to detect and address Y-belts that are incorrectly installed. The unsafe condition, if not addressed, could result in passenger injury due to head impact, on the front monument during an emergency landing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Within 24 months after the effective date of this AD, inspect each Y-belt for correct installation and damage and, if any incorrect installation or damage is found, within 24 months after the effective date of this AD, do all applicable corrective actions, in accordance with paragraph B, "Procedure," of the Accomplishment Instructions of MHI RJ Service Bulletin 670BA-25-135, Revision B, dated November 25, 2022. For this AD, damage includes dents or misshapen hooks that attach the belt to the seat.

Note 1 to paragraph (g): Y-belts are also known as lap belts.

(h) Exceptions to Service Information

Where paragraph B, "Procedure," of the Accomplishment Instructions of MHI RJ Service Bulletin 670BA-25-135, Revision B, dated November 25, 2022, specifies to "refer to AMM" replace those words with "in accordance with AMM."

(i) Maintenance Task Prohibition

As of the effective date of this AD, it is prohibited to use MHI RJ Aviation ULC Aircraft Maintenance Manual (AMM) task 25-21-04-400-801, revision 69 or earlier.

(j) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those

actions were performed before the effective date of this AD using the service information identified in paragraph (j)(1) or (2) of this AD, provided the actions were done using MHI RJ AMM Revision 70, dated May 25, 2022, or Revision 71, dated December 16, 2022.

(1) MHI RJ Service Bulletin 670BA-25-135, dated June 1, 2022.

(2) MHI RJ Service Bulletin 670BA-25-135, Revision A, dated August 30, 2022.

(k) Additional AD Provisions

The following provisions also apply to this AD.

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Manager of the International Validation Branch, mail it to ATTN: Program Manager, Continuing Operational Safety, at the address identified in paragraph (l)(2) of this AD or email to: 9-AVS-AIR-730-AMOC@faa.gov. If mailing information, also submit information by email. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or Transport Canada or MHI RJ Aviation ULC's Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(l) Additional Information

(1) Refer to Transport Canada AD CF-2023-10, dated February 17, 2023, for related information. This Transport Canada AD may be found in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-1823.

(2) For more information about this AD, contact Fatin Saumik, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone (516) 228-7300; email: 9-avs-nyaco-cos@faa.gov.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (m)(3) and (4) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) MHI RJ Service Bulletin 670BA-25-135, Revision B, dated November 25, 2022.

(ii) [Reserved]

(3) For MHI RJ Aviation ULC service information identified in this AD, contact MHI RJ Aviation Group, Customer Response Center, 3655 Ave. des Grandes-Tourelles,

Suite 110, Boisbriand, Québec J7H 0E2 Canada; North America toll-free telephone 833-990-7272 or direct-dial telephone 450-990-7272; fax 514-855-8501; email thd.crj@mhirj.com; website mhirj.com.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on September 7, 2023.

Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023-19673 Filed 9-12-23; 8:45 am]

BILLING CODE 4910-13-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 63

[EPA-HQ-OAR-2022-0441; FRL-8673-02-OAR]

RIN 2060-AV47

Regulatory Requirements for New HAP Additions

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: The U.S. Environmental Protection Agency (EPA) is proposing to amend the General Provisions for National Emission Standards for Hazardous Air Pollutants (NESHAP) to address applicability and compliance issues resulting from the addition of a compound to the list of hazardous air pollutants (HAP) under the Clean Air Act (CAA). This action focuses on issues related to newly applicable standards for sources that become major sources solely from the addition of a compound to the CAA HAP list. This action also includes a discussion of the impacts of a newly listed HAP on the federal operating permit program.

DATES:

Comments: Comments must be received on or before November 13, 2023.

Public hearing: If anyone contacts us requesting a public hearing on or before September 18, 2023, we will hold a virtual public hearing. See

SUPPLEMENTARY INFORMATION for