

dated November 11, 1999; perform a fourth eddy current inspection (bolt hole inspection) to detect cracking of the two fastener holes in the lower spar chord, in accordance with Part II of the Accomplishment Instructions of the service bulletin.

Follow-On Actions

(k) If no cracking is found during any inspection required by paragraph (d), (i), or (j) of this AD, prior to further flight, increase the diameter of the holes by the dimensions specified in the Accomplishment Instructions of Boeing Service Bulletin 757-54-0031, Revision 2, dated December 19, 1996, or Revision 4, dated November 11, 1999, and install new fasteners in accordance with the service bulletin.

(l) If any cracking is found during any inspection required by paragraph (d), (h), (i), or (j) of this AD, prior to further flight, accomplish paragraph (l)(1), (l)(2), or (l)(3) of this AD, as applicable, in accordance with the Accomplishment Instructions of Boeing Service Bulletin 757-54-0031, Revision 2, dated December 19, 1996, or Revision 4, dated November 11, 1999.

(1) If the cracking can be removed by increasing the diameter of the hole in accordance with the service bulletin: Increase the diameter of the hole by the dimensions specified in the Accomplishment Instructions of the service bulletin, and install new fasteners in accordance with the service bulletin.

(2) If the cracking cannot be removed by increasing the diameter of the hole in accordance with the Accomplishment Instructions of the service bulletin, but the cracking is within the limits specified in the service bulletin: Install the repair in accordance with the service bulletin. No further action is required by paragraph (d) of this AD.

(3) If the cracking is outside the limits specified in the service bulletin: Replace the lower spar chord with a new or serviceable chord in accordance with a method approved by the Manager, Seattle ACO.

Optional Terminating Modification

(m) Accomplishment of the modification of the nacelle strut and wing structure as required by AD 99-24-07, amendment 39-11431, constitutes terminating action for the requirements of this AD.

Alternative Methods of Compliance

(n) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(o) Special flight permits may be issued in accordance with sections 21.197 and 21.199

of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(p) Except as provided by paragraphs (c) and (l)(3) of this AD, the required actions shall be done in accordance with Boeing Service Bulletin 757-54-0031, Revision 2, dated December 19, 1996; or Boeing Service Bulletin 757-54-0031, Revision 4, dated November 11, 1999; as applicable.

(1) The incorporation by reference of Boeing Service Bulletin 757-54-0031, Revision 4, dated November 11, 1999, is approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) The incorporation by reference of Boeing Service Bulletin 757-54-0031, Revision 2, dated December 19, 1996, was approved previously by the Director of the Federal Register as of March 28, 1997 (62 FR 11760, March 13, 1997).

(3) Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(q) This amendment becomes effective on March 5, 2001.

Issued in Renton, Washington, on January 18, 2001.

Dorenda D. Baker,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 01-2111 Filed 1-26-01; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-CE-77-AD; Amendment 39-12088; AD 2001-02-04]

RIN 2120-AA64

Airworthiness Directives; Pilatus Aircraft LTD Model PC-6 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to all Pilatus Aircraft LTD (Pilatus) Model PC-6 airplanes that are equipped with a certain stabilizer trim actuator. This AD requires you to inspect the lower lug of the actuator for cracks, damage, or distortion; verify that the staked bearing is correctly installed in the bore of the lug; and repair any

cracked, damaged, or distorted parts and reassemble any incorrectly installed staked bearing, as necessary. This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Switzerland. The actions specified by this AD are intended to detect and correct damage, distortion, or cracks in the lower lug assembly, which could result in failure of the lower lug. Such failure could lead to loss of the stabilizer trim actuator with consequent loss of control of the airplane.

DATES: This AD becomes effective on March 13, 2001.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulations as of March 13, 2001.

ADDRESSES: You may get the service information referenced in this AD from Pilatus Aircraft Ltd., Customer Liaison Manager, CH-6371 Stans, Switzerland; telephone: +41 41 619 65 09; facsimile: +41 41 610 33 51. You may examine this information at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 99-CE-77-AD, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Roman T. Gabrys, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4141; facsimile: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Discussion

What events have caused this AD? The Federal Office for Civil Aviation (FOCA), which is the airworthiness authority for Switzerland, recently notified the FAA that an unsafe condition may exist on all Pilatus Model PC-6 airplanes that are equipped with a stabilizer trim actuator, part number (P/N) 978.73.18.101, 978.73.18.102, or 978.73.18.103 (Electomech P/N EM 483-1, 483-2, or 483-3). The FOCA reports an incident of a cracked, damaged, and distorted lower lug of the horizontal stabilizer trim actuator. Analysis of this incident reveals that the staked bearing was loose, which caused excessive wear and failure of the actuator lower lug.

What are the consequences if the condition is not corrected? Damage, distortion, or cracks in the lower lug assembly, if not detected and corrected, could result in failure of this part. Such failure could lead to loss of the

stabilizer trim actuator with consequent loss of control of the airplane.

Has FAA taken any action to this point? We issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to all Pilatus Model PC-6 airplanes that are equipped with a certain stabilizer trim actuator. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on November 2, 2000 (65 FR 65789). The NPRM proposed to require you to inspect the lower lug of the actuator for cracks, damage, or distortion; verify that the staked bearing is correctly installed in the bore of the lug; and repair any

cracked, damaged, or distorted parts and reassemble any incorrectly installed staked bearing, as necessary.

Was the public invited to comment? Interested persons were afforded an opportunity to participate in the making of this amendment. No comments were received on the proposed rule or the FAA's determination of the cost to the public.

The FAA's Determination

What is FAA's final determination on this issue? After careful review of all available information related to the subject presented above, we have determined that air safety and the public interest require the adoption of

the rule as proposed except for minor editorial corrections. We determined that these minor corrections:

- Will not change the meaning of the AD; and
- Will not add any additional burden upon the public than was already proposed.

Cost Impact

How many airplanes does this AD impact? We estimate that this AD affects 7 airplanes in the U.S. registry.

What is the cost impact of this AD on owners/operators of the affected airplanes? We estimate the following costs to accomplish the inspection :

Labor cost	Parts cost	Total cost per airplane	Total cost on U.S. airplane operators
1 workhour × \$60 per hour = \$60	Not applicable	\$60 per airplane	\$60 × 7=\$420.

If any distortion, damage, or cracks are found during the inspection, you will have to repair the actuator assembly in accordance with an FAA-approved repair scheme developed by the manufacturer. The FAA has no way of determining how much incorporating each repair scheme will cost since the damage to each airplane will be unique.

Regulatory Impact

Does this AD impact various entities? The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

Does this AD involve a significant rule or regulatory action? For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44

FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the final evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. FAA amends § 39.13 by adding a new AD to read as follows:

2001-02-04 Pilatus Aircraft Ltd.:

Amendment 39-12088; Docket No. 99-CE-77-AD.

(a) *What airplanes are affected by this AD?* This AD affects Model PC-6 airplanes, all serial numbers, that are:

- (1) Certificated in any category; and
- (2) Equipped with a stabilizer trim actuator, part number (P/N) 978.73.18.101, 978.73.18.102, or 978.73.18.103 (Electomech P/N EM 483-1, 483-2, or 483-3), or FAA-approved equivalent part number.

(b) *Who must comply with this AD?* Anyone who wishes to operate any of the above airplanes must comply with this AD.

(c) *What problem does this AD address?* The actions specified by this AD are intended to detect and correct damage, distortion, or cracks in the lower lug assembly, which could result in failure of the lower lug. Such failure could lead to loss of the stabilizer trim actuator with consequent loss of control of the airplane.

(d) *What actions must I accomplish to address this problem?* To address this problem, you must accomplish the following:

Action	Compliance time	Procedures
(1) Inspect the lower lug of the actuator for cracks, damage, or distortion, and assure that the staked bearing is correctly installed in the bore of the lug.	Upon accumulating 500 hours time-in-service (TIS) on the airplane or within the next 100 hours TIS after March 13, 2001 (the effective date of this AD), whichever occurs later, unless already accomplished.	Accomplish the inspection in accordance with the ACCOMPLISHMENT INSTRUCTIONS section of Pilatus Service Bulletin No. 178, dated September 29, 1999.
(2) Repair any cracked, damaged, or distorted parts, as necessary, and reassemble any incorrectly installed staked bearing.	Prior to further flight after the inspection required by paragraph (d)(1) of this AD.	Accomplish any repairs in accordance with an FAA-approved repair scheme obtained from the manufacturer. Accomplish the re-assembly in accordance with the instructions in the maintenance manual.

(e) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

(1) Your alternative method of compliance provides an equivalent level of safety; and

(2) The Manager, Small Airplane Directorate, approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

Note 1: This AD applies to each airplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already approved alternative methods of compliance?* Contact Roman T. Gabrys, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4141; facsimile: (816) 329-4090.

(g) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(h) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with Pilatus Service Bulletin No. 178, dated September 29, 1999. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You can get copies from Pilatus Aircraft Ltd., Customer Liaison Manager, CH-6371 Stans, Switzerland. You can look at copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(i) *When does this amendment become effective?* This amendment becomes effective on March 13, 2001.

Note 2: The subject of this AD is addressed in Swiss AD HB 99-507, dated October 1, 1999.

Issued in Kansas City, Missouri, on January 12, 2001.

Michael Gallagher,
Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01-2002 Filed 1-26-01; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-80-AD; Amendment 39-12089; AD 2001-02-05]

RIN 2120-AA64

Airworthiness Directives; CL-604 Variant of Bombardier Model Canadair CL-600-2B16 Series Airplanes Modified in Accordance With Supplemental Type Certificate SA8060NM-D, SA8072NM-D, or SA8086NM-D

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment supersedes an existing airworthiness directive (AD), applicable to Model CL-604 variant of Bombardier Model Canadair CL-600-2B16 series airplanes modified in accordance with certain Supplemental Type Certificates, that currently requires that the fuel service panel maintenance light on the fuel service panel be disconnected. This amendment requires modification of the wiring of the fuel port flood light (which is the name given to the fuel service panel maintenance light in the service bulletin that describes the wiring modification). This amendment is prompted by a report indicating that an electrical spark was noted when the fuel cap chain contacted the fuel port flood light housing of the fuel service panel. The actions specified by this AD are intended to prevent electrical sparks from a grounded object from coming into contact with the fuel port flood light housing of the fuel service panel, which could result in a fuel fire due to the proximity of the fuel service panel to the fuel port.

DATES: Effective March 5, 2001.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of March 5, 2001.

ADDRESSES: The service information referenced in this AD may be obtained from Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centreville, Montreal, Quebec H3C 3G9, Canada. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood,

California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Abby Malmir, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5351; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) by superseding AD 2000-01-51, amendment 39-11519 (65 FR 3379, January 21, 2000), which is applicable to Model CL-604 variant of Bombardier Model Canadair CL-600-2B16 series airplanes modified in accordance with certain Supplemental Type Certificates, was published in the **Federal Register** on October 5, 2000 (65 FR 59383). The action proposed to require modification of the wiring of the fuel port flood light (which is the name given to the fuel service panel maintenance light in the service bulletin that describes the wiring modification).

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

There are approximately 22 airplanes of U.S. registry that will be affected by this AD.

The modification required by this AD action will take approximately 2 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. The cost of the parts required for each airplane is minimal. Based on these figures, the cost impact of the requirements of this AD on U.S. operators is estimated to be \$2,640, or \$120 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include