

the Board is adopting the proposed rule as final, without modification.

Accordingly, the Board is amending 12 CFR 261a.12(b) to redesignate paragraph (b)(11) referencing BGFRS/OIG–1 Investigative Records as paragraph (b)(12) and adding “BGFRS–43, Security Sharing Platform” as new paragraph (b)(11).

#### Regulatory Flexibility Act

In accordance with 5 U.S.C. 605, the Board certifies that this rule will not have a significant economic impact on a substantial number of small entities because it applies only to internal personnel matters of the agency.

#### Administrative Procedure Act

This rule is exempt from the rulemaking provisions of the Administrative Procedure Act, 5 U.S.C. 553, and the Congressional Review Act, pursuant to 5 U.S.C. 804(3)(B) and (C), because it is a rule relating to agency management or personnel and a rule of agency procedure that does not substantially affect the rights or obligations of non-agency parties.

#### List of Subjects in 12 CFR Part 261a

Privacy.

#### Authority and Issuance

For the reasons stated in the preamble, the Board amends 12 CFR part 261a as follows:

#### PART 12 CFR 261a—RULES REGARDING ACCESS TO PERSONAL INFORMATION UNDER THE PRIVACY ACT 1974

- 1. The authority citation of part 261a continues to read as follows:

**Authority:** 5 U.S.C. 552a.

- 2. Amend § 261a.12(b) by redesignating paragraph (b)(11) as (b)(12) and adding new paragraph (b)(11) to read as follows:

##### § 261a.12 Exempt records.

\* \* \* \* \*

(b) \* \* \*

(11) BGFRS–43 Security Sharing Platform

\* \* \* \* \*

By order of the Board of Governors of Federal Reserve System.

**Ann Misback,**

*Secretary of the Board.*

[FR Doc. 2020–24088 Filed 11–18–20; 8:45 am]

**BILLING CODE 6210–01–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2020–0513; Product Identifier 2019–SW–037–AD; Amendment 39–21321; AD 2020–23–05]

RIN 2120–AA64

#### Airworthiness Directives; Airbus Helicopters

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is superseding Airworthiness Directive (AD) 2018–08–01 for Airbus Helicopters Model EC225LP helicopters. AD 2018–08–01 required inspecting the control rod attachment yokes (yoke) of certain main rotor rotating swashplates (swashplate). This new AD retains the inspection requirements of AD 2018–08–01, expands the applicability, establishes a life limit, and adds a one-time inspection of stripped yokes. This AD was prompted by the identification of additional swashplate serial numbers affected by the unsafe condition and the establishment of a life limit for the swashplates. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective December 24, 2020.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 24, 2020.

**ADDRESSES:** For service information identified in this final rule, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; telephone 972–641–0000 or 800–232–0323; fax 972–641–3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>. You may view the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–0513.

#### Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–0513; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the

European Union Aviation Safety Agency (EASA) AD, any service information that is incorporated by reference, any comments received, and other information. The address for Docket Operations is Document Operations, U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

#### FOR FURTHER INFORMATION CONTACT:

Matthew Fuller, AD Program Manager, Operational Safety Branch, Airworthiness Products Section, General Aviation & Rotorcraft Unit, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817–222–5110; email [Matthew.Fuller@faa.gov](mailto:Matthew.Fuller@faa.gov).

#### SUPPLEMENTARY INFORMATION:

#### Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2018–08–01, Amendment 39–19254 (83 FR 17617, April 23, 2018) (AD 2018–08–01) and add a new AD. AD 2018–08–01 applied to Airbus Helicopters Model EC225LP helicopters with certain serial-numbered swashplates part number (P/N) 332A31–3074–00 or P/N 332A31–3074–01 installed. The NPRM published in the **Federal Register** on June 3, 2020 (85 FR 34118). The NPRM proposed to require determining the date of manufacture of the swashplate and establishing a life limit of 12 years since the date of manufacture. The NPRM proposed to retain the repetitive visual inspections of AD 2018–08–01 to inspect each yoke for a crack at intervals not to exceed 15 hours time-in-service (TIS) for swashplates that have accumulated less than 7 years since the date of manufacture. For a swashplate that has accumulated 7 or more years, but less than 12 years since the date of manufacture, the NPRM proposed to require removing the grease and stripping certain areas of the yokes and inspecting these areas for corrosion, pitting, loss of material, and a crack. If there are no cracks, the NPRM proposed to require performing a dye penetrant inspection of the yoke for a crack. Depending on the results of this inspection, the NPRM proposed to require either repairing the surface of the swashplate or removing it from service.

The NPRM was prompted by EASA AD No. 2019–0074, dated March 28, 2019 (EASA AD 2019–0074) issued by EASA, which is the Technical Agent for the Member States of the European Union, to supersede EASA AD No. 2017–0191R2, dated December 15, 2017

(EASA AD 2017–0191R2). EASA AD 2019–0074 followed Airbus Helicopters revising Emergency Alert Service Bulletin (EASB) No. 05A051, Revision 1, dated November 16, 2017, to Revision 2, dated February 26, 2019, to establish a life limit (also called a service life limit) of 12 years for the swashplate and add a reporting requirement if there is a crack or corrosion in a yoke. EASA advises that additional analysis determined that it is necessary to introduce the new life limit for the affected swashplates. Accordingly, EASA AD 2019–0074 retains the requirements of EASA AD 2017–0191R2 and adds a life limit and a reporting requirement.

Additionally, when the FAA issued AD 2018–08–01 to address the unsafe condition of a crack in a swashplate yoke, the FAA did not require stripping certain yokes and performing a one-time inspection within 100 hours TIS for corrosion and a crack as specified in EASA AD 2017–0191R2, as there was sufficient time to allow for notice and comment prior to this long-term AD requirement going into effect. The FAA has determined that this inspection is needed to address this unsafe condition. Accordingly, the NPRM also proposed to require, within 100 hours TIS and for certain yokes, removing the grease and stripping certain areas of the yokes and inspecting these areas for corrosion, pitting, loss of material, and a crack.

#### Comments

The FAA gave the public the opportunity to participate in developing this AD. The FAA received no comments on the NPRM or on the determination of the cost to the public.

#### FAA's Determination

These helicopters have been approved by EASA and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the European Union, EASA has notified the FAA about the unsafe condition described in its AD. The FAA is issuing this AD after evaluating all of the known relevant information and determining that an unsafe condition is likely to exist or develop on other helicopters of the same type design and that air safety and the public interest require adopting the AD requirements as proposed.

#### Differences Between This AD and the EASA AD

The EASA AD requires performing a non-destructive inspection only if there is doubt whether there is a crack. Instead, this AD requires a visual inspection and if there are no cracks, requires a non-destructive inspection.

The EASA AD specifies instructions for reporting inspection reports; this AD does not.

#### Related Service Information Under 1 CFR Part 51

The FAA reviewed one document that co-publishes two Airbus Helicopters EASB identification numbers: EASB No. 05A051 for Model EC225LP helicopters and EASB No. 05A046 for non-FAA type-certificated Model EC725AP helicopters, each Revision 2 and dated February 26, 2019 (EASB 05A051 and EASB 05A046). EASB 05A051 is incorporated by reference in this AD. EASB 05A046 is not incorporated by reference in this AD.

This service information specifies inspections for swashplate P/N 332A31–3074–00 and P/N 332A31–3074–01. This service information specifies procedures for a repetitive inspection of the yokes for a crack and a one-time inspection of the stripped yokes for corrosion and a crack. If in doubt about whether there is a crack, this service information specifies performing a non-destructive inspection. This service information also specifies touching up the swashplate with varnish if there is corrosion, removing any damage within allowable limits, and refinishing the yokes. If there is a crack in a yoke, this service information specifies replacing the swashplate. This service information also specifies a life limit of 12 years since the date of manufacture for the swashplates and reporting requirements if a crack or corrosion is discovered.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

#### Other Related Service Information

The FAA reviewed one document that co-publishes two Airbus Helicopters EASB identification numbers: EASB No. 05A051 for Model EC225LP helicopters and EASB No. 05A046 for non-FAA type-certificated Model EC725AP helicopters, each Revision 1 and dated November 16, 2017. Revision 1 of this service information specifies the same inspections as Revision 2 of this service information. However, Revision 2 of this service information clarifies some of the inspection instructions and adds a life limit and a reporting requirement.

#### Costs of Compliance

The FAA estimates that this AD affects 26 helicopters of U.S. registry. The FAA estimates that operators may incur the following costs in order to comply with this AD. Labor rates are estimated at \$85 per work-hour.

Determining the date of manufacture of the swashplate takes about 0.5 work-hour for an estimated cost of \$43 per helicopter and \$1,118 for the U.S. fleet.

Inspecting the yokes takes about 0.25 work-hour for an estimated cost of \$21 per helicopter and \$546 for the U.S. fleet per inspection cycle.

Removing grease, stripping the yokes, and inspecting the stripped yokes takes about 8 work-hours, for a total estimated cost of \$680 per helicopter.

Dye-penetrant inspecting a yoke for a crack takes about 6 work-hours and parts cost about \$50, for an estimated cost of \$560 per yoke.

Removing any corrosion or repairing damage within the allowable limit takes about 3 work-hours, for an estimated cost of \$255 per yoke.

Replacing the swashplate takes about 6 work-hours, and parts cost about \$85,661 for an estimated cost of \$86,171 per instance.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2018–08–01, Amendment 39–19254 (83 FR 17617, April 23, 2018), and adding the following new AD:2020–23–05

**Airbus Helicopters:** Amendment 39–21321; Docket No. FAA–2020–0513; Product Identifier 2019–SW–037–AD.

#### (a) Applicability

This airworthiness directive (AD) applies to Airbus Helicopters Model EC225LP helicopters, certificated in any category, with a main rotor (M/R) rotating swashplate (swashplate) part number (P/N) 332A31–3074–00 or P/N 332A31–3074–01 installed.

#### (b) Unsafe Condition

This AD defines the unsafe condition as a crack in a swashplate control rod attachment yoke (yoke). This condition could result in failure of the yoke, loss of M/R control, and subsequent loss of control of the helicopter.

#### (c) Affected ADs

This AD replaces AD 2018–08–01, Amendment 39–19254 (83 FR 17617, April 23, 2018).

#### (d) Effective Date

This AD is effective December 24, 2020.

#### (e) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

#### (f) Required Actions

Before further flight, review Appendix 4.A. of Airbus Helicopters Emergency Alert Service Bulletin No. 05A051, Revision 2, dated February 26, 2019 (EASB 05A051) to determine the date of manufacture of the swashplate.

(1) If the swashplate has accumulated 12 or more years since the date of manufacture, remove from service the swashplate.

(2) If the swashplate has accumulated less than 12 years since the date of manufacture, create a component history card or

equivalent record indicating a life limit of 12 years since the date of manufacture. Thereafter, continue to record the life limit of the swashplate on its component history card or equivalent record and remove from service any swashplate before accumulating 12 years since the date of manufacture.

(3) For each swashplate that has accumulated less than 7 years since the date of manufacture, within 15 hours time-in-service (TIS) and thereafter at intervals not to exceed 15 hours TIS, until the swashplate accumulates 7 years since the date of manufacture, visually inspect each yoke for a crack, paying particular attention to the areas shown in Details B, C, and D of Figure 1 of EASB 05A051.

(i) If there are no cracks, perform a dye penetrant inspection of the yoke for a crack.

(ii) If there is a crack on a yoke, before further flight, remove from service the swashplate.

(4) For each swashplate that has accumulated 7 or more years, but less than 12 years, since the date of manufacture, within 100 hours TIS:

(i) Remove the grease from areas (E), (F), (G), (H), (J), and (K) of each yoke as shown in Details B, C, and D of Figure 1 of EASB 05A051. Using a plastic spatula, strip areas (E), (F), (G), (H), (J), and (K) of each yoke as shown in Details B, C, and D of Figure 1 of EASB 05A051. Do not use a metal tool to strip any area of a yoke.

(ii) Inspect areas (E), (F), (G), (H), (J) and (K) of each yoke as shown in Details B, C, and D of Figure 1 of EASB 05A051 for corrosion, pitting, and loss of material.

(A) If there is any corrosion less than 0.0078 in. (0.2 mm), before further flight, remove the corrosion and apply varnish (Vernelec 43022 or equivalent) to the surface of areas (E), (F), (G), (H), (J) and (K).

(B) If there is any pitting or loss of material of less than 0.0078 in. (0.2 mm), before further flight, remove the damage by sanding with sandpaper 200/400 or 330.

(C) If there is any corrosion, pitting, or loss of material of 0.0078 in. (0.2 mm) or greater, before further flight, remove from service the swashplate.

(iii) Visually inspect each yoke for a crack, paying particular attention to the areas shown in Details B, C, and D of Figure 1 of EASB 05A051.

(A) If there are no cracks, perform a dye penetrant inspection of the yoke for a crack.

(B) If there is a crack on a yoke, before further flight, remove from service the swashplate.

#### (g) Credit for Previous Actions

If you performed the actions in paragraph (f)(4) of this AD before the effective date of this AD using Airbus Helicopters Emergency Alert Service Bulletin No. 05A051, Revision 1, dated November 16, 2017, you met the requirements of paragraph (f)(4) of this AD.

#### (h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Rotorcraft Standards Branch, FAA, may approve AMOCs for this AD. Send your proposal to: Matthew Fuller, AD Program Manager, Operational Safety Branch, Airworthiness Products Section,

General Aviation & Rotorcraft Unit, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817–222–5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, the FAA suggests that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

#### (i) Additional Information

(1) Airbus Helicopters Emergency Alert Service Bulletin No. 05A051, Revision 1, dated November 16, 2017, which is not incorporated by reference, contains additional information about the subject of this AD. For service information identified in this AD, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; telephone 972–641–0000 or 800–232–0323; fax 972–641–3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>. You may view a copy of the service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in European Union Aviation Safety Agency (EASA) AD No. 2019–0074, dated March 28, 2019. You may view the EASA AD on the internet at <https://www.regulations.gov> in Docket No. FAA–2020–0513.

#### (j) Subject

Joint Aircraft Service Component (JASC) Code: 6230, Main Rotor Mast/Swashplate.

#### (k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Airbus Helicopters Emergency Alert Service Bulletin (EASB) No. 05A051, Revision 2, dated February 26, 2019.

(ii) [Reserved]

**Note 1 to paragraph (k)(2):** Airbus Helicopters EASB No. 05A051, Revision 2, dated February 26, 2019, is co-published as one document along with Airbus Helicopters EASB No. 05A046, Revision 2, dated February 26, 2019, which is not incorporated by reference in this AD.

(3) For service information identified in this AD, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; telephone 972–641–0000 or 800–232–0323; fax 972–641–3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817–222–5110.

(5) You may view this service information that is incorporated by reference at the

National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on October 29, 2020.

**Lance T. Gant,**

*Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2020-25472 Filed 11-18-20; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2020-0978; Project Identifier MCAI-2020-00459-R; Amendment 39-21318; AD 2020-23-02]

**RIN 2120-AA64**

#### Airworthiness Directives; Airbus Helicopters

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for all Airbus Helicopters Model EC225LP helicopters. This AD was prompted by a report of a manufacturing and control issue regarding the ceramic balls in the bearing installed in the swashplate assembly of the main rotor mast assembly. This AD requires repetitive inspections of the bearing in the swashplate assembly of the main rotor mast assembly for discrepancies (ceramic balls that have a hard point or sensitive axial play or both) and, depending on the findings, replacement of an affected main rotor mast assembly with a serviceable main rotor mast assembly, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products. **DATES:** This AD becomes effective December 4, 2020.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 4, 2020.

The FAA must receive comments on this AD by January 4, 2021.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 1000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817-222-5110. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0978.

#### Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0978; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

#### FOR FURTHER INFORMATION CONTACT:

Kathleen Arrigotti, Aviation Safety Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3218; email: [kathleen.arrigotti@faa.gov](mailto:kathleen.arrigotti@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Discussion

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2020-0079, dated April 1, 2020 (EASA AD 2020-0079) (also referred to as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for all Airbus Helicopters Model EC225LP helicopters. This AD was prompted by a report of a manufacturing and control issue

regarding the ceramic balls of the bearing installed in the swashplate assembly of the main rotor mast assembly.

The FAA is issuing this AD to address defective ceramic balls in the bearing installed in the swashplate assembly of the main rotor mast assembly, which could lead to premature spalling of the ball itself and of the bearing, loss of function of the bearing, and overload of the main rotor mast scissor, resulting in reduced control of the helicopter. See the MCAI for additional background information.

#### Related Service Information Under 1 CFR Part 51

EASA AD 2020-0079 describes procedures for repetitive inspections of the main rotor mast swashplate assembly for discrepancies (ceramic balls that have a hard point or sensitive axial play or both), and replacement of an affected main rotor mast assembly with a serviceable main rotor mast assembly. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

#### FAA's Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI referenced above. The FAA is issuing this AD because the FAA evaluated all pertinent information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

#### Requirements of This AD

This AD requires accomplishing the actions specified in EASA AD 2020-0079 described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD and except as discussed under "Difference Between this AD and the MCAI."

#### Explanation of Required Compliance Information

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA initially worked with Airbus and EASA to develop a process to use certain EASA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has since coordinated with other manufacturers