

Proposed Rules

Federal Register

Vol. 69, No. 46

Tuesday, March 9, 2004

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-CE-57-AD]

RIN 2120-AA64

Airworthiness Directives; LET a.s. Model Blanik L-13 AC Sailplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all LET a.s. (formerly LET n.p.) (LET) Model Blanik L-13 AC sailplanes. This proposed AD would require you to repetitively inspect the bedding of the front and rear control levers for cracks, and, if any cracks are found, replace with parts found free of cracks. This proposed AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for the Czech Republic. We are issuing this proposed AD to detect and correct cracks in the bedding of the front and rear control levers, which could result in failure of the bridge of controls for the sailplane. This failure could lead to loss of sailplane control.

DATES: We must receive any comments on this proposed AD by April 16, 2004.

ADDRESSES: Use one of the following to submit comments on this proposed AD:

- *By mail:* FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2003-CE-57-AD, 901 Locust, Room 506, Kansas City, Missouri 64106.
- *By fax:* (816) 329-3771.
- *By e-mail:* 9-ACE-7-Docket@faa.gov.

Comments sent electronically must contain "Docket No. 2003-CE-57-AD" in the subject line. If you send comments electronically as attached electronic files, the files must be formatted in Microsoft Word 97 for Windows or ASCII.

You may get the service information identified in this proposed AD from LET n.p., Kunovice 686 04, Czech Republic; telephone: +420 632 55 44 96; facsimile: +420 632 56 41 13.

You may view the AD docket at FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2003-CE-57-AD, 901 Locust, Room 506, Kansas City, Missouri 64106. Office hours are 8 a.m. to 4 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Greg Davison, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; facsimile: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Comments Invited

How do I comment on this proposed AD? We invite you to submit any written relevant data, views, or arguments regarding this proposal. Send your comments to an address listed under **ADDRESSES**. Include "AD Docket No. 2003-CE-57-AD" in the subject line of your comments. If you want us to acknowledge receipt of your mailed comments, send us a self-addressed, stamped postcard with the docket number written on it. We will date-stamp your postcard and mail it back to you.

Are there any specific portions of this proposed AD I should pay attention to? We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. If you contact us through a nonwritten communication and that contact relates to a substantive part of this proposed AD, we will summarize the contact and place the summary in the docket. We will consider all comments received by the closing date and may amend this proposed AD in light of those comments and contacts.

Discussion

What events have caused this proposed AD? The Civil Aviation Authority (CAA), which is the airworthiness authority for the Czech Republic, recently notified FAA that an unsafe condition may exist on certain LET Model Blanik L-13 AC sailplanes. The CAA reports one occurrence of cracks in the attachment of control levers on the bridge of controls

(Drawing No. A71 210N) on a Model Blanik L-13 AC sailplane after 130 hours time-in-service (TIS) of aerobatics. The cracks are due to material fatigue.

What are the consequences if the condition is not corrected? Failure of the bridge of controls for the sailplane could lead to loss of sailplane control.

Is there service information that applies to this subject? LET has issued Letecké Zavody Mandatory Bulletin No.: L13/095a, dated October 18, 2001.

What are the provisions of this service information? The service bulletin includes procedures for:

- Inspecting the bedding of the front and rear control levers (Drawing (DWG) No. A741 215N and DWG No. A741 210N) for cracks; and
- if any cracks are found, replacing with parts found free of cracks.

What action did the CAA take? The CAA classified this service bulletin as mandatory and issued Czech AD Number CAA-AD-090/2001, dated October 25, 2001, to ensure the continued airworthiness of these sailplanes in the Czech Republic.

Did the CAA inform the United States under the bilateral airworthiness agreement? These LET Model Blanik L-13 AC sailplanes are manufactured in the Czech Republic and are type-certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement.

Under this bilateral airworthiness agreement, the CAA has kept us informed of the situation described above.

FAA's Determination and Requirements of This Proposed AD

What has FAA decided? We have examined the CAA's findings, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Since the unsafe condition described previously is likely to exist or develop on other LET Model Blanik L-13 AC sailplanes of the same type design that are registered in the United States, we are proposing AD action to detect and correct cracks in the bedding of the front and rear control levers, which could result in failure of the bridge of controls for the sailplane.

What would this proposed AD require? This proposed AD would require you to incorporate the actions in the previously-referenced service bulletin.

How does the revision to 14 CFR part 39 affect this proposed AD? On July 10, 2002, we published a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs FAA's AD system.

This regulation now includes material that relates to altered products, special flight permits, and alternative methods of compliance. This material previously was included in each individual AD. Since this material is included in 14 CFR part 39, we will not include it in future AD actions.

Costs of Compliance

How many sailplanes would this proposed AD impact? We estimate that this proposed AD affects 5 sailplanes in the U.S. registry.

What would be the cost impact of this proposed AD on owners/operators of the affected sailplanes? We estimate the following costs to accomplish this proposed inspection:

Labor cost	Parts cost	Total cost per sailplane	Total cost on U.S. operators
1 workhour × \$65 per hour = \$65	Not Applicable.	\$65	\$65 × 5 = \$325

Since the replacement of parts will vary based on the damage found as a result of the proposed inspection, we are unable to estimate the costs to do any necessary replacements.

Regulatory Findings

Would this proposed AD impact various entities? We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

Would this proposed AD involve a significant rule or regulatory action? For the reasons discussed above, I certify that this proposed AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this proposed AD and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include "AD Docket No. 2003-CE-57-AD" in your request.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Actions	Compliance	Procedures
(1) Inspect the bedding of the front and rear control levers (Drawing (DWG) No. A741 215N and DWG No. A741 210N) for cracks.	Within the next 25 hours time-in-service (TIS) after the effective date of this AD, unless already done. Repetitively inspect thereafter at every 25 hours TIS.	Follow the WORK PROCEDURE paragraph of LET Letecke Zavody Mandatory Bulletin No.: L13/095a, dated October 18, 2001.
(2) If any cracks are found during any inspection required by paragraph (e)(1) of this AD, replace with parts shown free of cracks. Repetitive inspections are still required.	Before further flight after any inspection required by paragraph (e)(1) of this AD..	Follow the WORK PROCEDURE paragraph of LET Letecke Zavody Mandatory Bulletin No.: L13/095a, dated October 18, 2001, and the applicable sailplane maintenance manual.

May I Request an Alternative Method of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise,

send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Standards Office, Small Airplane Directorate, FAA. For information on any already approved alternative methods of

LET a.s.: Docket No. 2003-CE-57-AD

When Is the Last Date I Can Submit Comments on This Proposed AD?

(a) We must receive comments on this proposed airworthiness directive (AD) by April 16, 2004.

What Other ADs Are Affected by This Action?

(b) None.

What Sailplanes Are Affected by This AD?

(c) This AD affects Model Blanik L-13 AC sailplanes, serial numbers 988601, 988603, 988604, 008605, and 008606, that are certificated in any category.

What Is the Unsafe Condition Presented in This AD?

(d) This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for the Czech Republic. The actions specified in this AD are intended to detect and correct cracks in the bedding of the front and rear control levers, which could result in failure of the bridge of controls for the sailplane. This failure could lead to loss of sailplane control.

What Must I Do To Address This Problem?

(e) To address this problem, you must do the following:

compliance, contact Greg Davison, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; facsimile: (816) 329-4090.

May I Get Copies of the Documents Referenced in This AD?

(g) You may get copies of the documents referenced in this AD from LET a.s., Kunovice 686 04, Czech Republic; telephone: +420 632 55 44 96; facsimile: +420 632 56 41 13. You may view these documents at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106.

Is There Other Information That Relates to This Subject?

(h) Czech Airworthiness Directive CAA-AD-090/2001, dated October 25, 2001, also addresses the subject of this AD.

Issued in Kansas City, Missouri, on March 2, 2004.

Sandra J. Campbell,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-5264 Filed 3-8-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOMELAND SECURITY**Federal Emergency Management Agency****44 CFR Part 67**

[Docket No. FEMA-D-7584]

Proposed Flood Elevation Determinations

AGENCY: Federal Emergency Management Agency (FEMA), Emergency Preparedness and Response Directorate, Department of Homeland Security.

ACTION: Proposed rule.

SUMMARY: Technical information or comments are requested on the proposed Base (1% annual chance) Flood Elevations (BFEs) and proposed BFE modifications for the communities listed below. The BFEs are the basis for the floodplain management measures that the community is required either to adopt or to show evidence of being already in effect in order to qualify or remain qualified for participation in the

National Flood Insurance Program (NFIP).

DATES: The comment period is ninety (90) days following the second publication of this proposed rule in a newspaper of local circulation in each community.

ADDRESSES: The proposed BFEs for each community are available for inspection at the office of the Chief Executive Officer of each community. The respective addresses are listed in the table below.

FOR FURTHER INFORMATION CONTACT:

Doug Bellomo, P.E., Hazard Identification Section, Emergency Preparedness and Response Directorate, FEMA, 500 C Street, SW., Washington, DC 20472, (202) 646-2903.

SUPPLEMENTARY INFORMATION: FEMA proposes to make determinations of BFEs and modified BFEs for each community listed below, in accordance with section 110 of the Flood Disaster Protection Act of 1973, 42 U.S.C. 4104, and 44 CFR 67.4(a).

These proposed base flood and modified BFEs, together with the floodplain management criteria required by 44 CFR 60.3, are the minimum that are required. They should not be construed to mean that the community must change any existing ordinances that are more stringent in their floodplain management requirements. The community may at any time enact stricter requirements of its own, or pursuant to policies established by other Federal, state or regional entities. These proposed elevations are used to meet the floodplain management requirements of the NFIP and are also used to calculate the appropriate flood insurance premium rates for new buildings built after these elevations are made final, and for the contents in these buildings.

National Environmental Policy Act

This proposed rule is categorically excluded from the requirements of 44 CFR part 10, Environmental Consideration. No environmental impact assessment has been prepared.

Regulatory Flexibility Act

The Mitigation Division Director of the Emergency Preparedness and Response Directorate certifies that this proposed rule is exempt from the requirements of the Regulatory Flexibility Act because proposed or modified BFEs are required by the Flood Disaster Protection Act of 1973, 42 U.S.C. 4105, and are required to establish and maintain community eligibility in the NFIP. As a result, a regulatory flexibility analysis has not been prepared.

Regulatory Classification

This proposed rule is not a significant regulatory action under the criteria of Section 3(f) of Executive Order 12866 of September 30, 1993, Regulatory Planning and Review, 58 FR 51735.

Executive Order 12612, Federalism

This proposed rule involves no policies that have federalism implications under Executive Order 12612, Federalism, dated October 26, 1987.

Executive Order 12778, Civil Justice Reform

This proposed rule meets the applicable standards of Section 2(b)(2) of Executive Order 12778.

List of Subjects in 44 CFR Part 67

Administrative practice and procedure, Flood insurance, Reporting and recordkeeping requirements.

Accordingly, 44 CFR Part 67 is proposed to be amended as follows:

PART 67—[AMENDED]

1. The authority citation for Part 67 continues to read as follows:

Authority: 42 U.S.C. 4001 *et seq.*; Reorganization Plan No. 3 of 1978, 3 CFR, 1978 Comp., p. 329; E.O. 12127, 44 FR 19367, 3 CFR, 1979 Comp., p. 376.

§ 67.4 [Amended]

2. The tables published under the authority of § 67.4 are proposed to be amended as follows: