

Special conditions are initially applicable to the model for which they are issued. Should the type certificate for that model be amended later to include any other model that incorporates the same novel or unusual design feature, or should any other model already included on the same type certificate be modified to incorporate the same novel or unusual design feature, these special conditions would also apply to the other model under § 21.101.

In addition to the applicable airworthiness regulations and special conditions, the Bombardier Model BD-700-2A12 and BD-700-2A13 series airplanes must comply with the fuel-vent and exhaust-emission requirements of 14 CFR part 34, and the noise-certification requirements of 14 CFR part 36.

The FAA issues special conditions, as defined in 14 CFR 11.19, in accordance with § 11.38, and they become part of the type certification basis under § 21.101.

Novel or Unusual Design Features

The Model BD-700-2A12 and BD-700-2A13 series airplanes will incorporate the following novel or unusual design features:

Fly-by-wire EFCS that will limit pitch and roll functions to prevent the airplane from attaining certain pitch attitudes and roll angles greater than plus or minus 65 degrees, and introduce positive spiral stability introduced for roll angles greater than 30 degrees at speeds below V_{MO}/M_{MO} . This system generates the actual surface commands that provide for stability augmentation and flight control for all three airplane axes (longitudinal, lateral, and directional).

Discussion

Part 25 of title 14 of the CFR does not specifically relate to flight characteristics associated with fixed attitude limits. Bombardier proposes to implement on the airplanes pitch and roll attitude-limiting functions via the EFCS normal mode. This will prevent the airplane from attaining certain pitch attitudes and roll angles greater than plus or minus 65 degrees. In addition, positive spiral stability, introduced for roll angles greater than 30 degrees at speeds below V_{MO}/M_{MO} , and spiral stability characteristics, must not require excessive pilot strength to achieve bank angles up to the bank-angle limit.

Bombardier requested this amendment, in order to be performance-based rather than prescriptive and to more closely follow the language

developed in the Aviation Rulemaking Advisory Committee (ARAC) Flight Test Harmonization Working Group (FTHWG). The FAA concurs with this request.

The basic envelope protection requirement, historically applied, is to not unduly limit the maneuver capability of the airplane, or interfere with its ability to perform maneuvers required for normal and emergency operations. Since the design details used to meet this requirement vary from airplane to airplane, this amendment recognizes and adopts that philosophy for this specific design implementation. The substance of the special conditions is unchanged, in that, for this specific design, the design details support the objective of not unduly limiting the maneuver capability, while also protecting the airplane from adverse attitudes.

These special conditions are in addition to the requirements of § 25.143. These special conditions contain the additional safety standards that the Administrator considers necessary to establish a level of safety equivalent to that established by the existing airworthiness standards.

Applicability

As discussed above, these special conditions are applicable to the Model BD-700-2A12 and BD-700-2A13 series airplanes. Should Bombardier apply at a later date for a change to the type certificate to include another model incorporating the same novel or unusual design feature, these special conditions would apply to that model as well.

Conclusion

This action affects only certain novel or unusual design features on one model series of airplanes. It is not a rule of general applicability.

List of Subjects in 14 CFR Part 25

Aircraft, Aviation safety, Reporting and recordkeeping requirements.

Authority Citation

The authority citation for these special conditions is as follows:

Authority: 49 U.S.C. 106(f), 106(g), 40113, 44701, 44702, 44704.

The Special Conditions

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the following special conditions are issued as part of the type certification basis for Bombardier Model BD-700-2A12 and BD-700-2A13 series airplanes:

In addition to § 25.143, the following requirements apply to the electronic

flight-control system (EFCS) pitch- and roll-limiting functions:

1. The pitch-limiting function must not impede normal maneuvering for pitch angles up to the maximum required for normal maneuvering, including a normal, all-engines-operating takeoff, plus a suitable margin to allow for satisfactory speed control.

2. The pitch- and roll-limiting functions must not restrict or prevent attaining pitch attitudes necessary for emergency maneuvering, or roll angles up to 65 degrees. Spiral stability, which is introduced above 30 degrees of roll angle, must not require excessive pilot strength to achieve these roll angles. Other protections, which further limit the roll capability under certain extreme angle-of-attack, attitude, or high-speed conditions, are acceptable, as long as the airplane is able to perform coordinated turns as per § 25.143(h). A roll attitude limit of approximately 45 degrees at high angle-of-attack conditions is acceptable.

3. A reduced roll attitude limit is acceptable at extreme nose down pitch attitudes and beyond the overspeed warning to provide protection against high-speed combined pitch and roll upsets. The airplane should be able to perform operational turns at these speeds. A roll attitude limit of approximately 30 degrees at V_{df}/M_{df} is considered acceptable.

Issued in Des Moines, Washington.

Victor Wicklund,

Manager, Transport Standards Branch, Policy and Innovation Division, Aircraft Certification Service.

[FR Doc. 2018-16360 Filed 7-30-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2018-0630; Product Identifier 2018-NE-25-AD; Amendment 39-19347; AD 2018-16-07]

RIN 2120-AA64

Airworthiness Directives; General Electric Company Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain General Electric Company (GE) GENx-1B54, -1B58, -1B64, -1B67, -1B70, -1B54/P1, -1B58/P1, -1B64/P1, -1B67/

P1, -1B70/P1, -1B54/P2, -1B58/P2, -1B64/P2, -1B67/P2, -1B70/P2, -1B70C/P1, -1B70/72/P1, -1B70/75/P1, -1B74/75/P1, -1B75/P1, -1B70C/P2, -1B70/72/P2, -1B70/75/P2, -1B74/75/P2, -1B75/P2, -1B76/P2, -1B76A/P2, -1B78/P2, -2B67, -2B67B, and -2B67/P turbofan engines. This AD requires removal of affected high-pressure turbine (HPT) stator cases (HPT cases) from service and their replacement with a part eligible for installation. This AD was prompted by the discovery of a quality escape at a manufacturing facility. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective August 15, 2018.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of August 15, 2018.

We must receive comments on this AD by September 14, 2018.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
 - *Fax:* 202-493-2251.
 - *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
 - *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- For service information identified in this final rule, contact General Electric Company, GE Aviation, Room 285, 1 Neumann Way, Cincinnati, OH 45215; phone: 513-552-3272; email: aviation.fleetsupport@ge.com. You may view this service information at the FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7759. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0630.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0630; or in person at Docket Operations

between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations (phone: 800-647-5527) is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Herman Mak, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7147; fax: 781-238-7199; email: herman.mak@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We learned from GE of a quality escape at one of their suppliers. This supplier was performing welds on newly-manufactured components to correct errors introduced in their manufacturing process. These welds were not reviewed or approved by either GE or the FAA. GE's review of manufacturing records determined that these parts include HPT cases installed on GENx engines. These HPT cases are life limited. The unapproved repairs reduced the material capability of these cases which requires their removal prior to reaching their published Airworthiness Limitation Section life limit. This condition, if not addressed, could result in failure of the HPT case, engine fire, and damage to the airplane. We are issuing this AD to address the unsafe condition on these products.

Related Service Information Under 1 CFR Part 51

We reviewed GE Service Bulletin (SB) GENx-1B S/B 72-0424, Revision 03, dated June 29, 2018 and GENx-2B S/B 72-0360, Revision 03, dated June 29, 2018. The SBs describe procedures for removing the affected HPT cases from the engine. GE SB GENx-1B S/B 72-0424 is effective for GENx-1B engines with the serial numbers of HPT cases listed in that SB. GE SB GENx-2B S/B 72-0360 is effective for GENx-2B engines with the serial numbers of HPT cases listed in that SB. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Other Related Service Information

We reviewed Inspection 001, Subtask 72-52-01-230-001 of GENx-1B Cleaning, Inspection, and Repair Manual GEK112862, Rev 27, dated April 30, 2018, and GENx-2B Cleaning, Inspection, and Repair Manual

GEK114120, Rev 20, dated April 30, 2018. These manuals provide guidance for conducting Class A fluorescent penetrant inspections.

FAA's Determination

We are issuing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

AD Requirements

This AD requires removal of the affected HPT cases from service and their replacement with a part eligible for installation.

FAA's Justification and Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because the compliance time for the required action is shorter than the time necessary for the public to comment and for us to publish the final rule. Therefore, we find good cause that notice and opportunity for prior public comment are impracticable. In addition, for the reason stated above, we find that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment. However, we invite you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under the **ADDRESSES** section. Include the docket number FAA-2018-0630 and Product Identifier 2018-NE-25-AD at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this final rule. We will consider all comments received by the closing date and may amend this final rule because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this final rule.

Costs of Compliance

We estimate that this AD affects 13 engines installed on airplanes of U.S. registry.

We estimate the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replacement of HPT case	0 work-hours × \$85 per hour = \$0	\$362,400	\$362,400	\$4,711,200

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs" describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to engines, propellers, and associated appliances to the Manager, Engine and Propeller Standards Branch, Policy and Innovation Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2018–16–07 General Electric Company:
Amendment 39–19347; Docket No. FAA–2018–0630; Product Identifier 2018–NE–25–AD.

(a) Effective Date

This AD is effective August 15, 2018.

(b) Affected ADs

None.

(c) Applicability

This AD applies to General Electric Company (GE) GENx–1B54, –1B58, –1B64,

–1B67, –1B70, –1B54/P1, –1B58/P1, –1B64/P1, –1B67/P1, –1B70/P1, –1B54/P2, –1B58/P2, –1B64/P2, –1B67/P2, –1B70/P2, –1B70C/P1, –1B70/72/P1, –1B70/75/P1, –1B74/75/P1, –1B75/P1, –1B70C/P2, –1B70/72/P2, –1B70/75/P2, –1B74/75/P2, –1B75/P2, –1B76/P2, –1B76A/P2, –1B78/P2, –2B67, –2B67B, and –2B67/P turbofan engines with a high-pressure turbine (HPT) stator case (HPT case), part number (P/N) 2302M90G04 installed, and with any serial number (S/N) listed in Table 1, 2, or 3, in the Planning Information section of GE Service Bulletin (SB) GENx–2B S/B 72–0360, Revision 03, dated June 29, 2018, or GENx–1B S/B 72–0424, Revision 03, dated June 29, 2018, installed.

(d) Subject

Joint Aircraft System Component (JASC) Code 7250, Turbine Section.

(e) Unsafe Condition

This AD was prompted by the discovery of a quality escape at a manufacturing facility involving unapproved welds on HPT cases. We are issuing this AD to prevent failure of the HPT case. The unsafe condition, if not addressed, could result in engine fire and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) For HPT cases listed in Planning Information, Table 1 or 2, of GE SBs GENx–2B S/B 72–0360, Revision 03, dated June 29, 2018 and GENx–1B S/B 72–0424, Revision 03, dated June 29, 2018, determine the lesser of the following: Cycles since new (CSN) or cycles since Class A fluorescent penetrant inspection (CSFPI) of the entire HPT case.

(2) Using the determination made in paragraph (g)(1) of this AD, remove from service the HPT case after the effective date of this AD as specified in Table 1 to paragraph (g) of this AD. Replace the removed HPT case with a part eligible for installation.

Table 1 to Paragraph (g) of this AD – Compliance Times

CSN or CSFPI of HPT case	Remove from Service (cycles after the effective date of this AD)
Less than 1000	150 cycles
1000 to 2000	125 cycles
2001 to 3000	100 cycles
3001 to 4000	75 cycles
4001 to 5000	50 cycles
5001 or more	25 cycles

(3) Remove from service HPT cases listed in Planning Information, Table 3, of GE SBs GENx-2B S/B 72-0360, Revision 03, dated June 29, 2018 or GENx-1B S/B 72-0424, Revision 03, dated June 29, 2018, prior to exceeding 10 cycles after the effective date of this AD or exceeding the CSN limits listed in Table 3, whichever comes later. Replace the removed HPT case with a part eligible for installation.

(h) Installation Prohibition

(1) After the effective date of this AD, do not install any affected HPT case onto any engine.

(2) After the effective date of this AD, HPT cases listed in Planning Information, Table 3, in GE SB GENx-2B S/B 72-0360, Revision 03, dated June 29, 2018 or GENx-1B S/B 72-0424, Revision 03, dated June 29, 2018, and any higher level assemblies with these parts installed, may not be removed from a GENx-2B engine and installed on a GENx-1B engine or removed from a GENx-1B engine and installed on a GENx-2B engine.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

For more information about this AD, contact Herman Mak, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7147; fax: 781-238-7199; email: herman.mak@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) General Electric Company (GE) Service Bulletin (SB) GENx-2B S/B 72-0360, Revision 03, dated June 29, 2018.

(ii) GE SB GENx-1B S/B 72-0424, Revision 03, dated June 29, 2018.

(3) For GE service information identified in this AD, contact General Electric Company, GE Aviation, Room 285, 1 Neumann Way, Cincinnati, OH 45215; phone: 513-552-3272; email: aviation.fleetsupport@ge.com.

(4) You may view this service information at FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7759.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on July 25, 2018.

Karen M. Grant,

Acting Manager, Engine & Propeller Standards Branch, Aircraft Certification Service.

[FR Doc. 2018-16309 Filed 7-30-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF ENERGY

Federal Energy Regulatory Commission

18 CFR Part 40

[Docket No. RM18-2-000; Order No. 848]

Cyber Security Incident Reporting Reliability Standards

AGENCY: Federal Energy Regulatory Commission.

ACTION: Final rule.

SUMMARY: The Federal Energy Regulatory Commission (Commission) directs the North American Electric Reliability Corporation (NERC) to develop and submit modifications to the NERC Reliability Standards to augment the mandatory reporting of Cyber Security Incidents, including incidents that might facilitate subsequent efforts to harm the reliable operation of the bulk electric system (BES).

DATES: This rule will become effective October 1, 2018.

FOR FURTHER INFORMATION CONTACT:

Margaret Steiner (Technical Information), Office of Electric Reliability, Federal Energy Regulatory Commission, 888 First Street NE, Washington, DC 20426, (202) 502-6704, Margaret.Steiner@ferc.gov.

Kevin Ryan (Legal Information), Office of the General Counsel, Federal Energy Regulatory Commission, 888 First Street NE, Washington, DC 20426, (202) 502-6840, Kevin.Ryan@ferc.gov.

SUPPLEMENTARY INFORMATION:

Order No. 848—Final Rule (Issued July 19, 2018)

1. Pursuant to section 215(d)(5) of the Federal Power Act (FPA), the Commission directs the North American Electric Reliability Corporation (NERC) to develop and submit modifications to