

Rules and Regulations

Federal Register

Vol. 67, No. 152

Wednesday, August 7, 2002

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002–NM–130–AD; Amendment 39–12840; AD 2002–16–01]

RIN 2120–AA64

Airworthiness Directives; McDonnell Douglas Model DC–8–21, –31, –32, –33, –41, –42, and –43 Airplanes; and Model DC–8–50, –60, and –70 Series Airplanes; Modified per Supplemental Type Certificates SA1063SO, SA1862SO, or SA1832SO

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to certain McDonnell Douglas Model DC–8–21, –31, –32, –33, –41, –42, and –43 airplanes; and certain Model DC–8–50, –60, and –70 series airplanes; that have been converted from a passenger-to a cargo-carrying (“freighter”) configuration. This action requires gaining access to the floor beam attachments to the lower door jamb within the main cargo door area; performing repetitive inspections to detect cracking or damage of such attachments, including splice plates, angles, and clips; and, if necessary, expanding the inspection area and replacing any cracked or damaged part with a new part. This action is necessary to prevent failure of such floor beam attachments during ground or flight operations, which could cause damage to the floor structure and consequent jamming of the flight control cables, and result in loss of controllability of the airplane in flight.

DATES: Effective August 22, 2002.

Comments for inclusion in the Rules Docket must be received on or before October 7, 2002.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM–114, Attention: Rules Docket No. 2002–NM–130–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227–1232. Comments may also be sent via the Internet using the following address: 9-anm-iarccomment@faa.gov. Comments sent via fax or the Internet must contain “Docket No. 2002–NM–130–AD” in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

Information pertaining to this amendment may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Atlanta Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia.

FOR FURTHER INFORMATION CONTACT: *Technical Information:* Hassan Amini, Aerospace Engineer, Airframe and Propulsion Branch, ACE–117A, FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30349; telephone (770) 703–6080; fax (770) 703–6097.

Other Information: Sandi Carli, Airworthiness Directive Technical Editor/Writer; telephone (425) 687–4243, fax (425) 687–4271. Questions or comments may also be sent via the Internet using the following address: sandi.carli@faa.gov. Questions or comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

SUPPLEMENTARY INFORMATION: The FAA has received several reports of findings of cracked or broken angles and splice plates on floor beam attachments to the lower door jamb of the main cargo door area on certain McDonnell Douglas Model DC–8–21, –31, –32, –33, –41, –42, and –43 airplanes; and Model DC–8–50, –60, and –70 series airplanes. One

report revealed that, during a routine C-check on a Model DC–8–62 airplane, fractures were found in 9 of 11 of the floor beam attachments to the lower door jamb. Findings indicate that such fractures could be due to factors associated with flight operations and/or loading operations on the ground. Such conditions, if not corrected, could cause failure of such floor beam attachments during ground or flight operations. This could cause damage to the floor structure and consequent jamming of the control cables, and result in loss of controllability of the airplane in flight.

Explanation of Requirements of the Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design, this AD is being issued to prevent failure of the floor beam attachments to the lower door jamb. Such failure could cause damage to the floor structure and consequent jamming of the flight control cables, and result in loss of controllability of the airplane in flight. This AD requires gaining access to the floor beam attachments to the lower door jamb within the main cargo door area; and performing repetitive inspections to detect cracking or damage of such attachments, including splice plates, angles, and clips. If any cracking or damage is found, this AD also requires extending the area of inspection 60 inches forward and aft of the main cargo door area, and replacing any cracked or damaged part with a new part. Figure 1 of Appendix 1 of this AD identifies the inspection area and parts to be inspected.

This AD also requires operators to report the results of any detailed inspection required by paragraph (a) of this AD to the FAA.

Interim Action

This is considered to be interim action until final action is identified, at which time the FAA may consider further rulemaking. Because the cause of the addressed cracking or damage is not currently known, the intent of the required inspection report is to enable the FAA to determine how widespread such cracking or damage may be in the affected fleet. Based on the results of this report, further corrective action may be warranted.

Determination of Rule's Effective Date

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

Although this action is in the form of a final rule that involves requirements affecting flight safety and, thus, was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2002-NM-130-AD." The postcard will be date stamped and returned to the commenter.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2002-16-01 McDonnell

Douglas: Amendment 39-12840. Docket 2002-NM-130-AD.

Applicability: This AD applies to airplanes that have been converted from a passenger-to a cargo-carrying ("freighter") configuration per Supplemental Type Certificate SA1063SO, SA1862SO, or SA1832SO; certificated in any category; as listed in the following table:

TABLE—APPLICABILITY

Airplane Models
DC-8-21, -31, -32, -33, -41, -42, and -43 airplanes;
DC-8-51, -52, -53, and -55 airplanes;
DC-8-61, -62, and -63 airplanes; and
DC-8-71, -72, and -73 airplanes.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the floor beam attachments to the lower door jamb of the main cargo door due to cracking or damage during ground or flight operations, which could cause damage to the floor structure and consequent jamming of the flight control cables, and result in loss of controllability of the airplane in flight; accomplish the following:

Gaining Access and Repetitive Inspections

(a) Within 50 flight hours or 60 days after the effective date of this AD, whichever occurs later, accomplish the actions required by paragraphs (a)(1) and (a)(2) of this AD.

(1) Gain access to the floor beam attachments to the lower door jamb within the main cargo door area by removing the cargo handling system (including ball mats, roller trays, and pallet locks), floor panels, and cargo liner of the lower baggage compartment as necessary to access both sides of the floor beam attachments.

(2) Perform a detailed inspection of the main cargo door area to detect any cracking or damage of the floor beam attachments to the lower door jamb, including the splice plates, angles, and clips identified in Figure 1 of Appendix 1 of this AD. Thereafter, repeat the inspection at intervals not to exceed 2,500 flight cycles or 18 months, whichever occurs earlier.

Note 2: For the purposes of this AD, a detailed inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

Extending Inspection Area and Replacement

(b) If any cracking or damage is found during any inspection required by paragraph (a)(2) of this AD, before further flight, extend the area of inspection 60 inches forward and aft of the main cargo door area, and replace any cracked or damaged part with a new part identified in Figure 1 of Appendix 1 of this AD.

Reporting Requirement

(c) Within 10 days after performing any inspection required by paragraph (a)(2) of this AD: Send a report of the inspection findings to the Manager, Atlanta Aircraft Certification Office (ACO), One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30349; telephone (770) 703-6080; fax (770) 703-6097. The report must include the inspection results, including a description of any cracking or damage found, crack location and length, part number of any

cracked or damaged part, airplane serial number, number of flight cycles and flight hours on the airplane, and number of flight cycles and flight hours after the airplane was converted from a passenger-to a cargo-carrying ("freighter") configuration. Information collection requirements contained in this AD have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*) and have been assigned OMB Control Number 2120-0056.

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Atlanta ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add

comments and then send it to the Manager, Atlanta ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Atlanta ACO.

Special Flight Permits

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Effective Date

(f) This amendment becomes effective on August 22, 2002.

Appendix 1

BILLING CODE 4910-13-P




Figure 1.

Issued in Renton, Washington, on July 29, 2002.

Vi L. Lipski,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. 02-19879 Filed 8-6-02; 8:45 am]

BILLING CODE 4910-13-C

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-SW-24-AD; Amendment 39-12839; AD 2002-09-51]

RIN 2120-AA64

Airworthiness Directives; Bell Helicopter Textron, Inc. Model 204B, 205A, A-1, and B Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This document publishes in the **Federal Register** an amendment adopting Emergency Airworthiness Directive (EAD) 2002-09-51, sent previously to all known U.S. owners and operators of specified Bell Helicopter Textron, Inc. (Bell) model helicopters by individual letters. This AD requires cleaning and inspecting the tail rotor (T/R) grip to determine if the grip is made of steel and replacing any grip not made of steel with an airworthy, steel TR grip. This AD is prompted by reports of a certain timed-out life limited T/R grips being improperly identified and reinstalled on Bell Model 204B, 205A, A-1, and B helicopters. The actions specified by this AD are intended to prevent failure of the T/R grip and subsequent loss of helicopter control.

DATES: Effective August 22, 2002, to all persons except those persons to whom it was made immediately effective by EAD 2002-09-51, issued on May 9, 2002, which contained the requirements of this amendment.

Comments for inclusion in the Rules Docket must be received on or before October 7, 2002.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Office of the Regional Counsel, Southwest Region, Attention: Rules Docket No. 2002-SW-24-AD, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. You may also send comments electronically to the Rules Docket at the following address: 9-asw-adcomments@faa.gov.

FOR FURTHER INFORMATION CONTACT:

Kennedy Jones, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Rotorcraft Certification Office, Fort Worth, Texas 76193-0170, telephone (817) 222-5148, fax (817) 222-5783.

SUPPLEMENTARY INFORMATION: On May 9, 2002, the FAA superseded EAD 2002-08-53, issued April 22, 2002, with EAD 2002-09-51, issued May 9, 2002. EAD 2002-08-53 required, before further flight, cleaning and inspecting certain T/R grips and removing each unairworthy grip not made of steel. EAD 2002-09-51 retains those requirements and in addition corrects a statement in the preamble that T/R grip, part number (P/N) 205-011-711-101, has an unlimited life. That T/R grip has a life limit of 2,500 hours time-in-service. Also, EAD 2002-09-51 adds the Bell Model 204B helicopter to the applicability and clarifies the inspection requirements by specifying that the magnet be placed on the T/R grip body and not on the steel bushing or steel interior liner to determine if the grip is made of steel. EAD 2002-08-53, was prompted by reports that T/R grips, P/N 204-011-728-019, required to be removed from service by AD 73-17-04 (38 FR 22223, August 17, 1973), were being re-marked as P/N 205-011-711-101 and installed on certain Bell model helicopters. EAD 2002-09-51 was prompted by information from the manufacturer stating that the Bell Model 204B helicopter should be added to the applicability because the unairworthy grips could be installed on that model. This condition, if not detected, could result in failure of the T/R grip and subsequent loss of helicopter control.

This unsafe condition is likely to exist or develop on other Bell model helicopters of the same type design. Therefore, this AD requires cleaning and inspecting the T/R grip to determine if the grip is made of steel by placing a magnet on the exterior of the main body of the T/R grip. If the T/R grip is not made of steel, it must be removed from service. The short compliance time involved is required because the previously described critical unsafe condition can adversely affect the controllability of the helicopter. Therefore, this AD requires, before further flight, that you clean and inspect the T/R grip to determine if the grip is made of steel and remove any grip that is not made of steel, and this AD must be issued immediately.

Since it was found that immediate corrective action was required, notice and opportunity for prior public comment thereon were impracticable and contrary to the public interest, and

good cause existed to make the AD effective immediately by individual letters issued on May 9, 2002, to all known U.S. owners and operators of Bell Model 204B, 205A, A-1, and B helicopters. These conditions still exist, and the AD is hereby published in the **Federal Register** as an amendment to 14 CFR 39.13 to make it effective to all persons.

The FAA estimates that this AD will affect 269 helicopters of U.S. registry, that the required actions will take approximately 2 work hours per helicopter to accomplish, and that the average labor rate is \$60 per work hour. Required parts will cost approximately \$4864 per helicopter. Based on these figures, the FAA estimates the total cost impact of the AD on U.S. operators will be \$1,340,696 to clean, inspect, and replace one T/R grip on each helicopter in the entire fleet.

Comments Invited

Although this action is in the form of a final rule that involves requirements affecting flight safety and, thus, was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their mailed comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 2002-SW-24-AD." The postcard will be date