

TABLE 1.—INITIAL INSPECTIONS—Continued

AWL No.	Description	Compliance time (whichever occurs later)	
		Threshold	Grace period
28-AWL-10 .....	A special detailed inspection of the fault current bond of the fueling shutoff valve actuator of the center wing tank to verify electrical bond.	Within 144 months since the date of issuance of the original standard airworthiness certificate or the date of issuance of the original export certificate of airworthiness.	Within 60 months after the effective date of this AD.

#### Incorporation of Additional AWLs for Certain Airplanes

(i) For Model 747-400 series airplanes equipped with an auxiliary fuel tank: Before December 16, 2008, revise the FAA-approved maintenance program by incorporating AWLs No. 28-AWL-30, No. 28-AWL-31, and No. 28-AWL-32 of Subsection D of Revision March 2008 of the MPD. Accomplishing the revision in accordance with a later revision of the MPD is an acceptable method of compliance if the revision is approved by the Manager, Seattle ACO.

#### No Alternative Inspections, Inspection Intervals, or Critical Design Configuration Control Limitations (CDCCLs)

(j) After accomplishing the applicable actions specified in paragraphs (g), (h), and (i) of this AD, no alternative inspections, inspection intervals, or CDCCLs may be used unless the inspections, intervals, or CDCCLs are part of a later revision of Revision March 2008 of the MPD that is approved by the Manager, Seattle ACO; or unless the inspections, intervals, or CDCCLs are approved as an AMOC in accordance with the procedures specified in paragraph (l) of this AD.

#### Credit for Actions Done According to Previous Revisions of the MPD

(k) Actions done before the effective date of this AD in accordance with Section 9 of the Boeing 747-400 MPD Document, D621U400-9, Revision 23, dated March 2006; Revision 24, dated June 2006; Revision November 2006; Revision December 2006; Revision December 2006 R1; Revision May 2007; Revision October 2007; or Revision November 2007; are acceptable for compliance with the corresponding requirements of paragraphs (g) and (h) of this AD.

#### Alternative Methods of Compliance (AMOCs)

(l)(1) The Manager, Seattle ACO, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

#### Material Incorporated by Reference

(m) You must use Boeing Temporary Revision 09-010, dated March 2008, to the Boeing 747-400 Maintenance Planning Data (MPD) Document, D621U400-9, to do the actions required by this AD, unless the AD specifies otherwise. Boeing Temporary Revision 09-010 is published as Section 9 of the Boeing 747-400 Maintenance Planning Data (MPD) Document, D621U400-9, Revision March 2008.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

(3) You may review copies of the service information incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Renton, Washington, on April 28, 2008.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate,  
Aircraft Certification Service.*

[FR Doc. E8-9897 Filed 5-7-08; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

**[Docket No. FAA-2007-0045; Directorate Identifier 2007-NM-169-AD; Amendment 39-15501; AD 2008-09-20]**

**RIN 2120-AA64**

#### **Airworthiness Directives; Boeing Model 747-200F, 747-300, 747-400, and 747-400D Series Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain Boeing Model 747-200F, 747-300, 747-400, and 747-400D series airplanes. This AD requires a detailed inspection to detect missing fasteners from the shear clip at a certain stub frame to auxiliary sill joint, and applicable related investigative and corrective actions. This AD results from reports of missing fasteners from the shear clip of the stub frame to auxiliary sill joint and cracking of the adjacent exterior skin and internal doubler. We are issuing this AD to ensure that fasteners are installed in the shear clip of the stub frame to auxiliary sill joint. Missing fasteners could result in cracks in the adjacent exterior skin and internal doubler, which can propagate and result in loss of structural integrity and sudden in-flight decompression of the airplane.

**DATES:** This AD is effective June 12, 2008.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of June 12, 2008.

**ADDRESSES:** For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

#### **Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Ivan Li, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind

Avenue SW., Renton, Washington 98057-3356; telephone (425) 917-6437; fax (425) 917-6590.

#### SUPPLEMENTARY INFORMATION:

#### Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an airworthiness directive (AD) that would apply to certain Boeing Model 747-200F, 747-300, 747-400, and 747-400D series airplanes. That NPRM was published in the **Federal Register** on October 17, 2007 (72 FR 58768). That NPRM proposed to require a detailed inspection to detect missing fasteners from the shear clip at a certain stub frame to auxiliary sill joint, and applicable related investigative and corrective actions.

#### New Service Bulletin Revision

Since we issued the NPRM, we have reviewed Boeing Service Bulletin 747-53A2685, Revision 1, dated March 13, 2008. Revision 1 clarifies certain figures and part and material content. No additional work is necessary for airplanes on which the actions have been done in accordance with Boeing Alert Service Bulletin 747-53A2685, dated May 31, 2007 (referred to as the appropriate source of service information for accomplishing the actions specified in the NPRM). We have revised paragraphs (c), (f), and (g) of this AD to refer to Boeing Service Bulletin 747-53A2685, Revision 1, dated March 13, 2008. We have added a new paragraph (h) of this AD to give credit for actions done before the effective date of this AD according to Boeing Alert Service Bulletin 747-53A2685, dated May 31, 2007, and redesignated subsequent paragraphs of the AD accordingly.

#### Comments

We gave the public the opportunity to participate in developing this AD. We considered the comments received from two commenters. Boeing requested that Boeing Service Bulletin 747-53A2685, Revision 1, dated March 13, 2008, be used instead of Boeing Alert Service Bulletin 747-53A2685, dated May 31, 2007. All Nippon Airways requested clarification of technical information in the NPRM. These requests have been addressed in Revision 1 of the service bulletin, which is cited in the final rule.

#### Conclusion

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting the AD with the changes described previously.

We also determined that these changes will not increase the economic burden on any operator or increase the scope of the AD.

#### Costs of Compliance

There are about 98 airplanes of the affected design in the worldwide fleet. This AD affects about 8 airplanes of U.S. registry. The required actions take about 1 work hour per airplane, at an average labor rate of \$80 per work hour. Based on these figures, the estimated cost of the AD for U.S. operators is \$640, or \$80 per airplane.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979), and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

You can find our regulatory evaluation and the estimated costs of compliance in the AD Docket.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

**2008-09-20 Boeing:** Amendment 39-15501. Docket No. FAA-2007-0045; Directorate Identifier 2007-NM-169-AD.

#### Effective Date

(a) This airworthiness directive (AD) is effective June 12, 2008.

#### Affected ADs

(b) None.

#### Applicability

(c) This AD applies to Boeing Model 747-200F, 747-300, 747-400, and 747-400D series airplanes, certificated in any category; as identified in Boeing Service Bulletin 747-53A2685, Revision 1, dated March 13, 2008.

#### Unsafe Condition

(d) This AD results from two reports of cracks found in the exterior skin and internal doubler adjacent to the shear clip at the stub frame to auxiliary sill joint at stringer 30 (left and right sides), body station (BS) 488. In addition, on one of the airplanes, seven fasteners were missing from the shear clip on the left side of the airplane. The cause of the missing fasteners has been attributed to a manufacturing process error. We are issuing this AD to ensure fasteners in the shear clip of the stub frame to auxiliary sill joints (left and right sides) are installed. Missing fasteners could result in cracks in the adjacent exterior skin and internal doubler, which can propagate and result in loss of structural integrity and sudden in-flight decompression of the airplane.

#### Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

#### Inspection and Applicable Related Investigative and Corrective Actions

(f) At the applicable compliance time and repeat intervals listed in Tables 1 and 2 of paragraph 1.E., "Compliance," of Boeing Service Bulletin 747-53A2685, Revision 1, dated March 13, 2008; except where the service bulletin specifies a compliance time

after the date on the service bulletin, this AD requires compliance within the specified compliance time after the effective date of this AD: Do the inspection and applicable related investigative and corrective actions by accomplishing all the applicable actions specified in the Accomplishment Instructions of the service bulletin, except as provided by paragraph (g) of this AD.

#### Repair of Cracks

(g) If any crack is found during any inspection required by this AD, and Boeing Service Bulletin 747-53A2685, Revision 1, dated March 13, 2008, specifies to contact Boeing for appropriate action: Before further flight, repair the crack using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

#### Credit for Actions Done Using the Previous Service Information

(h) Actions accomplished before the effective date of this AD in accordance with Boeing Alert Service Bulletin 747-53A2685, dated May 31, 2007, are considered acceptable for compliance with the corresponding actions specified in paragraph (f) of this AD.

#### Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings.

#### Material Incorporated by Reference

(j) You must use Boeing Service Bulletin 747-53A2685, Revision 1, dated March 13, 2008, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

(3) You may review copies of the service information incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: [http://www.archives.gov/federal\\_register/](http://www.archives.gov/federal_register/)

[code\\_of\\_federal\\_regulations/ibr\\_locations.html](#).

Issued in Renton, Washington, on April 23, 2008.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate,  
Aircraft Certification Service.*

[FR Doc. E8-9894 Filed 5-7-08; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2008-0067; Airspace  
Docket No. 08-ANE-98]

#### Establishment of Class E Airspace; Rockport, ME

**AGENCY:** Federal Aviation  
Administration (FAA), DOT.

**ACTION:** Final rule, confirmation of  
effective date.

**SUMMARY:** This action confirms the effective date of a direct final rule published in the **Federal Register** (73 FR 9442) that establishes Class E Airspace at Rockport, ME to support a new Area Navigation (RNAV) Global Positioning System (GPS) Special Instrument Approach Procedure (IAP) that has been developed for medical flight operations into the Penobscot Bay Medical Center.

**DATES:** Effective 0901 UTC, June 5, 2008. The Director of the Federal Register approves this incorporation by reference action under title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

**FOR FURTHER INFORMATION CONTACT:**  
Melinda Giddens, System Support  
Group, Eastern Service Center, Federal  
Aviation Administration, P.O. Box  
20636, Atlanta, Georgia 30320;  
telephone (404) 305-5610.

#### SUPPLEMENTARY INFORMATION:

##### Confirmation of Effective Date

The FAA published this direct final rule with a request for comments in the **Federal Register** on February 21, 2008 (73 FR 9442), Docket No. FAA-2008-0067; Airspace Docket No. 08-ANE-98. The FAA uses the direct final rulemaking procedure for a non-controversial rule where the FAA believes that there will be no adverse public comment. This direct final rule advised the public that no adverse comments were anticipated, and that unless a written adverse comment, or a

written notice of intent to submit such an adverse comment, were received within the comment period, the regulation would become effective on June 5, 2008. No adverse comments were received, and thus this notice confirms that effective date.

Issued in College Park, Georgia, on April 18, 2008.

**John D. Haley,**

*Acting Manager, System Support Group,  
Eastern Service Center, Air Traffic  
Organization.*

[FR Doc. E8-9848 Filed 5-7-08; 8:45 am]

**BILLING CODE 4910-13-M**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2008-0060; Airspace  
Docket No. 08-ANE-91]

#### Establishment of Class E Airspace; Swans Island, ME

**AGENCY:** Federal Aviation  
Administration (FAA), DOT.

**ACTION:** Final rule, confirmation of  
effective date.

**SUMMARY:** This action confirms the effective date of a direct final rule published in the **Federal Register** (73 FR 9183) that establishes Class E Airspace at Swans Island, ME to support a new Area Navigation (RNAV) Global Positioning System (GPS) Special Instrument Approach Procedure (IAP) that has been developed for medical flight operations into the Swans Island Heliport.

**DATES:** Effective 0901 UTC, June 5, 2008. The Director of the Federal Register approves this incorporation by reference action under title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

**FOR FURTHER INFORMATION CONTACT:**  
Melinda Giddens, System Support  
Group, Eastern Service Center, Federal  
Aviation Administration, P. O. Box  
20636, Atlanta, Georgia 30320;  
telephone (404) 305-5610.

#### SUPPLEMENTARY INFORMATION:

##### Confirmation of Effective Date

The FAA published this direct final rule with a request for comments in the **Federal Register** on February 20, 2008 (73 FR 9183), Docket No. FAA-2008-0060; Airspace Docket No. 08-ANE-91. The FAA uses the direct final rulemaking procedure for a non-