

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2002–NM–293–AD." The postcard will be date stamped and returned to the commenter.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2002–26–06 Dornier Luftfahrt GMBH:

Amendment 39–12994. Docket 2002–NM–293–AD.

Applicability: All Model 328–300 series airplanes, certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent operation in weight/altitude/temperature conditions that exceed the performance capabilities of the airplane, which could result in impact with terrain during engine out performance-limited operations; accomplish the following:

Airplane Flight Manual Revision

(a) Within 7 days after the effective date of this AD: Revise the Performance Section of the Dornier 328–300 Airplane Flight Manual (AFM) to incorporate revised performance data for certain operations; as specified in Dornier 328 J All Operators Telefax (AOT) AOT–328J–00–006, dated October 1, 2002. This may be accomplished by inserting a copy of the AOT into the AFM.

(b) The AOT may be removed from the AFM when the revised performance data in the AOT specified in paragraph (a) of this AD has been incorporated into a general revision of the AFM.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA. Operators shall submit their requests through an appropriate FAA Principal Operations Inspector, who may add comments and then send it to the Manager, International Branch, ANM–116.

Note 1: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM–116.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(e) The AFM revision required by paragraph (a) of this AD shall be done in accordance with Dornier 328 J All Operators Telefax AOT–328J–00–006, dated October 1, 2002. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Fairchild Dornier, Dornier Luftfahrt GmbH, PO Box 1103, D–82230 Wessling, Germany. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the *Office of the Federal Register*, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 2: The subject of this AD is addressed in German airworthiness directive 2002–355, dated November 14, 2002.

Effective Date

(f) This amendment becomes effective on January 17, 2003.

Issued in Renton, Washington, on December 23, 2002.

Vi L. Lipski,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02–32879 Filed 12–31–02; 8:45 am]

BILLING CODE 4910–13–U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97–ANE–44–AD; Amendment 39–12989; AD 2000–16–02R1]

RIN 2120–AA64

Airworthiness Directives; Pratt & Whitney PW4164, PW4168, and PW4168A Series Turbofan Engines

AGENCY: Federal Aviation Administration, (DOT).

ACTION: Final rule.

SUMMARY: This amendment revises an existing airworthiness directive (AD), that is applicable to Pratt & Whitney PW4164, PW4168, and PW4168A series turbofan engines. That AD currently requires initial and repetitive torque checks for loose or broken front pylon mount bolts made from INCO 718 material and MP159 material. That AD also requires initial and repetitive visual inspections of the primary mount thrust load path. This amendment requires extension of the cycles accumulated before performing the initial inspection, reduces the frequency of repetitive inspections for MP159 material bolts, and adds a terminating action to the primary mount thrust load path inspections by introducing a new increased durability forward engine mount bearing housing. This amendment is prompted by component testing to assess the low cycle fatigue (LCF) life of the MP159 material bolts and the development of a new design forward engine mount bearing housing that meets the 8,000 flight cycle design intent for inspection. The actions specified by this AD are intended to prevent front pylon mount bolt and primary mount thrust load path failure, which could result in an engine separating from the airplane.

DATES: Effective February 6, 2003. The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of February 6, 2003. The incorporation by reference of certain other publications, as listed in the regulations, was approved previously by the Director of the Federal Register as of

October 16, 2002 (65 FR 49730; August 15, 2002).

ADDRESSES: The service information referenced in this AD may be obtained from Pratt & Whitney, 400 Main St., East Hartford, CT 06108; telephone (860) 565-8860; fax (860) 565-4503. This information may be examined, by appointment, at the Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Diane Cook, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (781) 239-7133; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) by revising AD 2000-16-02, Amendment 39-11856 (65 FR 49730, August 15, 2000), which is applicable to Pratt & Whitney PW4164, PW4168, and PW4168A series turbofan engines was published in the **Federal Register** on September 13, 2002 (67 FR 57987). That action proposed to require an extension of the cycles accumulated before performing the initial inspection for the MP 159 material bolts, reduce the frequency of repetitive inspections for MP159 material bolts, and add a terminating action to the primary mount thrust load path inspections by introducing a new increased durability forward engine mount bearing housing in accordance with Pratt & Whitney alert service bulletins (ASB's) PW4G-100-A71-9, Revision 1, dated November 24, 1997; ASB PW4G-100-A71-20, Revision 1, dated January 15, 2002; ASB PW4G-100-A71-18, Revision 2, dated January 15, 2002; and service bulletin (SB) PW4G-100-A71-22, dated January 15, 2002.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the comment received.

One commenter concurs with the proposed AD and states that the proposed AD is consistent with all appropriate PW service bulletins. The FAA agrees.

After careful review of the available data, including the comment noted above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed. The

FAA has determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

Economic Analysis

There are approximately 226 engines of the affected design in the worldwide fleet. The FAA estimates that 21 engines installed on aircraft of U.S. registry would be affected by this AD. The FAA also estimates that it would take approximately 3 work hours per engine to perform the actions, and that the average labor rate is \$60 per work hour. Required parts would cost approximately \$19,000 per engine. Based on these figures, the total cost of the AD to U.S. operators is estimated to be \$402,780.

Regulatory Analysis

This final rule does not have federalism implications, as defined in Executive Order 13132, because it would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Accordingly, the FAA has not consulted with state authorities prior to publication of this final rule.

For the reasons discussed above, I certify that this action (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing Amendment 39-11856 (65 FR 49730, August 15, 2000) and by adding a new airworthiness directive, Amendment 39-12989, to read as follows:

2000-16-02R1 Pratt & Whitney: Amendment 39-12989. Docket No. 97-ANE-44-AD. Revises AD 2000-16-02, Amendment 39-11856.

Applicability: This airworthiness directive (AD) is applicable to Pratt & Whitney PW4164, PW4168, and PW4168A series turbofan engines, with front pylon mount bolts, part numbers (P/N's) 54T670 or 51U615, installed. These engines are installed on but not limited to Airbus Industrie A330 series airplanes.

Note 1: This AD applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (f) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Compliance with this AD is required as indicated, unless already done.

To prevent front pylon mount bolt and primary mount thrust load path failure, which could result in engine separation from the airplane, do the following:

INCO 718 Material Bolts Torque Checks

(a) Perform initial and repetitive torque checks of INCO 718 material front pylon mount bolts, P/N 54T670, and replace, if necessary, with new bolts, in accordance with the Accomplishment Instructions of PW Alert Service Bulletin (ASB) No. PW4G-100-A71-9, Revision 1, dated November 24, 1997, as follows:

(1) For front pylon mount bolts, P/N 54T670, with fewer than 1,000 cycles-in-service-since-new (CSN) on the effective date of this AD, accomplish the following in accordance with Part (A) of the Accomplishment Instructions of the ASB:

(i) Perform an initial torque check prior to accumulating 1,250 CSN or at the next engine removal for cause, whichever occurs first.

(ii) Thereafter, perform torque checks at intervals of not less than 750 or greater than 1,250 cycles in service (CIS) since last torque check, not to exceed 11,000 CSN.

(2) For front pylon mount bolts, P/N 54T670, with 1,000 or more CSN but less than 5,750 CSN on the effective date of this AD, accomplish the following in accordance with Part (A) of the Accomplishment Instructions of the ASB:

(i) Perform an initial torque check within 250 CIS after the effective date of this AD, or

at the next engine removal for any cause, whichever occurs first.

(ii) Thereafter, perform torque checks at intervals of not less than 750 or greater than 1,250 CIS since last torque check, not to exceed 11,000 CSN.

(3) For front pylon mount bolts, P/N 54T670, with 5,750 or more CSN on the effective date of this AD, accomplish the following in accordance with Part (B) of the Accomplishment Instructions of the ASB:

(i) Perform an initial torque check within 250 CIS after the effective date of this AD, or prior to the next engine removal for any cause, whichever occurs first.

(ii) Thereafter, perform torque checks at intervals of not less than 750 or greater than 1,250 CIS since last torque check, not to exceed 11,000 CSN.

(4) Prior to further flight, replace all four bolts in accordance with Part (A), Paragraph 1(D) of the Accomplishment Instructions of the ASB, if any of the bolts are loose or broken.

INCO 718 Material Bolts Life Limit

(b) This AD establishes a new life limit of 11,000 CSN for front pylon mount bolts, P/N 54T670. Except as provided in paragraph (f) of this AD, no front pylon mount bolts, P/N 54T670, may exceed this new life limit after the effective date of this AD.

MP159 Material Bolts Inspections

(c) Perform initial and repetitive torque inspections of front pylon mount bolts, P/N 51U615, in accordance with the Accomplishment Instructions of Pratt & Whitney ASB PW4G-100-A71-20, Revision 1, dated January 15, 2002, as follows:

(1) For front pylon mount bolts with less than 4,100 CSN on the effective date of this AD, perform the initial torque inspection at the earlier of the following:

(i) Before accumulating 4,350 CSN; or
(ii) The next engine removal for any cause.

(2) For front pylon mount bolts with 4,100 or more CSN on the effective date of this AD, perform the initial torque check at the earlier of the following:

(i) Within 250 CIS after the effective date of this AD; or

(ii) The next engine removal for any cause.

(3) Thereafter, perform torque inspections at intervals not to exceed 4,350 CIS since last torque inspection.

(4) Prior to further flight, replace all four bolts, in accordance with Paragraph 1(D) of the Accomplishment Instructions of the ASB, if any are loose or broken.

Primary Mount Thrust Load Path Inspections

(d) Perform initial and repetitive visual inspections of the primary mount thrust load path, in accordance with the Accomplishment Instructions of PW ASB PW4G-100-A71-18, Revision 2, dated January 15, 2002, as follows:

(1) For forward engine mount assemblies with fewer than 1,000 CSN on the effective date of this AD, perform the initial visual inspection at the earlier of the following:

(i) Before accumulating 1,250 CSN; or
(ii) The next engine removal for any cause.

(2) For forward engine mount assemblies with 1,000 or more CSN on the effective date of this AD, perform the initial visual inspection at the earlier of the following:

(i) Within 250 CIS after the effective date of this AD; or

(ii) The next engine removal for any cause.

(3) Thereafter, perform visual inspections at intervals of not less than 750 or greater than 1,250 CIS since last visual inspection.

(4) Prior to further flight, replace all cracked parts with serviceable parts and

inspect the primary thrust load path components in accordance with Paragraph 4 of the accomplishment instructions of the SB.

Terminating Action

(e) Replacement of the forward engine mount bearing housing, P/N 59T794 or P/N 54T659 with P/N 52U420 in accordance with Service Bulletin (SB) PW 4G-100-71-22, dated January 15, 2002, constitutes terminating action to the inspection requirements of paragraph (d) of this AD.

Alternative Methods of Compliance

(f) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office (ECO). Operators must submit their request through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, ECO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the ECO.

Special Flight Permits

(g) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be done.

Documents That Have Been Incorporated By Reference

(h) The inspections must be done in accordance with the following Pratt & Whitney (PW) alert service bulletins (ASB's) and service bulletin (SB):

Document No.	Pages	Revision	Date
ASB PW4G-100-A71-9	1	1	Nov. 24, 1997.
	2	Original	July 31, 1997.
	3	1	Nov. 24, 1997.
	4-7	Original	July 31, 1997.
	8-9	1	Nov. 24, 1997.
	10-11	Original	July 31, 1997.
Total Pages: 11			
ASB PW4G-100-A71-20	1	1	Jan. 15, 2002.
	2	Original	Dec. 9, 1999.
	3-5	1	Jan. 15, 2002.
	6-7	Original	Dec. 9, 1999.
	8	1	Jan. 15, 2002.
	9	Original	Dec. 9, 1999.
	10	1	Jan. 15, 2002.
Total Pages: 10			
ASB PW4G-100-A71-18	1-2	2	Jan. 15, 2002.
	3	1	Dec. 9, 1999.
	4	2	Jan. 15, 2002.
	5-6	Original	Sept. 15, 1999.
	7	2	Jan. 15, 2002.
	8-12	Original	Sept. 15, 1999.
Total Pages: 12			
SB PW4G-100-71-22	All	Original	Jan. 15, 2002.
Total Pages: 8			

This incorporation by reference of certain publications was approved by the Director of the Federal Register in accordance with 5

U.S.C. 552(a) and 1 CFR part 51. The incorporation by reference of PW ASB PW4G-100-A71-9, Revision 1, dated

November 24, 1997, was approved by the Director of the Federal Register on October 16, 2000 (65 FR 49730; August 15, 2002).

Copies may be obtained from Pratt & Whitney, 400 Main St., East Hartford, CT 06108; telephone (860) 565-8860; fax (860) 565-4503. Copies may be inspected at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(i) This amendment becomes effective on February 6, 2003.

Issued in Burlington, Massachusetts, on December 19, 2002.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 02-32664 Filed 12-31-02; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 2002-NM-269-AD; Amendment 39-12995; AD 2002-26-07]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model CL-600-2C10 (Regional Jet Series 700 & 701) Series Airplanes

AGENCY: Federal Aviation Administration, (DOT).

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to certain Bombardier Model CL-600-2C10 (Regional Jet Series 700 & 701) series airplanes. This action requires revising the airplane flight manual (AFM) to advise the flightcrew to limit use of the auxiliary power unit (APU) to ground operation only, except for those in-flight emergencies described in the AFM when use of the APU is specified. This action also provides for optional terminating action for the requirements of this AD. This action is necessary to prevent fuel from being sprayed throughout the APU compartment and drawn out of the APU exhaust duct due to a cracked APU fuel nozzle, which could result in a fire or explosion in the APU compartment during flight. This action is intended to address the identified unsafe condition.

DATES: Effective January 17, 2003.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of January 17, 2003.

Comments for inclusion in the Rules Docket must be received on or before February 3, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-269-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-iarcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2002-NM-269-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in this AD may be obtained from Bombardier, Inc., Canadair, Aerospace Group, PO Box 6087, Station Centre-ville, Montreal, Quebec H3C 3G9, Canada. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York; or at the *Office of the Federal Register*, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: For questions regarding the AFM revision, contact James Delisio, Aerospace Engineer, Airframe and Propulsion Branch, ANE-171, FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; telephone (516) 256-7521; fax (516) 568-2716. For questions regarding the APU replacement, contact Roger Pesuit, Aerospace Engineer, Propulsion Branch, ANM-140L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5251; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION: Transport Canada Civil Aviation (TCCA), which is the airworthiness authority for Canada, recently notified the FAA that an unsafe condition may exist on certain Model CL-600-2C10 (Regional Jet Series 700 & 701) series airplanes. TCCA advises that fuel nozzles installed on the auxiliary power unit (APU) on these airplanes may crack and leak fuel into the APU compartment. According to the APU

manufacturer, the cracks develop during APU start. Cracks are not readily detectable when the APU is installed in the airplane. An APU fuel nozzle can crack due to fatigue, and the resulting leak could cause fuel to spray throughout the APU compartment and be drawn out of the APU exhaust duct. This condition, if not corrected, could result in a fire or explosion in the APU compartment during flight.

Explanation of Relevant Service Information

Bombardier has issued Temporary Revision (TR) RJ 700/28-2, dated November 5, 2002, to the Canadair Regional Jet Series 700 Airplane Flight Manual. The TR advises the flightcrew to limit use of the APU to ground operation only, except for those in-flight emergencies described in the AFM when use of the APU is specified. TCCA has approved the TR for these airplanes in Canada. By approving the TR, TCCA also mandates its immediate incorporation into the AFM; therefore, TCCA did not issue a Canadian airworthiness directive to specifically mandate incorporation of the TR.

The FAA has reviewed Honeywell Alert Service Bulletin RE220-49-A7714, dated November 4, 2002, which describes procedures for replacing all APU fuel nozzles with new fuel nozzles (including installing new seals and washers; reidentifying the APU; and torquing the bolts and fuel manifold connector within specified ranges). The service bulletin specifically cautions against intermixing fuel nozzle part numbers on an APU or interchanging the subject ("2") fuel nozzles on a modified APU.

U.S. Type Certification of the Airplane

This airplane model is manufactured in Canada and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, TCCA has kept the FAA informed of the situation described above. The FAA has reviewed all available information and determined that AD action is necessary for products of this type design that are certificated for operation in the United States. TCCA fully agrees with the requirements and compliance time specified in this AD.

Explanation of Requirements of Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United