

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. Section 39.13 is amended by adding the following new airworthiness directive:

2004-01-17 McDonnell Douglas:

Amendment 39-13431. Docket 2001-NM-164-AD.

Applicability: Model MD-11 and -11F airplanes, as listed in Boeing Alert Service Bulletin MD11-54A011, Revision 02, dated May 31, 2002; certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent potential chafing of the power feeder cables of the integrated drive generator (IDG) in engine pylons No. 1 and No. 3 on the wings, and consequent arcing on the fuel lines in the engine pylons and possible fuel fire, accomplish the following:

Note 1: Boeing has issued Information Notice MD11-54A011 R02 IN 02, dated July 11, 2002. The information notice informs operators of a typographical error for the string tie part number (P/N) specified in the Boeing Alert Service Bulletin MD11-54A011, Revision 02. The service bulletin specifies string tie P/N 190L0F21G/A; the correct P/N is 109 LOF 21G/A.

Initial Inspection

(a) Within 30 days after the effective date of this AD, do a general visual inspection of the power feeder cables of the IDG and the fuel feed lines of engine pylons No. 1 and No. 3 on the wings for proper clearance and damage, per Boeing Alert Service Bulletin MD11-54A011, Revision 02, dated May 31, 2002.

Note 2: For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to enhance visual access to all exposed surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

Condition 1: Proper Clearance and No Damage

(b) If proper clearance exists and no damage is detected during any inspection required by paragraph (a) of this AD, do the action(s) specified in paragraphs (b)(1), (b)(2), and (b)(3) of this AD, as applicable, per Boeing Alert Service Bulletin MD11-54A011, Revision 02, dated May 31, 2002.

(1) For Group 1 and Group 2 airplanes identified in the service bulletin: Repeat the inspection required by paragraph (a) of this AD every 6 months until the modification required by paragraph (b)(2) or (b)(3) of this AD, as applicable, has been done.

(2) For Group 1 airplanes identified in the service bulletin: Within 18 months after the effective date of this AD, install the brackets to support the IDG harness, and install new clamps on the power feeder cables of the IDG of the No. 1 and No. 3 pylons.

(3) For Group 2 airplanes identified in the service bulletin: Within 18 months after the effective date of this AD, replace the existing fairlead with a new clamp, and install new tape.

Condition 2: Improper Clearance and No Damage

(c) If improper clearance exists and no damage is detected during any inspection required by paragraph (a) of this AD, do the action(s) specified in paragraphs (c)(1), (c)(2), and (c)(3) of this AD, as applicable, per Boeing Alert Service Bulletin MD11-54A011, Revision 02, dated May 31, 2002.

(1) For Group 1 and Group 2 airplanes identified in the service bulletin: Before further flight, reposition cables, and repeat the inspection required by paragraph (a) of this AD every 6 months until the modification required by paragraph (c)(2) or (c)(3) of this AD, as applicable, has been done.

(2) For Group 1 airplanes identified in the service bulletin: Within 18 months after the effective date of this AD, install the brackets to support the IDG harness, and install new clamps on the power feeder cables of the IDG of engine pylons No. 1 and No. 3.

(3) For Group 2 airplanes identified in the service bulletin: Within 18 months after the effective date of this AD, replace the existing fairlead with a new clamp, and install new tape.

Condition 3: Improper Clearance and Damage Detected

(d) If improper clearance exists and any damage is detected during any inspection required by paragraph (a) of this AD, do the action(s) specified in paragraphs (d)(1), (d)(2), and (d)(3) of this AD, as applicable, per Boeing Alert Service Bulletin MD11-54A011, Revision 02, dated May 31, 2002.

(1) For Group 1 and Group 2 airplanes identified in the service bulletin: Before further flight, reposition cables; repair damage or replace damaged cables or fuel feed lines with new or serviceable cables or fuel feed lines; and repeat the inspection required by paragraph (a) of this AD every 6 months until the modification required by paragraph (d)(2) or (d)(3) of this AD, as applicable, has been done.

(2) For Group 1 airplanes identified in the service bulletin: Within 18 months after the

effective date of this AD, install the brackets to support the IDG harness, and install new clamps on the power feeder cables of the IDG of engine pylons No. 1 and No. 3.

(3) For Group 2 airplanes identified in the service bulletin: Within 18 months after the effective date of this AD, replace the existing fairlead with a new clamp, and install new tape.

Credit for Earlier Service Bulletin

(e) Accomplishment of the actions specified in this AD before the effective date of this AD per Boeing Alert Service Bulletin MD11-54A011, Revision 01, dated August 22, 2001, is acceptable for compliance with the requirements of this AD.

Alternative Methods of Compliance

(f) In accordance with 14 CFR 39.19, the Manager, Los Angeles Aircraft Certification Office (ACO), FAA, is authorized to approve alternative methods of compliance for this AD.

Incorporation by Reference

(g) Unless otherwise specified in this AD, the actions shall be done in accordance with Boeing Alert Service Bulletin MD11-54A011, Revision 02, dated May 31, 2002. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(h) This amendment becomes effective on February 24, 2004.

Issued in Renton, Washington, on January 2, 2004.

Kevin M. Mullin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-762 Filed 1-16-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 2001-NM-161-AD; Amendment 39-13430; AD 2004-01-16]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model MD-11 and -11F Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain McDonnell Douglas Model MD-11 and -11F airplanes, that requires revising the wire connection stackups for the terminal strip of the generator feeder tail compartment of the auxiliary power unit (APU), and removing a nameplate, as applicable. For certain airplanes, this AD also requires replacing the terminal strips and revising the terminal hardware stackup for the feeder of the center cargo loading system. This action is necessary to prevent arcing damage to the terminal strips and damage to the adjacent structure, which could result in smoke and/or fire in the center and/or aft cargo compartments. This action is intended to address the identified unsafe condition.

DATES: Effective February 24, 2004.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of February 24, 2004.

ADDRESSES: The service information referenced in this AD may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Brett Portwood, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712; telephone (562) 627-5350; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain McDonnell Douglas Model MD-11 and -11F airplanes was published in the **Federal Register** on July 24, 2003 (68 FR 43693). That action proposed to require revising the wire connection stackups for the terminal strip of the generator feeder tail compartment of the auxiliary power unit (APU), and removing a nameplate,

as applicable. For certain airplanes, that action also proposed to require replacing the terminal strips and revising the terminal hardware stackup for the feeder of the center cargo loading system.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Editorial Clarification

The FAA has revised the spelling of a word from "namplate" to "nameplate" in this AD.

Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule with the change described previously. The FAA has determined that this change will neither increase the economic burden on any operator nor increase the scope of this AD.

Cost Impact

There are approximately 154 Model MD-11 and -11F airplanes of the affected design in the worldwide fleet. We estimate that 67 airplanes of U.S. registry will be affected by this AD, that it will take approximately between 1 and 2 work hours per airplane (depending on the airplane configuration) to accomplish the required actions, and that the average labor rate is \$65 per work hour. Required parts will cost approximately \$102 per airplane. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be between \$11,189 and \$15,544, or between \$167 and \$232 per airplane (depending on the airplane configuration).

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. However, for affected airplanes within the period under the warranty agreement, we have been advised that the manufacturer has committed previously to its customers that it will bear the cost of replacement parts. We also have been advised that manufacturer warranty remedies are available for labor costs associated with accomplishing the actions required by this AD. Therefore, the future economic cost impact of this AD may be less than the cost impact figure indicated above.

The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. Section 39.13 is amended by adding the following new airworthiness directive:

2004-01-16 McDonnell Douglas:

Amendment 39-13430. Docket 2001-NM-161-AD.

Applicability: Model MD-11 and -11F airplanes, as listed in McDonnell Douglas Alert Service Bulletin MD11-24A173,

Revision 02, dated May 2, 2002; certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent arcing damage to the terminal strips and damage to the adjacent structure, which could result in smoke and/or fire in the center and/or aft cargo compartments, accomplish the following:

For Group 1 and Group 2 Airplanes: Revise Wire Connection Stackups, Remove Nameplate, and Inspect for Damage

(a) For Group 1 and Group 2 airplanes listed in McDonnell Douglas Alert Service Bulletin MD11-24A173, Revision 02, dated May 2, 2002: Within 18 months after the effective date of this AD, do the actions specified in paragraphs (a)(1) and (a)(2) of this AD per the service bulletin. Although the service bulletin references a reporting requirement in paragraph 4, "Appendix," such reporting is not required by this AD.

(1) Revise the wire connection stackups for the terminal strip of the generator feeder tail compartment of the auxiliary power unit (APU), and remove the nameplate, as applicable.

(2) Do a general visual inspection to detect arcing damage of the surrounding structure, adjacent system components, and electrical cables in the center cargo and aft cargo compartments.

Note: For the purposes of this AD, a general visual inspection is defined as "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or drop-light, and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

For Group 2 Airplanes: Replace Terminal Strips, Revise Terminal Hardware Stackup, Remove Nameplate, and Inspect for Damage

(b) For Group 2 airplanes listed in McDonnell Douglas Alert Service Bulletin MD11-24A173, Revision 02, dated May 2, 2002: Within 18 months after the effective date of this AD, do the actions specified in paragraphs (b)(1) and (b)(2) of this AD per the service bulletin. Although the service bulletin references a reporting requirement in paragraph 4, "Appendix," such reporting is not required by this AD.

(1) Replace the terminal strips and revise the terminal hardware stackup for the feeder of the center cargo loading system, and remove the nameplate, as applicable.

(2) Do a general visual inspection to detect arcing damage of the surrounding structure, adjacent system components, and electrical cables in the center cargo and aft cargo compartments.

Corrective Action if Necessary

(c) If any damage is detected during any inspection required by paragraph (a) or (b) of this AD, before further flight, repair damage or replace the damaged part with a new part, per McDonnell Douglas Alert Service Bulletin MD11-24A173, Revision 02, dated

May 2, 2002. If the type of structural material that has been damaged is not covered in the structural repair manual, repair per a method approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA. Although the service bulletin references a reporting requirement in paragraph 4, "Appendix," such reporting is not required by this AD.

Alternative Methods of Compliance

(d) In accordance with 14 CFR 39.19, the Manager, Los Angeles ACO, FAA, is authorized to approve alternative methods of compliance for this AD.

Incorporation by Reference

(e) Unless otherwise specified in this AD, the actions shall be done in accordance with McDonnell Douglas Alert Service Bulletin MD11-24A173, Revision 02, dated May 2, 2002. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(f) This amendment becomes effective on February 24, 2004.

Issued in Renton, Washington, on January 2, 2004.

Kevin M. Mullin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-761 Filed 1-16-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-NE-12-AD; Amendment 39-13434; AD 2004-01-20]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce plc RB211 Series Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for Rolls-Royce plc (RR) RB211-22B series, RB211-524B, -524C2, -524D4, -524G2, -524G3, and -524H series, and RB211-535C and -535E series turbofan engines

with high pressure compressor (HPC) stage 3 disc assemblies, part numbers (P/Ns) LK46210, LK58278, LK67634, LK76036, UL11706, UL15358, UL22577, UL22578, and UL24738 installed. This AD allows disc assemblies not modified by a certain RR service bulletin to reach their full life only after the disc assemblies are modified with anti-corrosion protection. This AD results from the manufacturer's reassessment of the corrosion risk on HPC stage 3 disc assemblies that have not yet been modified with sufficient application of anti-corrosion protection. We are issuing this AD to prevent corrosion-induced uncontained disc failure, resulting in damage to the airplane.

DATES: This AD becomes effective February 24, 2004.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of February 24, 2004.

ADDRESSES: You can get the service information identified in this AD from Rolls-Royce plc, PO Box 31, Derby, England, DE248BJ; telephone: 011-44-1332-242424; fax: 011-44-1332-245-418.

You may examine the AD docket, by appointment, at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA. You may examine the service information, at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Ian Dargin, Aerospace Engineer, Engine Certification Office, FAA, Engine And Propeller Directorate, 12 New England Executive Park; Burlington, MA 01803-5299; telephone (781) 238-7178; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION: The FAA proposed to amend 14 CFR Part 39 with a proposed airworthiness directive (AD). The proposed AD applies to RR RB211-22B series, RB211-524B, -524C2, -524D4, -524G2, -524G3, and -524H series, and RB211-535C and -535E series turbofan engines with HPC stage 3 disc assemblies, P/Ns LK46210, LK58278, LK67634, LK76036, UL11706, UL15358, UL22577, UL22578, and UL24738 installed. We published the proposed AD in the **Federal Register** on July 30, 2003 (68 FR 44672). That action proposed to allow disc assemblies not modified by a certain RR service bulletin to reach their full life only after the disc assemblies are modified with anti-corrosion protection.