

Proposed Rules

Federal Register

Vol. 66, No. 54

Tuesday, March 20, 2001

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-314-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747-100, -200B, -200F, -200C, -100B, -300, -100B SUD, -400, -400D, -400F, and 747 SR Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Boeing Model 747 series airplanes. This proposal would require repetitive inspections to find cracking of the frame web, strap, inner chords, and inner chord angle of the forward edge frame of the number 5 main entry door cutout, and repair, if necessary. This action is necessary to find and fix such cracking, which could result in severing of the frame, inability of the edge frame to react door stop loads, and consequent rapid depressurization of the airplane. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by May 4, 2001.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-314-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2000-NM-314-AD" in the

subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Rick Kawaguchi, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1153; fax (425) 227-1181.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments

submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2000-NM-314-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-314-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received reports indicating that cracking has been found in the frame strap and inner chord angle of the forward edge frame of the number 5 main entry door cutout at body station 2231 on several Boeing Model 747 series airplanes. The cracking originated at the fastener hole locations because of fatigue. Fatigue cracks in the frame web, strap, inner chords, and inner chord angle of the forward edge frame of the number 5 main entry door cutout, if not found, could extend to the inner chord of the frame and cause the inner chord to break, leading to failure of the outer chord and adjacent fuselage skin. This condition, if not corrected, could result in inability of the edge frame to react door stop loads, and consequent rapid depressurization of the airplane.

Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Alert Service Bulletin 747-53A2450, Revision 2, including Appendix A, dated January 4, 2001, which describes procedures for repetitive detailed visual, high frequency eddy current (HFEC), open hole HFEC, and low frequency eddy current inspections to find cracking of the frame web, strap, inner chords, and inner chord angle of the forward edge frame of the number 5 main entry door cutout. If cracking is found, the service bulletin specifies to contact Boeing for repair instructions.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require accomplishment of the actions

specified in the service bulletin described previously, except as discussed below.

Difference Between Service Bulletin and This Proposed AD

The service bulletin specifies that the manufacturer must be contacted for repair of certain conditions, but this proposal would require the repair of those conditions to be accomplished per a method approved by the FAA; or per data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative who has been authorized by the FAA to make such findings. For a method to be approved, the approval letter must specifically reference this AD.

Interim Action

This is considered to be interim action. The manufacturer has advised that it currently is developing a modification that will positively address the unsafe condition addressed by this AD. Once this modification is developed, approved, and available, the FAA may consider additional rulemaking.

Cost Impact

There are approximately 1,314 airplanes of the affected design in the worldwide fleet. The FAA estimates that 258 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 16 work hours per airplane to accomplish the proposed inspections, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$247,680 or \$960 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if

this proposed AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Boeing: Docket 2000–NM–314–AD.

Applicability: Model 747 series airplanes, as listed in Boeing Alert Service Bulletin 747–53A2450, Revision 2, dated January 4, 2001, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To find and fix cracking of the frame web, strap, inner chords, and inner chord angle of the forward edge frame of the number 5 main entry door cutout, which could result in severing of the frame, inability of the edge frame to react door stop loads, and consequent rapid depressurization of the airplane, accomplish the following:

Repetitive Inspections (No Terminating Action)

(a) Inspect the airplane for cracks per Boeing Alert Service Bulletin 747–53A2450, Revision 2, including Appendix A, dated January 4, 2001; at the later of the times specified in either paragraph (a)(1) or (a)(2) of this AD, per Table 1 of this AD, as follows:

TABLE 1.—INSPECTION REQUIREMENTS

Type of Inspection	Area to inspect
(1) Detailed Visual	Strap inner chords forward and aft of the web, and exposed web adjacent to the inner chords on station 2231 frame from stringer 23 through 31 per Figure 5 or Figure 6 of the service bulletin, as applicable.
(2) Surface High Frequency Eddy Current (HFEC)	Station 2231 inner chord angles at lower main sill interface per Figure 5 or Figure 6 of the service bulletin, as applicable.
(3) Open Hole HFEC	Station 2231 frame fastener locations per Figures 4 and 7, and either Figure 5 or 6 of the service bulletin, as applicable.
(4) Surface HFEC	Around fastener locations on station 2231 inner chords from stringer 23 through 31 per Figure 5 or Figure 6 of the service bulletin, as applicable.
(5) Low Frequency Eddy Current ...	Station 2231 frame strap in areas covered by the reveal per Figure 5 or Figure 6 of the service bulletin, as applicable.

(1) Where the compliance time in the logic diagram in Figure 1 of Boeing Alert Service Bulletin 747-53A2450, Revision 2, dated January 4, 2001, specifies a compliance time beginning, "from receipt of this service bulletin," this AD requires the compliance time begin "after the effective date of this AD." Repeat the inspections after that at intervals not to exceed 3,000 flight cycles.

(2) Within 3,000 flight cycles after accomplishment of the inspections specified in Figure 1 of Boeing Alert Service Bulletin 747-53A2450, dated May 4, 2000, or Revision 1, dated July 6, 2000. Repeat the inspections after that at intervals not to exceed 3,000 flight cycles.

Note 2: There is no terminating action currently available for the inspections required by paragraph (a) of this AD.

Note 3: Where there are differences between the AD and the alert service bulletin, the AD prevails.

Repair

(b) If any cracking is found during any inspection required by paragraph (a) of this AD, before further flight, repair per a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA; or per data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative who has been authorized by the Manager, Seattle ACO, to make such findings. For a repair method to be approved by the Manager, Seattle ACO, as required by this paragraph, the approval letter must specifically reference this AD.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 4: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permit

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on March 13, 2001.

Vi L. Lipski,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. 01-6792 Filed 3-19-01; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-323-AD]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model MD-90-30 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain McDonnell Douglas Model MD-90-30 Series Airplanes. This proposal would require revising the wiring of the selective calling (SELCAL) system. This action is necessary to prevent inadvertent very high frequency transmissions and subsequent loss of radio communications for airplane and/or airport operations; and to prevent inadvertent high frequency transmissions and subsequent electrical shock to ground service personnel and/or damage to the airplane during fueling operations or fuel tank maintenance. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by May 4, 2001.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-323-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2000-NM-323-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Technical Publications Business Administration, Dept. C1-L51 (2-60). This information

may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712.

FOR FURTHER INFORMATION CONTACT:

George Mabuni, Aerospace Engineer, Systems and Equipment Branch, ANM-130L; FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5341; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (*e.g.*, reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2000-NM-323-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the