

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2014-0493; Directorate Identifier 2013-SW-019-AD]

RIN 2120-AA64

Airworthiness Directives; Sikorsky Aircraft Corporation (Sikorsky) Model Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Sikorsky Model S-92A helicopters. This proposed AD would require installing a main gearbox (MGB) failed pump sensor and vacuum switch wiring, installing an MGB oil auto bypass system, activating Aircraft Management System (AMS) 7.1 software to show a new visual warning, and installing updated enhanced ground proximity warning system (EGPWS) software that includes an aural annunciation of a complete oil pressure loss condition. This proposed AD would also require inserting a Rotorcraft Flight Manual (RFM) Supplement into the applicable RFM. This proposed AD is prompted by investigation results of in-service oil leakage incidents. The proposed actions are intended to alert and prevent MGB oil loss, which could lead to failure of the MGB and subsequent loss of control of the helicopter.

DATES: We must receive comments on this proposed AD by September 22, 2014.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Docket:* Go to <http://www.regulations.gov>. Follow the online instructions for sending your comments electronically.

- *Fax:* 202-493-2251.

- *Mail:* Send comments to the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590-0001.

- *Hand Delivery:* Deliver to the "Mail" address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the Docket Operations Office between 9

a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the economic evaluation, any comments received, and other information. The street address for the Docket Operations Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

For the Sikorsky service information identified in this proposed AD, contact Sikorsky Aircraft Corporation, Customer Service Engineering, 124 Quarry Road, Trumbull, CT 06611; telephone 1-800-Winged-S or 203-416-4299; email sikorskywcs@sikorsky.com; or at <http://www.sikorsky.com>. For the Honeywell service information identified in this proposed AD, contact Honeywell International, Inc., at 15001 NE. 36 Street, Redmond, WA 98052-5316, telephone (800) 601-3099; email www.myaerospace.com. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

FOR FURTHER INFORMATION CONTACT:

Michael Schwetz, Aviation Safety Engineer, Boston Aircraft Certification Office, Engine & Propeller Directorate, FAA, 12 New England Executive Park, Burlington, Massachusetts 01803; telephone (781) 238-7761; email michael.schwetz@faa.gov.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to participate in this rulemaking by submitting written comments, data, or views. We also invite comments relating to the economic, environmental, energy, or federalism impacts that might result from adopting the proposals in this document. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should send only one copy of written comments, or if comments are filed electronically, commenters should submit only one time.

We will file in the docket all comments that we receive, as well as a report summarizing each substantive public contact with FAA personnel concerning this proposed rulemaking. Before acting on this proposal, we will consider all comments we receive on or before the closing date for comments. We will consider comments filed after the comment period has closed if it is possible to do so without incurring

expense or delay. We may change this proposal in light of the comments we receive.

Discussion

We propose to adopt a new AD for Sikorsky Model S-92A helicopters. This proposed AD would require, depending on the helicopter's serial number, installing an MGB failed pump sensor and vacuum switch wiring, installing an MGB oil auto bypass system, activating AMS 7.1 software to show a new MGB "OIL OUT" visual warning, updating the EGPWS software to include an aural annunciation of a complete oil pressure loss condition, and inserting an RFM Supplement into the applicable RFM.

This proposed AD is prompted by one accident and one in-service oil leakage incident where it was discovered during subsequent investigations that the pilot failed to activate the bypass valve within 5 seconds of the oil pressure dropping below 35 psi, as required by the RFM. Both accident and incident investigations found that the pilot activated the bypass valve well beyond the 5 seconds.

The manual operation of the bypass valve within 5 seconds of the oil pressure dropping below 35 psi has proven not to be a realistic expectation. The MGB failed pump sensor and vacuum switch wiring is a system that will detect an oil pressure drop in the input module and alert the pilot if the low oil pressure is the result of a failed oil pump. The MGB oil auto bypass system eliminates the need for the pilot to manually switch the bypass valve when the oil pressure drops below 35 psi. The AMS software upgrade is to automate the bypass valve and to alert the pilot that the low oil pressure may be the result of a failed oil pump. Knowing the low oil pressure is the result of a failed oil pump and not due to oil leakage will allow the pilot to switch the bypass valve out of bypass to cool the oil. When the oil is not cooled, the hot oil may cause the input module seals to fail allowing an excessive amount of oil to leak resulting in failure of the MGB. There have been several incidents of a pump failure where the oil had the potential to reach a high enough temperature to damage the seals. The EGPWS software change provides a new aural warning of a complete oil pressure loss.

FAA's Determination

We are proposing this AD because we evaluated all known relevant information and determined that an unsafe condition exists and is likely to exist or develop on other helicopters of this same type design.

Related Service Information

Sikorsky has issued the following service information:

- Alert Service Bulletin (ASB) No. 92–63–024C, Revision C, dated October 7, 2011, for certain serial-numbered helicopters specifies installing a main module input gear box switch assembly and modifying the MGB vacuum switch wiring. Before making the modification, the ASB states an AMS 4.1 or greater version must first be installed and the following Customer Service Notices (CSN) completed: CSN 92–068C, Revision C, dated March 27, 2012, and CSN 92–069A, Revision A, dated November 10, 2011.

- ASB 92–63–027, Basic Issue, dated January 21, 2013, for certain serial-numbered helicopters specifies installing an MGB oil pressure automatic bypass system, activating an MGB “OIL OUT” visual warning in the AMS 7.1 software, and performing systems operational checkout procedures. Before or when installing the MGB oil pressure auto bypass system, the ASB states the following must be complied with: CSN 92–089, Basic Issue, dated January 10, 2013; ASB 92–34–002, Basic Issue, dated January 21, 2013; and ASB 92–63–024C, Revision C, dated October 7, 2011.

- ASB 92–34–002, Basic Issue, dated January 21, 2013, for certain serial-numbered helicopters with certain part-numbered EGPWS installed, specifies installing EGPWS updated software version 030, which adds an MGB “OIL OUT” aural warning, in accordance with Honeywell International, Inc., Service Bulletin 965–1595–34–23, Revision 0, dated March 13, 2012. Before or during installation of the updated software, the ASB states the following must be complied with: ASB 92–63–027, Basic Issue, dated January 21, 2013, and CSN 92–089, Basic Issue, dated January 10, 2013.

Proposed AD Requirements

The proposed AD would require, within 500 hours time-in-service (TIS):

- Inserting a copy of the Sikorsky S–92A RFM Supplement No. 45, Part I, dated July 30, 2012, into the RFM.
- For certain serial-numbered helicopters, installing an MGB failed pump sensor and MGB vacuum switch wiring.
- For certain other serial-numbered helicopters, installing an MGB auto bypass system, activating AMS 7.1 software, and installing EGPWS software version 030.

Differences Between This Proposed AD and the Service Information

This AD proposes compliance within 500 hours TIS, and the service information specifies certain dates and calendar times.

Costs of Compliance

We estimate that this proposed AD would affect 44 helicopters of U.S. Registry.

We estimate that operators may incur the following costs in order to comply with this AD. Labor costs are estimated at \$85 per hour. The work hours and required parts costs are estimated as follows:

- .5 work hour to insert the RFM Supplement into the RFM.
- 8 work hours plus \$2,200 for required parts to install an MGB failed pump sensor;
- 4 work hours plus \$250 for required parts to install MGB vacuum switch wiring;
- 71.7 work hours plus \$4,100 for required parts to install an MGB oil pressure auto bypass system;
- 1 work hour to activate AMS 7.1; and
- 1 work hour plus \$500 for required parts to install EGPWS software.

The total cost of compliance for all actions would be about \$14,377 per helicopter and \$632,588 for the U.S. fleet.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This proposed regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national

Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed, I certify this proposed regulation:

- Is not a “significant regulatory action” under Executive Order 12866;
- Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
- Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction; and
- Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by Reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Sikorsky Aircraft Corporation: Docket No. FAA–2014–0493; Directorate Identifier 2013–SW–019–AD.

(a) Applicability

This AD applies to Model S–92A helicopters, serial number (S/N) 920006 through 920179, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as main gearbox (MGB) oil loss, which could lead to failure of the MGB and subsequent loss of control of the helicopter.

(c) Comments Due Date

We must receive comments by September 22, 2014.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

Within 500 hours time-in-service:

(1) Insert a copy of the Sikorsky S-92A Rotorcraft Flight Manual (RFM) Supplement No. 45, Part I, dated July 30, 2012, into the RFM.

(2) For helicopters with S/N 920006 through 920132:

(i) Install an MGB failed pump sensor, Modification Kit Part Number (P/N) 92070-35007-011.

(ii) Install MGB vacuum switch wiring, Modification Kit P/N 92070-55039-013.

(3) For helicopters with S/N 920006 through 920179:

(i) Install an MGB auto bypass system, Modification Kit P/N 92070-55061-011.

(ii) Activate Aircraft Management System 7.1 software to show a new MGB "OIL OUT" visual warning.

(iii) Install enhanced ground proximity warning system software version 030.

(f) Special Flight Permit

Special flight permits are prohibited.

(g) Alternative Methods of Compliance (AMOC)

(1) The Manager, Boston Aircraft Certification Office, FAA, may approve AMOCs for this AD. Send your proposal to: Michael Schwetz, Aviation Safety Engineer, Boston Aircraft Certification Office, Engine & Propeller Directorate, FAA, 12 New England Executive Park, Burlington, Massachusetts 01803; telephone (781) 238-7761; email michael.schwetz@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

(h) Additional Information

Sikorsky Alert Service Bulletin (ASB) No. 92-63-024C, Revision C, dated October 7, 2011; Sikorsky ASBs 92-63-027 and 92-34-002, both Basic Issue and both dated January 21, 2013; Sikorsky Customer Service Notice (CSN) 92-068C, Revision C, dated March 27, 2012; CSN 92-069A, Revision A, dated November 10, 2011; CSN 92-089, Basic Issue, dated January 10, 2013; and Honeywell International, Inc., Service Bulletin 965-1595-34-23, Revision 0, dated March 13, 2012, which are not incorporated by reference, contain additional information about the subject of this AD. For service information identified in this AD, contact Sikorsky Aircraft Corporation, Customer Service Engineering, 124 Quarry Road, Trumbull, CT 06611; telephone 1-800-Winged-S or 203-416-4299; email sikorskywcs@sikorsky.com; or at <http://www.sikorsky.com> and Honeywell International, Inc., at 15001 NE 36 Street, Redmond, WA 98052-5316, telephone (800) 601-3099; or at www.myaerospace.com. You may review a copy of this service information at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

(i) Subject

Joint Aircraft Service Component (JASC) Code: 6320 Main Rotor Gearbox.

Issued in Fort Worth, Texas, on July 17, 2014.

S. Frances Cox,

Acting Directorate Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2014-17334 Filed 7-22-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2014-0494; Directorate Identifier 2014-CE-017-AD]

RIN 2120-AA64

Airworthiness Directives; Pacific Aerospace Limited Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for Pacific Aerospace Limited Model 750XL airplanes. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as failure of the fin forward pickup due to possible fatigue cracks. We are issuing this proposed AD to require actions to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by September 8, 2014.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Pacific Aerospace Unlimited, Airport Road,

Hamilton, Private Bag HN3027, Hamilton 3240, New Zealand, phone: +64 7 843 6144; fax: +64 7 843 6134; email: pacific@aerospace.co.nz, internet: www.aerospace.co.nz. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0494; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4123; fax: (816) 329-4090; email: Karl.Schletzbaum@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2014-0494; Directorate Identifier 2014-CE-017-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The Civil Aviation Authority (CAA), which is the aviation authority for New Zealand, has issued AD DCA/750XL/16A, dated June 18, 2014 (referred to after this as "the MCAI"), to correct an