

are available for public inspection at the NRC Public Document Room (PDR) located at the Gelman Building, 2012 L Street, NW, Washington, DC 20555. Documents created or received at the NRC after November 1, 1999 are also available electronically at the NRC's Public Electronic Reading Room on the Internet at <http://www.nrc.gov/NRC/ADAMS/index.html>. From this site, the public can gain entry into the NRC's Agencywide Document Access and Management System (ADAMS), which provides text and image files of NRC's public documents. For more information, contact the NRC Public Document Room (PDR) Reference staff at 1-800-397-4209, or 202-634-3273, or by email to pdr@nrc.gov.

You may also provide comments via the NRC's interactive rulemaking website through the NRC home page (<http://ruleforum.llnl.gov>). This site provides the availability to view and upload comments as files (any format), if your web browser supports that function. For information about the interactive rulemaking website, contact Ms. Carol Gallagher, (301) 415-5905 (e-mail: CAG@nrc.gov).

FOR FURTHER INFORMATION CONTACT:

David L. Meyer, Office of Administration, U.S. Nuclear Regulatory Commission, Washington, DC 20555. Telephone: 301-415-7162 or Toll Free: 1-800-368-5642 or E-mail: DLM1@NRC.GOV.

SUPPLEMENTARY INFORMATION:

Background

The Nuclear Regulatory Commission received a petition for rulemaking dated May 3, 2000, submitted by the Union of Concerned Scientists (petitioner). The petitioner requests that the regulations governing renewal of operating licenses for nuclear power plants in 10 CFR parts 51 and 54 be amended to address potential concerns relating to degradation through aging of piping and components of liquid and gaseous radioactive waste systems at operating nuclear power plants. This petition was included as part of a document in which the petitioner details concerns related to the review of the license renewal application submitted by the owner of the Hatch Nuclear Plant. Specifically, the petitioner is concerned that the license renewal application for the Hatch facility has not addressed deficiencies it believes exists in the aging management of the liquid and gaseous radioactive waste (radwaste) systems. The petitioner concludes that the requirements pertaining to renewal of operating licenses for nuclear power plants do not adequately address

degradation from aging of liquid and gaseous radioactive waste systems. The petitioner requests that the regulations in 10 CFR part 51 and part 54 be amended to clarify that liquid and gaseous radioactive waste systems must be covered by aging management programs during license renewal periods.

The NRC has determined that the petition meets the threshold sufficiency requirements for a petition for rulemaking under 10 CFR 2.802. The petition has been docketed as PRM-54-1. The NRC is soliciting public comment on the petition for rulemaking.

Discussion of the Petition

The petitioner states that in 10 CFR part 51, appendix B to subpart A, "Environmental Effect of Renewing the Operating License of a Nuclear Power Plant," the NRC concluded that radiation exposures to the public and occupational exposures to workers during the license renewal term will continue at levels below regulatory limits. The petitioner believes that this conclusion is based on an assumption that the piping and components of the liquid and gaseous radioactive waste systems at nuclear power plants do not experience greater failure rates during the license renewal term.

Using the case of a recent license renewal application, the petitioner cites the Hatch Nuclear Plant as an example in contending that the plant is being operated outside its design and licensing bases because the material condition of piping and components of the liquid (Contention No. 1) and gaseous (Contention No. 2) radioactive waste systems are not being properly inspected and maintained. In its request for a generic communication by the NRC to all nuclear power plant owners about potential aging degradation of liquid and gaseous radioactive waste systems, the petitioner indicates that the Millstone facility received an Information Notice in 1979 regarding liquid radwaste system problems that the petitioner believes was ignored. The petitioner notes that in 1996 the Millstone facility received another Information Notice also regarding degradation problems with the liquid radwaste system.

The petitioner believes that from its review of the license renewal applications submitted by the owners of the Calvert Cliffs, Oconee, and Hatch facilities, it appears that 10 CFR 54.4(a)(1)(iii) has been interpreted to exclude the liquid and gaseous radioactive waste systems from aging management consideration. The petitioner requests that NRC amend 10

CFR parts 51 and 54 to clarify that the liquid and gaseous radioactive waste systems must be covered by aging management programs during the license renewal term. The petitioner believes that regulations imposing aging management for these systems are necessary to ensure that these systems do not experience greater failure rates that could result in an increased probability and/or consequences from design bases events.

The Petitioner's Conclusions

The petitioner has concluded that the NRC requirements governing renewal of operating licenses of nuclear power facilities do not adequately address degradation that may result from aging of liquid and gaseous radioactive waste systems. The petitioner has also concluded that the degradation by aging of these systems may result in an increased probability of adverse consequences from design and licensing bases events. The petitioner requests that the regulations in 10 CFR part 54 and part 51, if appropriate, be amended to clarify that liquid and gaseous radwaste systems must be covered by aging management programs during the license renewal term of an operating nuclear power facility.

Dated at Rockville, Maryland, this 3rd day of July, 2000.

For the Nuclear Regulatory Commission.

Andrew L. Bates,

Acting Secretary of the Commission.

[FR Doc. 00-17340 Filed 7-7-00; 8:45 am]

BILLING CODE 7590-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-365-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 767 Series Airplanes Powered by Pratt & Whitney Engines

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Boeing Model 767 series airplanes powered by Pratt & Whitney engines. This proposal would require modification of the nacelle strut and wing structure. This action is necessary to prevent fatigue cracking in primary

strut structure and consequent reduced structural integrity of the strut. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by August 24, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-365-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 99-NM-365-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: James Rehr, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2783; fax (425) 227-1181.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.

- For each issue, state what specific change to the proposed AD is being requested.

- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 99-NM-365-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-365-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received reports indicating that the airplane manufacturer has accomplished a structural reassessment of the damage tolerance capabilities of the Boeing Model 767 series airplane powered by Pratt & Whitney engines. This reassessment indicates that the actual operational loads applied to the nacelle strut and wing structure are higher than the analytical loads that were used during the initial design. Subsequent analysis and service history, which includes numerous reports of fatigue cracking on certain strut and wing structure, indicate that fatigue cracking can occur on the primary strut structure before an airplane reaches its design service objective of 20 years or 50,000 flight cycles. Analysis also indicates that such cracking, if it were to occur, would grow at a much greater rate than originally expected. Fatigue cracking in primary strut structure would result in reduced structural integrity of the strut.

Other Relevant Rulemaking

This proposed AD is related to AD 94-11-02, amendment 39-8918 (59 FR 27229, May 26, 1994), which is applicable to all Boeing Model 767 series airplanes, and requires repetitive detailed visual and eddy current

inspections to detect cracks of certain midspar fuse pins, and replacement of any cracked midspar fuse pin with a new fuse pin.

This proposed AD also is related to AD 99-07-06, amendment 39-11091 (64 FR 14578, March 26, 1999), which is applicable to certain Boeing Model 767 series airplanes, and requires repetitive inspections to detect cracking or damage of the forward and aft lugs of the diagonal brace of the nacelle strut, and follow-on actions, if necessary.

Accomplishment of the actions required by this AD would terminate the repetitive inspections required by AD 94-11-02 and AD 99-07-06.

Explanation of Relevant Service Information

Boeing recently has developed a modification of the strut-to-wing attachment structure installed on Model 767 series airplanes powered by Pratt & Whitney engines. This modification significantly improves the load-carrying capability and durability of the strut-to-wing attachments. Such improvement also will substantially reduce the possibility of fatigue cracking and corrosion developing in the attachment assembly.

The FAA has reviewed and approved Boeing Service Bulletin 767-54-0080, dated October 7, 1999, which describes procedures for modification of the nacelle strut and wing structure. The modification consists of replacing many of the significant load-bearing components of the strut (e.g., the side link fittings assemblies, the midspar fittings, the side load fittings, certain fuse bolt assemblies, etc.) with improved components.

The service bulletin contains a formula for calculating an optional compliance threshold for the specified modification. This formula is intended to be used as an alternative to the 20-year calendar threshold specified in the service bulletin.

In addition, Table 2 of the service bulletin also identifies six related service bulletin modifications that must be accomplished before or at the same time as the modification specified in Boeing Service Bulletin 767-54-0080:

- *Boeing Service Bulletin 767-53-0069:* The FAA has reviewed and approved Boeing Service Bulletin 767-53-0069, Revision 1, dated January 29, 1998, which describes procedures for replacement of the existing midspar fuse pins with new higher-strength fuse pins; installation of new higher-strength tension bolts and radius fillers in the side load fittings and backup support structure; and replacement of the existing fasteners located in the front

spar and rib number eight rib post with new higher-strength fasteners.

- *Boeing Service Bulletin 767-54-0083*: The FAA has reviewed and approved Boeing Service Bulletin 767-54-0083, dated September 17, 1998, which describes procedures for replacement of the upper link with a new, improved part that will increase the strength and durability of the upper link installation. That service bulletin also describes procedures for modification of a wire support bracket attached to the upper link.

- *Boeing Service Bulletin 767-54-0088*: The FAA has reviewed and approved Boeing Service Bulletin 767-54-0088, Revision 1, dated July 29, 1999, which describes procedures for replacement of the upper link fuse pin and aft pin with new, improved pins that will increase the strength and durability of the upper link installation.

- *Boeing Service Bulletin 767-54A0094*: The FAA has reviewed and approved Boeing Service Bulletin 767-54A0094, Revision 1, dated September 16, 1999, which describes procedures for repetitive detailed visual inspections of the one-piece diagonal brace lugs to detect cracking, and installation of a new three-piece diagonal brace or rework of the existing brace. Installation of the new three-piece diagonal brace would constitute terminating action for the repetitive inspections described in this bulletin.

- *Boeing Service Bulletin 767-57-0053*: The FAA has reviewed and approved Boeing Service Bulletin 767-57-0053, Revision 2, dated September 23, 1999, which describes procedures for repetitive ultrasonic and eddy current inspections of the pitch load fitting lugs of the wing front spar for cracking, and rework of the fittings, if necessary.

- *Boeing Service Bulletin 767-29-0057*: The FAA has reviewed and approved Boeing Service Bulletin 767-29-0057, dated December 16, 1993, including Notice of Status Change NSC 1, dated November 23, 1994, which describes procedures for modification of the electrical wiring located in the aft fairing area of the strut and installation of wire support brackets on the strut bulkhead.

Accomplishment of the actions specified in the service bulletins is intended to adequately address the identified unsafe condition.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would

require accomplishment of the actions specified in the service bulletins described previously, except as discussed below.

Difference Between Proposed Rule and Service Bulletin

Operators should note that, although Boeing Service Bulletin 767-54-0080 specifies that the manufacturer may be contacted for disposition of certain damage conditions that may be detected during accomplishment of the modification, this proposal would require the repair of those conditions to be accomplished in accordance with a method approved by the FAA.

Cost Impact

There are approximately 233 airplanes of the affected design in the worldwide fleet. The FAA estimates that 76 airplanes of U.S. registry would be affected by this proposed AD.

It would take approximately 708 work hours per airplane to accomplish the proposed modification of the nacelle strut and wing structure described in Boeing Service Bulletin 767-54-0080, at an average labor rate of \$60 per work hour. Required parts would be provided at no cost by the airplane manufacturer. Based on these figures, the cost impact of the modification proposed by this AD on U.S. operators is estimated to be \$3,228,480, or \$42,480 per airplane.

It would take approximately 106 work hours per airplane to accomplish the actions described in Boeing Service Bulletin 767-53-0069, Revision 1, at an average labor rate of \$60 per work hour. Required parts would be provided at no cost by the airplane manufacturer. Based on these figures, the cost impact of these proposed actions on U.S. operators is estimated to be \$483,360, or \$6,360 per airplane.

It would take approximately 1 work hour per airplane to accomplish the actions described in Boeing Service Bulletin 767-54-0083, at an average labor rate of \$60 per work hour. Required parts would be provided at no cost by the airplane manufacturer. Based on these figures, the cost impact of these proposed actions on U.S. operators is estimated to be \$4,560, or \$60 per airplane.

It would take approximately 2 work hours per airplane to accomplish the actions described in Boeing Service Bulletin 767-54-0088, Revision 1, at an average labor rate of \$60 per work hour. Required parts would be provided at no cost by the airplane manufacturer. Based on these figures, the cost impact of these proposed actions on U.S. operators is estimated to be \$9,120, or \$120 per airplane.

It would take approximately 20 work hours per airplane to accomplish the proposed actions described in Boeing Service Bulletin 767-54A0094, Revision 1, at an average labor rate of \$60 per work hour. Required parts would be provided at no cost by the airplane manufacturer. Based on these figures, the cost impact of these proposed actions on U.S. operators is estimated to be \$91,200, or \$1,200 per airplane.

It would take approximately 5 work hours per airplane to accomplish the proposed actions described in Boeing Service Bulletin 767-57-0053, Revision 2, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of these proposed actions on U.S. operators is estimated to be \$22,800, or \$300 per airplane.

It would take approximately 16 work hours per airplane to accomplish the proposed actions described in Boeing Service Bulletin 767-29-0057, at an average labor rate of \$60 per work hour. Required parts would be provided at no cost by the airplane manufacturer. Based on these figures, the cost impact of these proposed actions on U.S. operators is estimated to be \$72,960, or \$960 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this proposed AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Boeing: Docket 99–NM–365–AD.

Applicability: Model 767 series airplanes powered by Pratt & Whitney engines, line numbers 1 through 663 inclusive, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent fatigue cracking in primary strut structure and consequent reduced structural integrity of the strut, accomplish the following:

Modifications

(a) When the airplane has reached the flight cycle threshold as defined by the flight cycle threshold formula on page 67 of Boeing Service Bulletin 767–54–0080, dated October 7, 1999, or within 20 years since the date of manufacture, whichever occurs first: Modify the nacelle strut and wing structure on both the left and right sides of the airplane, in accordance with the service bulletin. Use of the flight cycle threshold formula described

on page 67 of the service bulletin is an acceptable alternative to the 20-year threshold, provided the conditions described in paragraphs 1 and 2 of page 67 have been met.

(b) Prior to or concurrently with the accomplishment of the modification of the nacelle strut and wing structure required by paragraph (a) of this AD; as specified in paragraph 1.D., Table 2, on page 8 of Boeing Service Bulletin 767–54–0080, dated October 7, 1999; accomplish the actions specified in Boeing Service Bulletins 767–53–0069, Revision 1, dated January 29, 1998; 767–54–0083, dated September 17, 1998; 767–54–0088, Revision 1, dated July 29, 1999; 767–54A0094, Revision 1, dated September 16, 1999; 767–57–0053, Revision 2, dated September 23, 1999; and 767–29–0057, dated December 16, 1993, including Notice of Status Change NSC 1, dated November 23, 1994; as applicable; in accordance with those service bulletins. Accomplishment of this paragraph constitutes terminating action for the repetitive inspections required by AD 94–11–02, amendment 39–8918, and AD 99–07–06, amendment 39–11091.

Note 2: Paragraph (b) of this AD specifies prior or concurrent accomplishment of Boeing Service Bulletin 767–57–0053, Revision 2, dated September 23, 1999; however, Table 2, on page 8 of Boeing Service Bulletin 767–54–0080, dated October 7, 1999, specifies prior or concurrent accomplishment of the original issue of the service bulletin. Therefore, accomplishment of the applicable actions specified in Boeing Service Bulletin 767–57–0053, dated June 27, 1996, or Revision 1, dated October 31, 1996, prior to the effective date of this AD, is considered acceptable for compliance with the actions required by paragraph (b) of this AD.

Repair

(c) If any damage to airplane structure is found during the accomplishment of the modification required by paragraph (a) of this AD; and the service bulletin specifies to contact Boeing for appropriate action: Prior to further flight, repair in accordance with a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. For a repair method to be approved by the Manager, Seattle ACO, as required by this paragraph, the Manager's approval letter must specifically reference this AD.

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on July 3, 2000.

Vi L. Lipski,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00–17302 Filed 7–7–00; 8:45 am]

BILLING CODE 4910–13–U

DEPARTMENT OF COMMERCE

United States Patent and Trademark Office

37 CFR Part 1

RIN 0651–AB19

Treatment of Unlocatable Application and Patent Files

AGENCY: United States Patent and Trademark Office, Commerce.

ACTION: Notice of proposed rulemaking.

SUMMARY: The United States Patent and Trademark Office is proposing to amend the rules of practice to provide for the replacement of application and patent files that cannot be located after a reasonable search. This change is designed to expedite the process of application and patent file reconstruction to minimize the processing or examination delays resulting when the Office cannot locate an application or patent file after a reasonable search.

DATES: *Comment Deadline Date:* To be ensured of consideration, written comments must be received on or before August 9, 2000. No public hearing will be held.

ADDRESSES: Comments should be sent by electronic mail message over the Internet addressed to: reconstruct.comments@uspto.gov. Comments may also be submitted by mail addressed to: Box Comments—Patents, Commissioner for Patents, Washington, DC 20231; or by facsimile to (703) 872–9411, marked to the attention of Robert W. Bahr. Although comments may be submitted by mail or facsimile, the Office prefers to receive comments via the Internet. If comments are submitted by mail, the Office would prefer that the comments be submitted on a DOS formatted 3½ inch disk accompanied by a paper copy.

The comments will be available for public inspection at the Office of Patent