

(2) Will not affect intrastate aviation in Alaska, and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Pacific Scientific Company: Docket No. FAA-2013-0752; Product Identifier 2009-SW-44-AD.

(a) Applicability

This AD applies to Pacific Scientific Company rotary buckle assembly (buckle), part numbers (P/Ns) 1111430 and 1111475, all dash numbers. These buckles may be installed on but not limited to Bombardier Inc., Learjet Inc., Textron Aviation, Inc. (Type Certificate (TC) previously held by Cessna Aircraft Company), and Viking Air Limited (TC previously held by de Havilland, Inc.) model airplanes and Airbus Helicopters (TC previously held by Eurocopter France) model helicopters, certificated in any category.

Note 1 to paragraph (a): The rotary buckle may be included as a component of a different part-numbered restraint system assembly. Pacific Scientific Service Bulletin SB 25-1111432, dated May 22, 2007 (SB 25-1111432), Appendix 1, includes a list of these restraint system P/Ns.

(b) Unsafe Condition

This AD defines the unsafe condition as a cracked rotary buckle handle, which could prevent a strap from releasing as intended when the buckle is rotated.

(c) Comments Due Date

The FAA must receive comments on this SNPRM November 9, 2020.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

(1) Within 6 months, inspect the buckle handle for a crack. If the buckle handle is cracked, before further flight, remove the buckle as depicted in Figure 5 and by following the Procedures, paragraph 9, of SB 25-1111432, and replace it with an airworthy buckle, except you are not required to return the removed buckle to Pacific Scientific.

(2) Within 12 months, measure the thickness of the buckle handle vane as depicted in Figure 3 of SB 25-1111432. If the handle vane thickness is 0.125 inch or greater, before further flight, remove the buckle from service and replace it with an airworthy buckle.

(3) As of the effective date of this AD, do not install a buckle or a restraint system with a buckle, P/N 1111430 or 1111475, all dash numbers, with a handle vane thickness of 0.125 inch or greater on any airplane or helicopter.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, may approve AMOCs for this AD. Send your proposal to: Kristi Bradley, Aviation Safety Engineer, International Validation Branch, General Aviation and Rotorcraft Unit, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817-222-5110; email kristin.bradley@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, the FAA suggests that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information

The subject of this AD is addressed in European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD No. 2007-0256, dated September 19, 2007. You may view the EASA AD on the internet at <https://www.regulations.gov> in Docket No. FAA-2013-0752.

(h) Subject

Joint Aircraft Service Component (JASC)
Code: 2500, Cabin Equipment/Furnishings.

Issued on September 14, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-20624 Filed 9-23-20; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-0850; Project Identifier AD-2020-00288-E]

RIN 2120-AA64

Airworthiness Directives; General Electric Company Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain GENx-1B64, 1B64/P1, -1B64/P2, -1B67, -1B67/P1, -1B67/P2, -1B70, -1B70/75/P1, -1B70/75/P2, -1B70/P1, -1B70/P2, -1B70C/P1, -1B70C/P2, -1B74/75/P1, -1B74/75/P2, -1B76/P2, -1B76A/P2, -2B67, -2B67/P, and -2B67B model turbofan engines. This proposed AD was prompted by a finding during an inspection by the manufacturer that two stages 6-10 compressor rotor spools in the high-pressure compressor (HPC) assembly were damaged at similar locations. Additionally, the manufacturer reported that certain stages 6-10 compressor rotor spool webs did not undergo a required fluorescent penetrant inspection (FPI) during production. This proposed AD would require inspection of the stages 6-10 compressor rotor spool and, depending on the result of the inspection, replacement of the stages 6-10 compressor rotor spool with a part eligible for installation. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by November 9, 2020.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** 202-493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact General Electric Company, 1 Neumann Way, Cincinnati,

OH 45215; phone: (513) 552-3272; email: aviation.fleetsupport@ae.ge.com; website: www.ge.com. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0850; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT: Mehdi Lamnyi, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7743; fax: (781) 238-7199; email: Mehdi.Lamnyi@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2020-0850; Project Identifier AD-2020-00288-E" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this NPRM because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact received about this proposed AD.

Confidential Business Information

Confidential Business Information (CBI) is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial

information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Mehdi Lamnyi, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA received a report from the manufacturer that an inspection had found two stages 6-10 compressor rotor spools in the HPC assembly damaged at similar locations on the webs. The subsequent investigation determined that tool marks were created during the manufacturing process. In addition, the manufacturer also reported that certain stages 6-10 compressor rotor spool webs did not undergo a required FPI during production. This condition, if not addressed, could result in failure of the compressor rotor spool, uncontained release of debris, damage to the engine, and damage to the airplane.

FAA's Determination

The FAA is proposing this AD because the agency evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Related Service Information Under 1 CFR Part 51

The FAA reviewed GE GENx-1B Service Bulletin (SB) 72-0472 R01, dated July 24, 2020 ("GENx-1B SB 72-0472") and GE GENx-2B SB 72-0415 R01, dated July 24, 2020 ("GENx-2B SB 72-0415").

GENx-1B SB 72-0472 describes procedures for performing a borescope inspection (BSI) or an eddy current inspection (ECI) of stage 6, stage 7, and stage 8 webs, web transitions, and bore faces of the stages 6-10 compressor rotor spool for GENx-1B model turbofan engines. GENx-1B SB 72-0472 also provides the affected part and serial numbers of the stages 6-10 compressor rotor spools installed on GENx-1B model turbofan engines.

GENx-2B SB 72-0415 describes procedures for performing a BSI or an

ECI of stage 6, stage 7, and stage 8 webs, web transitions, and bore faces of the stages 6-10 compressor rotor spool for GENx-2B model turbofan engines. GENx-2B SB 72-0415 also provides the affected part and serial numbers of the stages 6-10 compressor rotor spools installed on GENx-2B model turbofan engines.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Other Related Service Information

The FAA also reviewed Subtask 72-31-45-160-002 of TASK 72-31-45-200-807 in GE GENx-1B Engine Manual 05-21-00, Life Limits 001 Mandatory Inspections, Rev. 31 dated, January 31, 2020; and Subtask 72-31-45-160-002 of TASK 72-31-45-200-801 in GE GENx-2B Engine Manual 05-21-00, Life Limits 001 Mandatory Inspections, Rev. 24 dated, January 31, 2020. The Subtasks provide guidance on performing the ECI on the stages 6-10 compressor rotor spool on GE GENx-1B and GENx-2B model turbofan engines.

The FAA also reviewed the following GE SBs: GENx-1B SB 72-0448 R00, dated July 29, 2019 ("GENx-1B SB 72-0448"); GENx-1B SB 72-0460 R00, dated October 30, 2019 ("GENx-1B SB 72-0460"); GENx-2B SB 72-0385 R02, dated July 29, 2019 ("GENx-2B SB 72-0385"); and GENx-2B SB 72-0398 R00, dated October 30, 2019 ("GENx-2B SB 72-0398").

GENx-1B SB 72-0448 describes procedures for performing a BSI or an ECI of the stage 8 aft web of the HPC stages 6-10 rotor spool for GENx-1B model turbofan engines. GENx-1B SB 72-0460 describes procedures for performing a BSI or an ECI of the stage 6 and stage 7 aft web of the HPC stages 6-10 rotor spool for GENx-1B model turbofan engines.

GENx-2B SB 72-0385 describes procedures for performing a BSI or an ECI of the stage 8 aft web of the HPC stages 6-10 spool for GENx-2B model turbofan engines. GENx-2B SB 72-0398 describes procedures for performing a BSI or an ECI of the stage 6 and stage 7 aft web of the HPC stages 6-10 rotor spool for GENx-2B model turbofan engines.

Proposed AD Requirements in This NPRM

This proposed AD would require inspection of the stages 6-10 compressor rotor spool. Certain affected GENx-1B or GENx-2B model turbofan engines, identified in paragraphs (g)(1)(i) and (g)(1)(ii) of this proposed

AD, have already completed acceptable inspections of the aft web of stage 6, stage 7, and stage 8 of the stages 6–10 compressor rotor spool. This proposed AD would require those affected engines to complete the inspection of the stages 6–10 compressor rotor spool by the next engine shop visit. All other affected GENx–1B or GENx–2B model turbofan

engines would be required to complete inspection of the stages 6–10 compressor rotor spool before exceeding the compliance times in Table 1 to paragraph (g)(1) of this AD. Depending on the results of the inspection, this AD would require replacement of the stages 6–10 compressor rotor spool with a part eligible for installation.

Costs of Compliance

The FAA estimates that this AD, as proposed, would affect 268 engines installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
BSI of GENx–1B stage 6, stage 7, and stage 8 aft webs, web transitions and bore faces of the stages 6–10 compressor rotor spool.	6 work-hours × \$85 per hour = \$510	\$0	\$510	\$89,760
BSI of GENx–2B stage 6, stage 7, and stage 8 aft webs, web transitions and bore faces of the stages 6–10 compressor rotor spool.	6 work-hours × \$85 per hour = \$510	0	510	46,920

The FAA estimates the following costs to do any necessary replacements that would be required based on the

results of the proposed inspection. The FAA has no way of determining the

number of aircraft that might need these replacements:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Replace the stages 6–10 compressor rotor spool	64 work-hours × \$85 per hour = \$5,440	\$1,018,600	\$1,024,040

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

General Electric Company: Docket No. FAA–2020–0850; Project Identifier AD–2020–00288–E.

■ (a) Comments Due Date

The FAA must receive comments by November 9, 2020.

■ (b) Affected ADs

None.

■ (c) Applicability

This AD applies to:

(1) General Electric Company (GE) GENx–1B64, GENx–1B64/P1, GENx–1B64/P2, GENx–1B67, GENx–1B67/P1, GENx–1B67/P2, GENx–1B70, GENx–1B70/75/P1, GENx–1B70/75/P2, GENx–1B70/P1, GENx–1B70/P2, GENx–1B70C/P1, GENx–1B70C/P2, GENx–1B74/75/P1, GENx–1B74/75/P2, GENx–1B76/P2, GENx–1B76A/P2 model turbofan engines with stages 6–10 compressor rotor spools in the high-pressure compressor (HPC) assembly with the following part numbers (P/N) installed:

(i) P/N 2357M30G01, P/N 2357M30G02, P/N 2439M35G01, P/N 2439M35G02, or P/N 2445M40G02, all serial numbers (S/Ns);

(ii) P/N 2610M90G01 with the S/Ns listed in paragraph 4., APPENDIX—A, Table 1 of the GE GENx–1B Service Bulletin (SB) 72–0472 R01, dated July 24, 2020 (“SB 72–0472”); and

(iii) P/N 2628M56G01 with the S/Ns listed in paragraph 4., APPENDIX—A, Table 2 or Table 3 of SB 72–0472.

(2) GENx–2B67, GENx–2B67/P, GENx–2B67B model turbofan engines with the following stages 6–10 compressor rotor spools P/Ns installed:

(i) P/N 2357M30G02, P/N 2439M35G02, or P/N 2445M40G02, all S/Ns;

(ii) P/N 2340M36G01 with S/Ns listed in paragraph 4., APPENDIX—A, Table 1 of GE GENx-2B SB 72-0415 R01, dated July 24, 2020 (“SB 72-0415”); and

(iii) P/N 2628M56G01 with S/Ns listed in paragraph 4., APPENDIX—A, Table 2 or Table 3 of SB 72-0415.

(d) Subject

Joint Aircraft System Component (JASC) Code 7230, Turbine Engine Compressor Section.

(e) Unsafe Condition

This AD was prompted by a finding during an inspection that two stages 6-10

compressor rotor spools were damaged at similar locations. In addition, the manufacturer reported that certain stages 6-10 compressor rotor spool webs did not undergo a required fluorescent penetrant inspection (FPI) during production. The FAA is issuing this AD to prevent failure of the compressor rotor spool. The unsafe condition, if not addressed, could result in uncontained release of debris, damage to the engine, and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) For all affected GENx-1B and GENx-2B model turbofan engines, before exceeding the compliance time in Table 1 to paragraph (g)(1) of this AD, perform a borescope inspection (BSI) or eddy current inspection (ECI) of the stage 6, stage 7, and stage 8 webs, web transitions, and bore faces of the stages 6-10 compressor rotor spool in accordance with the Accomplishment Instructions, paragraph 3, of SB 72-0472 (for GENx-1B models) or the Accomplishment Instructions, paragraph 3, of SB 72-0415 (for GENx-2B models).

Table 1 to Paragraph (g)(1)

Cycles Since New (CSN) Accumulated on the stages 6-10 compressor rotor spool	Compliance Time
Less than 6,500 CSN	Next engine shop visit or before the stages 6-10 compressor rotor spool accumulates 6,500 CSN, whichever occurs first after the effective date of this AD
6,500 CSN or greater	Before further flight

(i) For GENx-1B model turbofan engines, except those identified in paragraph 4., APPENDIX—A, Table 3 of SB 72-0472, if the engines have previously undergone inspections of the aft web of stage 6, stage 7, and stage 8 of the stages 6-10 compressor rotor spool using both GE GENx-1B SB 72-0448 R00, dated July 29, 2019, and GE GENx-1B SB 72-0460 R00, dated October 30, 2019, regardless of the CSN accumulated on the stages 6-10 compressor rotor spool, perform the inspection required by paragraph (g)(1) of this AD no later than the next engine shop visit after the effective date of this AD.

(ii) For GENx-2B model turbofan engines, except those identified in paragraph 4., APPENDIX—A, Table 3 of SB 72-0415, if the engines have previously undergone inspections of the aft web of stage 6, stage 7, and stage 8 of the stages 6-10 compressor rotor spool using both GE GENx-2B SB 72-385 R02, dated July 29, 2019, and GE GENx-2B SB 72-0398 R00, dated October 30, 2019, regardless of the CSN accumulated on the stages 6-10 compressor rotor spool, perform the inspection required by paragraph (g)(1) of this AD no later than the next engine shop visit after the effective date of this AD.

(2) For all affected GENx-1B and GENx-2B model turbofan engines, during the inspections required by paragraph (g)(1) of this AD, if a rejectable indication is found, before further flight, remove the stages 6-10 compressor rotor spool from service and replace it with a part eligible for installation.

(h) Definition

For the purpose of this AD, an “engine shop visit” is the induction of an engine into the shop for maintenance involving the separation of pairs of major mating engine

flanges, except that the separation of engine flanges solely for the purposes of transportation of the engine without subsequent engine maintenance does not constitute an engine shop visit.

(i) Credit for Previous Action

(1) For affected GENx-1B model turbofan engines, you may take credit for the BSI or ECI required by paragraph (g)(1) of this AD, if the stages 6-10 compressor rotor spool webs, web transitions, and bore faces previously received an ECI using Subtask 72-31-45-160-002 of TASK 72-31-45-200-807 in GE GENx-1B Engine Manual 05-21-00, Life Limits 001 Mandatory Inspections, Rev. 31 dated, January 31, 2020, or earlier, and no rejectable indications were found.

(2) For affected GENx-2B model turbofan engines, you may take credit for the BSI or ECI required by paragraph (g)(1) of this AD, if the stages 6-10 compressor rotor spool webs, web transitions, and bore faces previously received an ECI using Subtask 72-31-45-160-002 of TASK 72-31-45-200-801 in GE GENx-2B Engine Manual 05-21-00, Life Limits 001 Mandatory Inspections, Rev. 24 dated, January 31, 2020, or earlier, and no rejectable indications were found.

(3) For affected GENx-1B and GENx-2B model turbofan engines, you may take credit for the BSI or ECI required by paragraph (g)(1) of this AD, if you performed these inspections using GE GENx-1B Service Bulletin (SB) 72-0472 R00, dated April 24, 2020, or GE GENx-2B SB 72-0415 R00, dated April 24, 2020, respectively, and no rejectable indications were found.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k)(1) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

(1) For more information about this AD, contact Mehdi Lamnyi, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7743; fax: (781) 238-7199; email: Mehdi.Lamnyi@faa.gov.

(2) For service information identified in this AD, contact General Electric Company, 1 Neumann Way, Cincinnati, OH 45215; phone: (513) 552-3272; email: aviation.fleetsupport@ae.ge.com; website: www.ge.com. You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759.

Issued on September 17, 2020.

Gaetano A. Sciortino,

*Deputy Director for Strategic Initiatives,
Compliance & Airworthiness Division,
Aircraft Certification Service.*

[FR Doc. 2020-20947 Filed 9-23-20; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2020-0835; Airspace
Docket No. 20-AEA-16]

RIN 2120-AA66

Proposed Establishment of Class E Airspace; Toughkenamon, PA

AGENCY: Federal Aviation
Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking
(NPRM).

SUMMARY: This action proposes to establish Class E airspace extending upward from 700 feet above the surface for New Garden Airport, Toughkenamon, PA, to accommodate new instrument procedures designed for the airport. Controlled airspace is necessary for the safety and management of instrument flight rules (IFR) operations in the area.

DATES: Comments must be received on or before November 9, 2020.

ADDRESSES: Send comments on this proposal to: The U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue SE, West Building Ground Floor, Room W12-140, Washington, DC 20590-0001; Telephone: (800) 647-5527, or (202) 366-9826. You must identify the Docket No. FAA-2020-0835; Airspace Docket No. 20-AEA-16, at the beginning of your comments. You may also submit comments through the internet at <https://www.regulations.gov>.

FAA Order 7400.11E, Airspace Designations and Reporting Points, and subsequent amendments can be viewed on line at https://www.faa.gov/air_traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; Telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11E at NARA, email fedreg.legal@nara.gov or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

FOR FURTHER INFORMATION CONTACT: John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, 1701 Columbia Avenue, College Park, GA 30337; Telephone (404) 305-6364.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would establish Class E airspace for New Garden Airport, Toughkenamon, PA, to support IFR operations in the area.

Comments Invited

Interested persons are invited to comment on this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (Docket No. FAA-2020-0835 and Airspace Docket No. 20-AEA-16) and be submitted in triplicate to DOT Docket Operations (see **ADDRESSES** section for the address and phone number). You may also submit comments through the internet at <https://www.regulations.gov>.

Persons wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed stamped postcard on which the following statement is made: "Comments to FAA Docket No. FAA-2020-0835; Airspace Docket No. 20-AEA-16". The postcard will be date/time stamped and returned to the commenter.

All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this document may be changed in light of the comments

received. All comments submitted will be available for examination in the public docket both before and after the comment closing date. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRMs

An electronic copy of this document may be downloaded through the internet at <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's web page at https://www.faa.gov/air_traffic/publications/airspace_amendments/.

You may review the public docket containing the proposal, any comments received and any final disposition in person in the Dockets Office (see the **ADDRESSES** section for address and phone number) between 9:00 a.m. and 5:00 p.m., Monday through Friday, except federal holidays. An informal docket may also be examined between 8:00 a.m. and 4:30 p.m., Monday through Friday, except federal holidays at the office of the Eastern Service Center, Federal Aviation Administration, Room 350, 1701 Columbia Avenue, College Park, GA 30337.

Availability and Summary of Documents for Incorporation by Reference

This document proposes to amend FAA Order 7400.11E, Airspace Designations and Reporting Points, dated July 21, 2020, and effective September 15, 2020. FAA Order 7400.11E is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.11E lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Proposal

The FAA proposes an amendment to Title 14 Code of Federal Regulations (14 CFR) part 71 to establish Class E airspace extending upward from 700 feet above the surface as new instrument approach procedures have been designed for New Garden Airport, Toughkenamon, PA.

Class E airspace designations are published in Paragraph 6005, of FAA Order 7400.11E, dated July 21, 2020, and effective September 15, 2020, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in the Order.

FAA Order 7400.11, Airspace Designations and Reporting Points, is