

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2002-16-11 Boeing: Amendment 39-12850. Docket 2000-NM-333-AD.

Applicability: Model 777 series airplanes, line numbers 1 through 263 inclusive; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent breakage of the aft axle pivot pin of the main landing gear (MLG), which could overload the center axle, causing the tires to blow out upon landing, and could disengage the aft axle so that it jams the gear in the wheel well, preventing proper extension of the MLG, accomplish the following:

Inspection

(a) Within 18 months after the effective date of this AD: Perform the actions specified in paragraph (a)(1) or (a)(2) of this AD, as applicable, in accordance with Boeing Special Attention Service Bulletin 777-32-0029, dated May 18, 2000.

(1) For airplanes which have line numbers 1 through 68 inclusive (designated as Group 1 airplanes in the service bulletin), and on which the aft axle pivot pin of the MLG has been replaced prior to the effective date of

this AD: Inspect the serial number of the pivot pin.

(i) If the serial number of the pivot pin does not have the prefix of EGL, no further action is required.

(ii) If the serial number of the pivot pin does have the prefix of EGL, within 18 months after the effective date of this AD, perform the actions required by paragraph (a)(2) of this AD.

(2) For airplanes which have line numbers 69 through 263 inclusive (designated as Group 2 airplanes in the service bulletin): Remove the aft axle pivot pin, remove the lube insert from the aft axle pivot pin, and inspect the aft axle pivot pin for heat damage. The inspection must be done either by the Barkhausen Noise Inspection method for chromium-plated parts, or by following all of the procedures in Figure 2 of the service bulletin (including nital etching and a magnetic particle inspection), in accordance with the service bulletin.

(i) If heat damage is found by the inspection required by paragraph (a)(2) of this AD: Prior to further flight, re-work the existing aft axle pivot pin, re-install the existing lube insert, and re-install the re-worked aft axle pivot pin or install a new or serviceable aft axle pivot pin in the MLG, in accordance with the service bulletin.

(ii) If no heat damage is found by the inspection required by paragraph (a)(2) of this AD: Prior to further flight, re-install the existing lube insert and re-install the existing aft axle pivot pin or install a new or serviceable aft axle pivot pin in the MLG, in accordance with the service bulletin.

Spares

(b) After the effective date of this AD, no person shall install an aft axle pivot pin having a serial number with the prefix "EGL" in the MLG, unless the pivot pin has been inspected as required by paragraph (a) of this AD.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a

location where the requirements of this AD can be accomplished.

Incorporation by Reference

(e) The actions shall be done in accordance with Boeing Special Attention Service Bulletin 777-32-0029, dated May 18, 2000. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, PO Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(f) This amendment becomes effective on September 20, 2002.

Issued in Renton, Washington, on August 7, 2002.

Vi Lipski,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-20510 Filed 8-15-02; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NE-17-AD; Amendment 39-12846; AD 2002-16-07]

RIN 2120-AA64

Airworthiness Directives; Bombardier-Rotax GmbH Type 912 F, 912 S, and 914 F Series Reciprocating Engines

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to certain serial numbers (SN's) of Bombardier-Rotax GmbH type 912 F, 912 S and 914 F series reciprocating engines. This action requires replacement of the valve spring retainers, part number (P/N) 854.182, with the new-reinforced valve spring retainers, P/N 854.184. This amendment is prompted by reports of several cracked valve spring retainers discovered in-service. The actions

specified in this AD are intended to prevent cracking of the valve spring retainers resulting in possible engine failure while in-flight.

DATES: Effective September 3, 2002. The incorporation by reference of certain publications listed in the rule is approved by the Director of the Federal Register as of September 3, 2002.

Comments for inclusion in the Rules Docket must be received on or before October 15, 2002.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 2002-NE-17-AD, 12 New England Executive Park, Burlington, MA 01803-5299. Comments may be inspected at this location, by appointment, between 8 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays. Comments may also be sent via the Internet using the following address: "*g-ane-adcomment@faa.gov*". Comments sent via the Internet must contain the docket number in the subject line.

The service information referenced in this AD may be obtained from Bombardier-Rotax GmbH, Welser Strasse 32, A-4623 Gunskirchen, Austria; telephone 7246-601-232; fax 7246-601-370. Information regarding this action may be examined, by appointment, at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: James Lawrence, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park; Burlington, MA 01803-5299; telephone 781 238-7176; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION: Austro Control, which is the airworthiness authority for Austria, notified the FAA that an unsafe condition may exist on certain SN's of Bombardier-Rotax GmbH type 912 F, 912 S, and 914 F series reciprocating engines, that have been converted to a single valve spring arrangement. Austro Control advises that they have received reports of several cracks on valve spring retainers in-service. It has been discovered that during the starting procedure a delayed purging of the lubrication system could occur, which may result in cracking of the valve spring retainer. This condition can occur if one or more hydraulic valve tappets lose their oil prime and fill with air. This is possible at first engine run or at oil change. This condition can be

caused by improper purging of the lubrication system, non-compliance of starting and warming up instructions, unsuitable motor oil, or lack of maintenance. A detailed crack detection of the affected valve spring retainers is very difficult and would have to be performed repeatedly. Due to this fact, all affected engines must be equipped with reinforced valve spring retainers that are more resistant to cracking.

Manufacturer's Service Information

Bombardier-Rotax GmbH has issued Mandatory Service Bulletin (MSB) No. SB-912-022/SB-914-011, dated March, 2001, that specifies procedures for replacement of valve spring retainers P/N 854.182. The Austro Control classified this service bulletin as mandatory and issued AD No. 108, in order to assure the airworthiness of these Bombardier-Rotax GmbH engines in Austria.

Bilateral Airworthiness Agreement

This engine model is manufactured in Austria and is type certificated for operation in the United States under the provisions of § 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the Austro Control has kept the FAA informed of the situation described above. The FAA has examined the findings of the Austro Control, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

FAA's Determination of an Unsafe Condition and Required Actions

Since an unsafe condition has been identified that is likely to exist or develop on other Bombardier-Rotax GmbH 912 F, 912 S, and 914 F series reciprocating engines of the same type design, this AD is being issued to prevent cracking of the valve spring retainers resulting in possible engine failure while in-flight. This AD requires replacement of valve spring retainers, P/N 854.182, on engines with the single valve spring configuration, with new-reinforced valve spring retainers, P/N 854.184. The actions must be done in accordance with the service bulletin described previously.

Immediate Adoption of This AD

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good

cause exists for making this amendment effective in less than 30 days.

Comments Invited

Although this action is in the form of a final rule that involves requirements affecting flight safety and, thus, was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2002-NE-17-AD." The postcard will be date stamped and returned to the commenter.

Regulatory Analysis

This final rule does not have federalism implications, as defined in Executive Order 13132, because it would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Accordingly, the FAA has not consulted with state authorities prior to publication of this final rule.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and is not a "significant regulatory action" under Executive Order 12866. It

has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2002-16-07 Bombardier-Rotax GmbH:
Amendment 39-12846. Docket No. 2002-NE-17-AD.

Applicability

This airworthiness directive (AD) is applicable to Bombardier-Rotax GmbH type 912 F, 912 S, and 914 F series reciprocating engines with the serial numbers (SN's) in Table 1 of this AD, and all engines that have been converted to a single valve spring arrangement at engine repair or general overhaul. Table 1 follows:

TABLE 1.—ENGINE SERIES BY SN

Engine model	Engine SN
912 F	4,412.757 to 4,412.794 4,412.796 to 4,412.807
912 S	4,922.501 to 4,922.534 4,922.536 to 4,922.552 4,922.554 to 4,922.577 4,922.579 to 4,922.636
914 F	4,420.039 to 4,420.048 4,420.050 to 4,420.067 4,420.069 to 4,420.082 4,420.084 to 4,420.097 4,420.099 to 4,420.114 4,420.116 to 4,420.155 4,420.157 to 4,420.253

These engines are installed on, but not limited to, Diamond Aircraft Industries,

DA20-A1, Diamond Aircraft Industries GmbH Model HK 36 TTS, Model HK 36TTC, and Model HK 36 TTC-ECO, Iniziative Industriali Italiane S.p.A. Sky Arrow 650 TC and Sky Arrow 650 TCN, Aeromot-Industria Meccanica Metalurgica Ltda., Models AMT-300 and AMT-200S, and Stemme S10-VT aircraft.

Note 1: This AD applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance

Compliance with this AD is required as indicated, unless already done.

To prevent cracking of the valve spring retainers resulting in possible engine failure while in-flight, do the following:

Replacement Procedure

(a) Replace valve spring retainers part number (P/N) 854.182, of single valve spring configuration, with valve spring retainers P/N 854.184, in accordance with 3.1.1 of the Accomplishment Instructions of Mandatory Service Bulletin (MSB) SB-912-022/SB-914-011, dated March, 2001, using the compliance times in the following Table 2:

TABLE 2.—COMPLIANCE SCHEDULE

Engine flight hours (FH) on the effective date of this AD	Replace
(1) 0 FH (new engine)	Before installing on aircraft.
(2) 10 hours or less ..	Within 10 FH after the effective date of this AD.
(3) More than 10 but less than or equal to 25 FH.	Within 25 FH after the effective date of this AD.
(4) More than 25 FH	Before exceeding 100 FH.

(b) For engines that have had the oil system accessed during repair or maintenance, replace the valve spring retainers in accordance with 3.1.1 of the Accomplishment Instructions of Mandatory Service Bulletin (MSB) SB-912-022/SB-914-011, dated March, 2001, within 10 FH after the effective date of this AD.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office (ECO). Operators must submit their requests through an appropriate

FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, ECO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the ECO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the aircraft to a location where the requirements of this AD can be done.

Documents That Have Been Incorporated by Reference

(e) The replacements must be done in accordance with Bombardier-Rotax GmbH Mandatory Service Bulletin (MSB) SB-912-022/SB-914-011, dated March, 2001. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Bombardier-Rotax GmbH, Welser Strasse 32, A-4623 Gunskirchen, Austria; telephone 7246-601-232; fax 7246-601-370. Copies may be inspected at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in Austro Control airworthiness directive No. 108.

Effective Date

(f) This amendment becomes effective on September 3, 2002.

Issued in Burlington, Massachusetts, on August 2, 2002.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 02-20266 Filed 8-15-02; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-CE-30-AD; Amendment 39-12856; AD 2002-16-17]

RIN 2120-AA64

Airworthiness Directives; Barry Aviation, LLC Model PZL-Krosno KR-03A "Peregrine" (Puchatek) Sailplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to certain Barry Aviation, LLC