

shown in Figure 1 of Part A in Pacific Aerospace Mandatory Service Bulletin PACSB/XL/113, Issue 2, dated March 8, 2019 (MSB PACSB/XL/113, Issue 2).

(d) Subject

Joint Aircraft System Component (JASC) Code 2820, Aircraft Fuel Distribution, and 2497, Electrical Power System Wiring.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as chafing of the engine fuel feed line hoses. The FAA is issuing this AD to prevent chafing of the engine fuel feed line hoses with electrical wiring and the ignition exciter located forward of the engine firewall. The unsafe condition, if not addressed, could result in a fuel leak and fire.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Within 50 hours time-in-service (TIS) or at the next annual inspection after the effective date of this AD, whichever occurs later, inspect the engine fuel feed line hoses and the electrical wiring for chafing and damage in accordance with the Accomplishment Instructions, Part A steps (3) and (4), in MSB PACSB/XL/113, Issue 2.

(1) If there is any chafing or damage that penetrates the orange outer covering of the fuel line fire sleeve or if there is any chafed or damaged electrical wiring, before further flight, inspect the fuel hose for chafing, replace any chafed fire sleeve or fuel hose, and reroute all fuel lines in accordance with the Accomplishment Instructions, Part B, in MSB PACSB/XL/113, Issue 2.

(2) If there are no chafed or damaged engine fuel feed line hoses and no chafed or damaged electrical wiring, within 50 hours TIS or at the next annual inspection, whichever occurs later, reroute all fuel lines in accordance with the Accomplishment Instructions, Part B, in MSB PACSB/XL/113, Issue 2.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i)(1) of this AD or email: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Mike Kiesov, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4144; fax: (816) 329-4090; email: mike.kiesov@faa.gov.

(2) Refer to Civil Aviation Authority (CAA) of New Zealand AD DCA/750XL/37, effective April 25, 2019, for more information. You may examine the CAA AD in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0711.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Pacific Aerospace Mandatory Service Bulletin PACSB/XL/113, Issue 2, dated March 8, 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact the CAA of New Zealand, Level 15, Asteron Centre, 55 Featherston Street, Wellington 6011; phone: +64 4 560 9400; fax: +64 4 569 2024; email: info@caa.govt.nz.

(4) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on November 2, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-26496 Filed 12-6-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2021-0779; Project Identifier MCAI-2020-01505-R; Amendment 39-21817; AD 2021-23-18]

RIN 2120-AA64

Airworthiness Directives; Airbus Helicopters Deutschland GmbH Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Airbus Helicopters Deutschland GmbH Model MBB-BK 117 D-2 helicopters. This AD was prompted by a report of chafing marks on a wiring harness near the locking washer of the lateral control rod. This AD requires an inspection of the wiring harness and the routing of the wiring harness and corrective actions if necessary, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective January 11, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 11, 2022.

ADDRESSES: For EASA material incorporated by reference (IBR) in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADS@easa.europa.eu; internet: www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. It is incorporated by reference is also available in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0779.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0779; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the European Union Aviation Safety Agency (EASA) AD, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Jacob Fitch, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; phone: (817) 222-4130; email: jacob.fitch@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2020–0246, dated November 10, 2020 (EASA AD 2020–0246), to correct an unsafe condition for certain Airbus Helicopters Deutschland GmbH, formerly Eurocopter Deutschland GmbH Model MBB–BK 117 D–2 helicopters.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Airbus Helicopters Deutschland GmbH Model MBB–BK 117 D–2 helicopters. The NPRM published in the **Federal Register** on September 14, 2021 (86 FR 51042). The NPRM was prompted by a report of chafing marks on a wiring harness near the locking washer of the lateral control rod. The NPRM proposed to require an inspection of the wiring harness and the routing of the wiring harness and corrective actions if necessary, as specified in EASA AD 2020–0246.

The FAA is issuing this AD to address chafing marks on a wiring harness near the locking washer of the lateral control rod. The unsafe condition, if not addressed, could result in in-flight loss of the hoist load and possible personal

injury, or could generate a burning smell and possible need for the flight crew to implement the applicable emergency procedure. See EASA AD 2020–0246 for additional background information.

Discussion of Final Airworthiness Directive

Comments

The FAA received no comments on the NPRM or on the determination of the costs.

Conclusion

These helicopters have been approved by EASA and are approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with the European Union, EASA has notified the FAA about the unsafe condition described in its AD. The FAA reviewed the relevant data and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these helicopters. Except for minor editorial changes, this AD is adopted as proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

EASA AD 2020–0246 requires an inspection of the wiring harness and the

routing of the wiring harness for discrepancies (includes damaged wire harnesses and insufficient clearances) and corrective actions (includes repair of wire harnesses and re-routing the wire harness) if necessary, and an update of the Aircraft Maintenance Programme (AMP) to incorporate certain tasks. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Differences Between This AD and the EASA AD

EASA AD 2020–0246 requires revising the “Aircraft Maintenance Programme (AMP),” whereas this proposed AD would not because not all U.S. operators are required to have a maintenance program.

Costs of Compliance

The FAA estimates that this AD affects 31 helicopters of U.S. Registry. Labor rates are estimated at \$85 per work-hour. Based on these numbers, the FAA estimates the following costs to comply with this AD.

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$2,635

The FAA estimates the following costs to do any necessary repairs and re-

routing that would be required based on the results of the inspection. The agency

has no way of determining the number of aircraft that might need these repairs:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Repairs and re-routing	Up to 1 work-hour × \$85 per hour = \$85	* \$0	\$85

* The FAA has received no definitive data on which to base the cost estimates for the on-condition repairs specified in this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA

with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order

13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative,

on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021–23–18 Airbus Helicopters

Deutschland GmbH: Amendment 39–21817; Docket No. FAA–2021–0779; Project Identifier MCAI–2020–01505–R.

(a) Effective Date

This airworthiness directive (AD) is effective January 11, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Helicopters Deutschland GmbH Model MBB–BK 117 D–2 helicopters, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2020–0246, dated November 10, 2020 (EASA AD 2020–0246).

(d) Subject

Joint Aircraft Service Component (JASC) Code: 2597, Equip/Furnishing System Wiring.

(e) Unsafe Condition

This AD was prompted by a report of chafing marks on a wiring harness near the locking washer of the lateral control rod. The FAA is issuing this AD to address chafing marks on a wiring harness near the locking washer of the lateral control rod. The unsafe condition, if not addressed, could result in in-flight loss of the hoist load and possible personal injury, or could generate a burning smell and possible need for the flight crew to implement the applicable emergency procedure.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2020–0246.

(h) Exceptions to EASA AD 2020–0246

(1) Where EASA AD 2020–0246 requires compliance in terms of flight hours, this AD requires using hours time-in-service.

(2) Where EASA AD 2020–0246 refers to its effective date, this AD requires using the effective date of this AD.

(3) Where Paragraph (3) of EASA AD 2020–0246 specifies to update the Aircraft Maintenance Programme (AMP) with certain tasks included in the service information referenced by EASA AD 2020–0246, this AD does not include that requirement.

(4) This AD does not require the “Remarks” section of EASA AD 2020–0246.

(i) Special Flight Permit

Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the actions of this AD can be performed, provided that no debris from chafing is visible that would allow jamming or fouling of the flight controls, the chafing does not interfere with the flight controls by jamming or fouling, and the systems impacted by the wiring harness are rendered inoperable by collaring the circuit breaker.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact Jacob Fitch, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; phone: (817) 222–4130; email: jacob.fitch@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2020–0246, dated November 10, 2020.

(ii) [Reserved].

(3) For EASA AD 2020–0246, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADS@easa.europa.eu; internet:

www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0779.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on November 4, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–26497 Filed 12–6–21; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2021–0213; Project Identifier 2018–CE–036–AD; Amendment 39–21818; AD 2021–23–19]

RIN 2120–AA64

Airworthiness Directives; Pacific Aerospace Limited Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Pacific Aerospace Limited Model 750XL airplanes. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as insufficient separation of ground terminations for individual power sources and static grounds. This AD requires inspecting and separating, if applicable, the battery and generator common ground connections on the airframe. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective January 11, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 11, 2022.