(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120–0056.

Related Information

(g) Refer to MCAI Airworthiness Authority of New Zealand AD DCA/R2000/12, dated June 29, 2006, and Avions Pierre Robin Service Bulletin 86, dated July 30, 1980, for related information.

Issued in Kansas City, Missouri, on December 28, 2006.

John R. Colomy,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-49 Filed 1-5-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-26598; Directorate Identifier 2006-CE-87-AD]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Models EMB-110P1 and EMB-110P2 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

It has been found cases of corrosion at regions of Wings-to-Fuselage attachments, Vertical Stabilizer to Fuselage attachments, Rib 1 Half-wing and Passenger Seat Tracks. Such corrosion may lead to subsequent fatigue cracking of the parts affected, reducing the aircraft structural integrity, which may in turn lead to structural failure and/or loss of some control surface.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by February 7, 2007.

ADDRESSES: You may send comments by any of the following methods:

- *DOT Docket Web site:* Go to *http://dms.dot.gov* and follow the instructions for sending your comments electronically.
 - Fax: (202) 493-2251.
- *Mail:* Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL–401, Washington, DC 20590–0001.
- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- Federal eRulemaking Portal: http://www.regulations.gov. Follow the instructions for submitting comments.

Examining the AD Docket

You may examine the AD docket on the Internet at http://dms.dot.gov; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647–5227) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Karl Schletzbaum, Aerospace Engineer, 901 Locust, Room 301, Kansas City, Missouri, 64106; telephone (816) 329–4146; fax (816) 329–4090.

SUPPLEMENTARY INFORMATION:

Streamlined Issuance of AD

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. The streamlined process will allow us to adopt MCAI safety requirements in a more efficient manner and will reduce safety risks to the public. This process continues to follow all FAA AD issuance processes to meet legal, economic, Administrative Procedure Act, and Federal Register requirements. We also continue to meet our technical decision-making responsibilities to identify and correct unsafe conditions on U.S.-certificated products.

This proposed AD references the MCAI and related service information that we considered in forming the engineering basis to correct the unsafe condition. The proposed AD contains

text copied from the MCAI and for this reason might not follow our plain language principles.

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the ADDRESSES section. Include "Docket No. FAA-2006-26598; Directorate Identifier 2006-CE-87-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to http://dms.dot.gov, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The National Agency of Civil Aviation (ANAC), which is the aviation authority for Brazil, has issued AD No.: 2006–10–01, dated October 25, 2006 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

It has been found cases of corrosion at regions of Wings-to-Fuselage attachments, Vertical Stabilizer to Fuselage attachments, Rib 1 Half-wing and Passenger Seat Tracks. Such corrosion may lead to subsequent fatigue cracking of the parts affected, reducing the aircraft structural integrity, which may in turn lead to structural failure and/or loss of some control surface.

You may obtain further information by examining the MCAI in the AD docket.

The MCAI requires:

Inspection for corrosion at regions of Wings-to Fuselage attachments, Vertical Stabilizer to Fuselage attachments, Rib 1 Half-wing and Passenger Seat Tracks; and if applicable, removal of the detected corrosion.

Relevant Service Information

Embraer—Empresa Brasileira de Aeronáutica S.A. (EMBRAER) has issued Service Bulletin S.B. No.: 110–00–0007, dated May 10, 2006. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This Proposed AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are described in a separate paragraph of the proposed AD. These requirements, if ultimately adopted, will take precedence over the actions copied from the MCAI.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 42 products of U.S. registry. We also estimate that it would take about 942 work-hours per product to comply with the proposed AD. The average labor rate is \$80 per work-hour. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$3,165,120 or \$75,360 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition

that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- 1. Is not a "significant regulatory action" under Executive Order 12866;
- 2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- 3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Empresa Brasileira de Aeronáutica S.A. (EMBRAER): Docket No. FAA-2006-26598; Directorate Identifier 2006-CE-87-AD.

Comments Due Date

(a) We must receive comments by February 7, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Models EMB–110P1 and EMB–P2 airplanes, all serial numbers, certificated in any category.

Reason

(d) The mandatory continuing airworthiness information (MCAI) states:

It has been found cases of corrosion at regions of Wings-to-Fuselage attachments, Vertical Stabilizer to Fuselage attachments, Rib 1 Half-wing and Passenger Seat Tracks. Such corrosion may lead to subsequent fatigue cracking of the parts affected, reducing the aircraft structural integrity, which may in turn lead to structural failure and/or loss of some control surface.

Actions and Compliance

- (e) Unless already done, do the following actions.
- (1) Within the next 30 days or 100 hours time-in-service after the effective date of this AD, whichever occurs first, carry out a general visual inspection (GVI) for corrosion at the regions of the Wings-to-fuselage attachments, Vertical Stabilizer to Fuselage attachments, Rib 1 Half-wing, and Passenger Seat Tracks, according to Parts I, II, and III of the Embraer—Empresa Brasileira de Aeronautica S.A. (EMBRAER) Service Bulletin S.B. No.: 110–00–0007, dated May 10, 2006.
- (i) All structures found corroded or cracked as a result of the inspections conducted above, must be addressed prior to further flight in accordance with detailed instructions and procedures described in EMBRAER Service Bulletin S.B. No.: 110–00–0007, dated May 10, 2006.
- (ii) Previous accomplishment of the EMBRAER Alert Service Bulletin S.B. No.: 110–00–A007, dated March 6, 2006, or the implementation of the tasks above, required by section VI of the Maintenance Planning Guides TP 110P2/145, PM 110/652, or PM 110/165, are considered acceptable methods of compliance with the requirements of (e)(1) of this AD.
- (2) Within the next 30 days after the effective date of this AD, accomplish Part IV of the EMBRAER Service Bulletin S.B. No.: 110–00–0007, dated May 10, 2006. All structures found corroded or cracked as a result of the inspections conducted above, must be addressed prior to further flight in accordance with detailed instructions and procedures described in EMBRAER Service Bulletin S.B. No.: 110–00–0007, dated May 10, 2006.
- (3) Within the next 12 months after the effective date of this AD, accomplish Part V of the EMBRAER Service Bulletin S.B. No.: 110–00–0007, dated May 10, 2006. All structures found corroded or cracked as a result of the inspections conducted above, must be addressed prior to further flight in accordance with detailed instructions and procedures described in EMBRAER Service Bulletin S.B. No.: 110–00–0007, dated May 10, 2006.

Note 1: For the purpose of this AD a GVI is: "A visual examination of an interior or exterior area, installation or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance, unless otherwise specified. A mirror may be necessary to enhance visual access to all exposed surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight; and may require removal or opening of

access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

FAA AD Differences

Note 2: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(f) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Staff, FAA, ATTN: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(g) Refer to MCAI National Agency of Civil Aviation (ANAC) AD No.: 2006-10-01, dated October 25, 2006, EMBRAER Service Bulletin S.B. No.: 110-00-0007, dated May 10, 2006, and EMBRAER Alert Service Bulletin S.B. No.: 110-00-A007, dated March 6, 2006 for related information.

Issued in Kansas City, Missouri, on December 28, 2006.

John R. Colomy,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-51 Filed 1-5-07; 8:45 am]

BILLING CODE 4910-13-P

SECURITIES AND EXCHANGE COMMISSION

17 CFR Part 270

[File No. S7-03-04]

RIN 3235-AJ62

Investment Company Governance

AGENCY: Securities and Exchange Commission.

ACTION: Notice of comment deadline.

On December 21, 2006, the Commission published a document in the Federal Register reopening the

comment period on its June 2006 request for comment regarding amendments to investment company governance provisions ("Request for Additional Comment") (Investment Company Release No. 27600 (Dec. 15, 2006) [71 FR 76618 (Dec. 21, 2006) (FR Doc. No. E6–21903)]). The purpose of the additional comment period is to permit public comment on two papers prepared by the Office of Economic Analysis on this topic. The Request for Additional Comment stated that comments must be received on or before 60 days after publication of the second of the two staff economic papers in the public comment file. The second of these papers was published in the public comment file on December 29, 2006, and both papers are available on the Commission's Internet Web site (http://www.sec.gov/rules/proposed/ s70304/oeamemo122906powerstudy.pdf; http://www.sec.gov/ rules/proposed/s70304/

oeamemo122906-litreview.pdf).

Comments must be received on or before March 2, 2007.

Dated: December 29, 2006.

Jill M. Peterson,

Assistant Secretary.

[FR Doc. E7-13 Filed 1-5-07; 8:45 am]

BILLING CODE 8011-01-P

DEPARTMENT OF COMMERCE

International Trade Administration

19 CFR Part 351

[Docket No. 061121303-6301-01]

RIN 0625-AA73

Antidumping and Countervailing Duty Proceedings: Documents Submission Procedures: APO Procedures: Proposed Rule

AGENCY: Import Administration, International Trade Administration, Department of Commerce.

ACTION: Proposed Rule; request for Comments.

SUMMARY: The Department of Commerce ("the Department") proposes to amend its regulations in antidumping ("AD") and countervailing duty ("CVD") proceedings governing information submitted to the Department and administrative protective orders in order to improve the Department's procedures and provide clarification to some aspects of the Department's regulations. Specifically, the Department proposes to amend its regulations as follows: To reflect a transfer in the function of

receiving submissions filed in AD/CVD proceedings from the Central Records Unit to the Administrative Protective Order ("APO") Unit, and to change the name of the APO Unit to APO/Dockets Unit: to reflect a transfer in the function of maintaining public service lists from the Central Records Unit to the APO/ Dockets Unit; to update the definition of "Customs Service" to reflect the reorganization of the Executive Branch; to clarify that documents filed with the Department will only be time stamped when appropriate, for example, when an interested party submits a request for treatment as a voluntary respondent; to clarify when an APO will be placed on the record with respect to new shipper reviews, applications for scope rulings and changed circumstances reviews; to clarify when a party must serve business proprietary information already on the administrative record to new authorized applicants to the APO; to require a formal letter of appearance to request placement on the service list of any segment of an AD/CVD proceeding; and to clarify when a party is to be considered an "interested party" for the purposes of the APO. Finally, the Department proposes amending its short form application for an APO (Form ITA-367).

DATES: To be assured of consideration, written comments must be received no later than February 28, 2007.

ADDRESSES: Submit comments to David M. Spooner, Assistant Secretary for Import Administration, U.S. Department of Commerce, Central Records Unit, Room 1870, Pennsylvania Avenue and 14th Street, NW., Washington, DC 20230; Attention: APO Regulations.

FOR FURTHER INFORMATION CONTACT: Ann Sebastian at (202) 482-3354 or William Kovatch at (202) 482-5052.

SUPPLEMENTARY INFORMATION:

Background

Pursuant to section 777(c)(1)(A) of the Tariff Act of 1930, as amended ("the Act") (19 U.S.C. 1677f(c)(1)(A)), the Department must make available to interested parties, under an APO, all business proprietary information submitted to it during the course of an antidumping or countervailing duty proceeding. Section 777(c)(1)(B) of the Act authorizes the Department to issue regulations governing the APO process. The Department's current regulations are codified at 19 CFR Part 351.

The Department last amended its APO regulations in 1998 (see 63 FR 24391). The Department is always interested in reviewing its APO procedures and improving them through its regulations. Since the adoption of regulations in