

(1) *Group 1 (maintains the actions from AD 82-07-04):*

Model	Serial Nos.
(i) G-164A ...	1726A through 1730A.
(ii) G-164B ..	335B through 659B.
(iii) G-164C	1C through 44C.
(iv) G-164D	1D through 22D.

(2) *Group 2:*

Model	Serial Nos.
(i) G-164	All.

Model	Serial Nos.
(ii) G-164A	All except 1726A through 1730A.
(iii) G-164B and G-164B with 73" wing gap.	All except 335B through 659B.
(iv) G-164B-15T	All.
(v) G-164B-20T	All.
(vi) G-164B-34T	All.
(vii) G-164C	All except 1C through 44C.
(iv) G-164D and G-164D with 73" wing gap.	All except 1D through 22D.

Unsafe Condition

(d) This AD results from our determination to add airplane models and serial numbers that were not previously included in the applicability. We are issuing this AD to prevent turning the fuel shut-off valve clockwise past the "ON" position which, if not corrected, could allow the fuel valve to be rotated to an un placarded "OFF" position.

Compliance

(e) To address this problem, you must do the following, unless already done:

Actions	Compliance	Procedures
(1) Modify the fuel shut-off valve control by installation of a new stop-plate, P/N A1552-71 (or FAA-approved equivalent).	(i) <i>For Group 1 Airplanes:</i> Within the next 100 hours time-in-service (TIS) after April 6, 1982 (the effective date of AD 82-07-04). (ii) <i>For Group 2 Airplanes:</i> Within the next 100 hours TIS after September 18, 2007 (the effective date of this AD).	Follow Schweizer Aircraft Corp. Ag-Cat Service Bulletin No. 78, dated January 26, 1982.
(2) Do not install any Gemini fuel shut-off valve P/N 3/4-86-6-RT-6 (A3580-1) on any airplane unless the stop-plate is installed per paragraph (e)(1) of this AD.	<i>For all Airplanes:</i> As of the next 100 hours TIS after September 18, 2007 (the effective date of this AD).	Follow Schweizer Aircraft Corp. Ag-Cat Service Bulletin No. 78, dated January 26, 1982.

Alternative Methods of Compliance (AMOCs)

(f) The Manager, Fort Worth Airplane Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Matt Wilbanks, Aerospace Engineer, Fort Worth ACO, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone: (817) 222-5051; fax: (817) 222-5960. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(g) AMOCs approved for AD 82-07-04 are approved for this AD.

Material Incorporated by Reference

(h) You must use Schweizer Aircraft Corp. Ag-Cat Service Bulletin No. 78, dated January 26, 1982, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Allied Ag Cat Productions, Inc., 301 West Walnut Street, P.O. Box 482, Walnut Ridge, Arkansas 72479; telephone: (870) 866-2111.

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Kansas City, Missouri, on August 6, 2007.

Kim Smith,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-15793 Filed 8-13-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-28256; Directorate Identifier 2007-NM-041-AD; Amendment 39-15155; AD 2007-16-16]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-135BJ Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

It has been found the occurrence of smoke on the passenger cabin originated from the valance panel lighting system wiring.

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective September 18, 2007.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of September 18, 2007.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT: Todd Thompson, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1175; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on May 24, 2007 (72 FR 29091). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

It has been found the occurrence of smoke on the passenger cabin originated from the valance panel lighting system wiring.

The corrective action is replacement of the valance panel lighting system wiring. You may obtain further information by examining the MCAI in the AD docket.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow our FAA policies. Any such differences are highlighted in a NOTE within the AD.

Costs of Compliance

Based on the service information, we estimate that this AD affects about 15 products of U.S. registry. We also estimate that it takes about 36 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$80 per work-hour. Required parts cost between \$7,900 and \$8,610 per product, depending on the airplane configuration. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these costs. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the AD on U.S. operators to be between \$161,700 and \$172,350 for the fleet, or between \$10,780 and \$11,490 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I,

section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

2007-16-16 Empresa Brasileira de Aeronautica S.A. (EMBRAER):
Amendment 39-15155. Docket No. FAA-2007-28256; Directorate Identifier 2007-NM-041-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective September 18, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-135BJ airplanes, certificated in any category, serial numbers 145412, 145462, 145484, 145495, 145505, 145516, 145528, 145540, 145549, 145555, 145586, 145625, 145637, 145642, 145644, and 145678.

Subject

(d) Air Transport Association (ATA) of America Code 25: Equipment/Furnishings.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states: It has been found the occurrence of smoke on the passenger cabin originated from the valance panel lighting system wiring. The corrective action is replacement of the valance panel lighting system wiring.

Actions and Compliance

(f) Within 48 months after the effective date of this AD, unless already done, replace the wiring of the valance panel lighting system by another one that complies with the current inverter specifications, in accordance with the Accomplishment Instructions of EMBRAER Service Bulletin 145LEG-25-0070, dated October 11, 2006.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested

using the procedures found in 14 CFR 39.19. Send information to ATTN: Todd Thompson, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1175; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI Brazilian Airworthiness Directive 2007-01-03, effective January 22, 2007, and EMBRAER Service Bulletin 145LEG-25-0070, dated October 11, 2006, for related information.

Material Incorporated by Reference

(i) You must use EMBRAER Service Bulletin 145LEG-25-0070, dated October 11, 2006, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 2, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. E7-15588 Filed 8-13-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2007-28145; *Airspace*
Docket No. 07-AAL-06]

Revision of Class E Airspace; Fort Yukon, AK

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action revises Class E airspace at Fort Yukon, AK to provide adequate controlled airspace to contain aircraft executing Standard Instrument Approach Procedures (SIAPs). One Standard Instrument Approach Procedure (SIAP) is being amended and three new SIAPs are being developed for the Fort Yukon Airport. A Departure Procedure (DP) and a Direction Finding (DF) procedure (used by Flight Service Station personnel) is also being amended. This action revises existing Class E airspace upward from the surface, from 700 feet (ft.) and 1,200 ft. above the surface at the Fort Yukon Airport, Fort Yukon, AK.

DATES: *Effective Date:* 0901 UTC, October 25, 2007. The Director of the Federal Register approves this incorporation by reference action under title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT: Gary Rolf, AAL-538G, Federal Aviation Administration, 222 West 7th Avenue, Box 14, Anchorage, AK 99513-7587; telephone number (907) 271-5898; fax: (907) 271-2850; email: gary.ctr.rolf@faa.gov; Internet address: <http://www.alaska.faa.gov/at>.

SUPPLEMENTARY INFORMATION:

History

On Tuesday, May 22, 2007, the FAA proposed to amend part 71 of the Federal Aviation Regulations (14 CFR part 71) to revise Class E airspace upward from the surface, from 700 ft. above the surface and from 1,200 ft. above the surface at Fort Yukon, AK (72 FR 28626). The action was proposed in order to create Class E airspace sufficient in size to contain aircraft while executing SIAPs for the Fort Yukon Airport. Class E controlled airspace extending upward from the surface, from 700 ft. above the surface and from 1,200 ft. above the surface, in the Fort Yukon Airport area is revised by this action.

Interested parties were invited to participate in this rulemaking proceeding by submitting written comments on the proposal to the FAA. No comments were received. The rule is adopted as proposed.

The area will be depicted on aeronautical charts for pilot reference. The coordinates for this airspace docket are based on North American Datum 83. The Class E airspace areas designated as surface areas are published in paragraph 6002 of FAA Order 7400.9P, *Airspace Designations and Reporting Points*, dated September 1, 2006, and effective September 15, 2006, which is incorporated by reference in 14 CFR 71.1. The Class E airspace areas designated as 700/1,200 ft. transition areas are published in paragraph 6005 of FAA Order 7400.9P, *Airspace Designations and Reporting Points*, dated September 1, 2006, and effective September 15, 2006, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in the Order.

The Rule

This amendment to 14 CFR part 71 revises Class E airspace at the Fort Yukon Airport, Alaska. This Class E airspace is revised to accommodate aircraft executing new and amended DPs and SIAPs, and will be depicted on aeronautical charts for pilot reference. The intended effect of this rule is to provide adequate controlled airspace for Instrument Flight Rules (IFR) operations at the Fort Yukon Airport, Fort Yukon, Alaska.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA’s authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle 1, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs,