

thereafter at intervals not to exceed 4,000 flight hours.

Note 2: For the purposes of this AD, a detailed inspection is: "An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required."

(1) Before accumulating 4,000 total flight hours on the inboard flap trunnion since new.

(2) Within 4,000 flight hours after accomplishing paragraph (f) of this AD.

(3) Within 600 flight hours after the effective date of this AD.

No Reporting Requirement

(h) Although Airbus Service Bulletin A320-57-1133, dated July 28, 2005, specifies to submit certain information to the manufacturer, this AD does not include that requirement.

Compliance Times

(i) Where Airbus Service Bulletin A320-57-1133, dated July 28, 2005, specifies replacing the sliding panel at the next opportunity, replace it within 600 flight hours after the inspection required by paragraph (g) of this AD. If the trunnion is found damaged during any inspection required by paragraph (g) of this AD, do the corrective actions specified in the service bulletin before further flight. Where the service bulletin specifies contacting the manufacturer for a grace period assessment after replacing the trunnion or flap, contact the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, or Direction Générale de l'Aviation Civile (DGAC) for the grace period assessment.

Alternative Methods of Compliance (AMOCs)

(j)(1) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with 14 CFR 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Related Information

(k) French airworthiness directive F-2005-139, dated August 3, 2005, also addresses the subject of this AD.

Material Incorporated by Reference

(l) You must use Airbus Service Bulletin A320-27-1117, Revision 02, dated January 18, 2000; and Airbus Service Bulletin A320-57-1133, excluding Appendix 01, dated July 28, 2005, as applicable, to perform the actions that are required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of

Airbus Service Bulletin A320-57-1133, excluding Appendix 01, dated July 28, 2005, in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) On January 8, 2001 (65 FR 75603, December 4, 2000), the Director of the Federal Register approved the incorporation by reference of Airbus Service Bulletin A320-27-1117, Revision 02, dated January 18, 2000.

(3) Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on February 6, 2006.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 06-1405 Filed 2-16-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2005-22872; Directorate Identifier 2005-NM-198-AD; Amendment 39-14490; AD 2006-04-09]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900) Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Bombardier Model CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900) airplanes. This AD requires replacing the Camloc fasteners on the sidewall of the center pedestal. This AD results from reports of the Camloc fasteners on the sidewall of the center pedestal disengaging and interfering with an inboard rudder pedal. We are issuing this AD to prevent these fasteners from disengaging and

interfering with an inboard rudder pedal, which could reduce directional controllability of the airplane.

DATES: This AD becomes effective March 24, 2006.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of March 24, 2006.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, room PL-401, Washington, DC.

Contact Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centre-ville, Montreal, Quebec H3C 3G9, Canada, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT:

Daniel Parrillo, Aerospace Engineer, Systems and Flight Test Branch, ANE-172, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, suite 410, Westbury, New York 11590; telephone (516) 228-7305; fax (516) 794-5531.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to certain Bombardier Model CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900) airplanes. That NPRM was published in the **Federal Register** on November 9, 2005 (70 FR 67946). That NPRM proposed to require replacing the Camloc fasteners on the sidewall of the center pedestal.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the single comment received.

Request To Allow Use of Alternative Parts

The commenter agrees with the proposed 5,500-flight-hour compliance time. But the commenter requests that we allow installation of operator-supplied hardware with operator-fabricated gang-nut plates in lieu of the parts specified in the referenced service bulletin. The commenter states that this will facilitate compliance with the proposed AD because operators will not be dependent on parts availability.

We do not agree with the commenter's request. We have discussed the question of parts availability with the manufacturer, and the manufacturer states that there is no problem with availability of the kit needed to complete the requirements of this AD. Therefore, parts availability does not justify allowing operators to install parts other than those specified in the service bulletin. Also, it is not appropriate to address such a request in an AD. We recommend that the commenter apply for approval of an alternative method of compliance (AMOC) and provide specific information about the hardware proposed in the comment. Operators who choose to submit an AMOC request should include data supporting that the proposed alternative hardware will provide an acceptable level of safety. We have not changed the final rule in this regard.

Conclusion

We have carefully reviewed the available data, including the comment received, and determined that air safety and the public interest require adopting the AD as proposed.

Costs of Compliance

This AD affects about 209 airplanes of U.S. registry. The required actions will take about 2 work hours per airplane, at an average labor rate of \$65 per work

hour. Required parts will cost between \$141 and \$150 per airplane. Based on these figures, the estimated cost of this AD for U.S. operators is between \$56,639 and \$58,520, or between \$271 and \$280 per airplane.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the ADDRESSES section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

2006-04-09 Bombardier, Inc. (Formerly Canadair): Amendment 39-14490. Docket No. FAA-2005-22872; Directorate Identifier 2005-NM-198-AD.

Effective Date

- (a) This AD becomes effective March 24, 2006.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to the airplanes identified in Table 1 of this AD, certificated in any category.

TABLE 1.—APPLICABILITY

Bombardier models	Serial Nos.
CL-600-2C10 (Regional Jet Series 700, 701, & 702) airplanes CL-600-2D15 (Regional Jet Series 705) airplanes, CL-600-2D24 (Regional Jet Series 900) airplanes.	10003 through 10218 inclusive. 15001 through 15047 inclusive.

Unsafe Condition

(d) This AD results from reports of the Camloc fasteners on the sidewall of the center pedestal disengaging and interfering with an inboard rudder pedal. We are issuing this AD to prevent these fasteners from disengaging and interfering with an inboard rudder pedal, which could reduce directional controllability of the airplane.

Compliance

- (e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Replacement of Fasteners

- (f) Within 5,500 flight hours after the effective date of this AD, replace, with screws and nut plate assemblies, the Camloc fasteners on the left and right sidewalls of the

center pedestal, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 670BA-25-037, Revision A, dated August 25, 2005.

Actions Accomplished Previously

- (g) Replacing fasteners before the effective date of this AD in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 670BA-25-037, dated June

23, 2005, is acceptable for compliance with the requirements of paragraph (f) of this AD.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, New York Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Related Information

(i) Canadian airworthiness directive CF-2005-31, dated August 17, 2005, also addresses the subject of this AD.

Material Incorporated by Reference

(j) You must use Bombardier Service Bulletin 670BA-25-037, Revision A, dated August 25, 2005, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centre-ville, Montreal, Quebec H3C 3G9, Canada, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on February 6, 2006.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 06-1406 Filed 2-16-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2005-22558; Directorate Identifier 2005-NM-107-AD; Amendment 39-14491; AD 2006-04-10]

RIN 2120-AA64

Airworthiness Directives; Cessna Model 500, 550, S550, 560, 560XL, and 750 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Cessna Model 500, 550, S550, 560, 560XL, and 750 airplanes. This AD requires installing identification sleeves on the wires for the positive and negative terminal studs of the engine and/or auxiliary power unit (APU) fire extinguishing bottles, as applicable, and re-connecting the wires to the correct terminal studs. This AD results from a report of mis-wired fire extinguishing bottles. We are issuing this AD to ensure that the fire extinguishing bottles are activated in the event of an engine or APU fire, and that flammable fluids are not supplied during a fire, which could result in an unextinguished fire in the nacelle or APU.

DATES: This AD becomes effective March 24, 2006.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of March 24, 2006.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, room PL-401, Washington, DC.

Contact Cessna Aircraft Co., P.O. Box 7706, Wichita, Kansas 67277, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT:

Robert D. Adamson, Aerospace Engineer, Systems and Propulsion Branch, ACE-116W, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, room 100, Mid-Continent Airport, Wichita, Kansas 67209; telephone (316) 946-4145; fax (316) 946-4107.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the ADDRESSES section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to certain Cessna Model 500, 550, S550, 560, 560XL, and 750 airplanes. That NPRM was published in the

Federal Register on September 30, 2005 (70 FR 57213). That NPRM proposed to require installing identification sleeves on the wires for the positive and negative terminal studs of the engine and/or auxiliary power unit (APU) fire extinguishing bottles, as applicable, and re-connecting the wires to the correct terminal studs.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the comments received.

Request To Use Parts Other Than Factory Kit

The commenter sees the need for the proposed AD, but does not like the fact that it is tied to a factory service bulletin. The commenter states that the kits specified in the service bulletin that are necessary to do the actions in the NPRM are often out of stock at the manufacturer. The commenter further points out that the actions in the NPRM can be accomplished without waiting for the kit because the actions can be done using standard items and practices in the field. In addition, the commenter states that the kits are much more costly than the estimate provided in the NPRM.

We infer that the commenter is requesting confirmation that the factory-provided kits are available for all affected airplanes to accomplish the required actions, and that the kits will not be more costly than stated in the NPRM. The manufacturer has assured us that the kits are available and that the parts costs cited in the NPRM are correct. The manufacturer also noted that there is no cost for kits if the affected airplane is within its five-year warranty period. If the commenter has difficulty getting a kit or kits, or wishes to use standard items and practices in the field, the commenter can apply for an alternative method of compliance in accordance with the procedures in paragraph (j) of this AD.

We have not changed the AD in this regard.

Request To Correct Incorrect Statement Regarding Shutoff Valves

Another commenter supports the need for the proposed AD, but states that the "Discussion" section incorrectly indicates that the mis-wiring will cause the shutoff valves for the main engine fuel and hydraulic firewall to open. The commenter suggests that we delete this statement. The commenter explains that the valves are motor-operated and remain in the last position when power is absent. They