

the agency provides assignment rights under this part by:

(1) Determining the representative rate of positions not covered by a pay band consistent with § 351.203;

(2) Determining the representative rate of each pay band, or competitive level within the pay band(s), consistent with § 351.203;

(3) As determined by the agency, providing assignment rights under paragraph (b) of this section (bumping), or paragraphs (c) and (d) of this section (retreating), consistent with the grade intervals covered in paragraphs (b)(2) and (c)(2) of this section, and the pay band intervals in paragraph (h) of this section.

[FR Doc. E7-4701 Filed 3-14-07; 8:45 am]

BILLING CODE 6325-39-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-27560; Directorate Identifier 2006-NM-211-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 757-200, -200PF, and -200CB Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Boeing Model 757-200, -200PF, and -200CB series airplanes. This proposed AD would require inspections to detect scribe lines and cracks of the fuselage skin, lap joints, circumferential butt splice strap, and external and internal approved repairs; and related investigative/corrective actions if necessary. This proposed AD results from reports of scribe lines adjacent to the skin lap joints. We are proposing this AD to detect and correct cracks, which could grow and cause rapid decompression of the airplane.

DATES: We must receive comments on this proposed AD by April 30, 2007.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- **DOT Docket Web site:** Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- **Government-wide rulemaking Web site:** Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- **Mail:** Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, room PL-401, Washington, DC 20590.

- **Fax:** (202) 493-2251.

- **Hand Delivery:** Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for the service information identified in this proposed AD.

FOR FURTHER INFORMATION CONTACT:

Dennis Stremick, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6450; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed in the **ADDRESSES** section. Include the docket number "FAA-2007-27560; Directorate Identifier 2006-NM-211-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management

Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System receives them.

Discussion

We have received reports of scribe lines found adjacent to the skin lap joints on Model 757-200 airplanes. The scribe lines appear to have been made on the skin when sealant was removed as part of preparation of the airplane for repainting. The airplanes had between 13,300 and 16,800 flight cycles. Although no cracks as a result of scribe lines have been reported on Model 757 airplanes, scribe lines have caused cracks on other airplanes. Undetected cracking, if not corrected, could grow and result in rapid decompression.

Related AD

This proposed AD is similar to AD 2006-07-12, amendment 39-14539 (71 FR 16211), March 31, 2006. That AD applies to all Boeing Model 737-100, -200, -200C, -300, -400, and -500 series airplanes. That AD requires a one-time inspection for scribe lines and cracks in the fuselage skin at certain lap joints, butt joints, external repair doublers, and other areas; and related investigative/corrective actions if necessary. That AD resulted from reports of fuselage skin cracks adjacent to the skin lap joints on airplanes that had scribe lines.

Relevant Service Information

We have reviewed Boeing Alert Service Bulletin 757-53A0092, Revision 1, dated January 10, 2007. The service bulletin describes procedures for removing paint and sealant at the applicable zonal locations, and doing detailed inspections to detect scribe lines and cracks of the fuselage skin, lap joints, circumferential butt splice strap, and external and internal approved repairs. The service bulletin specifies repairing scribe lines before further flight, except when a limited return to service (LRTS) program for qualifying scribe lines would allow return to service for a limited period before scribe lines are repaired.

The LRTS program includes repetitive inspections to detect cracks where scribe lines were found. To qualify for an LRTS program, a scribe line must meet certain criteria including the total flight cycles on the airplane, and the location and extent of the scribe lines.

The service bulletin specifies contacting Boeing for final repair instructions for the LRTS program, which would eliminate the need for the repetitive inspections of the LRTS program. The repetitive intervals for the LRTS program range from 1,500 to 8,000 flight cycles, depending on the location of the scribe lines and the configuration of the airplane.

Each piece of structure susceptible to a scribe line is assigned to a zone. Based on criticality of location, the service bulletin addresses the most critical areas (zones) first and appropriately reduces the compliance requirements for less critical areas. The service bulletin has specific instructions for calculating separate inspection thresholds. These thresholds are based on (1) fatigue life for the identified zonal locations and (2) potential scribe line opportunities in an airplane's maintenance history. The compliance times for inspecting are 20,000 flight cycles (Zone 1) and 30,000 flight cycles (Zone 2) after the first scribe opportunity. If a maintenance records-based threshold program is not

used, however, the service bulletin specifies 6,000 flight cycles as the first scribe opportunity. Since a scribe line can occur at any time during the service life of an airplane and at many locations, the service bulletin uses both total flight cycles and structural criticality of locations to determine the inspection requirements.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other airplanes of this same type design. For this reason, we are proposing this AD, which would require accomplishing the actions specified in the service information described previously, except as discussed below.

Differences Between the Proposed AD and Service Information

The service bulletin specifies to contact the manufacturer for instructions on how to repair certain conditions, but this proposed AD would

require repairing those conditions by using a method that we approve, or by using data that meet the certification basis of the airplane, and that have been approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization whom we have authorized to make those findings.

The service bulletin specifies compliance times relative to the date of issuance of the service bulletin; however, this proposed AD would require compliance before the specified compliance time relative to the effective date of the AD.

Costs of Compliance

There are about 945 airplanes of the affected design in the worldwide fleet; of these, about 634 are U.S.-registered airplanes. The following table provides the estimated costs for U.S. operators to comply with this proposed AD. There are no U.S.-registered airplanes in Group 5 or Group 6.

ESTIMATED COSTS

Inspections	Work hours	Average labor rate per hour	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Group 1	127	\$80	\$10,160	144	\$1,463,040
Group 2	122	80	9,760	6	58,560
Group 3	154	80	12,320	75	924,000
Group 4	128	80	10,240	409	4,188,160

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism

implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

Boeing: Docket No. FAA-2007-27560; Directorate Identifier 2006-NM-211-AD.

Comments Due Date

- (a) The FAA must receive comments on this AD action by April 30, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Boeing Model 757–200, –200PF, and –200CB series airplanes, certificated in any category; as identified in Boeing Alert Service Bulletin 757–53A0092, Revision 1, dated January 10, 2007.

Unsafe Condition

(d) This AD results from reports of scribe lines adjacent to the fuselage skin lap joints. We are issuing this AD to detect and correct cracks, which could grow and cause rapid decompression of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspections

(f) Perform detailed inspections to detect scribe lines and cracks of the fuselage skin, lap joints, circumferential butt splice strap, and external and internal approved repairs; and perform related investigative and corrective actions. Do the actions in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 757–53A0092, Revision 1, dated January 10, 2007, except as required by paragraph (g) of this AD. Do the actions within the applicable compliance times specified in paragraph 1.E. of the service bulletin, except as required by paragraph (h) of this AD.

Exceptions to Service Bulletin Specifications

(g) Where Boeing Alert Service Bulletin 757–53A0092, Revision 1, dated January 10, 2007, specifies to contact Boeing for appropriate repair instructions, repair using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(h) Boeing Alert Service Bulletin 757–53A0092, Revision 1, dated January 10, 2007, specifies compliance times relative to the date of issuance of the service bulletin; however, this proposed AD would require compliance before the specified compliance time relative to the effective date of the AD.

Credit for Prior Accomplishment

(i) Inspections done before the effective date of this AD in accordance with Boeing Alert Service Bulletin 757–53A0092, dated September 18, 2006, are acceptable for compliance with the corresponding requirements of paragraph (f) of this AD.

Alternative Methods of Compliance (AMOCs)

(j)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane.

Issued in Renton, Washington, on March 1, 2007.

Ali Bahrami,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. E7–4742 Filed 3–14–07; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2007–27565; Directorate Identifier 2006–NM–215–AD]

RIN 2120–AA64

Airworthiness Directives; Airbus Model A330 and A340–200 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede an existing airworthiness directive (AD) that applies to certain Airbus Model A330–200, A330–300, A340–200, and A340–300 series airplanes; and Model A340–541 and –642 airplanes. The existing AD currently requires repetitively resetting the display units (DUs) for the electronic instrument system (EIS), either by switching them off and back on again or by performing a complete electrical shutdown of the airplane. This proposed AD would require installing new software, which would end the actions required by the existing AD. This proposed AD also would add additional airplanes that may be placed on the U.S. Register in the future. This proposed AD results from an incident in which all of the DUs for the EIS went blank simultaneously during flight. We are proposing this AD to prevent automatic reset of the DUs for the EIS during flight and consequent loss of data from the DUs, which could reduce the ability of the flightcrew to control the airplane during adverse flight conditions.

DATES: We must receive comments on this proposed AD by April 16, 2007.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- **DOT Docket Web site:** Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- **Government-wide rulemaking Web site:** Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- **Mail:** Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL–401, Washington, DC 20590.

- **Fax:** (202) 493–2251.

- **Hand Delivery:** Room PL–401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for service information identified in this proposed AD.

FOR FURTHER INFORMATION CONTACT: Tim Backman, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 227–2797; fax (425) 227–1149.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed in the **ADDRESSES** section. Include the docket number “Docket No. FAA–2007–27565; Directorate Identifier 2006–NM–215–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review the DOT’s complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477–78), or you may visit <http://dms.dot.gov>.