

Inspection Thresholds,” Row B, of EASA AD 2018–0289R1.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* For any service information referenced in EASA AD 2018–0289R1 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Related Information

(1) For information about EASA AD 2018–0289R1, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0501.

(2) For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3223; email Sanjay.Ralhan@faa.gov.

Issued on June 10, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–12603 Filed 6–15–21; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2021–0463; Project Identifier 2018–SW–050–AD]

RIN 2120–AA64

Airworthiness Directives; Leonardo S.p.a. Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for Leonardo S.p.a. (Leonardo) Model AB139 and AW139 helicopters with certain main rotor blades MRB installed. This proposed AD was prompted by a report of an in-flight loss of a main rotor blade (MRB) tip cap. This proposed AD would require inspecting the MRB tip cap for disbonding. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by August 2, 2021.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493–2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Leonardo S.p.A. Helicopters, Emanuele Bufano, Head of Airworthiness, Viale G. Agusta 520, 21017 C. Costa di Samarate (Va) Italy; telephone +39–0331–225074; fax +39–0331–229046; or at <https://customerportal.leonardocompany.com/en-US/>. You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No.

FAA–2021–0463 or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the European Aviation Safety Agency (now European Union Aviation Safety Agency (EASA) AD, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT:

Bang Nguyen, Aerospace Engineer, Certification Section, Fort Worth ACO Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222–4973; email bang.nguyen@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA–2021–0463; Project Identifier 2018–SW–050–AD” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI

should be sent to Bang Nguyen, Aerospace Engineer, Certification Section, Fort Worth ACO Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-4973; email bang.nguyen@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

On January 22, 2018, the FAA issued AD 2018-03-01, Amendment 39-19174 (83 FR 4136, January 30, 2018) (AD 2018-03-01) for Agusta S.p.A. (now Leonardo) Model AB139 and AW139 helicopters with MRB part number (P/N) 3G6210A00131 with a serial number (S/N) 3615, 3634, 3667, or 3729 installed. AD 2018-03-01 requires inspecting the MRB tip cap for disbonding and was prompted by EASA AD 2017-0175-E, dated September 13, 2017 (EASA AD 2017-0175-E), issued by EASA, which is the Technical Agent for the Member States of the European Union. EASA advised of an in-flight loss of an MRB tip cap on an AW139 helicopter where the pilot was able to safely land the helicopter. EASA further advised that an investigation determined the cause as incorrect bonding procedures used during production on MRB P/N 3G6210A00131, S/N 3615, 3634, 3667, and 3729. According to EASA, this condition could result in loss of an MRB tip cap, increased pilot workload, and reduced control of the helicopter. To address this unsafe condition, EASA AD 2017-0175-E requires a one-time inspection of the affected MRB tip caps within 5 hours and replacing the affected MRBs within 10 hours if not replaced as a result of the inspection. EASA AD 2017-0175-E also prohibits installing the affected MRBs on a helicopter. AD 2018-03-01 requires the same corrective actions.

Actions Since AD 2018-03-01 Was Issued

After the FAA issued AD 2018-03-01, EASA issued EASA AD 2018-0130, dated June 18, 2018 (EASA AD 2018-0130), to correct the same unsafe condition for Leonardo AB139 and AW139 helicopters with additional serial-numbered MRBs installed. EASA advises that further investigations after EASA AD 2017-0175-E was issued determined that another batch of P/N 3G6210A00131 MRBs may have been subject to the incorrect bonding procedure, but to a less critical extent. EASA AD 2018-0130, which neither revises nor supersedes EASA AD 2017-

0175-E, applies to the following serial-numbered MRBs with less than 1,200 flight hours: 2709, 3558, 3624, 3707, 3790, 3486, 3561, 3625, 3717, 3795, 3488, 3569, 3626, 3720, 3798, 3495, 3570, 3627, 3725, 3803, 3500, 3574, 3628, 3726, 3807, 3501, 3575, 3633, 3734, 3812, 3502, 3582, 3636, 3735, 3822, 3503, 3583, 3638, 3738, 3824, 3508, 3586, 3642, 3739, 3825, 3510, 3590, 3648, 3741, 3827, 3513, 3592, 3649, 3743, 3831, 3520, 3595, 3650, 3744, 3832, 3527, 3597, 3651, 3745, 3838, 3528, 3599, 3657, 3753, 3841, 3529, 3602, 3665, 3754, 3842, 3531, 3603, 3672, 3761, 3847, 3536, 3605, 3682, 3766, 3850, 3539, 3609, 3684, 3770, 3851, 3544, 3612, 3686, 3771, 3852, 3549, 3613, 3690, 3777, 3853, 3551, 3616, 3691, 3783, 3854, 3556, 3620, 3695, 3788, 3855, 3557, 3622, 3696, and 3789.

Accordingly, EASA AD 2018-0130 requires within 50 flight hours (FH) and thereafter at intervals not to exceed 50 FH, tap inspecting the MRB for disbonding. If there is disbonding within permitted limits, EASA AD 2018-0130 requires tap inspecting the disbonded area within 10 FH and thereafter at intervals not to exceed 10 FH. If disbonding that exceeds the permitted limits is found during any inspection, EASA AD 2018-0130 requires replacing the part. EASA AD 2018-0130 also prohibits installing the affected part unless it is a serviceable part and includes a terminating action for the repetitive inspections, which is accumulation of 1,200 FH by an affected part without findings of disbonded area, or findings of disbonded area within the limits specified in Annex A of Leonardo Helicopters Alert Service Bulletin No. 139-520, dated April 26, 2018 (ASB 139-520).

FAA's Determination

These helicopters have been approved by EASA and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the European Union, EASA has notified the FAA about the unsafe condition described in its AD. The FAA is proposing this AD after evaluating all known relevant information and determining that the unsafe condition described previously is likely to exist or develop on other helicopters of the same type designs.

Related Service Information Under 1 CFR Part 51

The FAA reviewed ASB 139-520. This service information specifies procedures for repetitively inspecting the tip cap on a certain batch of MRBs for disbonding using a tap test and

replacing the MRB if disbonding is not within permitted limits.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

Proposed AD Requirements in This NPRM

This proposed AD would require, for helicopters with affected MRBs with less than 1,200 total hours time-in-service (TIS) installed, within 50 hours TIS, tap inspecting each MRB tip cap for disbonding using a tap hammer or equivalent. If there is no disbonding, tap inspecting the MRB tip cap at intervals not to exceed 50 hours TIS would be required. If there is any disbonding that does not exceed the specified limits in ASB 139-520, tap inspecting the MRB would be required at intervals not to exceed 10 hours TIS. If there is any disbonding that exceeds the specified limits in ASB 139-520, removing the MRB from service would be required before further flight. The accumulation of 1,200 total hours TIS on the affected part without findings of any disbonded area or with findings of any disbonded area that is within the permitted limits in Annex A of ASB 139-520 would constitute terminating action for the proposed repetitive inspections. This proposed AD would also prohibit installing any MRB that is identified in the applicability section on any helicopter.

Differences Between This Proposed AD and the EASA AD

EASA AD 2018-0130 allows replacing an affected part with a serviceable part, which is marked with the letter "R" (repaired tip cap) as the last digit of the serial number, as a terminating action for the repetitive inspections specified in that AD, whereas this proposed AD would not.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 114 helicopters of U.S. Registry. Labor rates are estimated at \$85 per work-hour. Based on these numbers, the FAA estimates the following costs to comply with this proposed AD.

Tap inspecting an MRB tip cap would require 1 work-hour, for a cost per helicopter of \$85 per inspection cycle for a total U.S. fleet cost of \$9,690. Replacing 1 MRB, if required, would take 4 work-hours, and required parts would cost \$141,725, for a total cost of \$142,065 per MRB.

The FAA has included all known costs in its cost estimate. According to

the manufacturer, however, some of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected operators.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Leonardo S.p.a.: Docket No. FAA-2021-0463; Project Identifier 2018-SW-050-AD.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by August 2, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Leonardo S.p.a. Model AB139 and AW139 helicopters, certificated in any category, with a main rotor blade (MRB) that has less than 1,200 total hours time-in-service (TIS) and has part number 3G6210A00131 with any serial number listed in Table 1 of Leonardo Helicopters Alert Service Bulletin No. 139-520, dated April 26, 2018 (ASB 139-520), installed.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 6210, Main Rotor Blades.

(e) Unsafe Condition

This AD was prompted by a report of disbonding of an MRB tip cap, which if not detected and corrected, could result in loss of the MRB tip cap, severe vibrations, and subsequent loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Within 50 hours TIS after the effective date of this AD, using a tap hammer or equivalent, tap inspect each MRB tip cap for disbonding in the area depicted in Figure 1 of ASB 139-520.

(i) If there is no disbonding, tap inspect each MRB tip cap as required by paragraph (g)(1) of this AD at intervals not to exceed 50 hours TIS.

(ii) If there is any disbonding that does not exceed the limits specified in Annex A, paragraphs 2.3 and 2.4 of ASB 139-520, tap inspect the MRB tip cap as required by paragraph (g)(1) of this AD at intervals not to exceed 10 hours TIS.

(iii) If there is any disbonding that exceeds the limits specified in Annex A, paragraphs 2.3 and 2.4 of ASB 139-520, remove the MRB from service before further flight.

(2) Accumulation of 1,200 total hours TIS on the affected part without findings of any disbonded area or with findings of any disbonded area that is within the permitted limits specified in Annex A, paragraphs 2.3 and 2.4 of ASB 139-520, constitutes terminating action for the repetitive inspections required by paragraphs (g)(1)(i) and (ii) of this AD.

(3) As of effective date of this AD, do not install any MRB that is identified in paragraph (c) of this AD on any helicopter.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (i)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Bang Nguyen, Aerospace Engineer, Certification Section, Fort Worth ACO Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-4973; email bang.nguyen@faa.gov.

(2) For service information identified in this AD, contact Leonardo S.p.A. Helicopters, Emanuele Bufano, Head of Airworthiness, Viale G. Agusta 520, 21017 C. Costa di Samarate (Va) Italy; telephone +39-0331-225074; fax +39-0331-229046; or at <https://customerportal.leonardocompany.com/en-US/>. You may view this referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(3) The subject of this AD is addressed in European Aviation Safety Agency (now European Union Aviation Safety Agency (EASA) AD 2018-0130, dated June 18, 2018. You may view the EASA AD at <https://www.regulations.gov> in Docket No. FAA-2021-0463.

Issued on June 9, 2021.

Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-12515 Filed 6-15-21; 8:45 am]

BILLING CODE 4910-13-P