

Proposed Rules

Federal Register

Vol. 90, No. 69

Friday, April 11, 2025

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2025-0349; Project Identifier AD-2024-00208-T]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 737-700, 737-800, 737-900, 737-900ER, 737-8, and 737-9 series airplanes. This proposed AD was prompted by a report of a passenger being unable to exit the lavatory during flight due to a broken latch that prevented toggling of the lock. This proposed AD would require replacing lavatory bifold door latches with latches having an improved design. This proposed AD would also prohibit the installation of affected parts. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by May 27, 2025.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to *regulations.gov*. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at *regulations.gov* under Docket No. FAA-2025-0349; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT:

Nicole Tsang, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3959; email: *nicole.s.tsang@faa.gov*.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2025-0349; Project Identifier AD-2024-00208-T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such

marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Nicole Tsang, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3959; email: *nicole.s.tsang@faa.gov*. Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA has received a report indicating that during flight, a passenger was unable to exit the lavatory due to a broken latch that prevented toggling of the lock. Flight attendants were unable to open the bifold door, leading the flightcrew to accomplish an unscheduled landing. It was determined that bifold door latches failed in service, preventing the bifold door from opening without mechanic assistance. The root cause was material fatigue of the plastic structure of the bifold door latch. The material fatigue was caused primarily by excessive stress combined with weld-line and machining marks from drilling holes for inserts into the plastic structure. In an otherwise survivable emergency event (e.g., severe turbulence, medical emergency, or emergency egress), potential damages to the lavatory lock could impede access to the passenger and impede egress during an emergency evacuation, which may result in serious injury to the trapped occupant.

FAA’s Determination

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require replacing the lavatory bifold door latch having part number (P/N) SC1L500031-3/20218-3, SC1L500031-4/20218-4, SC1L500031-5/20218-5/20218-7, or SC1L500031-6/20218-6/20218-8 with lavatory bifold door latch having P/N SC1L500031-9/20218-9 or SC1L500031-10/20218-10. This proposed AD would also prohibit the installation of the affected part.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 2,612

airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replacement	2 work-hours × \$85 per hour = \$170 per latch.	Up to \$481 per latch	Up to \$1,302 (Up to 2 latches per airplane).	Up to \$3,400,824.

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some or all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected operators.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(f), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

The Boeing Company: Docket No. FAA–2025–0349; Project Identifier AD–2024–00208–T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by May 27, 2025.

(b) Affected ADs

None.

(c) Applicability

This AD applies to certain The Boeing Company Model 737–700, 737–800, 737–900, 737–900ER, 737–8, and 737–9 series airplanes, certificated in any category, with lavatory bifold door latch part number (P/N) SC1L500031–3/20218–3, SC1L500031–4/20218–4, SC1L500031–5/20218–5/20218–7, or SC1L500031–6/20218–6/20218–8.

(d) Subject

Air Transport Association (ATA) of America Code 25; Equipment/Furnishings.

(e) Unsafe Condition

This AD was prompted by a report that a passenger was unable to exit the lavatory during flight due to a broken latch that prevented toggling of the lock. The FAA is issuing this AD to address bifold door latch failure during service preventing the bifold door from opening without mechanic assistance. In an otherwise survivable emergency event (e.g., severe turbulence, medical emergency, or emergency egress), potential damages to the lavatory lock could impede access to the passenger and impede

egress during an emergency evacuation, which may result in serious injury to the trapped occupant.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Replace Lavatory Bifold Door Latch

Within 4 months after the effective date of this AD. Replace lavatory bifold door latch having part number SC1L500031–3/20218–3, SC1L500031–4/20218–4, SC1L500031–5/20218–5/20218–7, or SC1L500031–6/20218–6/20218–8 with lavatory bifold door latch having part number SC1L500031–9/20218–9 or SC1L500031–10/20218–10.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in B/E Aerospace Service Bulletin 1L3–25–0069, Revision 4, dated April 18, 2024.

Note 2 to paragraph (g): For airplanes modified via Supplemental Type Certificate (STC) ST02574SE, guidance for accomplishing the actions required by this AD can be found in B/E Aerospace Service Bulletin 1L3–25–0083, Revision 2, dated August 26, 2020.

Note 3 to paragraph (g): For airplanes modified via STC ST02582SE, guidance for accomplishing the actions required by this AD can be found in B/E Aerospace Service Bulletin 1L3–25–0112, Revision 1, dated August 26, 2020.

(h) Parts Installation Prohibition

As of the effective date of this AD, no person may install, on any airplane, a lavatory bifold door latch having part number SC1L500031–3/20218–3, SC1L500031–4/20218–4, SC1L500031–5/20218–5/20218–7, or SC1L500031–6/20218–6/20218–8.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, AIR–520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, AIR-520, Continued Operational Safety Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

(1) For more information about this AD, contact Nicole Tsang, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3959; email: nicole.s.tsang@faa.gov.

(2) For B/E Aerospace material identified in this AD that is not incorporated by reference, contact Collins Aerospace, Interiors—B/E Aerospace—ALCI, 11404 Commando Road, Suite B, Everett, WA 98204, United States; telephone +1-888-232-2594; email interiors.techsupport@collins.com; website customers.collinsaerospace.com.

(k) Material Incorporated by Reference

None.

Issued on March 13, 2025.

Peter A. White,

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2025-06157 Filed 4-10-25; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2025-0616; Project Identifier MCAI-2024-00304-T]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Bombardier, Inc., Model CL-600-1A11 (600) and CL-600-2A12 (601) airplanes, and certain Model CL-600-2B16 (601-3A, 601-3R, and 604 Variants) airplanes. This proposed AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. This proposed AD would require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations.

The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by May 27, 2025.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.
- **Fax:** 202-493-2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2025-0616; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For Bombardier material identified in this proposed AD, contact Bombardier Business Aircraft Customer Response Center, 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-2999; email ac.yul@aero.bombardier.com; website bombardier.com.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

FOR FURTHER INFORMATION CONTACT:

Brenda L. Buitrago, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7300; email: 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2025-0616; Project Identifier MCAI-2024-00304-T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change,

and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Brenda L. Buitrago, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7300; email: 9-avs-nyaco-cos@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

Transport Canada, which is the aviation authority for Canada, has issued Transport Canada AD CF-2024-16, dated May 23, 2024 (Transport Canada AD CF-2024-16) (also referred to after this as the MCAI), to correct an unsafe condition for all Bombardier, Inc., Model CL-600-1A11 (600), CL-600-2A12 (601), and CL-600-2B16 (601-3A, 601-3R, and 604 Variants) airplanes. The MCAI states that new or more restrictive airworthiness limitations have been developed.

Model CL-600-2B16 (604 Variant) airplanes having serial numbers 6193 and subsequent must comply with the airworthiness limitations specified as part of the approved type design. Therefore, this proposed AD does not include those airplanes in the applicability.