

investigation, suitability determination, and suitability action taken under this part, as required in OPM issuances.

[FR Doc. E8–13990 Filed 6–20–08; 8:45 am]

BILLING CODE 6325–39–P

FARM CREDIT ADMINISTRATION

12 CFR Chapter VI

RIN 3052–AC39

Statement on Regulatory Burden

AGENCY: Farm Credit Administration.

ACTION: Notice of intent; request for comment.

SUMMARY: The Farm Credit Administration (FCA, our, or we) is issuing a notice of regulatory review and request for comment. The FCA will review its regulations to consider whether existing regulations are inefficient or burdensome. The FCA is seeking public comment on the appropriateness of the requirements it imposes on the Farm Credit System (System). We ask for comments on our regulations that may duplicate other requirements, are ineffective, or impose burdens that are greater than the benefits received. We are taking this action to improve the regulatory framework within which System institutions operate.

DATES: Please send your comments to the FCA by August 22, 2008.

ADDRESSES: We offer a variety of methods for you to submit your comments. For accuracy and efficiency reasons, commenters are encouraged to submit comments by e-mail or through the FCA's Web site or the Federal eRulemaking Web site. As faxes are difficult for us to process and achieve compliance with section 508 of the Rehabilitation Act, please consider another means to submit your comment if possible. Regardless of the method you use, please do not submit your comment multiple times via different methods. You may submit comments by any of the following methods:

- *E-mail:* Send us an e-mail at reg-comm@fca.gov.
- *FCA Web Site:* <http://www.fca.gov>. Select "Public Commenters," then "Public Comments," and follow the directions for "Submitting a Comment."
- *Federal eRulemaking Portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Mail:* Gary K. Van Meter, Deputy Director, Office of Regulatory Policy, Farm Credit Administration, 1501 Farm Credit Drive, McLean, VA 22102–5090.
- *Fax:* (703) 883–4477. Posting and processing of faxes may be delayed.

Please consider another means to comment, if possible.

You may review copies of comments we receive at our office in McLean, Virginia, or from our Web site at <http://www.fca.gov>. Once you are in the Web site, select "Public Commenters," then "Public Comments," and follow the directions for "Reading Submitted Public Comments." We will show your comments as submitted, but for technical reasons we may omit items such as logos and special characters. Identifying information that you provide, such as phone numbers and addresses, will be publicly available. However, we will attempt to remove e-mail addresses to help reduce Internet spam.

FOR FURTHER INFORMATION CONTACT: Jacqui Melvin, Policy Analyst, Office of Regulatory Policy, Farm Credit Administration, McLean, VA 22102–5090, (703) 883–4268, TTY (703) 883–4434, or Mary Alice Donner, Senior Attorney, Office of General Counsel, Farm Credit Administration, McLean, VA 22102–5090, (703) 883–4020, TTY (703) 883–4020.

SUPPLEMENTARY INFORMATION:

I. Objective

The objective of this notice is to continue our comprehensive review of regulations governing the System and to eliminate, consistent with law, safety, and soundness, all regulations that are unnecessary, unduly burdensome or costly, or not based on the law. We are requesting public comment to identify FCA regulations that:

- May duplicate other requirements;
- Are ineffective; or
- Impose burdens that are greater than the benefits received.

To accomplish our objective, we are targeting particular regulations for a more focused and in-depth review.

II. Background

The FCA is the independent Federal agency in the executive branch of the Government responsible for examining and regulating System institutions. As a Government-sponsored enterprise, the System primarily provides loans to farmers, ranchers, aquatic producers and harvesters, agricultural cooperatives, and rural utilities.

III. Regulations Under Review

The regulations of FCA that are subject to regulatory review described in this notice are codified in title 12, chapter VI, of the Code of Federal Regulations. In our previous notices, we asked the public to comment on all of our regulations, and we were able to

accomplish our objective of reducing regulatory burden. In this notice, we would like the public to comment specifically on these targeted regulations:

- (1) Part 607—Assessment and Apportionment of Administrative Expenses;
- (2) Part 614—Loan Policies and Operations;
- (3) Part 616—Leasing;
- (4) Part 617—Borrower Rights;
- (5) Part 618—General Provisions; and
- (6) Part 626—Nondiscrimination in Lending.

IV. Requesting Comments

Your comments are appreciated and will assist us in our continuing efforts to identify and reduce regulatory burden on System institutions. We will also continue our efforts to maintain and adopt regulations and policies that are necessary to implement the Farm Credit Act of 1971, as amended, and ensure the safety and soundness of the System. These actions will enable the System to better serve America's farmers, ranchers, aquatic producers and harvesters, agricultural cooperatives, and rural utilities in changing agricultural credit markets.

Dated: June 17, 2008.

Roland E. Smith,

Secretary, Farm Credit Administration Board.

[FR Doc. E8–14101 Filed 6–20–08; 8:45 am]

BILLING CODE 6705–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2008–0685; Directorate Identifier 2008–CE–037–AD]

RIN 2120–AA64

Airworthiness Directives; Diamond Aircraft Industries GmbH Model DA 42 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

The original designed bellcrank for the aileron control system in the wing needed to be installed with slightly bent rod ends during production of the aircraft to avoid friction and possible chafing. In addition to being a nonpreferable production practice, this creates the risk of replacement parts being installed during subsequent in-service maintenance without being bent or not being bent correctly. This condition, if not detected and corrected, could lead to chafing damage of the aileron control system and consequent loss of control of the aircraft.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by July 23, 2008.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Sarjapur Nagarajan, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4145; fax: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-0685; Directorate Identifier 2008-CE-037-AD" at the beginning of your comments. We specifically invite

comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued AD No. 2008-0086, dated May 13, 2008 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

The original designed bellcrank for the aileron control system in the wing needed to be installed with slightly bent rod ends during production of the aircraft to avoid friction and possible chafing. In addition to being a nonpreferable production practice, this creates the risk of replacement parts being installed during subsequent in-service maintenance without being bent or not being bent correctly. This condition, if not detected and corrected, could lead to chafing damage of the aileron control system and consequent loss of control of the aircraft. Diamond Aircraft Industries GmbH has now developed a new aileron bellcrank that allows for additional angular movement of the push rod, thereby eliminating the chafing risk without using bent rod ends.

For the reasons described above, this EASA Airworthiness Directive (AD) requires the replacement of the aileron bellcrank with an improved part and the replacement of any bent rod ends P/N DAI-9027-00-01. In addition, this AD prohibits the reinstallation of P/N DA4-2717-50-00 aileron bellcranks and bent rod ends P/N DAI-9027-00-01 as replacement in the future.

Relevant Service Information

Diamond Aircraft Industries GmbH has issued Mandatory Service Bulletin No. MSB-42-043/1, dated April 3, 2008; Diamond Aircraft Industries GmbH Work Instruction WI-MSB-42-043, dated February 4, 2008; and Diamond Aircraft Industries GmbH Drawing Number D60-2717-00-00, dated January 24, 2008. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation

in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This Proposed AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the proposed AD.

Costs of Compliance

We estimate that this proposed AD will affect 156 products of U.S. registry. We also estimate that it would take about 3 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour (no labor cost; 3 work-hours warranty given by manufacturer). Required parts would cost \$0 (warranty credit given by manufacturer) per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these costs. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$0, or \$0 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with

promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Diamond Aircraft Industries GmbH: Docket No. FAA-2008-0685; Directorate Identifier 2008-CE-037-AD.

Comments Due Date

- (a) We must receive comments by July 23, 2008.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to Model DA 42 airplanes, all serial numbers, with aileron bellcranks part number (P/N) DA4-2717-50-00 installed, certificated in any category.

Subject

- (d) Air Transport Association of America (ATA) Code 27: Flight Controls.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

The original designed bellcrank for the aileron control system in the wing needed to be installed with slightly bent rod ends during production of the aircraft to avoid friction and possible chafing. In addition to being a nonpreferable production practice, this creates the risk of replacement parts being installed during subsequent in-service maintenance without being bent or not being bent correctly. This condition, if not detected and corrected, could lead to chafing damage of the aileron control system and consequent loss of control of the aircraft. Diamond Aircraft Industries GmbH has now developed a new aileron bellcrank that allows for additional angular movement of the push rod, thereby eliminating the chafing risk without using bent rod ends.

For the reasons described above, this EASA Airworthiness Directive (AD) requires the replacement of the aileron bellcrank with an improved part and the replacement of any bent rod ends P/N DAI-9027-00-01. In addition, this AD prohibits the reinstallation of P/N DA4-2717-50-00 aileron bellcranks and bent rod ends P/N DAI-9027-00-01 as replacement in the future.

Actions and Compliance

- (f) Unless already done, do the following actions:

- (1) Within the next 200 hours time-in-service (TIS) after the effective date of this AD, replace the aileron bellcrank, P/N DA4-2717-50-00, with the improved design aileron bellcrank, P/N DA4-2717-50-00_01, and replace any bent rod ends, P/N DAI-9027-00-01, with straight rod ends, P/N DAI-9027-00-01, following Mandatory Service Bulletin No. MSB-42-043/1, dated April 3, 2008; Diamond Aircraft Industries GmbH Work Instruction WI-MSB-42-043, dated February 4, 2008; and Diamond Aircraft Industries GmbH Drawing Number D60-2717-00-00, dated January 24, 2008.

- (2) As of the effective date of this AD, do not install any aileron bellcrank, P/N DA4-2717-50-00, or bent rod ends, P/N DAI-9027-00-01.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

- (g) The following provisions also apply to this AD:

- (1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to

ATTN: Sarjapur Nagarajan, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4145; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

- (2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

- (3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

- (h) Refer to MCAI European Aviation Safety Agency (EASA) AD No. 2008-0086, dated May 13, 2008; Diamond Aircraft Industries GmbH Mandatory Service Bulletin No. MSB-42-043/1, dated April 3, 2008; Diamond Aircraft Industries GmbH Work Instruction WI-MSB-42-043, dated February 4, 2008; and Diamond Aircraft Industries GmbH Drawing Number D60-2717-00-00, dated January 24, 2008, for related information.

Issued in Kansas City, Missouri, on June 17, 2008.

David R. Showers,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-14078 Filed 6-20-08; 8:45 am]

BILLING CODE 4910-13-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 82

[EPA-HQ-OAR-2002-0064; FRL-8683-6]

RIN 2060-AK26

Protection of Stratospheric Ozone: Listing of Substitutes for Ozone-Depleting Substances—n-Propyl Bromide in Adhesives, Coatings, and Aerosols; Notice of Data Availability

AGENCY: Environmental Protection Agency (EPA).

ACTION: Notice of data availability and request for comment period.

SUMMARY: The Environmental Protection Agency (EPA) is making available to the public information related to a May 30, 2007 proposed rule under the Significant New Alternatives Policy