(b) Neither discovery nor oral hearings will be permitted in appeals from final SBA loan review decisions.

(c) All appeals under this subpart will be decided solely on a review of the administrative record, the appeal petition, any response, any reply or supplemental pleading, and filings related to objection to the administrative record.

§134.1210 Standard of review.

The standard of review is whether the final SBA loan review decision was based on clear error of fact or law. The appellant has the burden of proof.

§134.1211 Decision on appeal.

(a) Time limits and contents. The Judge will issue his or her decision within 45 calendar days after the close of record, as practicable. The decision will contain findings of fact and conclusions of law, the reasons for such findings and conclusions, and any relief ordered. The decision will be served upon appellant and SBA utilizing the OHA Case Portal.

(b) *Initial decision*. The Judge's decision on the appeal is an initial decision. However, unless a request for reconsideration is filed pursuant to paragraph (c) of this section or the SBA Administrator, solely within the Administrator's discretion, decides to review or reverse the initial decision pursuant to paragraph (d) of this section, an initial decision shall become the final decision of SBA 30 calendar days after its service. The discretionary authority of the Administrator does not create any additional rights of appeal on the part of an appellant not otherwise specified in SBA regulations in this chapter. Any decision pursuant to this subpart applies only to the PPP and does not apply to SBA's 7(a) Loan Program generally or to any interpretation or application of the regulations in part 120 or 121 of this chapter.

(c) Reconsideration. An initial decision of the Judge may be reconsidered. If a request for reconsideration is filed and the SBA Administrator does not exercise discretion to review or reverse the initial decision under paragraph (d) of this section, OHA will decide the request for reconsideration and OHA's decision on the request for reconsideration is a reconsidered initial OHA decision.

(1) Either SBA or appellant may request reconsideration by filing with the Judge and serving a petition for reconsideration within 10 calendar days after service of the Judge's decision. The request for reconsideration must clearly show an error of fact or law material to the decision. SBA does not have to have filed a response to the borrower's appeal petition to request reconsideration of the initial decision of the Judge.

(2) The Judge may also reconsider a decision on his or her own initiative within 20 calendar days after service of

the Judge's decision.

(3) A reconsidered initial OHA decision becomes the final decision of SBA 30 calendar days after its service unless the SBA Administrator, solely within the Administrator's discretion, decides to review or reverse the reconsidered initial OHA decision under paragraph (d) of this section. The discretionary authority of the Administrator does not create any additional rights of appeal on the part of an appellant not otherwise specified in SBA regulations in this chapter.

(d) Administrator review. Within 30 calendar days after the service of an initial OHA decision or a reconsidered initial OHA decision of a Judge, the SBA Administrator, solely within the Administrator's discretion, may elect to review and/or reverse an initial OHA decision or a reconsidered initial OHA decision. In the event that the Administrator elects to review and/or reverse an initial OHA decision and a timely request for reconsideration of a Judge's initial decision is also filed by an appellant pursuant to paragraph (c) of this section, the Administrator will consider such request for reconsideration. The Administrator's decision will become the final decision of the SBA upon issuance.

(e) Precedent. Neither initial nor final decisions rendered by OHA under this

subpart are precedential.

(f) Publication. Final decisions are normally published without redactions on OHA's website. PPP decisions will likely contain confidential business and financial information and/or personally identifiable information. Therefore, OHA, within its full discretion, may publish final decisions issued under this section with any necessary redactions.

(g) Appeal to Federal district court. Final decisions may be appealed to the appropriate Federal district court only.

§ 134.1212 Effects of the decision.

OHA may affirm, reverse, or remand a final SBA loan review decision. If remanded, OHA no longer has jurisdiction over the matter unless a new appeal is filed as a result of a new final SBA loan review decision.

§ 134.1213 Equal Access to Justice Act.

A prevailing appellant is not entitled to recover attorney's fees. Appeals to

OHA from final SBA loan review decisions under the PPP are not proceedings that are required to be conducted by an Administrative Law Judge under § 134.603.

§ 134.1214 Confidential information.

If a filing or other submission made pursuant to an appeal in this subpart contains confidential business and financial information; personally identifiable information; source selection sensitive information; income tax returns; documents and information covered under § 120.1060 of this chapter; or any other exempt information, that information is not available to the public pursuant to the Freedom of Information Act (FOIA), 5 U.S.C. 552.

Isabella Casillas Guzman,

Administrator.

[FR Doc. 2021–19985 Filed 9–14–21; 11:15 am]

BILLING CODE 8026–03–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2021-0701; Project Identifier MCAI-2021-00365-T; Amendment 39-21704; AD 2021-18-03]

RIN 2120-AA64

Airworthiness Directives; Yaborã Indústria Aeronáutica S.A. (Type Certificate Previously Held by Embraer S.A.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT. **ACTION:** Final rule; request for comments.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2020–26– 02, which applied to certain Yaborã Indústria Aeronáutica S.A. (type certificate previously held by Embraer S.A.) Model ERJ 190-400 airplanes. AD 2020-26-02 required amending the existing airplane flight manual (AFM) to incorporate a new limitation and revise certain normal procedures. This AD retains those requirements and also requires upgrading the electronic engine control (EEC) software, as specified in an Agência Nacional de Aviação Civil (ANAC) AD, which is incorporated by reference. This AD was prompted by a report of an in-flight shutdown (IFSD) due in part to failure in the low-pressure compressor (LPC) rotor 1 during operation in high altitude at high thrust settings, and by the development of updated EEC software, which would

terminate the requirement to amend the existing AFM. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD becomes effective October 1, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of October 1, 2021.

The FAA must receive comments on this AD by November 1, 2021.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to https://www.regulations.gov. Follow the instructions for submitting comments.
 - Fax: 202-493-2251.
- *Mail*: U.S. Department of Transportation, Docket Operations, M– 30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• Hand Delivery: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For material incorporated by reference (IBR) in this AD, contact National Civil Aviation Agency (ANAC), Aeronautical Products Certification Branch (GGCP), Rua Dr. Orlando Feirabend Filho, 230— Centro Empresarial Aquarius—Torre B—Andares 14 a 18, Parque Residencial Aquarius, CEP 12.246–190—São José dos Campos—SP, BRAZIL, Tel: 55 (12) 3203-6600; Email: pac@anac.gov.br; internet www.anac.gov.br/en/. You may find this IBR material on the ANAC website at https://sistemas.anac.gov.br/ certificacao/DA/DAE.asp. You may view this IBR material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at https:// www.regulations.gov by searching for and locating Docket No. FAA-2021-0701.

Examining the AD Docket

You may examine the AD docket on the internet at https://www.regulations.gov by searching for and locating Docket No. FAA-2021-0701; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT:

Krista Greer, Aerospace Engineer, Large

Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3221; email krista.greer@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued AD 2020–26–02, Amendment 39–21357 (85 FR 81790, December 17, 2020) (AD 2020–26–02), which applied to Yaborã Indústria Aeronáutica S.A. (type certificate previously held by Embraer S.A.) Model ERJ 190–400 airplanes. AD 2020–26–02 required amending the existing AFM to incorporate a new limitation and revise certain normal procedures. The FAA issued AD 2020–26–02 to address uncontained release of the LPC rotor 1 and damage to the engine and airplane structure, which could result in loss of control of the airplane.

Actions Since AD 2020–26–02 Was Issued

AD 2020–26–02 and the corresponding ANAC AD 2020–07–01 considered their requirements interim action. ANAC AD 2020–07–01 indicated that further mandatory actions may be necessary as a result of the investigation into failures in engines similar to those on affected airplanes. The manufacturer has since developed upgraded EEC software that will prevent the unsafe condition. The FAA has determined that further rulemaking is necessary; this AD follows from that determination.

Since the FAA issued AD 2020–26–02, ANAC, which is the aviation authority for Brazil, has issued ANAC AD 2020–07–01R01, effective March 26, 2021 (ANAC AD 2020–07–01R01) (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for certain Model ERJ 190–400 airplanes. ANAC AD 2020–07–01R01 supersedes ANAC AD 2020–07–01.

This AD was prompted by a report of an IFSD due in part to failure in the LPC rotor 1 during operation in high altitude at high thrust settings, and the development of upgraded EEC software, which eliminates the need for the amendments to the existing AFM required by AD 2020–26–02. The FAA is issuing this AD to address uncontained release of the LPC rotor 1 and damage to the engine and airplane structure, which could result in loss of control of the airplane. See the MCAI for additional background information.

Explanation of Retained Requirements

Although this AD does not explicitly restate the requirements of AD 2020–26–02, this AD retains all of the

requirements of AD 2020–26–02. Those requirements are referenced in ANAC AD 2020–07–01R01, which, in turn, is referenced in paragraph (g) of this AD.

Related Service Information Under 1 CFR Part 51

ANAC AD 2020–07–01R01 describes procedures for amending the existing AFM to incorporate a new limitation and revise the normal procedures to limit the engine N1 setting for flights above 33,000 ft. ANAC AD 2020–07–01R01 also describes procedures for upgrading the EEC software and subsequently removing the AFM amendments. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA's Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI referenced above. The FAA is issuing this AD because the FAA has evaluated all pertinent information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Requirements of This AD

This AD requires accomplishing the actions specified in the MCAI described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD.

Explanation of Required Compliance Information

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, ANAC AD 2020-07-01R01 is incorporated by reference in this AD. This AD requires compliance with ANAC AD 2020-07-01R01 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this AD. Service information required by ANAC AD 2020-07-01R01 for compliance will be available at https:// www.regulations.gov by searching for

and locating Docket No. FAA-2021-0701 after this AD is published.

FAA's Justification and Determination of the Effective Date

There are currently no domestic operators of these products. Therefore, the FAA finds that notice and opportunity for prior public comment are unnecessary and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this AD. Send your comments to an address listed under ADDRESSES. Include "Docket No. FAA—2021—0701; Project Identifier MCAI—2021—00365—T" at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to https://www.regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Krista Greer, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3221. Any commentary that the FAA receives which is not

specifically designated as CBI will be placed in the public docket for this rulemaking.

Interim Action

The FAA considers this AD interim action. Investigation into failures in engines similar to those installed on the affected airplanes will enable the manufacturer to obtain better insight into the nature, cause, and extent of the IFSDs, and eventually to develop final action to address the unsafe condition. Once final action has been identified, the FAA might consider further rulemaking.

Regulatory Flexibility Act (RFA)

The requirements of the RFA do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because the FAA has determined that it has good cause to adopt this rule without notice and comment, RFA analysis is not required.

Costs of Compliance

Currently, there are no affected U.S.-registered airplanes. If an affected airplane is imported and placed on the U.S. Register in the future, the FAA provides the following cost estimates to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product
Retained actions from AD 2020–26–02 New required actions	1 work-hour × \$85 per hour = \$85 Up to 3 work-hours × \$85 per hour = Up to \$255		\$85. Up to \$255.

According to the manufacturer, some or all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected operators. The FAA does not control warranty coverage for affected operators. As a result, the FAA has included all known costs in the cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing

regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a "significant regulatory action" under Executive Order 12866, and

(2) Will not affect intrastate aviation in Alaska.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by:
- a. Removing airworthiness directive (AD) 2020–26–02, Amendment 39–

21357 (85 FR 81790, December 17, 2020), and

■ b. Adding the following new AD:

2021–18–03 Yaborã Indústria Aeronáutica S.A. (Type Certificate Previously Held by Embraer S.A.) Airplanes:

Amendment 39–21704; Docket No. FAA–2021–0701; Project Identifier MCAI–2021–00365–T.

(a) Effective Date

This airworthiness directive (AD) becomes effective October 1, 2021.

(b) Affected ADs

This AD replaces AD 2020–26–02, Amendment 39–21357 (85 FR 81790, December 17, 2020) (AD 2020–26–02).

(c) Applicability

This AD applies to Yaborã Indústria Aeronáutica S.A. (type certificate previously held by Embraer S.A.) Model ERJ 190–400 airplanes, certificated in any category, as identified in Agência Nacional de Aviação Civil (ANAC) AD 2020–07–01R01, effective March 26, 2021 (ANAC AD 2020–07–01R01).

(d) Subject

Air Transport Association (ATA) of America Code 72, Turbine/turboprop engine.

(e) Reason

This AD was prompted by a report of an in-flight shutdown (IFSD) due in part to failure in the low-pressure compressor (LPC) rotor 1 during operation in high altitude at high thrust settings, and by the development of updated electronic engine control (EEC) software that will prevent the unsafe condition. The FAA is issuing this AD to address uncontained release of the LPC rotor 1 and damage to the engine and airplane structure, which could result in loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, ANAC AD 2020–07–01R01.

(h) Exceptions to ANAC AD 2020-07-01R01

- (1) Where ANAC AD 2020–07–01R01 refers to "the effective date of [ANAC] AD 2020–07–01," this AD requires using January 4, 2021 (the effective date of FAA AD 2020–26–02).
- (2) Where ANAC AD 2020–07–01R01 says to "upgrade de EEC software," this AD requires to "upgrade the EEC software."
- (3) Where ANAC AD 2020–07–01R01 refers to its effective date, this AD requires using the effective date of this AD.
- (4) The "Alternative method of compliance (AMOCs)" section of ANAC AD 2020–07–01R01 does not apply to this AD.
- (5) Where paragraph (c)(2) of ANAC AD 2020–07–01R01 requires removing the airplane flight manual (AFM) amendments, this AD requires that the amendments to the

existing AFM be removed before further flight after the EEC software has been updated.

(i) Other FAA AD Provisions

The following provisions also apply to this

- (1) Alternative Methods of Compliance (AMOCs): The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.
- (2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or ANAC; or ANAC's authorized Designee. If approved by the ANAC Designee, the approval must include the Designee's authorized signature.

(j) Related Information

For more information about this AD, contact Krista Greer, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3221; email krista.greer@faa.gov.

(j) Material Incorporated by Reference

- (1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.
- (2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.
- (i) Agência Nacional de Aviação Civil (ANAC) AD 2020–07–01R01, effective March 26, 2021.
 - (ii) [Reserved]
- (3) For ANAC AD 2020–07–01R01, contact National Civil Aviation Agency (ANAC), Aeronautical Products Certification Branch (GGCP), Rua Dr. Orlando Feirabend Filho, 230—Centro Empresarial Aquarius—Torre B—Andares 14 a 18, Parque Residencial Aquarius, CEP 12.246–190—São José dos Campos—SP, BRAZIL, Tel: 55 (12) 3203–6600; Email: pac@anac.gov.br; internet www.anac.gov.br/en/. You may find this IBR material on the ANAC website at https://sistemas.anac.gov.br/certificacao/DA/DAE.asp.
- (4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket on the internet at https://www.regulations.gov by searching for and locating Docket No. FAA–2021–0701.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: https://www.archives.gov/federal-register/cfr/ibrlocations.html.

Issued on September 9, 2021.

Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–19847 Filed 9–15–21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2021-0306; Project Identifier MCAI-2020-01493-E; Amendment 39-21706; AD 2021-18-05]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce Deutschland Ltd & Co KG (Type Certificate Previously Held by Rolls-Royce plc) Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2020-15-12 for certain Rolls-Royce Deutschland Ltd & Co KG (RRD) Trent 1000 model turbofan engines. AD 2020–15–12 required initial and repetitive ultrasonic or visual inspections of the intermediate-pressure compressor (IPC) stage 1 rotor blade root (front face), IPC stage 2 rotor blade root (front and rear face), and IPC shaft stage 2 dovetail post (front face), and removal of any cracked parts from service. AD 2020–15–12 also required an inspection after asymmetric power and cabin depressurization events. This AD was prompted by IPC rotor blade separations resulting in engine failures. This AD requires initial and repetitive ultrasonic or visual inspections of certain IPC stage 1 rotor blade root, IPC stage 2 rotor blade root, and IPC shaft stage 2 dovetail posts until replacement of the IPC stage 1 and stage 2 rotor blades with redesigned IPC stage 1 and stage 2 rotor blades in kitted sets. The FAA is issuing this AD to address the unsafe condition on these products. DATES: This AD is effective October 21,

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of October 21, 2021.

2021.