

Proposed Rules

Federal Register

Vol. 83, No. 11

Wednesday, January 17, 2018

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF AGRICULTURE

Agricultural Marketing Service

7 CFR Part 205

[Document Number AMS–NOP–17–0057; NOP–17–08]

Meeting of the National Organic Standards Board

AGENCY: Agricultural Marketing Service, USDA.

ACTION: Public meeting.

SUMMARY: In accordance with the Federal Advisory Committee Act, as amended, the Agricultural Marketing Service (AMS), U.S. Department of Agriculture (USDA), is announcing a meeting of the National Organic Standards Board (NOSB) to assist the USDA in the development of standards for substances to be used in organic production and to advise the Secretary of Agriculture on any other aspects of the implementation of the Organic Foods Production Act.

DATES: The Board will receive public comments via webinars on April 17 and 19, 2018, from 1:00 p.m. to approximately 4:00 p.m. Eastern Time (ET). An in-person meeting will be held April 25–27, 2018, from 8:30 a.m. to approximately 6:00 p.m. Mountain Time. In-person oral comments will be heard on Wednesday, April 25, and Thursday, April 26, 2018. The deadline to submit written comments and/or sign up for oral comment at either the webinar or face-to-face meeting is 11:59 p.m. ET, April 4, 2018.

ADDRESSES: The webinars are virtual and will be accessed via the internet and/or phone. Access information will be available on the AMS website prior to the webinars. The in-person meeting will take place at the Tucson University Park Hotel, 880 East Second Street, Tucson, Arizona 85719, United States. Detailed information pertaining to the webinars and in-person meeting can be found at www.ams.usda.gov/NOSBMeetings.

FOR FURTHER INFORMATION CONTACT: Ms. Michelle Arsenault, Advisory Committee Specialist, National Organic Standards Board, USDA–AMS–NOP, 1400 Independence Ave. SW, Room 2642–S, Mail Stop 0268, Washington, DC 20250–0268; Phone: (202) 720–3252; Email: nosb@ams.usda.gov.

SUPPLEMENTARY INFORMATION: The NOSB makes recommendations to the Department of Agriculture about whether substances should be allowed or prohibited in organic production and/or handling, assists in the development of standards for organic production, and advises the Secretary on other aspects of the implementation of the Organic Foods Production Act. The NOSB is holding a public meeting to discuss and vote on proposed recommendations to the USDA, receive updates from the USDA National Organic Program (NOP) on issues pertaining to organic agriculture, and receive comments from the organic community. The meeting and webinars are open to the public. All meeting documents, including the meeting agenda, NOSB proposals and discussion documents, instructions for submitting and viewing public comments, and instructions for requesting time for oral comments, will be available on the AMS website at www.ams.usda.gov/NOSBMeetings. Please check the website periodically for updates. Meeting topics will encompass a wide range of issues, including substances petitioned for addition to or deletion from the National List of Allowed and Prohibited Substances (National List), substances on the National List that are under sunset review, and guidance on organic policies. Participants and attendees may take photos and video at the meeting, but not in a manner that disturbs the proceedings.

Public Comments: Comments should address specific topics noted on the meeting agenda.

Written Comments: Written public comments will be accepted on or before 11:59 p.m. ET on April 4, 2018, via <http://www.regulations.gov>: Document #AMS–NOP–17–0057. Comments submitted after this date will be provided to the NOSB, but Board members may not have adequate time to consider those comments prior to making recommendations. The NOP strongly prefers comments to be submitted electronically. However,

written comments may also be submitted (*i.e.*, postmarked) via mail to the person listed under **FOR FURTHER INFORMATION CONTACT** by or before the deadline.

Oral Comments: The NOSB is providing the public multiple dates and opportunities to provide oral comments and will accommodate as many individuals and organizations as time permits. Persons or organizations wishing to make oral comments must pre-register by 11:59 p.m. ET, April 4, 2018, and can register for only one speaking slot: Either during the webinars scheduled for April 17 and 19, or at the in-person meeting, scheduled for April 25–27, 2018. Due to the limited time allotted for in-person public comments during the in-person meeting, commenters are strongly encouraged to comment during the webinar(s). Instructions for registering and participating in the webinar can be found at www.ams.usda.gov/NOSBMeetings.

Meeting Accommodations: The meeting hotel is ADA Compliant, and the USDA provides reasonable accommodation to individuals with disabilities where appropriate. If you need a reasonable accommodation to participate in this public meeting, please notify the person listed under **FOR FURTHER INFORMATION CONTACT**. Determinations for reasonable accommodation will be made on a case-by-case basis.

Dated: December 26, 2017.

Bruce Summers,

Acting Administrator, Agricultural Marketing Service.

[FR Doc. 2017–28170 Filed 1–16–18; 8:45 am]

BILLING CODE 3410–02–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2017–1247; Product Identifier 2017–NM–085–AD]

RIN 2120–AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Bombardier, Inc., Model BD-100-1A10 airplanes. This proposed AD was prompted by a report indicating that certain lanyards for the passenger oxygen masks located in the airplane's entry area are too long. This proposed AD would require replacement of certain oxygen mask lanyards with shorter lanyards. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by March 5, 2018.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone: 514-855-5000; fax: 514-855-7401; email: thd.crj@aero.bombardier.com; internet: <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW, Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for

and locating Docket No. FAA-2017-1247; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Cesar Gomez, Aerospace Engineer, Airframe and Mechanical Systems Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone: 516-228-7318; fax: 516-794-5531.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2017-1247; Product Identifier 2017-NM-085-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this NPRM.

Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian AD CF-2017-22, dated June 23, 2017 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for certain Bombardier, Inc.,

Model BD-100-1A10 airplanes. The MCAI states:

Bombardier, Inc., has discovered that the entry area passenger oxygen mask lanyards are too long. Upon deployment during an emergency, this may result in difficulties to start the oxygen flow for tall individuals. This [Canadian] AD mandates the replacement of the existing entry area passenger oxygen mask lanyards with shorter ones for proper operation.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-1247.

Related Service Information Under 1 CFR Part 51

Bombardier, Inc., has issued Service Bulletin 100-35-08, dated April 11, 2017. This service information describes procedures for replacing the lanyards in the passenger oxygen masks located in the passenger entry area. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD affects 187 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replacement	1 work-hour × \$85 per hour = \$85	(¹)	\$85	\$15,895

¹ We have received no definitive data that would enable us to provide cost estimates for the required parts.

According to the manufacturer, some of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a

result, we have included all available costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue

rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes to the Director of the System Oversight Division.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Bombardier, Inc.: Docket No. FAA–2017–1247; Product Identifier 2017–NM–085–AD.

(a) Comments Due Date

We must receive comments by March 5, 2018.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc., Model BD–100–1A10 airplanes, certificated in any category, serial numbers 20003 through 20424 inclusive and 20426 through 20500 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 35, Oxygen.

(e) Reason

This AD was prompted by a report indicating that certain lanyards for the passenger oxygen masks located in the airplane’s entry area are too long. The length of the oxygen mask lanyard might cause the safety pin tethered to the opposite end of the lanyard to remain engaged in the oxygen flow mechanism when the mask is pulled to the passenger’s face. We are issuing this AD to detect and correct lanyards that are too long, which might result in difficulties starting the flow of oxygen in an emergency.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Lanyard Replacement

Within 36 months after the effective date of this AD: For any entry area passenger oxygen mask dispensing unit (POMDU) having part number (P/N) 833–830–01, replace the lanyards in the POMDU with new lanyards having P/N 289–65–10, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 100–35–08, dated April 11, 2017.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly

to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone: 516–228–7300; fax: 516–794–5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.’s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(i) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF–2017–22, dated June 23, 2017, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2017–1247.

(2) For more information about this AD, contact Cesar Gomez, Aerospace Engineer, Airframe and Mechanical Systems Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone: 516–228–7318; fax: 516–794–5531.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone: 514–855–5000; fax: 514–855–7401; email: thd.crj@aero.bombardier.com; internet: <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW, Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on January 5, 2018.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018–00664 Filed 1–16–18; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2017–1248; Product Identifier 2017–NM–162–AD]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.