

directors.¹¹ Dangerous and abusive behavior is considered any violent, belligerent, unreasonably disruptive, or abusive behavior. Examples of dangerous and abusive conduct include, but are not limited to, a member threatening physical harm to employees, a member repeatedly and unwelcomely giving gifts to or asking tellers on dates, a member repeatedly using racial or sexist language towards employees, and a member threatening to follow a loan officer home for denying a loan.

A credit union must provide notice of the expulsion to the member. The notice must include the reason for the expulsion, and if a hearing was conducted or written testimony provided, the credit union should provide a response to the member's statements. The notice must be specific and not just include conclusory statements regarding the reason for the member's expulsion. For example, a general statement that the member's behavior has been deemed abusive and the member is being subject to expulsion procedures would be insufficient as an explanation. A credit union is prohibited from expelling a class of members under this provision. That would include a board acting to remove all delinquent members or class of delinquent members.

If a special meeting of the members is called to expel the member, only in-person voting is permitted in conjunction with the special meeting, so that the affected member has an opportunity to present the member's case and respond to the credit union's concerns. However, an in-person meeting is not required if a member is expelled by a two-thirds vote of the board of directors. In addition, FCUs should consider the commentary under Article XVI about members using accounts for unlawful purposes.

Optional Standard Disclosure of Expulsion Policy

We may terminate your membership in [name of FCU] in one of three ways. The first way is through a special meeting. Under this option, we may call a special meeting of the members, provide you an opportunity to be heard, and obtain a two-thirds vote of the members present at the special meeting in favor of your expulsion. The second way to terminate your membership is under a nonparticipation policy given to each member that follows certain requirements. The third way to terminate your membership is by a two-thirds vote of a quorum of the directors of the credit union for cause.

Cause is defined as follows: (A) a substantial or repeated violation of [name of membership agreement] with [us]; (B) a substantial or repeated disruption, including dangerous or abusive behavior, to the credit union's operations; or (C) fraud, attempted fraud, or a conviction of other illegal conduct that a member has been convicted of in relation to [us], including in connection with our employees conducting business on behalf of us.

Before the board votes on an expulsion, [we] must provide written notice to your mail address (or email, if applicable) on record or

personally provide the written notice. [We] must provide the specific reasons for the expulsion and allow you an opportunity to rebut those reasons through a hearing if you choose. It is your responsibility to keep your contact information with [us] up to date, and to open and read notices from [us]. Unless [we] determine to allow otherwise, there is no right to an in-person hearing with the board. If you fail to request a hearing within 60 calendar days of receipt of the notice, you will be expelled. You may submit any complaints about your pending expulsion or expulsion to NCUA's Consumer Assistance Center if the complaint cannot be resolved with the credit union.

[We] will confirm any expulsion with a letter with information on the effect of the expulsion and how you can request reinstatement. Expulsion or withdrawal from membership does not relieve a member of liability to the credit union, and we may demand immediate repayment of the money you owe to us after expulsion, subject to any applicable contract terms and conditions.

For additional information on expulsion and a copy of our expulsion policy, see [Article XIV of our Bylaws].

* * * * *

[FR Doc. 2023-15715 Filed 7-25-23; 8:45 am]

BILLING CODE 7535-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2023-1500; Project Identifier MCAI-2023-00642-T; Amendment 39-22511; AD 2023-14-11]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Bombardier, Inc., Model BD-100-1A10 airplanes. This AD was prompted by reports of unexpected pitch upset upon autopilot disconnect. This AD requires revising the Non-Normal Procedures section of the existing airplane flight manual (AFM) associated with Auto Flight. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective August 10, 2023.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of August 10, 2023.

The FAA must receive comments on this AD by September 11, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- **Fax:** 202-493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-1500; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For service information identified in this final rule, contact Bombardier Business Aircraft Customer Response Center, 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-2999; email ac.yul@aero.bombardier.com; website [bombardier.com](https://www.bombardier.com).

- You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-1500.

FOR FURTHER INFORMATION CONTACT:

Deep Gaurav, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email: deep.gaurav@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this final rule. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2023-1500; Project Identifier MCAI-2023-00642-T" at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

¹¹ See 12 U.S.C. 1764.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Deep Gaurav, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email: deep.gaurav@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

Transport Canada, which is the aviation authority for Canada, has issued Transport Canada AD CF-2023-26, dated May 3, 2023 (Transport Canada AD CF-2023-26) (referred to after this as the MCAI), to correct an unsafe condition on certain Bombardier, Inc., Model BD-100-1A10 airplanes. The MCAI states that during several in-service events, the crew experienced an unexpected pitch upset upon autopilot disconnect. Investigations of these events identified that the airplane gained altitude via manual command of the elevator control surface without the use of the horizontal stabilizer pitch trim, even though the manual pitch trim was fully functional. The autopilot was then engaged while the airplane was in an out-of-trim condition. Subsequent disengagement of the autopilot when the horizontal stabilizer is not correctly

trimmed can lead to high control column forces and difficulties in controlling the airplane.

The FAA is issuing this AD to address the unsafe condition on these products. You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA-2023-1500.

Related Service Information Under 1 CFR Part 51

Bombardier has issued the following AFM procedures, which include a Caution to the Auto Flight Non-Normal Procedures, to instruct crews to minimize changes to airspeed and configuration when using the autopilot disconnect switch in an out-of-trim situation.

- Section 05-14, Auto Flight, of Chapter 05, Non-Normal Procedures, of the Bombardier Challenger 300 (Imperial Version) Airplane Flight Manual, Publication No. CSP 100-1, Revision 68, dated June 14, 2022. (For obtaining the procedures for Bombardier Challenger 300 (Imperial Version) Airplane Flight Manual, Publication No. CSP 100-1, use Document Identification No. CH 300 AFM-I.)

- Section 05-14, Auto Flight, of Chapter 05, Non-Normal Procedures, of the Bombardier Challenger 350 Airplane Flight Manual, Publication No. CH 350 AFM, Revision 34, dated June 14, 2022. (For obtaining the procedures for Bombardier Challenger 350 AFM, Publication No. CH 350 AFM, use Document Identification No. CH 350 AFM.)

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in ADDRESSES section.

FAA's Determination

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service information referenced above. The FAA is issuing this AD after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

AD Requirements

This AD requires accomplishing the actions specified in the service information described previously.

Justification for Immediate Adoption and Determination of the Effective Date

Section 553(b)(3)(B) of the Administrative Procedure Act (APA) (5 U.S.C. 551 *et seq.*) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for "good cause," finds that those procedures are "impracticable, unnecessary, or contrary to the public interest." Under this section, an agency, upon finding good cause, may issue a final rule without providing notice and seeking comment prior to issuance. Further, section 553(d) of the APA authorizes agencies to make rules effective in less than thirty days, upon a finding of good cause.

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has found that the risk to the flying public justifies forgoing notice and comment prior to adoption of this rule because several events have occurred where the crew experienced an unexpected pitch upset upon autopilot disconnect. Such a result is hazardous as it could lead to high control column forces and difficulties in controlling the airplane. Accordingly, notice and opportunity for prior public comment are impracticable and contrary to the public interest pursuant to 5 U.S.C. 553(b)(3)(B).

In addition, the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in less than 30 days, for the same reasons the FAA found good cause to forgo notice and comment.

Regulatory Flexibility Act

The requirements of the Regulatory Flexibility Act (RFA) do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because the FAA has determined that it has good cause to adopt this rule without prior notice and comment, RFA analysis is not required.

Costs of Compliance

The FAA estimates that this AD affects 338 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
1 work-hour × \$85 per hour = \$85	\$0	\$85	\$28,730

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2023–14–11 Bombardier, Inc.: Amendment 39–22511; Docket No. FAA–2023–1500; Project Identifier MCAI–2023–00642–T.

(a) Effective Date

This airworthiness directive (AD) is effective August 10, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc., Model BD–100–1A10 airplanes, certificated in any category, serial numbers 20003 through 20910 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code: 27, Flight controls.

(e) Reason

This AD was prompted by reports of unexpected pitch upset upon autopilot disconnect. The FAA is issuing this AD to address an unexpected pitch upset occurrence when the autopilot is engaged while the airplane is in an out-of-trim condition and later disengaged. The unsafe condition, if not addressed, could result in high control column forces and difficulties in controlling the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Airplane Flight Manual (AFM) Revision

Within 30 days after the effective date of this AD: revise the existing AFM to include the information specified in Section 05–14, Auto Flight, of Chapter 05, Non-Normal Procedures, of the Bombardier Challenger 300 Airplane Flight Manual (Imperial Version), Publication No. CSP 100–1, Revision 68, dated June 14, 2022; or the Bombardier Challenger 350 Airplane Flight Manual, Publication No. CH 350 AFM, Revision 34, dated June 14, 2022; as applicable.

Note 1 to paragraph (g): For obtaining the procedures for Bombardier Challenger 300 AFM (Imperial Version), Publication No. CSP 100–1, use Document Identification No. CH 300 AFM–I.

Note 2 to paragraph (g): For obtaining the procedures for Bombardier Challenger 350 AFM, Publication No. CH 350 AFM, use Document Identification No. CH 350 AFM.

(h) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, mail it to the address identified in paragraph (i)(2) of this AD or email to: 9-AVS-AIR-730-AMOC@faa.gov. If mailing information, also submit information by email. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or Transport Canada; or Bombardier, Inc.'s Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(i) Additional Information

(1) Refer to Transport Canada AD CF–2023–26, dated May 3, 2023, for related information. This Transport Canada AD may be found in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2023–1500.

(2) For more information about this AD, contact Deep Gaurav, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; email: deep.gaurav@faa.gov.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Section 05–14, Auto Flight, of Chapter 05, Non-Normal Procedures, of the Bombardier Challenger 300 Airplane Flight Manual (Imperial Version), Publication No. CSP 100–1, Revision 68, dated June 14, 2022.

Note 3 to paragraph (j)(2)(i): For obtaining this section of Bombardier Challenger 300 AFM (Imperial Version), Publication No. CSP 100–1, use Document Identification No. CH 300 AFM–I.

(ii) Section 05–14, Auto Flight, of Chapter 05, Non-Normal Procedures, of the Bombardier Challenger 350 Airplane Flight Manual, Publication No. CH 350 AFM, Revision 34, dated June 14, 2022.

Note 4 to paragraph (j)(2)(ii): For obtaining this section of Bombardier Challenger 350

AFM, Publication No. CH 350 AFM, use Document Identification No. CH 350 AFM.

(3) For service information identified in this AD, contact Bombardier Business Aircraft Customer Response Center, 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-2999; email ac.yul@aero.bombardier.com; website bombardier.com.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on July 13, 2023.

Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023-15862 Filed 7-24-23; 11:15 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2023-1020; Airspace Docket No. 21-AEA-31]

RIN 2120-AA66

Establishment of Area Navigation (RNAV) Routes; Eastern United States

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends one and establishes three low altitude United States Area Navigation (RNAV) routes. The purpose of the new RNAV routes is to expand the availability of the enroute structure and provide additional RNAV routing within the National Airspace System (NAS) in support of transitioning it from ground-based to satellite-based navigation.

DATES: Effective date 0901 UTC, October 5, 2023. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

ADDRESSES: A copy of the Notice of Proposed Rulemaking (NPRM), all comments received, this final rule, and all background material may be viewed online at www.regulations.gov using the FAA Docket number. Electronic

retrieval help and guidelines are available on the website. It is available 24 hours each day, 365 days each year.

FAA Order JO 7400.11G, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at www.faa.gov/air_traffic/publications/. You may also contact the Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

FOR FURTHER INFORMATION CONTACT: Brian Vidis, Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would expand the availability of RNAV in the eastern United States and improve the efficient flow of air traffic within the NAS by lessening the dependency on ground-based navigation.

History

The FAA published a notice of proposed rulemaking for Docket No. FAA-2023-1020 in the **Federal Register** (88 FR 29559; May 8, 2023), proposing to amend one and establish three low-altitude RNAV routes in support of transitioning the NAS from a ground-based to a satellite-based navigation. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

Differences From the NPRM

In the NPRM's description of RNAV route T-452, the FAA incorrectly listed the VINSE, PA; BADDI, PA; JOANE, PA; and GEERI, PA route points as waypoints (WP). The route points are actually identified as Fixes in the National Airspace System Resource (NASR) database and charted as Fixes

accordingly. This action corrects the error and changes the route points to be listed as Fixes.

Additionally, in the NPRM's description of RNAV route T-456, the FAA incorrectly listed the DELRO, PA, route point as a WP instead of Fix. This action also corrects the DELRO, PA, route point to be listed as a Fix.

Incorporation by Reference

United States Area Navigation Routes are published in paragraph 6011 of FAA Order JO 7400.11, Airspace Designations and Reporting Points, which is incorporated by reference in 14 CFR 71.1 on an annual basis. This document amends the current version of that order, FAA Order JO 7400.11G, dated August 19, 2022, and effective September 15, 2022. FAA Order JO 7400.11G is publicly available as listed in the **ADDRESSES** section of this document. These amendments will be published in the next update to FAA Order JO 7400.11.

FAA Order JO 7400.11G lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Rule

This action amends 14 CFR part 71 by amending one and establishing three low altitude RNAV T-routes in the northeast United States in support of transitioning from ground-based navigation aids to satellite-based navigation. The routes are described below.

T-299: Prior to this final rule, T-299 extended from the UCREEK, VA, WP to the SCAPE, PA, WP. This action extends T-299 to the southwest from the Montebello, VA (MOL), Very High Frequency (VHF) Omnidirectional Range/Distance Measuring Equipment (VOR/DME) 279° radial at 5.5 nautical miles (OBEPE, VA, Fix) to the UCREEK, VA, WP, and to the northeast to the intersection of the Harrisburg, PA (HAR), VOR/Tactical Air Navigation (VORTAC) 235° radial and the Westminster, MD (EMI), VORTAC 324° radial (SCAPE, PA, Fix) to the Albany, NY (ALB), VORTAC. The route overlays VOR Federal airway V-377 from the SCAPE, PA, Fix to the Harrisburg, PA (HAR), VORTAC; VOR Federal airway V-162 from the Harrisburg, PA (HAR), VORTAC to the Huguenot, NY (HUO), VOR/DME; and VOR Federal airway V-489 from the Huguenot, NY (HOU), VOR/DME to the Albany, NY (ALB), VORTAC.

T-452: T-452 is a new route that extends from the VINSE, PA, Fix to the REESY, PA, WP. The route is replacing VOR Federal airway V-469 from the St. Thomas, VA (THS), VORTAC to the