

that the applicant can show that the test conditions are scaled appropriately.

Except as discussed above, the special conditions are adopted as proposed.

Applicability

As discussed above, these special conditions are applicable to Boeing Model 737 series airplanes. Should Boeing apply at a later date for a change to the type certificate to include another model incorporating the same novel or unusual design feature, these special conditions would apply to that model as well.

Conclusion

This action affects only one novel or unusual design feature on one model series of airplanes. It is not a rule of general applicability.

List of Subjects in 14 CFR Part 25

Aircraft, Aviation safety, Reporting and recordkeeping requirements.

Authority Citation

The authority citation for these special conditions is as follows:

Authority: 49 U.S.C. 106(f), 106(g), 40113, 44701, 44702, 44704.

The Special Conditions

Accordingly, pursuant to the authority delegated to me by the Administrator, the following special conditions are issued as part of the type certification basis for Boeing Model 737 series airplanes.

In addition to the requirements of § 25.562, passenger seats incorporating an inertia locking device (ILD) must meet the following:

1. *Level of Protection Provided by ILD*—It must be demonstrated by test that the seats and attachments, when subject to the emergency-landing dynamic conditions specified in § 25.562, and with one ILD not deployed, do not experience structural failure that could result in:

a. Separation of the seat from the airplane floor.

b. Separation of any part of the seat that could form a hazard to the seat occupant or any other airplane occupant.

c. Failure of the occupant restraint or any other condition that could result in the occupant separating from the seat.

2. *Protection Provided Below and Above the ILD Actuation Condition*—If step-change effects on occupant protection exist for impacts below and above that at which the ILD deploys, tests must be performed to demonstrate that the occupant is shown to be protected at any condition at which the ILD does or does not deploy, up to the

maximum severity pulse specified by § 25.562. Test conditions must take into account any necessary tolerances for deployment.

3. *Protection Over a Range of Crash Pulse Vectors*—The ILD must be shown to function as intended for all test vectors specified in § 25.562.

4. *Protection During Secondary Impacts*—The ILD activation setting must be demonstrated to maximize the probability of the protection being available when needed, considering a secondary impact that is above the severity at which the device is intended to deploy up to the impact loading required by § 25.562.

5. *Protection of Occupants other than 50th Percentile*—Protection of occupants for a range of stature from a 2-year-old child to a 95th percentile male must be shown.

6. *Inadvertent Operation*—It must be shown that any inadvertent operation of the ILD does not affect the performance of the device during a subsequent emergency landing.

7. *Installation Protection*—It must be shown that the ILD installation is protected from contamination and interference from foreign objects.

8. *Reliability*—The performance of the ILD must not be altered by the effects of wear, manufacturing tolerances, aging/drying of lubricants, and corrosion.

9. *Maintenance and Functional Checks*—The design, installation and operation of the ILD must be such that it is possible to functionally check the device in place. Additionally, a functional-check method and a maintenance-check interval must be included in the seat installer's instructions for continued airworthiness (ICA) document.

10. *Release Function*—If a means exists to release an inadvertently activated ILD, the release means must not introduce additional hidden failures that would prevent the ILD from functioning properly.

Issued in Des Moines, Washington, on October 25, 2019.

James E. Wilborn,

Acting Manager, Transport Standards Branch, Policy and Innovation Division, Aircraft Certification Service.

[FR Doc. 2019-23740 Filed 10-30-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 25

[Docket No. FAA-2019-0814; Special Conditions No. 25-759-SC]

Special Conditions: Airbus Model A340 Series Airplanes; Seats With Inertia Locking Devices

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final special conditions; request for comments.

SUMMARY: These special conditions are issued for the Airbus Model A340 series airplanes. These airplanes will have a novel or unusual design feature when compared to the state of technology envisioned in the airworthiness standards for transport category airplanes. This design feature is seats with inertia locking devices (ILD). The applicable airworthiness regulations do not contain adequate or appropriate safety standards for this design feature. These special conditions contain the additional safety standards that the Administrator considers necessary to establish a level of safety equivalent to that established by the existing airworthiness standards.

DATES: This action is effective on Airbus on October 31, 2019. Send comments on or before December 16, 2019.

ADDRESSES: Send comments identified by Docket No. FAA-2019-0814 using any of the following methods:

- *Federal eRegulations Portal:* Go to <http://www.regulations.gov/> and follow the online instructions for sending your comments electronically.

- *Mail:* Send comments to Docket Operations, M-30, U.S. Department of Transportation (DOT), 1200 New Jersey Avenue SE, Room W12-140, West Building Ground Floor, Washington, DC 20590-0001.

- *Hand Delivery or Courier:* Take comments to Docket Operations in Room W12-140 of the West Building Ground Floor at 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- *Fax:* Fax comments to Docket Operations at 202-493-2251.

Privacy: The FAA will post all comments it receives, without change, to <http://www.regulations.gov/>, including any personal information the commenter provides. Using the search function of the docket website, anyone can find and read the electronic form of all comments received into any FAA docket, including the name of the

individual sending the comment (or signing the comment for an association, business, labor union, etc.). DOT's complete Privacy Act Statement can be found in the **Federal Register** published on April 11, 2000 (65 FR 19477–19478).

Docket: Background documents or comments received may be read at <http://www.regulations.gov/> at any time. Follow the online instructions for accessing the docket or go to Docket Operations in Room W12–140 of the West Building Ground Floor at 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Shannon Lennon, Cabin and Airframe Safety Section, AIR–675, Transport Standards Branch, Policy and Innovation Division, Aircraft Certification Service, Federal Aviation Administration, 2200 South 216th Street, Des Moines, Washington 98198; telephone and fax 206–231–3209; email Shannon.Lennon@faa.gov.

SUPPLEMENTARY INFORMATION: The substance of these special conditions has been subject to the notice and comment period in several prior instances and has been derived without substantive change from those previously issued. It is unlikely that prior public comment would result in a significant change from the substance contained herein. Therefore, the FAA has determined that prior public notice and comment are unnecessary, and finds that, for the same reason, good cause exists for adopting these special conditions upon publication in the **Federal Register**.

Comments Invited

The FAA invites interested people to take part in this rulemaking by sending written comments, data, or views. The most helpful comments reference a specific portion of the special conditions, explain the reason for any recommended change, and include supporting data.

The FAA will consider all comments received by the closing date for comments. The FAA may change these special conditions based on the comments received.

Background

On December 19, 2017, Airbus applied for a change to Type Certificate No. A43NM for seats with ILD in the Model A340 series airplanes. The Airbus Model A340 series airplane is a four-engine, transport category airplane with a maximum takeoff weight of 824,528 pounds and seating for 440 passengers.

Type Certification Basis

Under the provisions of title 14, Code of Federal Regulations (14 CFR) 21.101, Airbus must show that the Airbus Model A340 series airplanes, as changed, continue to meet the applicable provisions of the regulations listed in Type Certificate No. A43NM, or the applicable regulations in effect on the date of application for the change, except for earlier amendments as agreed upon by the FAA.

If the Administrator finds that the applicable airworthiness regulations (e.g., 14 CFR part 25) do not contain adequate or appropriate safety standards for the Airbus Model A340 series airplanes because of a novel or unusual design feature, special conditions are prescribed under the provisions of § 21.16.

Special conditions are initially applicable to the model for which they are issued. Should the type certificate for that model be amended later to include any other model that incorporates the same novel or unusual design feature, or should any other model already included on the same type certificate be modified to incorporate the same novel or unusual design feature, these special conditions would also apply to the other model under § 21.101.

In addition to the applicable airworthiness regulations and special conditions, the Airbus Model A340 series airplanes must comply with the fuel vent and exhaust emission requirements of 14 CFR part 34, and the noise certification requirements of 14 CFR part 36.

The FAA issues special conditions, as defined in 14 CFR 11.19, in accordance with § 11.38, and they become part of the type certification basis under § 21.101.

Novel or Unusual Design Features

The Airbus Model A340 series airplanes will incorporate the following novel or unusual design features:

Seats with inertia locking devices.

Discussion

Airbus will install, in Model A340 series airplanes, Thompson Aero Seating Ltd. first-class passenger seats that can be translated in the fore and aft direction by an electrically powered motor (actuator) that is attached to the seat primary structure. Under typical service-loading conditions, the motor internal brake is able to translate the seat and hold the seat in the translated position. However, under the inertial loads of emergency-landing loading conditions specified in 14 CFR 25.562,

the motor internal brake may not be able to maintain the seat in the required position. The ILD is an “active” device intended to control seat movement (i.e., a system that mechanically deploys during an impact event) to lock the gears of the motor assembly in place. The ILD mechanism is activated by the higher inertial load factors that could occur during an emergency-landing event. Each seat place incorporates two ILDs, one on either side of the seat pan. Only one ILD is required to hold an occupied seat in position during worst-case dynamic loading specified in § 25.562.

The ILD will self-activate only in the event of a predetermined airplane loading condition such as that occurring during crash or emergency landing, and will prevent excessive seat forward translation. A minimum level of protection must be provided if the seat-locking device does not deploy.

The normal means of satisfying the structural and occupant protection requirements of § 25.562 result in a non-quantified, but nominally predictable, progressive structural deformation or reduction of injury severity for impact conditions less than the maximum specified by the rule. A seat using ILD technology, however, may involve a step change in protection for impacts below and above that at which the ILD activates and deploys to retain the seat pan in place. This could result in structural deformation or occupant injury output being higher at an intermediate impact condition than that resulting from the maximum impact condition. It is acceptable for such step-change characteristics to exist, provided the resulting output does not exceed the maximum allowable criteria at any condition at which the ILD does or does not deploy, up to the maximum severity pulse specified by the requirements.

The ideal triangular maximum severity pulse is defined in Advisory Circular (AC) 25.562–1B. For the evaluation and testing of less-severe pulses for purposes of assessing the effectiveness of the ILD deployment setting, a similar triangular pulse should be used with acceleration, rise time, and velocity change scaled accordingly. The magnitude of the required pulse should not deviate below the ideal pulse by more than 0.5g until 1.33 t_1 is reached, where t_1 represents the time interval between 0 and t_1 on the referenced pulse shape as shown in AC 25.562–1B. This is an acceptable method of compliance to the test requirements of the special conditions.

Conditions 1 through 5 address ensuring that the ILD activates when intended, to provide the necessary

protection of occupants. This includes protection of a range of occupants under various accident conditions. Conditions 6 through 10 address maintenance and reliability of the ILD, including any outside influences on the mechanism, to ensure it functions as intended.

These special conditions contain the additional safety standards that the Administrator considers necessary to establish a level of safety equivalent to that established by the existing airworthiness standards.

Applicability

As discussed above, these special conditions are applicable to the Airbus Model A340 series airplanes. Should Airbus apply at a later date for a change to the type certificate to include another model incorporating the same novel or unusual design feature, these special conditions would apply to that model as well.

Conclusion

This action affects only a certain novel or unusual design feature on one model series of airplanes. It is not a rule of general applicability.

List of Subjects in 14 CFR Part 25

Aircraft, Aviation safety, Reporting and recordkeeping requirements.

Authority Citation

The authority citation for these special conditions is as follows:

Authority: 49 U.S.C. 106(f), 106(g), 40113, 44701, 44702, 44704.

The Special Conditions

Accordingly, pursuant to the authority delegated to me by the Administrator, the following special conditions are issued as part of the type certification basis for Airbus Model A340 series airplanes.

In addition to the requirements of § 25.562, passenger seats incorporating an inertia locking device (ILD) must meet the following:

1. Level of Protection Provided by ILD—It must be demonstrated by test that the seats and attachments, when subject to the emergency-landing dynamic conditions specified in § 25.562, and with one ILD not deployed, do not experience structural failure that could result in:

a. Separation of the seat from the airplane floor.

b. Separation of any part of the seat that could form a hazard to the seat occupant or any other airplane occupant.

c. Failure of the occupant restraint or any other condition that could result in the occupant separating from the seat.

2. Protection Provided Below and Above the ILD Actuation Condition—If step-change effects on occupant protection exist for impacts below and above that at which the ILD deploys, tests must be performed to demonstrate that the occupant is shown to be protected at any condition at which the ILD does or does not deploy, up to the maximum severity pulse specified by § 25.562. Test conditions must take into account any necessary tolerances for deployment.

3. Protection Over a Range of Crash Pulse Vectors—The ILD must be shown to function as intended for all test vectors specified in § 25.562.

4. Protection During Secondary Impacts—The ILD activation setting must be demonstrated to maximize the probability of the protection being available when needed, considering a secondary impact that is above the severity at which the device is intended to deploy up to the impact loading required by § 25.562.

5. Protection of Occupants other than 50th Percentile—Protection of occupants for a range of stature from a two-year-old child to a 95th percentile male must be shown.

6. Inadvertent Operation—It must be shown that any inadvertent operation of the ILD does not affect the performance of the device during a subsequent emergency landing.

7. Installation Protection—It must be shown that the ILD installation is protected from contamination and interference from foreign objects.

8. Reliability—The performance of the ILD must not be altered by the effects of wear, manufacturing tolerances, aging or drying of lubricants, and corrosion.

9. Maintenance and Functional Checks—The design, installation, and operation of the ILD must be such that it is possible to functionally check the device in place. Additionally, a functional check method and a maintenance check interval must be included in the seat installer's instructions for continued airworthiness (ICA) document.

10. Release Function—If a means exists to release an inadvertently activated ILD, the release means must not introduce additional hidden failures that would prevent the ILD from functioning properly.

Issued in Des Moines, Washington, on October 25, 2019.

James E. Wilborn,

Manager, Transport Standards Branch, Policy and Innovation Division, Aircraft Certification Service.

[FR Doc. 2019-23798 Filed 10-30-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-0716; Product Identifier 2019-NM-168-AD; Amendment 39-19764; AD 2019-20-11]

RIN 2120-AA64

Airworthiness Directives; ATR-GIE Avions de Transport Régional Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all ATR-GIE Avions de Transport Régional Model ATR72 airplanes. This AD was prompted by reports of incorrectly installed main landing gear (MLG) bushings. This AD requires a one-time general visual inspection of the bushing installation on the left-hand and right-hand MLG, and replacement of incorrectly installed bushings, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD becomes effective November 15, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain publications listed in this AD as of November 15, 2019.

The FAA must receive comments on this AD by December 16, 2019.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For the material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 1000; email ADs@easa.europa.eu;