

## SCHEDULE OF MATERIALS ANNUAL FEES AND FEES FOR GOVERNMENT AGENCIES LICENSED BY NRC

[See footnotes at end of table]

Category of materials licenses						Annual fees <sup>1 2 3</sup>
*	*	*	*	*	*	*
(2) All other special nuclear materials licenses not included in Category 1.A.(1) which are licensed for fuel cycle activities.						
*	*	*	*	*	*	*

[FR Doc. Z9-13425 Filed 7-17-09; 8:45 am]

BILLING CODE 1505-01-D

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2009-0313; Directorate Identifier 2008-NM-144-AD; Amendment 39-15769; AD 2008-26-03]

RIN 2120-AA64

**Airworthiness Directives; Bombardier Model DHC-8-102, DHC-8-103, DHC-8-106, DHC-8-201, DHC-8-202, DHC-8-301, DHC-8-311, and DHC-8-315 Airplanes Equipped With a Cockpit Door Electronic Strike System Installed in Accordance With Supplemental Type Certificate (STC) ST02014NY**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule; correction.

**SUMMARY:** The FAA is correcting an error in an existing airworthiness directive (AD) that was published in the **Federal Register** on April 7, 2009 (74 FR 15665). The error resulted in an incorrect product identification line in the regulatory portion of the AD. This AD applies to the transport category airplanes listed above. This AD requires modifying the electronic strike system of the cockpit door.

**DATES:** Effective April 13, 2009.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140,

1200 New Jersey Avenue, SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:**

Fabio Buttitta, Aerospace Engineer, Systems and Flight Test Branch, ANE-171, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7303; fax (516) 794-5531.

**SUPPLEMENTARY INFORMATION:** On March 30, 2009, the FAA issued AD 2008-26-03, Amendment 39-15769 (74 FR 15665, April 7, 2009), for Bombardier Model DHC-8-102, DHC-8-103, DHC-8-106, DHC-8-201, DHC-8-202, DHC-8-301, DHC-8-311, and DHC-8-315 airplanes equipped with a cockpit door electronic strike system installed in accordance with supplemental type certificate (STC) ST02014NY. The AD requires modifying the electronic strike system of the cockpit door.

As published in the **Federal Register**, the AD identifies "TTF Aerospace LLC" in the product identification line of the AD; however, the name in the product identification line was changed to "Bombardier, Inc.," in the version posted to the FAA Web site (*i.e.*, the Regulatory and Guidance Library (<http://rgl.faa.gov>)). All copies of ADs available to the public must be consistent; therefore, we are correcting the version of the AD published in the **Federal Register** to appropriately identify Bombardier, Inc., in the product identification line.

No other part of the regulatory information has been changed; therefore, the final rule is not republished in the **Federal Register**.

The effective date of this AD remains April 13, 2009.

**§ 39.13 [Corrected]**

■ In the **Federal Register** of April 7, 2009, on page 15666, in the first column, the paragraph that states "2008-26-03 TTF Aerospace LLC:" of AD 2008-26-03 is corrected to read as follows:

\* \* \* \* \*

**2008-26-03 Bombardier, Inc.:**

\* \* \* \* \*

Issued in Renton, Washington, on July 8, 2009.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E9-17116 Filed 7-17-09; 8:45 am]

BILLING CODE 4910-13-P

**DEPARTMENT OF STATE****22 CFR Part 121**

[Public Notice 6695]

**Amendment to the International Arms Traffic in Arms Regulations: The United States Munitions List; Correction**

**AGENCY:** Department of State.

**ACTION:** Correcting amendment.

**SUMMARY:** The Department of State published a final rule in the **Federal Register** on September 9, 1994 (59 FR 46548), revising Category XII(c) of the United States Munitions List. The language in the note after paragraph (c) contains a typographical error by using the term "hold" instead of "hole." A technical error in that rule resulted in the unintended removal of the note after Category XII paragraph (c). Consequently, a correction was published on April 24, 2009 (74 FR 18628) to restore the language in the note after Category XII paragraph (c). That correction used the term "hold" when the correct term is "hole." This document corrects the typographical error dating from September 9, 1994 to utilize the correct term "hole."

**DATES:** *Effective Date:* Effective on July 20, 2009.

**FOR FURTHER INFORMATION CONTACT:**

Director Charles B. Shotwell, Office of Defense Trade Controls Policy, Department of State, Telephone (202) 663-2792 or Fax (202) 261-8199; e-mail [DDTCResponseTeam@state.gov](mailto:DDTCResponseTeam@state.gov). Attn: Regulatory Change, Category XII.