

a savings association serves a geographic area that extends substantially beyond a state boundary, the savings association shall delineate separate assessment areas for the areas in each state. If a savings association serves a geographic area that extends substantially beyond an MSA boundary, the savings association shall delineate separate assessment areas for the areas inside and outside the MSA.

\* \* \* \* \*

■ 5. In § 563e.42, revise paragraph (i) to read as follows:

**§ 563e.42 Data collection, reporting, and disclosure.**

\* \* \* \* \*

(i) *Aggregate disclosure statements.* The OTS, in conjunction with the Board of Governors of the Federal Reserve System, the Federal Deposit Insurance Corporation, and the Office of the Comptroller of the Currency, prepares annually, for each MSA or metropolitan division (including an MSA or metropolitan division that crosses a state boundary) and the nonmetropolitan portion of each state, an aggregate disclosure statement of small business and small farm lending by all institutions subject to reporting under this part or parts 25, 228, or 345 of this title. These disclosure statements indicate, for each geography, the number and amount of all small business and small farm loans originated or purchased by reporting institutions, except that the OTS may adjust the form of the disclosure if necessary, because of special circumstances, to protect the privacy of a borrower or the competitive position of an institution.

\* \* \* \* \*

Dated: June 21, 2004.

**John D. Hawke, Jr.,**  
*Comptroller of the Currency.*

By order of the Board of Governors of the Federal Reserve System, July 1, 2004.

**Jennifer J. Johnson,**  
*Secretary of the Board.*

Dated: June 28, 2004.

By Order of the Board of Directors of the Federal Deposit Insurance Corporation.

**Valerie J. Best,**  
*Assistant Executive Secretary.*

Dated: May 24, 2004.

By the Office of Thrift Supervision.

**James E. Gilleran,**  
*Director.*

[FR Doc. 04-15526 Filed 7-7-04; 8:45 am]

BILLING CODE 4810-33-P, 6210-01-P, 6714-01-P, 6720-01-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2004-NM-29-AD; Amendment 39-13673; AD 2004-03-34 R1]

RIN 2120-AA64

#### Airworthiness Directives; Boeing Model 737-100, -200, -200C, -300, -400, and -500 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule; correction.

**SUMMARY:** This document corrects a typographical error that appeared in airworthiness directive (AD) 2004-03-34 R1 that was published in the **Federal Register** on June 16, 2004 (69 FR 33555). A reference to the amendment number was inadvertently omitted from a heading in the AD. This AD is applicable to certain Boeing Model 737-100, -200, -200C, -300, -400, and -500 series airplanes. This AD requires replacing existing screw, nut, and washers that attach the latch cable assembly to the latch block assembly of the door mounted escape slides, with new, improved screw, nut, and washers.

**DATES:** Effective July 21, 2004.

**FOR FURTHER INFORMATION CONTACT:**

Keith Ladderud, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6435; fax (425) 917-6590.

**SUPPLEMENTARY INFORMATION:**

Airworthiness Directive (AD) 2004-03-34 R1, amendment 39-13673, applicable to certain Boeing Model 737-100, -200, -200C, -300, -400, and -500 series airplanes, was published in the **Federal Register** on June 16, 2004 (69 FR 33555). That AD requires replacing existing screw, nut, and washers that attach the latch cable assembly to the latch block assembly of the door mounted escape slides, with new, improved screw, nut, and washers.

As published, the heading preceding the "Applicability" paragraph has a typographical error. That airworthiness directive reads as "2004-03-34 R1 Boeing; Docket 2004-NM-29-AD. Revises AD 2004-03-34, Amendment 39-13478." However, the new amendment number, 39-13673, was inadvertently omitted. That airworthiness directive should have read "2004-03-34 R1 Boeing; amendment 39-13673. Docket 2004-

NM-29-AD. Revises AD 2004-03-34, Amendment 39-13478."

Since no other part of the regulatory information has been changed, the final rule is not being republished in the **Federal Register**.

The effective date of this AD remains July 21, 2004.

#### PART 39—AIRWORTHINESS DIRECTIVES

##### § 39.13 [Corrected]

■ On page 33556, in the third column, the section preceding the "Applicability" paragraph of AD 2004-03-34 R1 is corrected to read as follows:

\* \* \* \* \*

**2004-03-34 R1 Boeing:** Amendment 39-13673. Docket 2004-NM-29-AD. Revises AD 2004-03-34, Amendment 39-13478.

\* \* \* \* \*

Issued in Renton, Washington, on June 29, 2004.

**Kalene C. Yanamura,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*  
[FR Doc. 04-15365 Filed 7-7-04; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2004-17616; Airspace Docket No. 04-ASO-6]

#### Amendment of Class E Airspace; Dayton, TN

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action amends Class E5 airspace at Dayton, TN. As a result of an evaluation, it has been determined a modification should be made to the Dayton, TN, Class E5 airspace area to contain the Nondirectional Radio Beacon (NDB) Runway 3, Standard Instrument Approach Procedure (SIAP) to Hardwick Field Airport, Cleveland, TN. Additional controlled airspace extending upward from 700 feet Above Ground Level (AGL) is needed to contain the SIAP.

**DATES:** 0901 UTC, September 30, 2004.

**FOR FURTHER INFORMATION CONTACT:**

Walter R. Cochran, Manager, Airspace Branch, Air Traffic Division, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320, telephone (404) 305-5627.

**SUPPLEMENTARY INFORMATION:**