

presented for evidentiary purposes (see 28 U.S.C. 1733).

§ 1707.209 Procedure when a decision is not made prior to the time a response is required.

If a response to a demand or request is required before the General Counsel can make the determination referred to in § 1707.201, the General Counsel, when necessary, will provide the court or other competent authority with a copy of this part, inform the court or other competent authority that the demand or request is being reviewed, and seek a stay of the demand or request pending a final determination.

§ 1707.210 Procedure in the event of an adverse ruling.

If the court or other competent authority fails to stay the demand, the employee upon whom the demand is made, unless otherwise advised by the General Counsel, will appear at the stated time and place, produce a copy of this part, state that the employee has been advised by counsel not to provide the requested testimony or produce documents, and respectfully decline to comply with the demand, citing *United States ex rel. Touhy v. Ragen*, 340 U.S. 462 (1951). A written response may be offered to a request, or to a demand, if permitted by the court or other competent authority.

Subpart C—Schedule of Fees

§ 1707.301 Fees.

(a) *Generally.* The General Counsel may condition the production of records or appearance for testimony upon advance payment of a reasonable estimate of the costs to DNFSB.

(b) *Fees for records.* Fees for producing records will include fees for searching, reviewing, and duplicating records, costs of attorney time spent in reviewing the demand or request, and expenses generated by materials and equipment used to search for, produce, and copy the responsive information. Costs for employee time will be calculated on the basis of the hourly pay of the employee (including all pay, allowance, and benefits). Fees for duplication will be the same as those charged by DNFSB in its Freedom of Information Act fee regulations at 10 CFR part 1703.

(c) *Witness fees.* Fees for attendance by a witness will include fees, expenses, and allowances prescribed by the court's rules. If no such fees are prescribed, witness fees will be determined based upon the rule of the Federal district court closest to the location where the witness will appear. Such fees will include cost of time spent

by the witness to prepare for testimony, in travel, and for attendance in the legal proceeding.

(d) *Payment of fees.* You must pay witness fees for current DNFSB employees and any records certification fees by submitting to the General Counsel a check or money order for the appropriate amount made payable to the Treasury of the United States. In the case of testimony by former DNFSB employees, you must pay applicable fees directly to the former employee in accordance with 28 U.S.C. 1821 or other applicable statutes.

(e) *Certification (authentication) of copies of records.* The Defense Nuclear Facilities Safety Board may certify that records are true copies in order to facilitate their use as evidence. If you seek certification, you must request certified copies from DNFSB at least 45 days before the date they will be needed. The request should be sent to the General Counsel. You will be charged a certification fee of \$15.00 for each document certified.

(f) *Waiver or reduction of fees.* The General Counsel, in his or her sole discretion, may, upon a showing of reasonable cause, waive or reduce any fees in connection with the testimony, production, or certification of records.

(g) *De minimis fees.* Fees will not be assessed if the total charge would be \$10.00 or less.

Subpart D—Penalties

§ 1707.401 Penalties.

(a) An employee who discloses official records or information or gives testimony relating to official information, except as expressly authorized by DNFSB or as ordered by a Federal court after DNFSB has had the opportunity to be heard, may face the penalties provided in 18 U.S.C. 641 and other applicable laws. Additionally, former DNFSB employees are subject to the restrictions and penalties of 18 U.S.C. 207 and 216.

(b) A current DNFSB employee who testifies or produces official records and information in violation of this part shall be subject to disciplinary action.

[FR Doc. 01-28543 Filed 11-13-01; 8:45 am]

BILLING CODE 3670-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-CE-10-AD]

RIN 2120-AA64

Airworthiness Directives; SOCATA—Groupe AEROSPATIALE Model TBM 700 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes to adopt a new airworthiness directive (AD) that would apply to certain SOCATA—Groupe AEROSPATIALE (SOCATA) Model TBM 700 airplanes. This proposed AD would require you to install a new strainer draining system in the cabin fuselage. This proposed AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for France. The actions specified by this proposed AD are intended to prevent water from accumulating in the fuselage, then freezing and interfering with or causing the elevator controls to seize. This could result in loss of elevator control with consequent loss of airplane control.

DATES: The Federal Aviation Administration (FAA) must receive any comments on this proposed rule on or before December 12, 2001.

ADDRESSES: Submit comments to FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2001-CE-10-AD, 901 Locust, Room 506, Kansas City, Missouri 64106. You may view any comments at this location between 8 a.m. and 4 p.m., Monday through Friday, except Federal holidays.

You may get service information that applies to this proposed AD from SOCATA-Groupe AEROSPATIALE, Customer Support, Aerodrome Tarbes-Ossun-Lourdes, BP 930-F65009 Tarbes Cedex, France; telephone: (33) (0)5.62.41.73.00; facsimile: (33) (0)5.62.41.76.54; or the Product Support Manager, SOCATA—Groupe AEROSPATIALE, North Perry Airport, 7501 Pembroke Road, Pembroke Pines, Florida 33023; telephone: (954) 894-1160; facsimile: (954) 964-4191. You may also view this information at the Rules Docket at the address above.

FOR FURTHER INFORMATION CONTACT: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106;

telephone: (816) 329-4146; facsimile: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Comments Invited

How do I comment on this proposed AD? The FAA invites comments on this proposed rule. You may submit whatever written data, views, or arguments you choose. You need to include the rule's docket number and submit your comments to the address specified under the caption **ADDRESSES**. We will consider all comments received on or before the closing date. We may amend this proposed rule in light of comments received. Factual information that supports your ideas and suggestions is extremely helpful in evaluating the effectiveness of this proposed AD action and determining whether we need to take additional rulemaking action.

Are there any specific portions of this proposed AD I should pay attention to? The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this proposed rule that might suggest a need to modify the rule. You may view all comments we receive before and after the closing date of the rule in the Rules Docket. We will file a report in the Rules Docket that summarizes each contact we have with the public that concerns the substantive parts of this proposed AD.

How can I be sure FAA receives my comment? If you want FAA to acknowledge the receipt of your comments, you must include a self-addressed, stamped postcard. On the postcard, write "Comments to Docket No. "2001-CE-10-AD." We will date

stamp and mail the postcard back to you.

Discussion

What events have caused this proposed AD? The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, recently notified FAA that an unsafe condition may exist on certain SOCATA Model TBM 700 airplanes. The DGAC reports an incident in which the elevator controls jammed on one of the affected airplanes.

Jamming of the elevator controls occurred because water accumulated in the fuselage and froze. Water had accumulated in the fuselage because the strainer and draining hole became clogged.

What are the consequences if the condition is not corrected? If this condition is not corrected, water may accumulate in the fuselage, freeze and interfere with or cause the elevator controls to seize. This could result in loss of elevator control.

Is there service information that applies to this subject? ocata has issued Service Bulletin SB 70-082 53, dated June 2000.

What are the provisions of this service information? The service bulletin includes procedures for installing a new strainer draining system in the cabin fuselage.

What action did DGAC take? The DGAC classified this service bulletin as mandatory and issued French AD 2000-373(A), dated October 18, 2000, in order to assure the continued airworthiness of these airplanes in France.

Was this in accordance with the bilateral airworthiness agreement? This airplane model is manufactured in

France and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept FAA informed of the situation described above.

The FAA's Determination and an Explanation of the Provisions of This Proposed AD

What has FAA decided? The FAA has examined the findings of the DGAC; reviewed all available information, including the service information referenced above; and determined that:

- The unsafe condition referenced in this document exists or could develop on other Socata Model TBM 700 airplanes of the same type design;
- The actions specified in the previously-referenced service information should be accomplished on the affected airplanes; and
- AD action should be taken in order to correct this unsafe condition.

What would this proposed AD require? This proposed AD would require you to incorporate the actions in the previously-referenced service bulletin.

Cost Impact

How many airplanes would this proposed AD impact? We estimate that this proposed AD affects 79 airplanes in the U.S. registry.

What would be the cost impact of this proposed AD on owners/operators of the affected airplanes? We estimate the following costs to accomplish this proposed modification:

Labor cost	Parts cost	Total cost per airplane	Total cost on U.S. operators
2 workhours × \$60 = \$120	\$114	\$234	\$18,486

Compliance Time of This Proposed AD

What would be the compliance time of this proposed AD? The compliance time of this proposed AD is "within the next 3 months after the effective date of this AD".

Why is the compliance time presented in calendar time instead of hours time-in-service (TIS)? Although water in the cabin fuselage could interfere with the elevator controls and become unsafe during flight, the condition is not a direct result of airplane operation. The chance of this situation occurring is the same for an airplane with 10 hours time-in-service (TIS) as it would be for an

airplane with 500 hours TIS. A calendar time for compliance will assure that the unsafe condition is addressed on all airplanes in a reasonable time period.

Regulatory Impact

Would this proposed AD impact various entities? The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposed rule

would not have federalism implications under Executive Order 13132.

Would this proposed AD involve a significant rule or regulatory action? For the reasons discussed above, I certify that this proposed action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft

regulatory evaluation prepared for this action has been placed in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the

Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. FAA amends § 39.13 by adding a new airworthiness directive (AD) to read as follows:

SOCATA—Groupe Aerospatiale: Docket No. 2001—CE—10AD

(a) *What airplanes are affected by this AD?* This AD affects Model TBM 700 airplanes, serial numbers 1 through 164, that are certificated in any category.

(b) *Who must comply with this AD?* Anyone who wishes to operate any of the above airplanes must comply with this AD.

(c) *What problem does this AD address?* The actions specified by this AD are intended to prevent water from accumulating in the fuselage, then freezing and interfering with or causing the elevator controls to seize. This could result in loss of elevator control with consequent loss of airplane control.

(d) *What actions must I accomplish to address this problem?* To address this problem, you must accomplish the following:

Actions	Compliance	Procedures
Incorporate Kit No. OPT70 K072—53	Within the next 3 months after the effective date of this AD, unless already accomplished.	In accordance with the Technical Instructions supplied with Kit No. OPT70 K072—53, as specified in Socata. Service Bulletin SB 70—082 53, dated June 2000.

(e) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

(1) Your alternative method of compliance provides an equivalent level of safety; and

(2) The Manager, Small Airplane Directorate, approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

Note 1: This AD applies to each airplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* Contact Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329—4146; facsimile: (816) 329—4090.

(g) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(h) *How do I get copies of the documents referenced in this AD?* You may get copies of the documents referenced in this AD from SOCATA—Groupe AEROSPATIALE, Customer Support, Aerodrome Tarbes-Ossun-Lourdes, BP 930—F65009 Tarbes Cedex, France; telephone: (33) (0)5.62.41.73.00;

facsimile: (33) (0)5.62.41.76.54; or the Product Support Manager, SOCATA—Groupe AEROSPATIALE, North Perry Airport, 7501 Pembroke Road, Pembroke Pines, Florida 33023; telephone: (954) 894—1160; facsimile: (954) 964—4191. You may view these documents at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106.

Note 2: The subject of this AD is addressed in French AD 2000—373(A), dated October 18, 2000.

Issued in Kansas City, Missouri, on November 5, 2001.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01—28420 Filed 11—13—01; 8:45 am]

BILLING CODE 4910—13—P

SOCIAL SECURITY ADMINISTRATION

20 CFR Part 404

[Regulations No. 4]

RIN 0960—AF28

Revised Medical Criteria for Evaluating Impairments of the Digestive System

AGENCY: Social Security Administration.

ACTION: Proposed rules.

SUMMARY: We are proposing to revise the criteria in the Listing of Impairments (the Listings) that we use to evaluate claims involving digestive impairments. We apply these criteria at step three of our sequential evaluation processes when you claim benefits based on disability under title II and title XVI of the Social Security Act (the Act). The proposed revisions will reflect advances

in medical knowledge, treatment, and methods of evaluating digestive impairments. We also propose to remove listings that are redundant and only refer to other listings.

DATES: To be sure your comments are considered, we must receive them by January 14, 2002.

ADDRESSES: You may give us your comments by using: our Internet site facility (*i.e.*, Social Security Online) at <http://www.ssa.gov/regulations/index.htm>, e-mail to regulations@ssa.gov, telefax to (410) 966—2830 or by sending a letter to the Commissioner of Social Security, P.O. Box 17703, Baltimore, Maryland 21235—7703. You may also deliver them to the Office of Process and Innovation Management, Social Security Administration, L2109 West Low Rise Building, 6401 Security Boulevard, Baltimore, Maryland 21235—6401, between 8 a.m. and 4 p.m. on regular business days. We post comments on our Internet site, or you may inspect them on regular business days by making arrangements with the contact person shown in this preamble.

A list of the sources we consulted when developing these proposed rules, *e.g.*, various medical texts and pertinent articles, will be posted on the above Internet site. The list is also available upon request by letter to the Office of Disability, Division of Medical & Vocational Policy, Social Security Administration, 3rd A—8 Operations Building, 6401 Security Boulevard, Baltimore, MD 21235, Attn: Cheryl Wrobel, or by email to Cheryl.Wrobel@SSA.gov. Electronic Version: The electronic file of this document is available on the date of