

Specifically, the petitioner claims that non-U.S. certified 2000–2001 Mercedes Benz S500 and S600 passenger cars are identical to their U.S. certified counterparts with respect to compliance with Standard Nos. 102 *Transmission Shift Lever Sequence* \* \* \* \* \*, 103 *Defrosting and Defogging Systems*, 104 *Windshield Wiping and Washing Systems*, 105 *Hydraulic Brake Systems*, 106 *Brake Hoses*, 109 *New Pneumatic Tires*, 113 *Hood Latch Systems*, 116 *Brake Fluid*, 124 *Accelerator Control Systems*, 202 *Head Restraints*, 204 *Steering Control Rearward Displacement*, 205 *Glazing Materials*, 206 *Door Locks and Door Retention Components*, 207 *Seating Systems*, 209 *Seat Belt Assemblies*, 210 *Seat Belt Assembly Anchorages*, 212 *Windshield Retention*, 216 *Roof Crush Resistance*, 219 *Windshield Zone Intrusion*, 301 *Fuel System Integrity*, and 302 *Flammability of Interior Materials*, as well as 49 CFR Part 581.

The petitioner also contends that the vehicles are capable of being readily altered to meet the following standards, in the manner indicated:

Standard No. 101 *Controls and Displays*: (a) Substitution of the word “Brake” for the international ECE warning symbol on the markings for the brake failure indicator lamp; (b) replacement of the speedometer with one calibrated in miles per hour. The petitioner states that the entire instrument cluster will be replaced with a U.S.-model component.

Standard No. 108 *Lamps, Reflective Devices and Associated Equipment*: (a) installation of U.S.-model headlamps and front sidemarker lamps, (b) installation of U.S.-model taillamp assemblies which incorporate rear sidemarker lamps and (c) installation of U.S.-model high-mounted stop light assembly (if necessary).

Standard No. 110 *Tire Selection and Rims*: installation of a tire information placard.

Standard No. 111 *Rearview Mirror*: replacement of the passenger side rearview mirror with a U.S.-model component.

Standard No. 114 *Theft Protection*: Installation of a warning buzzer and a warning buzzer microswitch in the steering lock assembly.

Standard No. 118 *Power Window Systems*: installation of a relay in the power window system so that the window transport is inoperative when the ignition is switched off on vehicles that are not already so equipped.

Standard No. 201 *Occupant Protection in Interior Impact*: Inspect each vehicle and replace any non-U.S. model parts with U.S. model parts.

Standard No. 208 *Occupant Crash Protection*: (a) Installation of a seat belt warning buzzer, wired to the driver's seat belt latch; (b) inspection of all vehicles and replacement of the driver's and passenger's side air bags, knee bolsters, control units, sensors, and seat belts with U.S.-model components on vehicles that are not already so equipped. The front and rear outboard designated seating positions have combination lap and shoulder belts that are self-tensioning and that release by means of a single red pushbutton.

Standard No. 214 *Side Impact Protection*: Inspect vehicles and replace any non-complying part with U.S. model parts.

The petitioner also states that a vehicle identification plate must be affixed to the vehicles near the left windshield post and a reference and certification label must be affixed in the area of the left front door post to meet the requirements of 49 CFR Part 565.

Interested persons are invited to submit comments on the petition described above. Comments should refer to the docket number and be submitted to: Docket Management, Room PL-401, 400 Seventh St., SW, Washington, DC 20590. [Docket hours are from 9 am to 5 pm]. It is requested but not required that 10 copies be submitted.

All comments received before the close of business on the closing date indicated above will be considered, and will be available for examination in the docket at the above address both before and after that date. To the extent possible, comments filed after the closing date will also be considered. Notice of final action on the petition will be published in the **Federal Register** pursuant to the authority indicated below.

**Authority:** 49 U.S.C. 30141(a)(1)(A) and (b)(1); 49 CFR 593.8; delegations of authority at 49 CFR 1.50 and 501.8.

Issued on: July 13, 2001.

**Marilynne Jacobs,**

*Director, Office of Vehicle Safety Compliance.*  
[FR Doc. 01-17994 Filed 7-18-01; 8:45 am]

**BILLING CODE 4910-59-P**

## DEPARTMENT OF THE TREASURY

### Fiscal Service

#### **Surety Companies Acceptable on Federal Bonds: Termination; Highlands Insurance Company, Highland Underwriters Insurance Company**

**AGENCY:** Financial Management Service, Fiscal Service, Department of the Treasury.

**ACTION:** Notice.

**SUMMARY:** This is Supplement No. 22 to the Treasury Department Circular 570; 2000 Revision, published June 30, 2000 at 65 FR 40868.

**FOR FURTHER INFORMATION CONTACT:** Surety Bond Branch at (202) 874-6765.

**SUPPLEMENTARY INFORMATION:** Notice is hereby given that the Certificates of Authority issued by the Treasury to the above named Companies, under the United States Code, Title 31, Sections 9304-9308, to qualify as an acceptable sureties on Federal bonds is terminated effective today.

The Companies were last listed as an acceptable sureties on Federal bonds at 65 FR 40886, June 30, 2000.

With respect to any bonds, including continuous bonds, currently in force with above listed Companies, bond-approving officers should secure new bonds with acceptable sureties in those instances where a significant amount of liability remains outstanding. In addition, in no event, should bonds that are continuous in nature be renewed.

The Circular may be viewed and downloaded through the Internet at <http://www.fms.treas.gov/c570/index.html>. A hard copy may be purchased from the Government Printing Office (GPO), Subscription Service, Washington, DC, telephone (202) 512-1800. When ordering the Circular from GPO, use the following stock number: 048-000-00536-5.

Questions concerning this notice may be directed to the U.S. Department of the Treasury, Financial Management Service, Financing Accounting and Services Division, Surety Bond Branch, 3700 East-West Highway, Room 6A04, Hyattsville, MD 20782.

Dated: June 30, 2001.

**Judith R. Tillman,**

*Assistant Commissioner, Financial Operations, Financial Management Service.*  
[FR Doc. 01-18101 Filed 7-18-01; 8:45 am]

**BILLING CODE 4810-35-M**

## DEPARTMENT OF THE TREASURY

### Internal Revenue Service

[EE-43-92]

#### **Proposed Collection: Comment Request for Regulation Project**

**AGENCY:** Internal Revenue Service (IRS), Treasury.

**ACTION:** Notice and request for comments.

**SUMMARY:** The department of the Treasury, as part of its continuing effort