

## LENDING AND INVESTMENT POWERS CHART

Category	Statutory authorization <sup>1</sup>	Statutory investment limitations (Endnotes contain applicable regulatory limitations)
* * *	* * *	* *
Rural business investment companies .....	7 U.S.C. 2009cc-9 .....	Five percent of total capital.
* * *	* * *	* *

**Endnotes**

1. All references are to section 5 of the Home Owners' Loan Act (12 U.S.C. 1464) unless otherwise indicated.

\* \* \* \* \*

**PART 561—DEFINITIONS FOR REGULATIONS AFFECTING ALL SAVINGS ASSOCIATIONS**

■ 10. The authority citation for part 561 continues to read as follows:

**Authority:** 12 U.S.C. 1462, 1462a, 1463, 1464, 1467a.

■ 11. Revise § 561.16 by removing paragraph (b), removing the designation for paragraph (a), and revising "which" to read "that" in both instances that it appears.

**PART 567—CAPITAL**

■ 12. The authority citation for part 567 continues to read as follows:

**Authority:** 12 U.S.C. 1462, 1462a, 1463, 1464, 1467a, 1828 (note).

■ 13. Amend 567.6(b)(5)(v)(B) by revising "1381o(g)" to read "1831o(g)".

Dated: December 21, 2005.

By the Office of Thrift Supervision.

**Scott M. Polakoff,**

*Deputy Director.*

[FR Doc. 05-24499 Filed 12-27-05; 8:45 am]

**BILLING CODE 6720-01-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 25**

[Policy Statement No. ANM-115-05-14]

**Acceptable Methods of Compliance with § 25.562(c)(5) for Front Row Passenger Seats**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of final policy.

**SUMMARY:** The Federal Aviation Administration (FAA) announces the availability of final policy on Acceptable Methods of Compliance with Title 14 Code of Federal

Regulations (CFR) § 25.562(c)(5) for Front Row Passenger Seats.

**DATES:** The final policy was issued by the Transport Airplane Directorate on December 14, 2005.

**FOR FURTHER INFORMATION CONTACT:** John Sheldon, Federal Aviation Administration, Transport Airplane Directorate, Transport Standards Staff, Airframe/Cabin Safety Branch, ANM-115, 1601 Lind Avenue, SW., Renton, WA 98055-4056; telephone (425) 227-2785; fax (425) 227-1232; e-mail: [John.sheldon@faa.gov](mailto:John.sheldon@faa.gov).

**SUPPLEMENTARY INFORMATION:****Disposition of Comments**

A notice of proposed policy was published in the **Federal Register** on April 26, 2005 (70 FR 21343). The comment period was reopened on June 9, 2005 (70 FR 33720). Eight (8) commenters responded to the requests for comments.

**Background**

The purpose of the policy memorandum is to clarify FAA certification policy of the acceptable substantiation methods used to provide protection under § 25.562(a) when meeting the performance standards in § 25.562(c) for "front row" seats. Front row seats are those seats which are located directly aft of a partition, monument, or other commodity, including all passenger seats not considered "row-to-row." The policy is not directed toward other seats. The policy provides an acceptable means of protection for front row occupants.

The final policy as well as the disposition of public comments received are available on the Internet at the following address: <http://airweb.faa.gov.rgl>. If you do not have access to the Internet, you can obtain a copy of the policy by contacting the person listed under **FOR FURTHER INFORMATION CONTACT**.

Issued in Renton, Washington, on December 14, 2005.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 05-24503 Filed 12-27-05; 8:45 am]

**BILLING CODE 4910-13-M**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2005-22156; Directorate Identifier 2005-CE-43-AD; Amendment 39-14435; AD 2005-26-14]

**RIN 2120-AA64**

**Airworthiness Directives; BURKHARDT GROB LUFT-UND RAUMFAHRT GmbH & CO KG Model G103 TWIN ASTIR Sailplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA adopts a new airworthiness directive (AD) for all BURKHARDT GROB LUFT-UND RAUMFAHRT GmbH & CO KG (Burkhardt Grob) Model G103 TWIN ASTIR sailplanes. This AD requires you to replace the elevator lever, part number (P/N) 103-3521, with an improved design part, P/N 103-3523. This AD results from mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Germany. We are issuing this AD to prevent cracks in the elevator lever, which could cause the elevator lever to fail. This failure could result in loss of control of the sailplane.

**DATES:** This AD becomes effective on February 6, 2006.

As of February 6, 2006, the Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulation.

**ADDRESSES:** To get the service information identified in this AD, contact BURKHARDT GROB LUFT-UND RAUMFAHRT GmbH & CO KG, Letenbachstrasse 9, D-86874 Tussenhausen-Mattsies, Germany;