

*Question 1.* Does the existing regulatory framework properly consider all aspects of the Bank Merger Act as currently codified in Section 18(c) of the Federal Deposit Insurance Act?

*Question 2.* What, if any, additional requirements or criteria should be included in the existing regulatory framework to address the financial stability risk factor included by the Dodd-Frank Act? Are there specific quantitative or qualitative measures that should be used to address financial stability risk that may arise from bank mergers? If so, are there specific quantitative measures that would also ensure greater clarity and administrability? Should the FDIC presume that any merger transaction that results in a financial institution that exceeds a predetermined asset size threshold, for example \$100 billion in total consolidated assets, poses a systemic risk concern?

*Question 3.* To what extent should prudential factors (for example, capital levels, management quality, earnings, etc.) be considered in acting on a merger application? Should bright line minimum standards for prudential factors be established? If so, what minimum standard(s) should be established and for which prudential factor(s)?

*Question 4.* To what extent should the convenience and needs factor be considered in acting on a merger application? Is the convenience and needs factor appropriately defined in the existing framework? Is the reliance on an insured depository institution's successful Community Reinvestment Act performance evaluation record sufficient? Are the convenience and needs of all stakeholders appropriately addressed in the existing regulatory framework? To what extent and how should the convenience and needs factor take into consideration the impact that branch closings and consolidations may have on affected communities? To what extent should the FDIC differentiate its consideration of the convenience and needs factor when considering merger transactions involving a large insured depository institution and merger transactions involving a small insured depository institution? To what extent should the CFPB be consulted by the FDIC when considering the convenience and needs factor and should that consultation be formalized?

*Question 5.* In addition to the HHI, are there other quantitative measures that the federal banking agencies should consider when reviewing a merger application? If so, please describe the measures and how such measures

should be considered in conjunction with the HHI. To what extent should such quantitative measures be differentiated when considering mergers involving a large insured depository institution and mergers involving only small insured depository institutions?

*Question 6.* How and to what extent should the following factors be considered in determining whether a particular merger transaction creates a monopoly or is otherwise anticompetitive?

Please address the following factors:

(a) The merging parties do not significantly compete with one another;

(b) Rapid economic change has resulted in an outdated geographic market definition and an alternate market is more appropriate;

(c) Market shares are not an adequate indicator of the extent of competition in the market;

(d) A thrift institution is actively engaged in providing services to commercial customers, particularly loans for business startup or working capital purposes and cash management services;

(e) A credit union has such membership restrictions, or lack of restrictions, and offers such services to commercial customers that it should be considered to be in the market;

(f) There is actual competition by out-of-market institutions for commercial customers, particularly competition for loans for business startup or working capital purposes; and

(g) There is actual competition by non-bank institutions for commercial customers, particularly competition for loans for business startup or working capital purposes. With respect to the preceding factors, how and to what extent should the activity of current branches or pending branch applications be considered?

*Question 7.* Does the existing regulatory framework create an implicit presumption of approval? If so, what actions should the FDIC take to address this implicit presumption?

*Question 8.* Does the existing regulatory framework require an appropriate burden of proof from the merger applicant that the criteria of the Bank Merger Act have been met? If not, what modifications to the framework would be appropriate with respect to the burden of proof?

*Question 9.* The Bank Merger Act provides an exception to its requirements if the responsible agency finds that it must act immediately in order to prevent the probable failure of one of the insured depository institutions involved in the merger transaction. To what extent has this

exception proven beneficial or detrimental to the bank resolution process and to financial stability? Should any requirements or controls be put into place regarding the use of this exemption, for example when considering purchase and assumption transactions in a large bank resolution? Are there attributes of GSIB resolvability, such as a Total Loss-Absorbing Capacity (TLAC) requirement, that could be put into place that would facilitate the resolution of a large insured depository institution without resorting to a merger with another large institution or a purchase and assumption transaction with another large institutions?

*Question 10.* To what extent would responses to Questions 1–9 differ for the consideration of merger transactions involving a small insured depository institution? Should the regulations and policies of the FDIC be updated to differentiate between merger transactions involving a large insured depository institution and those involving a small insured depository institution? If yes, please explain. How should the FDIC define large insured depository institutions for these purposes?

Federal Deposit Insurance Corporation.

By order of the Board of Directors.

Dated at Washington, DC, on December 6, 2021.

**Harrel M. Pettway,**  
Executive Secretary.

**Editorial note:** This document was received for publication by the Office of the Federal Register on March 25, 2022.

[FR Doc. 2022–06720 Filed 3–30–22; 8:45 am]

**BILLING CODE 6714–01–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2022–0382; Project Identifier MCAI–2021–01452–T]

**RIN 2120–AA64**

### Airworthiness Directives; Airbus SAS Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all Airbus SAS Model A350–941 and –1041 airplanes. This proposed AD was prompted by reports that passenger door

stop screws were found with missing screw heads. This proposed AD would require repetitive inspections of each passenger door stop screw for any missing screw heads and applicable corrective actions, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by May 16, 2022.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** 202-493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For material that will be incorporated by reference (IBR) in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0382.

#### Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0382; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

**FOR FURTHER INFORMATION CONTACT:** Dan Rodina, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th Street, Des Moines, WA 98198; telephone and fax 206-231-3225; email [dan.rodina@faa.gov](mailto:dan.rodina@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2022-0382; Project Identifier MCAI-2021-01452-T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

##### Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Dan Rodina, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th Street, Des Moines, WA 98198; telephone and fax 206-231-3225; email [dan.rodina@faa.gov](mailto:dan.rodina@faa.gov). Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

##### Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2021-0291, dated December 22, 2021 (EASA AD 2021-0291) (also referred to as the MCAI), to correct an unsafe condition

for all Airbus SAS Model A350-941 and -1041 airplanes.

This proposed AD was prompted by reports that passenger door stop screws were found with missing screw heads. The FAA is proposing this AD to address missing door stop screw heads, which could result in reduced structural integrity of the airplane. See the MCAI for additional background information.

#### Related Service Information Under 1 CFR Part 51

EASA AD 2021-0291 specifies procedures for repetitive general visual inspections (GVI) of each passenger door stop screw for any missing screw heads, and applicable corrective actions. The corrective actions include replacement of the passenger door stop screw, repair, and follow-up actions (GVI of the adjacent door stop area and surrounding structure for damage, including any broken door stop screws). EASA AD 2021-0291 also specifies procedures for reporting results of the initial inspection to Airbus. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

#### FAA's Determination

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop in other products of the same type design.

#### Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in EASA AD 2021-0291 described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD.

#### Explanation of Required Compliance Information

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to

incorporate EASA AD 2021–0291 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2021–0291 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in EASA AD 2021–0291 does not mean

that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in EASA AD 2021–0291. Service information required by EASA AD 2021–0291 for compliance will be available at <https://www.regulations.gov>

by searching for and locating Docket No. FAA–2022–0382 after the FAA final rule is published.

#### Costs of Compliance

The FAA estimates that this proposed AD would affect 27 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

#### ESTIMATED COSTS FOR REQUIRED ACTIONS \*

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
8 work-hours × \$85 per hour = \$680 .....	\$0	\$680	\$18,360

\* Table does not include estimated costs for reporting.

The FAA estimates that it would take about 1 work-hour per product to comply with the proposed reporting requirement in this proposed AD. The average labor rate is \$85 per hour. Based on these figures, the FAA estimates the

cost of reporting the inspection results on U.S. operators to be \$2,295, or \$85 per product.

The FAA estimates the following costs to do any necessary on-condition screw replacement that would be

required based on the results of any required actions. The FAA has no way of determining the number of aircraft that might need this on-condition action:

#### ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
1 work-hour × \$85 per hour = \$85 per screw replacement.	\$875 per screw .....	\$960 per screw replacement.

The FAA has received no definitive data on which to base the cost estimates for the on-condition repairs or applicable follow-up actions specified in this proposed AD.

According to the manufacturer, some or all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. The FAA does not control warranty coverage for affected individuals. As a result, the FAA has included all known costs in the cost estimate.

#### Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120–0056. Public reporting for this collection of information is estimated to take approximately 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the

data needed, and completing and reviewing the collection of information. All responses to this collection of information are mandatory. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to: Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177–1524.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of

that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Would not affect intrastate aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**Airbus SAS:** Docket No. FAA–2022–0382; Project Identifier MCAI–2021–01452–T.

#### (a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by May 16, 2022.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to all Airbus SAS Model A350–941 and –1041 airplanes, certificated in any category.

#### (d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

#### (e) Unsafe Condition

This AD was prompted by reports that passenger door stop screws were found with missing screw heads. The FAA is issuing this AD to address the missing door stop screw heads, which could result in reduced structural integrity of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2021–0291, dated December 22, 2021 (EASA AD 2021–0291).

#### (h) Exceptions to EASA AD 2021–0291

(1) Where EASA AD 2021–0291 refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA AD 2021–0291 does not apply to this AD.

(3) Paragraph (4) of EASA AD 2021–0291 specifies to report results of the initial inspection to Airbus within a certain compliance time. For this AD, report inspection results of the initial inspection at the applicable time specified in paragraph (h)(3)(i) or (ii) of this AD.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(4) Where Note 2 of paragraph (2) of EASA AD 2021–0291 specifies using “the instructions from an applicable Airbus Repair Design Approval Form (RDAF)” is acceptable for compliance with the corrective actions, this AD requires using corrective actions approved using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(5) Where paragraph (2) of EASA AD 2021–0291 refers to passenger door stop screws that are “damaged, as defined in the SB” this AD defines damage as broken passenger door stop screws.

(6) Where service information referenced in EASA AD 2021–0291 specifies “a general visual inspection of the adjacent door stop area and surrounding structure (no lining removal required),” for this AD do a general visual inspection for any damage (e.g., broken passenger door stop screws), and repair any damage before further flight using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

#### (i) Return of Parts

Although the service information referenced in EASA AD 2021–0291 specifies to send broken screws to Airbus, this AD does not include that requirement.

#### (j) Special Flight Permit

Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the airplane to a location where the actions of this AD can be performed (if the operator elects to do so), provided no passengers are onboard.

#### (k) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (l)(2) of this AD. Information may be emailed to: [9-AVS-AIR-730-AMOC@faa.gov](mailto:9-AVS-AIR-730-AMOC@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section,

International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* Except as required by paragraph (k)(2) of this AD, if any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

#### (l) Related Information

(1) For EASA AD 2021–0291, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADS@easa.europa.eu](mailto:ADS@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2022–0382.

(2) For more information about this AD, contact Dan Rodina, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th Street, Des Moines, WA 98198; telephone and fax 206–231–3225; email [dan.rodina@faa.gov](mailto:dan.rodina@faa.gov).

Issued on March 24, 2022.

**Lance T. Gant,**

*Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2022–06601 Filed 3–30–22; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2022–0387; Project Identifier AD–2021–01225–R]

RIN 2120–AA64

### Airworthiness Directives; Bell Textron Inc., Helicopters

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for