

Rules and Regulations

Federal Register

Vol. 88, No. 144

Friday, July 28, 2023

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

NUCLEAR REGULATORY COMMISSION

10 CFR Part 73

[NRC–2023–0068]

Regulatory Guide: Cybersecurity Event Notifications

AGENCY: Nuclear Regulatory Commission.

ACTION: Final guide; issuance.

SUMMARY: The U.S. Nuclear Regulatory Commission (NRC) is issuing Revision 1 to Regulatory Guide (RG), 5.83, “Cybersecurity Event Notifications.” This revision describes methods that the staff of the NRC considers acceptable for licensees to meet requirements in NRC regulations to report and record cybersecurity events.

DATES: Revision 1 to RG 5.83 is available on July 28, 2023.

ADDRESSES: Please refer to Docket ID NRC–2023–0068 when contacting the NRC about the availability of information regarding this document. You may obtain publicly available information related to this document using any of the following methods:

- *Federal Rulemaking Website:* Go to <https://www.regulations.gov> and search for Docket ID NRC–2023–0068. Address questions about Docket IDs in *Regulations.gov* to Stacy Schumann; telephone: 301–415–0624; email: Stacy.Schumann@nrc.gov. For technical questions, contact the individuals listed in the **FOR FURTHER INFORMATION CONTACT** section of this document.

- *NRC’s Agencywide Documents Access and Management System (ADAMS):* You may obtain publicly available documents online in the ADAMS Public Documents collection at <https://www.nrc.gov/reading-rm/adams.html>. To begin the search, select “Begin Web-based ADAMS Search.” For problems with ADAMS, please contact the NRC’s Public Document Room (PDR) reference staff at 1–800–397–4209, at 301–415–4737, or by email to

PDR.Resource@nrc.gov. The ADAMS accession number for each document referenced (if it is available in ADAMS) is provided the first time that it is mentioned in this document.

- *NRC’s PDR:* The PDR, where you may examine and order copies of publicly available documents, is open by appointment. To make an appointment to visit the PDR, please send an email to PDR.Resource@nrc.gov or call 1–800–397–4209 or 301–415–4737, between 8 a.m. and 4 p.m. eastern time (ET), Monday through Friday, except Federal holidays.

Revision 1 to RG 5.83 and the response to public comments may be found in ADAMS under Accession Nos. ML23087A017 and ML23087A018, respectively.

Regulatory guides are not copyrighted, and NRC approval is not required to reproduce them.

FOR FURTHER INFORMATION CONTACT:

Daniel Warner, Office of Nuclear Security and Incident Response, telephone: 301–287–3642; email: Daniel.Warner@nrc.gov; and Stanley Gardocki, Office of Nuclear Regulatory Research, telephone: 301–415–1067; email: Stanley.Gardocki@nrc.gov. Both are staff of the U.S. Nuclear Regulatory Commission, Washington, DC 20555–0001.

SUPPLEMENTARY INFORMATION:

I. Discussion

The NRC is issuing a revision in the NRC’s “Regulatory Guide” series. This series was developed to describe methods that are acceptable to the NRC staff for implementing specific parts of the agency’s regulations, to explain techniques that the staff uses in evaluating specific issues or postulated events, and to describe information that the staff needs in its review of applications for permits and licenses.

The proposed Revision 1 to RG 5.83 was issued with a temporary identification of Draft Regulatory Guide, DG–5079 (ADAMS Accession No. ML22250A443).

This revision of the guide (Revision 1) addresses new concerns identified since the NRC first issued RG 5.83 in 2015. The primary changes made have been to align the definitions in the glossary with those in recent updates to RG 5.71, and to provide clarification in the eight-hour notification section about the reportability of malicious activity

against devices that reside on the same networks as critical digital assets (CDAs) or that support CDAs.

II. Additional Information

The NRC published a notice of the availability of DG–5079 in the **Federal Register** on April 24, 2023 (88 FR 24715), for a 30-day public comment period. The public comment period closed on May 24, 2023. Public comments on DG–5079 and the staff responses to the public comments are available under ADAMS under Accession No. ML23087A018.

As noted in the **Federal Register** on December 9, 2022 (87 FR75671), this document is being published in the “Rules” section of the **Federal Register** to comply with publication requirements under title 1 of the *Code of Federal Regulations* (1 CFR), chapter I.

III. Congressional Review Act

This RG is a rule as defined in the Congressional Review Act (5 U.S.C. 801–808). However, the Office of Management and Budget has not found it to be a major rule as defined in the Congressional Review Act.

IV. Backfitting, Forward Fitting, and Issue Finality

Issuance of RG 5.83, Revision 1, does not constitute backfitting as defined in § 50.109 of title 10 of the *Code of Federal Regulations* (10 CFR), “Backfitting,” and as described in NRC Management Directive (MD) 8.4, “Management of Backfitting, Forward Fitting, Issue Finality, and Information Requests” (ADAMS Accession No. ML18093B087); constitute forward fitting as that term is defined and described in MD 8.4; or affect issue finality of any approval issued under 10 CFR part 52, “Licenses, Certifications, and Approvals for Nuclear Power Plants.” As explained in RG 5.83, Revision 1, applicants and licensees are not required to comply with the positions set forth in this guide.

V. Submitting Suggestions for Improvement of Regulatory Guides

A member of the public may, at any time, submit suggestions to the NRC for improvement of existing RGs or for the development of new RGs. Suggestions can be submitted on the NRC’s public website at <https://www.nrc.gov/reading-rm/doc-collections/reg-guides/>

contactus.html. Suggestions will be considered in future updates and enhancements to the “Regulatory Guide” series.

Dated: July 24, 2023.

For the Nuclear Regulatory Commission.

Meraj Rahimi,

Chief, Regulatory Guide and Programs Management Branch, Division of Engineering, Office of Nuclear Regulatory Research.

[FR Doc. 2023–15990 Filed 7–27–23; 8:45 am]

BILLING CODE 7590–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2023–0935; Project Identifier MCAI–2022–01311–T; Amendment 39–22491; AD 2023–13–06]

RIN 2120–AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Bombardier, Inc., Model BD–100–1A10 airplanes. This AD was prompted by an in-service event where the nose gear door amber caution message displayed on the crew alerting system during the initial climb after gear retraction. This AD requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective September 1, 2023.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of September 1, 2023.

ADDRESSES:

AD Docket: You may examine the AD docket at *regulations.gov* under Docket No. FAA–2023–0935; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For service information identified in this final rule, contact Bombardier Business Aircraft Customer Response Center, 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514–855–2999; email *ac.yul@aero.bombardier.com*; website *bombardier.com*.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available at *regulations.gov* under Docket No. FAA–2023–0935.

FOR FURTHER INFORMATION CONTACT:

Gabriel D. Kim, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7343; email *g-avs-nyaco-cos@faa.gov*.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Bombardier, Inc., Model BD–100–1A10 airplanes. The NPRM published in the **Federal Register** on April 25, 2023 (88 FR 24924). The NPRM was prompted by AD CF–2022–57, dated October 5, 2022, issued by Transport Canada, which is the aviation authority for Canada (referred to after this as the MCAI). The MCAI states an in-service event occurred where the nose gear door amber caution message displayed on the crew alerting system during the initial climb after gear retraction. After landing, an inspection found that one of the nose landing gear (NLG) door hinge fitting assemblies were broken. The absence of an inspection to detect cracks in the fillet radii of the NLG door hinge fitting could result in door misalignment with the airplane.

In the NPRM, the FAA proposed to require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. The FAA is issuing this AD to address cracked fillet radii of NLG door hinge fittings. The unsafe condition, if not addressed, could result in a NLG door misalignment, which could increase the drag and yawing movement during flight, could cause jamming of the door affecting the ability to extend or retract the NLG, or could potentially result in the NLG door detaching from the airplane.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA–2023–0935.

Discussion of Final Airworthiness Directive

Comments

The FAA received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on this product. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Bombardier Challenger 300 BD–100 Time Limits/Maintenance Checks Temporary Revision (TR) TR5–2–101, dated June 30, 2022; and (Bombardier) Challenger 350 BD–100 Time Limits/Maintenance Checks Temporary Revision TR5–2–30, dated June 30, 2022. This service information specifies new or more restrictive airworthiness limitations for the NLG door hinge fittings fillet radii. These documents are distinct because they apply to different airplane configurations.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD, would affect 716 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

The FAA has determined that revising the maintenance or inspection program takes an average of 90 work-hours per operator, although the agency recognizes that this number may vary from operator to operator. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), the FAA has determined that a per-operator estimate is more accurate than a per-airplane