

Models	Serial numbers	(b) <i>Who must comply with this AD?</i> Anyone who wishes to operate any of the above airplanes on the U.S. Register must comply with this AD. (c) <i>What problem does this AD address?</i> The actions specified in this document are intended to correct substandard quality cockpit voice recordings caused by the configuration of the present CVR system, which could affect air safety if important	information that the CVR provides is not available after an accident. This information helps determine the probable cause of an accident and aids in developing necessary corrective action or design changes to prevent future accidents. (d) <i>What actions must I accomplish to address this problem?</i> To address this problem, you must accomplish the following:
1900 and 1900C.	All serial number airplanes where RAC installed the cockpit voice recorder (CVR).		
1900D	UE-1 through UE-376.		
Action	Compliance time	Procedures	
Accomplish the CVR system modifications specified in Raytheon Recommended Service Bulletin SB 23-3094, Issued: November 1999..	Within 12 months after the effective date of this AD..	Do the modifications in accordance with procedures in the ACCOMPLISHMENT INSTRUCTIONS section of Raytheon Recommended Service Bulletin SB 23-3094, Issued: November, 1999.	

(e) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

(1) Your alternative method of compliance provides an equivalent level of safety; and
(2) The Manager, Wichita Aircraft Certification Office (ACO), approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO.

Note: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* You can contact Mr. Harvey Nero, Aerospace Engineer, Wichita Aircraft Certification Office, FAA, 1801 Airport Road, Mid-Continent Airport, Wichita, Kansas 67209; telephone: (316) 946-4137; facsimile: (316) 946-4407.

(g) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(h) *How do I get copies of the documents referenced in this AD?* You may obtain copies of the documents referenced in this AD from the Raytheon Aircraft Corporation, P.O. Box 85, Wichita, Kansas 67201-0085. You may examine these documents at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106.

Issued in Kansas City, Missouri, on June 6, 2000.

Marvin R. Nuss,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-14942 Filed 6-13-00; 8:45 am]

BILLING CODE 4910-13-p

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 92-NM-206-AD]

RIN 2120-AA64

Airworthiness Directives; Gulfstream Model G-IV Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Proposed rule; withdrawal.

SUMMARY: This action withdraws a notice of proposed rulemaking (NPRM) that proposed a new airworthiness directive (AD), applicable to certain Gulfstream Model G-IV series airplanes. That action would have required inspection of the data plate on the bottom of the hydraulic brake control module (HBCM) to verify the part and serial numbers, and replacement of the HBCM, if necessary. Since the issuance of the NPRM, the Federal Aviation Administration (FAA) has received new data indicating that the proposed actions have been accomplished on all affected airplanes; therefore, the previously identified unsafe condition no longer exists. Accordingly, the proposed rule is withdrawn.

FOR FURTHER INFORMATION CONTACT: Neil Barryman, Aerospace Engineer, Systems and Flight Test Branch, ACE-116A, FAA, Small Airplane Directorate, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia

30349; telephone (770) 703-6098; fax (770) 703-6097.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to add a new airworthiness directive (AD), applicable to certain Gulfstream Model G-IV series airplanes, was published in the **Federal Register** as a Notice of Proposed Rulemaking (NPRM) on April 9, 1993 (58 FR 18347). The proposed rule would have required inspection of the data plate on the bottom of the hydraulic brake control module (HBCM) to verify the part and serial numbers, and replacement of the HBCM, if necessary. That action was prompted by a landing incident that involved a malfunction of the braking system. The proposed actions were intended to prevent a malfunction of the braking system, which could lead to reduced controllability of the airplane on the ground.

Actions that Occurred Since the NPRM Was Issued

Since the issuance of that NPRM, Gulfstream has provided evidence to the FAA that the actions proposed in the NPRM have been accomplished on all affected airplanes (Evidence was provided to the FAA in Gulfstream's letter of May 30, 2000, which is filed in the Rules Docket.)

FAA's Conclusions

Upon further consideration, the FAA has determined that, based on this evidence, the previously identified unsafe condition no longer exists with regard to the Gulfstream Model G-IV series airplanes. Accordingly, the proposed rule is hereby withdrawn.

Withdrawal of this notice of proposed rulemaking constitutes only such action, and does not preclude the agency from issuing another notice in the future, nor does it commit the agency to any course of action in the future.

Regulatory Impact

Since this action only withdraws a notice of proposed rulemaking, it is neither a proposed nor a final rule and therefore is not covered under Executive Order 12866, the Regulatory Flexibility Act, or DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979).

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Withdrawal

Accordingly, the notice of proposed rulemaking, Docket 92–NM–206–AD, published in the **Federal Register** on April 9, 1993 (58 FR 18347), is withdrawn.

Issued in Renton, Washington, on June 7, 2000.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00–14952 Filed 6–13–00; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 95–NM–202–AD]

RIN 2120–AA64

Airworthiness Directives; Gulfstream G–1159 (G–II), G–1159A (G–III), and G–1159B (G–IIB) Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Proposed rule; withdrawal.

SUMMARY: This action withdraws a notice of proposed rulemaking (NPRM) that proposed a new airworthiness directive (AD), applicable to all Gulfstream G–1159 (G–II), G–1159A (G–III), and G–1159B (G–IIB) series airplanes. That action would have required a one-time inspection to detect corrosion of the material layers of the lower aft fuselage skin in Fuselage Station (FS) 580 bulkhead assembly, and repair, if necessary. The proposal also would have required modification of the aft fuselage area and various follow-on actions. Since the issuance of the NPRM, the Federal Aviation Administration (FAA) has received new data from the manufacturer verifying that all airplanes have accomplished those actions. Accordingly, the proposed rule is withdrawn.

FOR FURTHER INFORMATION CONTACT: Neil Berryman, Aerospace Engineer, Systems

and Flight Test Branch, ACE–116A, FAA, Small Airplane Directorate, Atlanta Aircraft Certification, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30349; telephone (770) 703–6098; fax (770) 703–6097.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to add a new airworthiness directive (AD), applicable to all Gulfstream G–1159 (G–II), G–1159A (G–III), and G–1159B (G–IIB) series airplanes, was published in the **Federal Register** as a Notice of Proposed Rulemaking (NPRM) on June 24, 1996 (61 FR 32369). The proposed rule would have required a one-time inspection to detect corrosion of the material layers of the lower aft fuselage skin in Fuselage Station (FS) 580 bulkhead assembly, and repair, if necessary. The proposal also would have required modification of the aft fuselage area and various follow-on actions. That action was prompted by reports of varying levels of corrosion in the structure at FS 580. The proposed actions were intended to prevent the retention of moisture in the fuselage structure, and subsequent corrosion in FS 580 bulkhead assembly, which could result in reduced structural capability of the skin joint and resultant depressurization of the airplane.

Actions That Occurred Since the NPRM Was Issued

Since the issuance of that NPRM, Gulfstream has provided evidence to the FAA that the actions proposed in the NPRM have been accomplished on all affected airplanes. (Evidence was provided to the FAA in Gulfstream's letter of May 30, 2000, which is filed in the Rules Docket.)

FAA's Conclusions

Upon further consideration, the FAA has determined that the unsafe condition no longer exists on the subject airplanes. Accordingly, the proposed rule is hereby withdrawn.

Withdrawal of this notice of proposed rulemaking constitutes only such action, and does not preclude the agency from issuing another notice in the future, nor does it commit the agency to any course of action in the future.

Regulatory Impact

Since this action only withdraws a notice of proposed rulemaking, it is neither a proposed nor a final rule and therefore is not covered under Executive Order 12866, the Regulatory Flexibility Act, or DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979).

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Withdrawal

Accordingly, the notice of proposed rulemaking, Docket 95–NM–202–AD, published in the **Federal Register** on June 24, 1996 (61 FR 32369), is withdrawn.

Issued in Renton, Washington, on June 7, 2000.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00–14953 Filed 6–13–00; 8:45 am]

BILLING CODE 4910–13–U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 96–NM–90–AD]

RIN 2120–AA64

Airworthiness Directives; Gulfstream Model G–1159 (G–II), G–1159A (G–III), and G–1159B (G–IIB) Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Proposed rule; withdrawal.

SUMMARY: This action withdraws a notice of proposed rulemaking (NPRM) that proposed a new airworthiness directive (AD), applicable to all Gulfstream Model G–1159 (G–II), G–1159A (G–III), and G–1159B (G–IIB) series airplanes. That action would have required inspections to detect cracking and/or corrosion at various locations of the wings, and modification of cracked and/or corroded parts. Since the issuance of the NPRM, the Federal Aviation Administration (FAA) has received new data verifying that all affected airplanes have complied with the requirements proposed by that NPRM. Accordingly, the proposed rule is withdrawn.

FOR FURTHER INFORMATION CONTACT: Neil Berryman, Aerospace Engineer, Systems and Flight Test Branch, ACE–116A, FAA, Small Airplane Directorate, Atlanta Aircraft Certification, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30349; telephone (770) 703–6098; fax (770) 703–6097.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to add a new airworthiness directive (AD), applicable to all Gulfstream Model G–